

1552010

INS. CASE OWNER:

CC LPC1801

LKK:

IDAC:

Surveyor:

marcus

DOI:

21/10/18

Date / Time:

21/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJK 4047M

Claim No.:

18/10/18/1010101068

Name of Insured:

PHARAH AN HOOR MORNAM

Policy No.:

218205018082

Insured Tel No.:

HP:

91807352

Make / Model:

KUNNOM

Excess Sec II :SS

D.O.A.:

25/10/18

Place of Accident:

Minitown

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJK 4047M



INSRS:

WSP:

Tel:

Liability:

RMKS:

TAN LIM



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
21/10/18	Non-Reporting ltr (1st):	
21/10/18	Non-Reporting ltr (2nd):	
21/10/18	Non-Reporting ltr (Final):	
21/10/18	Notification ltr (if non-pickup):	
21/10/18	Call OI:	
21/10/18	After call ltr to OI:	
21/10/18	Documentation Check List:	Handler Typist
21/10/18	Notification ltr (if non-pickup)	
21/10/18	After call ltr to Of:	
21/10/18	Authorisation To Act:	
21/10/18	Release Voucher:	
21/10/18	Final Repair Bill:	
21/10/18	Car Rental Invoice:	
21/10/18	Towing Invoice:	
21/10/18	LTA / GIA:	
21/10/18	Medical Bill:	
21/10/18	PIR:	
21/10/18	Mandate/Reject Instruction:	
21/10/18	LOD:	
21/10/18	Payment Breakdown Form:	
21/10/18	Post-Repair Photos:	
21/10/18	Others:	

<b>PRELIMINARY ADVICE</b>	Date/Time:	Sent By:	Confirm by: CUS
<b>FINALIZATION</b>	Date/Time:	Confirm with:	Confirm by: CUS
Repair Cost:	PIP SS 1,929.50	(3 days) Reduction:	53 %
<b>FINAL SETTLEMENT</b>	Date/Time: 17.1.19	Confirm with JOHNSON	Email <input checked="" type="checkbox"/> Cal <input type="checkbox"/>
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	21
Repair Cost:	W1651 SS 2,064.51	01 REP ENDED TP	
Loss of Rental (LOR):	SS -	( days)	
Loss of Use (LOU):	SS 240.00	(S 60 x 4 days)	
Loss of Income (LOI):	SS -	(S x days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[Tick only one]		
GIA/LTA Search	SS 2.00		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
<b>Total:</b>	SS 2,306.51	<b>Global Sum SS:</b>	
<b>FINAL PAYMENT</b>	Date/Time: 17.1.19	Confirm with: JOHNSON	Email <input checked="" type="checkbox"/> Cal <input type="checkbox"/>
Payee 1:	SS 2,306.51	Name 1:	TAN LIM MOTOR PTE LTD
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC6/LPC18019622/Ueb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 29-10-2018	
			Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJX 4047U		Veh. Inspected	SLK 2447G
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	29/10/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	25/10/2018		Inspection Date	29/10/2018
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Singapore NRIC

Owner ID:

9648B

**Vehicle Details**

Vehicle No.:

SLK2447G

Vehicle to be Exported:

No

Intended Deregistration Date:

26 Oct 2018

Vehicle Make:

MERCEDES BENZ

Vehicle Model:

CLA180 SB (R18 BI)

Primary Colour:

White

Manufacturing Year:

2015

Engine No.:

27091030671371

Chassis No.:

WDD1179422N221160

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$29,600.00

Original Registration Date:

28 Apr 2016

First Registration Date:

28 Apr 2016

Transfer Count:

1

Actual ARF Paid:

\$28,440.00

**Intended PARF Rebate Details**

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

27 Apr 2026

PARF Rebate Amount:

\$21,330.00

**Intended COE Rebate Details**

COE Expiry Date:

27 Apr 2026

COE Category:

A - Car up to 1600cc &amp; 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$45,504.00

COE Rebate Amount:

\$34,140.00

**Total Rebate Amount:****\$55,470.00**

The information contained herein is correct as at 26 Oct 2018

OK

Lonpac Insured's Veh No : SJX4047U  
Date of Accident : 25 October 2018

*not authorized  
28/10/18  
3 day.  
who phd before  
party.*



陳林摩哆私人有限公司  
**TAN LIM MOTOR PTE LTD**

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

Mr Seet Boon Kian (Xue wengqiang)

Date : 29 October 2018

*LKK motor -  
29/10/18 1030h*

Estimate To Repair SLK2447G - Mercedes Benz CLA180 (R18 BI)  
Chassis No : WDD1179422N221160

S/No	Quantity	Description	Amount
<b>NETT ITEMS</b>			
01	1 pc	rear bumper <i>pen</i>	\$ 0.00
02	1 pc	rear bumper reinforcement <i>?</i>	\$ 0.00
03	1 pc	rear bumper lower centre <i>80-2-1</i>	\$ 0.00
04	1 pc	rear bumper parking sensor side right <i>Subh</i>	\$ 0.00
05	1 pc	rear bumper parking sensor centre right <i>11X</i>	\$ 0.00
06	1 pc	rear bumper parking sensor centre holder right <i>11X</i>	\$ 0.00
07	1 pc	rear bumper inner frame <i>11X</i>	\$ 0.00
08	1 pc	right rear lamp <i>11X</i>	\$ 0.00
09	1 pc	rear bumper lower tow cover <i>11X</i>	\$ 0.00
10	1 pc	rear bumper lower diffuser <i>11X</i>	\$ 0.00
Less 10 %			\$ 0.00
<b>LABOUR &amp; MISC. CHARGES</b>			
01		To check electrical lighting concerned.	\$ 60.00
02		To reinstall of rear bumper parking sensor.	\$ 150.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 400.00
04		Putty and spray painting of the affected portion.	\$ 580.00
			\$ 1,190.00
<b>Total</b>			<b>\$ 1,190.00</b>

*20  
50  
250  
300*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Lonpac Insured's Veh No : SJX4047U

Date of Accident : 25 October 2018

not Authorized  
29/10/18  
3 day  
p/p \$ 1929.50/-  
subur paly



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216  
Tel : 68585151 (24 Hours) Fax : 68580877  
GST Regn. No. : M2-8922054-2

Mr Seet Boon Kian (Xue wengqiang)

Date : 01 November 2018

**Estimate To Repair SLK2447G - Mercedes Benz CLA180 (R18 BI)**

Chassis No : WDD1179422N221160

S/No	Quantity	Description	Amount
		<b>NETT ITEMS</b>	
01	1 pc	rear bumper	\$ 1,055.00
02	1 pc	rear bumper reinforcement	\$ 530.00
03	1 pc	rear bumper lower centre	\$ 235.00
04	1 pc	rear bumper parking sensor side right	\$ 165.00
05	1 pc	rear bumper parking sensor centre right	\$ 165.00
06	1 pc	rear bumper inner frame	\$ 105.00
07	1 pc	right rear lamp	\$ 735.00
08	1 pc	rear bumper lower tow cover	\$ 35.00
09	1 pc	rear bumper lower diffuser	\$ 200.00
		Less 10 %	\$ 3,225.00 \$ 322.50
			\$ 2,902.50
		<b>LABOUR &amp; MISC. CHARGES</b>	
01		To check electrical lighting concerned.	\$ 60.00
02		To reinstall of rear bumper parking sensor.	\$ 150.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 400.00
04		Putty and spray painting of the affected portion.	\$ 580.00
			\$ 1,190.00
		<b>Total</b>	\$ 4,092.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P - 1455  
10%  
1309.50  
620.00  
1929.50

**Shu Pei (LKKAUTO)**

---

**From:** ONG LI LI <lilong@lonpac.com>  
**Sent:** Wednesday, 31 October 2018 4:58 PM  
**To:** Shu Pei (LKKAUTO)  
**Cc:** MT\_Claim\_SG; Admin A; Asher Sng (LKKAUTO)  
**Subject:** RE: Direct Settlement - Accident Involving SJX4047U (OI : LPC - 18/18/18/VP05/021068) AND SLK2447G (TP : LKK REF - CC6/LPC18019622/Ueb3) on 25.10.2018  
**Attachments:** SJX4047U 251018.PDF

Dear Shu Pei

Please see attached for our Insured's GIA report for your handling.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]  
**Sent:** Tuesday, 30 October, 2018 6:12 PM  
**To:** GERALD POH WEE BIN; ericwoo; ONG LI LI  
**Cc:** MT\_Claim\_SG; Admin A; Asher Sng (LKKAUTO)  
**Subject:** Direct Settlement - Accident Involving SJX4047U (OI : LPC - TBA) AND SLK2447G (TP : LKK REF - CC6/LPC18019622/Ueb3) on 25.10.2018

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SLK 2447G at M/s Tan Lim Motor Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Our case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeit@lkkauto.com](mailto:shupeit@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



**Asher Sng (LKKAuto)**

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Tuesday, 13 November 2018 10:02 AM  
**To:** 'Johnson Chua'; 'Wei Shong'; 'Patricia Tan - Tan Lim Motor Pte Ltd'  
**Subject:** Accident Involving SLK 2447G & SJX 4047U on 25/10/2018

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Your Ref: SLK 2447G  
Our Ref: CC6/LPC18019622/Ueb3

Dear Sir/Madam,

**Accident Involving SLK 2447G & SJX 4047U on 25/10/2018**

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You,

Best Regards,

**Asher Sng** | Case Handler  
**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC18019622/Ueb3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 28-02-2019



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJX 4047U	Veh. Inspected	SLK 2447G
Policy No.	Z18VP05018682	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/021068	Excess (\$)	0.00
Assign From		Assign Date	29/10/2018

### 2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ CLA180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDD1179422N221160	Colour	WHITE
Odometer	37632	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40 ZR18	GOODYEAR	6 mm
L/H Front Tyre	225/40 ZR18	GOODYEAR	6 mm
R/H Rear Tyre	225/40 ZR18	GOODYEAR	6 mm
L/H Rear Tyre	225/40 ZR18	GOODYEAR	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	25/10/2018	Inspection Date	29/10/2018
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 2447G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (N)	TORN	1,055.00	1,055.00
1	REAR BUMPER REINFORCEMENT (N)	TO REPAIR SEE LABOUR	530.00	-
1	REAR BUMPER LOWER CENTRE (N)	GRAZED	235.00	235.00
1	REAR BUMPER PARKING SENSOR SIDE RIGHT (N)	SHORTED	165.00	165.00
1	REAR BUMPER PARKING SENSOR CENTRE RIGHT (N)	NOT NECESSARY	165.00	-
1	REAR BUMPER INNER FRAME (N)	NOT NECESSARY	105.00	-
1	RIGHT REAR LAMP (N)	NOT NECESSARY	735.00	-
1	REAR BUMPER LOWER TOW COVER (N)	NOT NECESSARY	35.00	-
1	REAR BUMPER LOWER DIFFUSER (N)	NOT NECESSARY	200.00	-
	LESS 10% DISCOUNT		-322.50	-145.50
			2,902.50	1,309.50
	<b><u>LABOUR</u></b>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		150.00	50.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT.		400.00	250.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		580.00	300.00
			1,190.00	620.00
	<b>GRAND TOTAL</b>		<b>4,092.50</b>	<b>1,929.50</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,929.50</b>

Report Ref No. CC6/LPC18019622/Ueb3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.