

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188
Customer Detail

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to use for attractive items!

ESTIMATE

Account Detail	Account No	Mr Koh Hwee Liang 511 Choa Chu Kang Street 51 #12-243 Singapore 680511 Home: 67695446
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006/ICIII1	
	Document No	
	Document Date	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	MWYNKT	S3	27/06/2018	SDV0775J	4678	17245	7DS/SDV0775J/251014
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

MHF228H3400055277	2NRX342887	60	Sam San Joi	26/10/2018	9.50	--/--/----	0.00
--------------------------	-------------------	-----------	--------------------	-------------------	-------------	-------------------	-------------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SKC6065C DRIVE IN:26/10/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				✓ 30.00
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				✓ 183.18
3	S	BP-SUBLET DRILL HOLE & INSTALL REAR REVERSE SENSOR				✓ 154.00
4	S	BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST				✓ 154.00
5	S	BP-SUBLET SEALANT - TAILGATE, REAR END PANEL				80 160.00
6	S	BP-SUBLET REMOVE & INSTALL REAR REVERSE CAMERA				✓ 154.00
7	S	BP-SUBLET REPLACE & INSTALL REAR WINDSCREEN GLASS				✓ 396.00
8	S	BP-SUBLET TRANSFER & INSTALL COMPONENTS TO NEW TAILGATE				✓ 308.00
9	S	BP-SUBLET REMOVE & INSTALL REAR COMPARTMENT CARPET , GARNISH A TRIMMING TO ASSIST REPAIR				✗ 308.00
10	B	BP-ECU TO RESET ECU AND REPROGRAMME				✓ 134.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

PLEASE TEAR ALONG PERFORATED LINE

3798872

TO SECURITY GUARD

3798872

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME **08/11/2018**
15:58

VEHICLE NO

SDV0775J

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sgCo Reg No : 196700086Z
GST Reg No : MR-8500000-9Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!**ESTIMATE**Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188
Customer Detail

Account Detail	Account No	Mr Koh Hwee Liang 511 Choa Chu Kang Street 51 #12-243 Singapore 680511 Home: 67695446
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006/ICIII1	
	Document No	
	0	
	Document Date	
	08/11/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	MWYNKT	S3	NSP170R	27/06/2018	SDV0775J	4678	17245
Chassis No Engine No TWC No Terms Service Engineer Vehicle In Collected On							

MHFZ28H3400055277	2NRX342887	60	Sam San Joi	26/10/2018	9.50	--/--/----	0.00
-------------------	------------	----	-------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	S	BP-SUBLET REPLACE REAR BUMPER, TAILGATE, REAR BUMPER LOWER, ETC STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED D AREAS				1232 3080.00
12	S	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS				1012 2530.00
13	1	S52159-OU919 COVER, RR BUMPER, L <i>Delud</i>	1.00	310.20		✓ 310.20
14	2	S52156-OD100 SUPPORT, RR BUMPER S	1.00	72.20		✓ 72.20
15	3	S52576-OD270 RETAINER, RR BUMPER	1.00	69.30		✓ 69.30
16	4	S52155-OD110 SUPPORT, RR BUMPER S	1.00	72.20		✓ 72.20
17	5	S52575-OD280 RETAINER, RR BUMPER	1.00	69.30		✓ 69.30
18	6	S52161-OK040 CLIPS <i>new</i>	10.00	4.00		✓ 40.00
19	7	S52151-OD010 EXTENSION, RR BUMPER <i>ut</i>	1.00	186.40		✓ 186.40
20	8	S58302-OD010 PANEL SUB-ASSY, LWR <i>Repr</i>	1.00	683.30		✓ 683.30
21	9	S64716-OD170 C0 COVER, DECK TRIM, RR <i>new</i>	1.00	150.90		✓ 150.90
22	0	S67005-OD360 PANEL SUB-ASSY, BACK <i>Dealed</i>	1.00	1110.70		✓ 1110.70
23	1	S67881-OD130 WEATHERSTRIP, BACK D <i>new</i>	1.00	365.20		✓ 365.20
24	2	S68105-OD260 GLASS SUB-ASSY, BACK <i>new</i>	1.00	987.90		✓ 987.90
25	3	S67751-OD060 C0 BOARD, BACK DOOR TRI <i>new</i>	1.00	186.40		✓ 186.40
26	4	T90467-08186 C3 CLIP <i>new</i>	10.00	2.00		✓ 20.00
27	5	S69350-OD240 LOCK ASSY, BACK DOOR <i>new</i>	1.00	458.50		✓ 458.50

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3798873

TO SECURITY GUARD

3798873

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE
TIME
08/11/2018
15:58

VEHICLE NO

SDV0775J

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188
Customer Detail

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

ESTIMATE

Account Detail	Account No	Mr Koh Hwee Liang 511 Choa Chu Kang Street 51 #12-243 Singapore 680511 Home: 67695446
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	
	Document No	
	0	
	Document Date	
	08/11/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	MWYNKT	S3	NSP170R	27/06/2018	SDV0775J	4678	17245
Chassis No							
Engine No							
TWC No							
Terms							
Service Engineer							
Vehicle In							
Collected On							

MHFZ28H3400055277	2NRX342887	60	Sam San Joi	26/10/2018	9.50	--/--/----	0.00
-------------------	------------	----	-------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
28	6	S69430-0D090 STRIKER ASSY, BACK D <i>Not in</i>	1.00	25.30		X 25.30
29	7	T90975-02086 FRONT BONNET EMBLEM, <i>Not in</i>	1.00	72.20		✓ 72.20
30	8	S75441-0D070 PLATE, BACK DOOR NAM <i>Not in</i>	1.00	52.10		✓ 52.10
31	9	S75442-0D300 PLATE, BACK DOOR NAM <i>Not in</i>	1.00	34.80		✓ 34.80
32	0	SPC507-0D014 17 BACK SENSOR (1D4, SILVER ME) <i>Not in</i>	1.00	172.40		X 172.40
Adrian Lij P/P 12/11/18 050 days.						
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	12,730.48
		Labour	5,139.30
		Materials	164.00
		Lubrication/Fluid	7,427.18
		Others	0.00
		0.00	GST 7.00%
			Less
			Amount Due
			13,621.61

PLEASE TEAR ALONG PERFORATED LINE

3798874

TO SECURITY GUARD

3798874

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE
TIME
08/11/2018
15:58

VEHICLE NO

SDV0775J

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors