



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKG5275Z

Hexacon Construction Pte Ltd

432 Balestier Road
#02-432 Public Mansion
Singapore 329813
Attn: Mr Pang Hoe Sang
96380542

Vehicle & Document Information

WIP No 27920
Reg No/Reg Date SKG5275Z / 17/07/2018
Date In/Mileage / 0
Chassis No WDD2130452A475322
Engine No 27492031519027
Make/Model MB/MB E 250 SEDAN EXCLUSIVE/EXCLUSIVE
Colour/Trim 021 197 Obsidian Bl/ 048 815 Nappa Porce

Account No	Terms	Date/Time Printed	CSE	Operator
WCV10652	CRDVCH	27/10/2018/ 10:32		301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				960.00
A BPIRES				1920.00
RESpray REAR BUMPER				
A BPILAB				
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.			0.10	380.00
A BPILAB				
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				
M REAR BUMPER	1.00	1430.46	00.00	1430.46
M LH/ REAR BUMPER CHROME MOULDING	1.00	121.18	00.00	121.18
M RH/ REAR BUMPER CHROME MOULDING	1.00	121.18	00.00	121.18
M REAR BUMPER LOWER TRIM	1.00	260.25	00.00	260.25
M REAR BUMPER LOWER CHROME MOULDING	1.00	301.99	00.00	301.99
M CTR/ BASIC MOUNTING FOR BUMPER	1.00	79.85	00.00	79.85

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Cycle & Carriage Industries Pte Ltd

Customer Service Centre - Pandan Loop

Tauhin 92495449
PWP
3/12/18 e 2pm
03 days
surelwhants.com

Nett 5,574.91
7% GST on 5574.91 390.24
Total Payable 5,965.15

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg