


MBM WHEELPOWER PTE LTD



Your Ref: SMD3743U

Our Ref: SLZ5161G

*Not Authorised
Resurvey By paint
2-3 days*

To: AXA

CC

Fax

Date: 27/10/2018
From: Stephanie
Fax: 64525333
Contact: 86865188
Make / Model: MERCEDES BENZ GLA200 AUTO
Chassis No.: WDC1569432J440001
Engine No.: 27091031450399
Year of Make: 2017
Accident Date: 24 October 2018

ESTIMATE FOR VEHICLE NO. : SLZ5161G

DESCRIPTION	QTY	List Price
TAIL LAMP LH	1	\$ 945.00
TAIL LAMP BRACKET LH	1	\$ 125.00
REAR BUMPER	1	\$ 1,890.00
REAR BUMPER CLIPS/RIVETS	10	\$ 80.00
REAR BUMPER REINFORCEMENT	1	\$ 720.00
REAR BUMPER SPONGE	1	\$ 119.00
REAR BUMPER LH SIDE RETAINER	1	\$ 65.00
REAR BUMPER REVERSE SENSORS @ \$250 EACH	2	\$ 500.00
SENSOR SPACER RINGS	2	\$ 30.00
REAR BUMPER LOWER COVER	1	\$ 1,199.00
REAR BUMPER LOWER DIFFUSER	1	\$ 720.00
REAR LH WHEEL ARCH MOULDING	1	\$ 276.00
REAR LH FENDER	1	\$ 2,520.00
REAR LH FENDER INNERSHIELD	1	\$ 345.00
REAR LH FENDER INNERSHIELD CLIPS	10	\$ 80.00
Total:		\$ 9,614.00
LESS 10%		\$ (961.40)
Parts Total:		\$ 8,652.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SPECIAL NETT

BODY SEALANT

1 \$ 80.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

\$ 1,200.00

TO REMOVE & REPLACE BUMPER SENSORS

\$ 100.00

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$ 120.00

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ 1,200.00

Total: \$ 11,352.60

7% GST: \$ 794.68

Grand Total: \$ 12,147.28

Mbm wheelpower pte ltd

160 SIN MING DRIVE #06-02

SIN MING AUTOCITY

t62628888 f64525333

Company Registration Number : 200204110W