

MBM WHEELPOWER PTE LTD

Your Ref: SDG5289S

Our Ref: SJW757K


To: AXA

CC

Fax

Not Authorized
Re survey by pain
3 days

Date: 30/10/2018
From: Stephanie
Fax: 64525333
Contact: 86865188
Make / Model: PORSCHE CAYENNE 3.6 AT ABS
AIRBAGS 4WD 5DR
Chassis No.: WP1ZZZ92ZELA07470
Engine No.: M5502E08623
Year of Make: 2014
Accident Date: 25 October 2018



ESTIMATE FOR VEHICLE NO. : SJW757K

DESCRIPTION

FRONT BUMPER
FRONT BUMPER CLIPS
FRONT BUMPER RIVETS
FRONT BUMPER RH SIGNAL LAMP
FRONT BUMPER RH FOG LAMP
FRONT BUMPER RH FOG LAMP COVER
FRONT BUMPER SENSORS @ \$350 EACH
SENSOR SPACER RINGS
FRONT BUMPER LOWER COVER
FRONT RH WHEEL ARCH MOLDING

QTY		List Price
1	\$	<i>Bulld</i> 3,600.00 ✓
10	\$	<i>m</i> 90.00 ✓
10	\$	<i>m</i> 90.00 ✓
1	\$	<i>SL</i> 320.00 X
1	\$	<i>SL</i> 500.00 i
1	\$	<i>SL</i> 210.00)
2	\$	<i>SL</i> 700.00)
2	\$	<i>m</i> 30.00 i
1	\$	1,320.00 ✓
1	\$	<i>Not Rep</i> 890.00 ✓
Total: \$		7,750.00
LESS 10% \$		(775.00)
Parts Total: \$		6,975.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SPECIAL NETT

BODY SEALANT

1

\$

nr 80.00 *1*

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO
KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.

\$

4001 1,200.00

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$

301 120.00

TO REMOVE & REPLACE BUMPER SENSORS

\$

601 100.00

TO SPRAY PAINT ON THE AFFECTED AREAS

\$

5001 900.00

Total: \$ 9,375.00

7% GST: \$ 656.25

Grand Total: \$ 10,031.25

Mbm wheelpowerpte ltd

160 SIN MING DRIVE #06-02

SIN MING AUTOCITY

t62628888 f64525333

Company Registration Number : 200204110W