

22/03/2012

ASS. REC. BY:

REF: CS / CTL18019667 / Tltber | Special Instruction:

SUNVAYOR  
MortimerASSIGNMENT (Office)

From (Person): Elaine Owing of CTL Date/Time: 21/02/08 4:13pm

Estimated Cost: Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLR 381m Insured: SLP 358S

at Workshop m/s Performance Tel: 63190174

of 318 Alexandra Rd

Policy No: DMHCSN 1737 361801 Claim No: SHM18005015C02

Sum Insured: Excess:

Make of Veh: D.O.A. 20-10-2008  
(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time: 21-10-2008 528pm Person Contacted: Caroline Vehicle IN / OUT

Date/Time Action/Instruction ( ✓ ) Estimate

SLR 381m - X

SLP 358S - X

Part m Part \$3,349.80 Cred: 1388.15, 29%

Signature: *Tanji*

REF:

CTI

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: *Kevin*

Veh No: *SLR 381M* Yr Regn: *2017 July*  
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: *BMW X1* C.C. *1499*  
 Colour: *white* A/C: Insured / Std / NI / NA  
 Sp. Reading: *12479* T/Radio: Insured / Std / NI / NA  
 Eng/No: *1*  
 C/No: *WBAHS120905597315*  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: *225/45R18*  
 R: *7*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front Rear  
 R/Bal. *G* mm R/Bal. *C* mm  
 L/Bal. *L* mm L/Bal. *L* mm  
 D.O.A. D.O.I. *7/11/18*  
 Survey held at *PML*  
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 04 DEC 2018

*[Signature]*  
*4/12/2018*

Date/Time, File Pass to?

☐ : Preli. Report  
☒ : Final Report

Days Of Repair: *3*

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Invs (\$)  
☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS, St

Photos

Others

TOTAL

Report Format: *TP*

Lump Sum / I.B.I. (\$) *3349.80*

*220*

*220*

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Oct 2018		29 Oct 2018 16:13 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All																				
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>																						
Insured:	SWEE SENG LEASING PTE LTD, Co. Reg. No.: 201111948K																							
Main Claimant:	WU LI LIN ALLISON, ID: S9243485J																							
Vehicle Reg. No.:	SLR381M	Date of Loss:	20/10/2018 21:00 - :59																					
Claim Type:	TP / SNM18D05015C02	Policy/Cover Note No.:	DMHCSN1737361801 (Comprehensive)																					
Vehicle Reg. No. (Insured):	SLP358S	Policy No. (Claimant):	5101826809																					
		Excess:	S\$0.00																					
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174																							
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]																							
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/11/2018]																							
Driver/Custodian (Insured):	KIM MINSUN (43 / Female), NRIC: G5247862L, Tel: +6581809599																							
Adj Asg. Remarks:	EST \$4984.17, CASE WITH SJE.																							
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>																						
There are no mail for this case.																								
<div> <div> <div>ALL ASSOCIATED TASKS</div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> </div> <table> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Tuesday, 4 December 2018 2:59 PM  
**To:** PBSP; Taufikh (LKKAUTO); SUR  
**Subject:** RE: FINAL REPORT / SLR381M

Dear Caroline,

Confirm Labour & Parts : 3,349.80

Repair days: 3

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP <pml-pbsp@sime-darby.com.sg>  
**Sent:** Wednesday, 28 November 2018 5:57 PM  
**To:** Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** FINAL REPORT / SLR381M

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 1,976.00  
Total Parts : 1,373.80  
Total Labour & Parts : 3,349.80

Repair days: 3

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/10/2018 23:32
Date Of Accident	20/10/2018 21:25
Exact Location Of Accident	7 9 BISHAN STREET 15 S(573908)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR381M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	WU LI LIN ALLISON
NRIC No	S9243485J
Email Address	ALLISONLILIN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91378653
Alternative Phone No	OTHERS-91378653

### Vehicle Particulars

Manufacturer	BMW
Model	X1
Exact Purpose for which vehicle was being used at time of accident	PERSONAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101826809
Cover Note Number	

### Driver

Name of Driver	WU LI LIN ALLISON
NRIC No	S9243485J
Date Of Birth	15/11/1992
Occupation	INDOOR
Date Of Driving Pass	11/12/2015
Driving Experience	2 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91378653
Fax Number	
Contact Number	OTHERS-91378653
Email Address	ALLISONLILIN@GMAIL.COM

Address	BLK 123 BISHAN STREET 12 #11-15
Postcode	570123
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : WEE CHNG GENDER: : MALE
Passenger 2	NAME: : WEE AN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP358S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KIM
NRIC/Passport Number	G5247862L
Contact Number	81819599
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. The Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for Archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same, as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms may/are permitted to collect, use, disclose and/or process my Personal Information for and/or make of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents including their lawyers/law firms, which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared and/or used:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirement under any regulatory laws or court orders.

Policyholder's signature:

Date & Time: 26/1/2025

Driver's signature:

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's signature:

Name: Phua Jiah


Date received: 26/1/2025



## Sketch Plan #2

### SKETCH PLAN

A = 2018 KIA  
B = 2018 KIA



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23/01/2018 at 21:00hrs my vehicle was parked along  
the drop-off point of Sky Habitat Condo when 2018 KIA  
reversed into me. No injuries were sustained in the accident.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 24/01/2018

21:00

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: JIMMY LEE

NRIC ID No: 990101-00000

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

27 OCT 2018

## ESTIMATE

Estimate No. : b1 48902  
Date Estimated : 27/10/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

## - ESTIMATE REPAIR FOR -

Wu Li Lin Allison  
123 Bishan Street 12  
#11-15

Singapore 570123

## - ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR381M	5J97315	28/07/2017	X1 sDrive18i	0

## DESCRIPTION

To replace front right door assembly & all attachments  
cause by accident.

## VALUE

850 / 1,700.00

Painting on front right door assembly

796 / 885.00

To check electrical wiring systems for proper function.

150 / 177.00

To carry out body cavity preservation.  
(Per panel).Frt RH door

100 / 118.00

Sundries.

? / 80.00

Total Labour 1: 2,960.00

## DESCRIPTION

FRT RH DOOR  
FRT RH MOULDING ROCKER PANEL  
LETTERING S DRIVE 18i  
Channel seal  
FRT RH DOOR EXTERIOR CHANNEL COVER  
FRT RH DOOR WINDOW FRAME COVER (ALU)  
FRT RH DOOR JOINT SEAL  
FRT RH DOOR JOINT SEALING ENTRANCE

QTY	PRIC	VALUE
1	1,168.60	1,168.60
1	74.60	? 74.60
1	93.85	93.85
1	66.10	? 66.10
1	126.30	? 126.30
1	74.90	? 74.90
1	59.00	? 59.00
1	34.75	? 34.75

Total Parts : 1,698.10

**Performance Motors Limited**

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

**GST REG. NO : M2 - 0020081 - X****E S T I M A T E**

Estimate No. : **b1 48902**  
Date Estimated : **27/10/2018**  
Prepared By : **Kevin Leong Wai Kit**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLR381M</b>	<b>5J97315</b>	<b>28/07/2017</b>	<b>X1 sDrive18i</b>	<b>0</b>

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*[Signature]*  
9/11/18

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date&Time 9/11/18 @ 12pm Excess S\$ \_\_\_\_\_

Surveyor's Name Tanfilm Sign [Signature]

Surveyor's Tel 97495449 Authorised Yes / No \_\_\_\_\_

Authorised Date 'WP' Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR ☒ Yes / No PML Yes / No \_\_\_\_\_

Surveyor's E-mail tanfilm@lkkauto.com

No. of Working Days Recommend 03 days

Labour 1	:	<b>2,960.00</b>
Parts	:	<b>1,698.10</b>
Labour 2	:	<b>0.00</b>
Excess	:	<b>0.00</b>
Total GST @ 7%	:	<b>326.07</b>
<b>Grand Total</b>	:	<b>4,984.17</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

1769.45

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 48902  
Date Estimated : 27/10/2018  
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -  
Wu Li Lin Allison  
123 Bishan Street 12  
#11-15

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

Singapore 570123

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SLR381M	5J97315	28/07/2017	X1 sDrive18i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT DOOR BRAKE *	77.05	1.00		77.05 d/s ✓
# TORX-BOLT WITH WASHER *	1.40	2.00		2.80 m ✓

Total Labour :	
Total Parts :	79.85
Total Labour & Parts :	79.85

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 48902  
Date Estimated : 27/10/2018  
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -  
Wu Li Lin Allison  
123 Bishan Street 12  
#11-15

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

Singapore 570123

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE	
SLR381M	5J97315	28/07/2017	X1 sDrive18i	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
To replace front RH door and all attachments include knocking out dents caused by the accident	850.00		850.00		
To spray paint front RH door	796.00		796.00		
To check electrical wiring systems and lightings at the RH section for proper function	150.00		150.00		
To carry out body cavity preservation. (Per panel)	100.00		100.00		
Sundries.	80.00		80.00		

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT RH DOOR	1,197.80	1.00		1,197.80
LETTERING S DRIVE 18i	96.15	1.00		96.15
# FRT DOOR BRAKE *	77.05	1.00		77.05
# TORX-BOLT WITH WASHER *	1.40	2.00		2.80

# SUPPLEMENTARY ITEMS

Total Labour :	1,976.00
Total Parts :	1,373.80
Total Labour & Parts :	3,349.80
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,349.80
GST @7%:	234.49
Grand Total :	3,584.29

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

#### CLAIM SUBFOLDER TRACKING





Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Oct 2018		29 Oct 2018 16:13 <a href="#">Edit Adj Rpt</a>	<b>S\$3,349.80</b> <a href="#">Edit Estimates</a>	<b>S\$3,349.80</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	SWEE SENG LEASING PTE LTD, Co. Reg. No.: 201111948K								
Main Claimant:	WU LI LIN ALLISON, ID: S9243485J								
Vehicle Reg. No.:	SLR381M	Date of Loss:	20/10/2018 21:00 - :59 [14 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D05015C02	Policy/Cover Note No.:	DMHCSN1737361801 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLP358S	Policy No. (Claimant):	5101826809						
		Excess:	S\$0.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/11/2018]								
Driver/Custodian (Insured):	KIM MINSUN (43 / Female), NRIC: G5247862L, Tel: +6581809599								
Adj Asg. Remarks:	EST \$4984.17, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


















## Claim Documents

\*SLR381M (SNM18D05015C02)  
[SLP358S]  
TP  
WU LI LIN ALLISON  
Oct 20 2018 9:00PM  
[SWEE SENG LEASING PTE LTD]  
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)								Thumbnail	Print
1	21/10/18 00:13	Accident Statement								Load HTM	
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)								Thumbnail	Print
1	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
2	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
3	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
4	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
5	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
6	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
7	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
8	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
9	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
10	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
11	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
12	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
13	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
14	21/10/18 00:09	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>
2	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>
3	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>
4	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>
5	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>
6	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>
7	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>
8	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>
9	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>
10	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>
11	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>
12	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>
13	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>
14	04/12/18 15:24	General View								Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/10/18 16:13	REPAIR EST WITH TP GIA	 Load PDF	
2	29/10/18 16:13	OI GIA	 Load PDF	
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	21/10/18 00:08	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	21/10/18 00:08	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	21/10/18 00:13	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	21/10/18 00:09	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)	Thumbnail	Print
1	21/10/18 00:08	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	21/10/18 00:08	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</div> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> <div> <input type="checkbox"/> Show Remarks To: Handling Insurer  <small>Note: Remarks are private unless you show it to other parties.</small> </div>			



# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18019667/T1TBE2

Date: 05/12/2018

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMHCSN1737361801

Claimant Vehicle  
No: SLR381MInsured Vehicle  
No: SLP358S

Date of Loss: 20/10/2018

Nature of Claim: TP

Claim  
No: SNM18D05015C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR381M**Make & Model: BMW X1 SDRIVE18I, 2.0 D/AB 2WD 5DR GAS/D  
SR (A)

Engine No: F416H456B38A15A

Reg. Date: 28/07/2017 (Man. Year: 2017)

Chassis No: WBAHS120905J97315

Colour: White

Odometer: 12479 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size: 225/45 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,889.45	1,453.80	435.65	23.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,896.00	984.00	34.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,769.45</b>	<b>3,349.80</b>	<b>1,419.65</b>	<b>29.77</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>333.86</b>	<b>234.49</b>	<b>99.37</b>	<b>29.76</b>
<b>Nett Amount (S\$)</b>	<b>5,103.31</b>	<b>3,584.29</b>	<b>1,519.02</b>	<b>29.77</b>

### INSPECTION

Date of Assignment: 29/10/2018

Date Inspected: 07/11/2018 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2018)
<b>Parts:</b>	M1-SUV	BMW X1 SDRIVE18I 2.0 D/AB 2WD 5DR GAS/D SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLR381M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*FRT RH DOOR	Bent	1,197.80 FS	*1,197.80 FS
3	1		*FRT RH MOULDING ROCKER PANEL	Not Necessary	74.60 FS	*- FS
4	1		*LETTERING S DRIVE 18I	Necessary	96.15 FS	*96.15 FS
5	1		*CHANNEL SEAL	Not Necessary	66.10 FS	*- FS
6	1		*FRT RH DOOR EXTERIOR CHANNEL COVER	Not Necessary	126.30 FS	*- FS
7	1		*FRT RH DOOR WINDOW FRAME COVER (ALU	Not Necessary	74.90 FS	*- FS
8	1		*FRT RH DOOR JOINT SEAL	Not Necessary	59.00 FS	*- FS
9	1		*FRT RH DOOR JOINT SEALING ENTRANCE	Not Necessary	34.75 FS	*- FS
10	1		*FRT DOOR BRAKE	Distorted	77.05 FS	*77.05 FS
11	2		*TORX-BOLT WITH WASHER	Necessary	2.80 FS	*2.80 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>1,889.45</b>	<b>1,453.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT RIGHT DOOR ASSEMBLY & ALL ATTACHMENTS CAUSE BY ACCIDENT	New	1,700.00	850.00
2	PAINTING ON FRONT RIGHT DOOR ASSEMBLY	New	885.00	796.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS FOR PROPER FUNCTION	New	177.00	150.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) FRT RH DOOR	New	118.00	100.00
Gross Labour Cost (S\$)			<b>2,880.00</b>	<b>1,896.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >