

ASS. REC. BY:

REF: CS/CTU8019668/Rlsbnz Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Melmen Irene Tay of CTU Date/Time: 29.10.2018 4:31pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 1855M Insured: PZ 676Zat Workshop m/s Accord Auto Tel: 9274 0999of Blk 1009 Bukit Merah Lorp 3 #01-80Policy No: DMB1 SN 3065 211800 Claim No: SNM1SD05106C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 26.10.2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

30.10.2018

H.O.D. Endorsement: _____

Date/Time: 29.10.2018 5:44pm Person Contacted: Celia Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	PC 1855M - NBA / ENC18019561 / Y	DA: 26.10.18
	PZ 676Z - FA / MSG14015419 / d2	DA: 12.03.14

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Oct 2018		29 Oct 2018 16:31 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

[Created by insurer]

Insured:	LIM CHIN YONG TRANSPORT PTE LTD, Co. Reg. No.: 201115637H		
Main Claimant:	TOPSTEEL SOLUTIONS ASIA PTE LTD, Co. Reg. No.: 200915808N		
Vehicle Reg. No.:	PC1855M	Date of Loss:	26/10/2018 07:00 - :59
Claim Type:	TP / SNM18D05106C02	Policy/Cover Note No.:	DMB1SN3065211800 (TP, Fire & Theft)
Vehicle Reg. No. (Insured):	PZ676Z	Policy No. (Claimant):	S102002312
		Excess:	S\$0.00
Repairer:	Accord Auto Services Pte Ltd (Bukit Merah) BLK 1009 BUKIT MERAH LANE 3, #01-80, 159723 Bukit Merah - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/11/2018]		
Driver/Custodian (Insured):	MOHAMMAD RAIS BIN ABIDIN (39 / Male), NRIC: S78319561, Tel: +6581431483		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

View All | Compose Case Mail

There are no mail for this case.

View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Thursday, 10 January 2019 2:59 PM
To: Shirley Hiew (LKK Auto)
Subject: FW: Photos After Repair PC1855M
Attachments: PC 1855M.pdf

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Rasul (LKKAuto)
Sent: Wednesday, 9 January, 2019 10:17 AM
To: 'Accord Claims(AV)'
Subject: RE: Photos After Repair PC1855M

Hi Celia,

Refer to attachment,

Take note, labour part UPHOLSTREY DETAILS CLEANING \$50 my senior surveyor check and said this item cannot be given

Finalise amount is \$ 3,350.00 / 5 days lump sum

Kindly confirm


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Accord Claims(AV) [<mailto:avclaims@mycarworkshop.com.sg>]
Sent: Tuesday, 8 January, 2019 11:56 AM
To: Rasul (LKKAuto)
Cc: Admin A; assignments
Subject: Re: Photos After Repair PC1855M

Dear Mr Rasul,

Kindly finalize as soon as possible.

Finalize request on 8.11.2018 till date still do not receive any reply from your side.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd
Blk 1009 Bukit Merah Lane 3
#01-80
Singapore 159723

Mobile: (65) 9274 0999
Tel : (65) 6271 7433
Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On Thu, Nov 8, 2018 at 7:53 PM Accord Claims(AV) <avclaims@mycarworkshop.com.sg> wrote:

Dear Rasul,

Kindly refer photos as attached file.

- Supplementary of the Decal
- Invoice of the solar film

Please finalize as soonest.

Thank you.

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd
Blk 1009 Bukit Merah Lane 3
#01-80
Singapore 159723

Mobile: (65) 9274 0999
Tel : (65) 6271 7433
Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/10/2018 17:48
Date Of Accident	26/10/2018 07:45
Exact Location Of Accident	SLIP ROAD FROM KJE TOWARDS CHOA CHU KANG DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC1855M
Insured/Policyholder	
Name Of Registered Owner	TOPSTEEL SOLUTIONS ASIA PTE LTD
Co Reg No	200915808N
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90261472
Alternative Phone No	Office-62616866

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORKING PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102002312
Cover Note Number	

Driver

Name of Driver	TEO YONG HWA
NRIC No	S1551824C
Date Of Birth	15/12/1962
Occupation	OUTDOOR
Date Of Driving Pass	03/01/1986
Driving Experience	32 YEARS AND 9 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-90261472
Fax Number	
Contact Number	OFFICE-66648298
Email Address	NOEMAIL
Address	BLK 419 FAJAR ROAD #06-463
Postcode	670419
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : IVAN TEO Gender: : Male

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PZ676Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	

NRIC/Passport Number
Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

SKETCH PLAN

Veh A: PC 1855 M

Veh B: P2 6762



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I was travelling along Ship Road from KJE toward Choa Chu Kang Dr. I stopped my vehicle at the Junction for traffic. Suddenly Vehicle B from my rear hit onto my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



12.30 pm
26/10/18

26/10/2018
Rishi Kumar

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL: 62715133, 62717433 FAX: 62745715

ESTIMATE REPAIR

Pg 1

China Taiping Insurance (Singapore) Pte Ltd

Date: 29.10.2018

Owner's Name : Topsteel Solutions Asia Pte Ltd

Vehicle No : PC1855M

Claim Type: Third Party Claim

Vehicle Make & Model : Toyota Hiace Auto

Chassis No: JTFHT02P900119645

Registration Date : 6 Aug 2013 (YOM 2013) COE Expiry Date 5 Aug 2023

DOA: 26.10.2018

No	Description	Unit	List (\$)
1	REAR TAIL GATE - Bl ✓	1	\$ 1,680.60
2	REAR TAIL GATE HINGE X } ✓	2	\$ 257.20
3	REAR TAIL GATE ABSORBER X }	2	\$ 574.54
4	REAR TAIL GATE LOCK X }	1	\$ 269.40
5	REAR TAIL GATE STRICK X }	1	\$ 160.60
6	REAR TAIL GATE LOGO nu ✓	1	\$ 78.80
7	REAR LAMP LH X }	1	\$ 240.80
8	REAR LAMP RH X }	1	\$ 240.80
9	REAR LAMP PANEL LH X }	1	\$ 139.70
10	REAR LAMP PANEL RH X }	1	\$ 139.70
11	REAR BUMPER DE ✓	1	\$ 387.25
12	REAR SIDE RETAINER LH X }	1	\$ 68.40
13	REAR SIDE RETAINER RH X }	1	\$ 68.40
14	REAR BUMPER CLIPS nu ✓	10	\$ 60.00
15	REAR TAIL GATE GLASS Bko ✓	1	\$ 840.00
			3046.65
			25%
			2284.98
Total (A) :	\$		5,206.19
Less 25% :	\$		1,301.55
Total:	\$		3,904.64

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 62715133 62717433 FAX: 62745715

Pg 2

ESTIMATE REPAIR

China Taiping Insurance (Singapore) Pte Ltd

Date: 29.10.2018

Owner's Name : Topsteel Solutions Asia Pte Ltd

Vehicle No : PC1855M

Vehicle Make & Model : Toyota Hiace Auto

Registration Date : 6 Aug 2013 (YOM 2013) COE Expiry Date 5 Aug 2023

Claim Type: Third Party Claim

Chassis No: JTFHT02P900119645

DOA: 26.10.2018

No	Description	Unit	List (\$)
Special Nett			
1	REAR CAR PLATE NUMBER WITH HOLDER	1	\$ 300 X 55.00
2	REAR REVERSE SENSOR	1	\$ cut / 250.00
3	STICKER '70 km/h)	1	\$ ne / 18.00
4	REAR TAIL GATE SEALANT	1	\$ ne / 100.00
5	SOLAR FILM	1	\$ ne / 300.00
Labour			
1	Spray Painting to All Affected Areas	1	\$ 450 800.00
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	1	\$ 500 1,000.00
3	Check Wiring System & Light	1	\$ nn X 100.00
4	Anti Rust Treatment	1	\$ 60 120.00
5	To Check & Adjust Wheel Aligment	1	\$ nn X 100.00
6	To Remove / Refix Rear Tail Gate Attachment, Mechemism & Assy To New Rear Tail Gate	1	\$ 80 200.00
7	To Remove/ Refix Reverse Sensor	1	\$ 60 120.00
8	To Remove / Refix Inner Compartment, Rear Chair & Etc...	1	\$ nn X 120.00
9	To Remove /Refix/Replace Rear Tail Gate Glass	1	\$ 120 150.00
10	Upholstery Details Cleaning	1	\$ nn X 50 220.00
<p>KK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 			
Total (B) :			\$ 3,653.00
Grand Total:			\$ 7,557.64

Acknowledged by Repairer

Signature:

Date:

30/10/18 @ 14:00
Resurvey after repair

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133;62717433 FAX:62745715

SUPPLEMENTARY ESTIMATE REPAIR

Pg 1

China Taiping Insurance (Singapore) Pte Ltd

Date: 29.10.2018

Owner's Name : Topsteel Solutions Asia Pte Ltd

Vehicle No : PC1855M

Vehicle Make & Model : Toyota Hiace Auto

Registration Date : 6 Aug 2013 (YOM 2013) COE Expiry Date 5 Aug 2023

Claim Type: Third Party Claim

Chassis No: JTFHT02P900119645

DOA: 26.10.2018

[illegible]

Parts - 2284.98
s/n - 518.00
Labour - 1270.00
Supp s/n - 150.00

Total - 4222.98
20%
3378.38

45-3350
5 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18019668/R1SBN2

Date: 11/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN3065211800
Claimant Vehicle No :	PC1855M	Insured Vehicle No :	PZ676Z
Date of Loss:	26/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D05106C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC1855M	Engine No:	1KD2311960
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	JTFHT02P900119645
Reg. Date:	06/08/2013 (Man. Year: 2013)	Odometer:	83530 km
Colour:	Grey		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80R15	Rear Tyre Size:	195R15C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,927.64	2,952.99	1,974.65	40.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,270.00	1,660.00	56.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,857.64	4,222.99	3,634.65	46.26
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	7,857.64	3,350.00	4,507.64	57.37
+ GST 7.00/7.00% (S\$)	550.03	234.50	315.53	57.37
Nett Amount (S\$)	8,407.67	3,584.50	4,823.17	57.37

INSPECTION

Date of Assignment:	29/10/2018	
Date Inspected:	30/10/2018 Inspected At:	Accord Auto Services Pte Ltd (Bukit Merah) BLK 1009 BUKIT MERAH LANE 3, #01-80 Singapore 159723

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Jan 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC1855M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Bent	1,680.60 FL	*1,680.60 FL
2	2		*REAR TAIL GATE HINGE	Serviceable	257.20 FL	*- FL
3	2		*REAR TAIL GATE ABSORBER	Serviceable	574.54 FL	*- FL
4	1		*REAR TAIL GATE LOCK	Serviceable	269.40 FL	*- FL
5	1		*REAR TAIL GATE STIRCK	Serviceable	160.60 FL	*- FL
6	1		*REAR TAIL GATE LOGO	Necessary	78.80 FL	*78.80 FL
7	1		*REAR LAMP LH	Not Necessary	240.80 FL	*- FL
8	1		*REAR LAMP RH	Not Necessary	240.80 FL	*- FL
9	1		*REAR LAMP PANEL LH	Not Necessary	139.70 FL	*- FL
10	1		*REAR LAMP PANEL RH	Not Necessary	139.70 FL	*- FL
11	1		*REAR BUMPER	Deformed	387.25 FL	*387.25 FL
12	1		*REAR SIDE RETAINER LH	Not Necessary	68.40 FL	*- FL
13	1		*REAR SIDE RETAINER RH	Not Necessary	68.40 FL	*- FL
14	10		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
15	1		*REAR TAIL GATE GLASS	Broken	840.00 FL	*840.00 FL
16	1		*REAR CAR PLATE NUMBER WITH HOLDER	Serviceable	55.00 FS	*- FS
17	1		*REAR REVERSE SENSOR	Cut	250.00 FS	*200.00 FS
18	1		*STICKER 70KM/H	Necessary	18.00 FS	*18.00 FS
19	1		*REAR TAIL GATE SEALANT	Necessary	100.00 FS	*60.00 FS
20	1		*SOLAR FILM	Necessary	300.00 FS	*240.00 FS
21	1		*DECAL REAR TAILGATE	Necessary	300.00 FS	*150.00 FS
					Sub Total (S\$)	6,229.19 3,714.65
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,301.55 761.66
					Total Parts (S\$)	4,927.64 2,952.99

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING TO ALL AFFECTED AREAS	New	800.00	450.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	500.00
3	CHECK WIRING SYSTEM & LIGHT	New	100.00	-
4	ANTI RUST TREATMENT	New	120.00	60.00
5	TO CHECK & ADJUST WHEEL ALIGNMENT	New	100.00	-
6	TO REMOVE/REFIX REAR TAIL GATE ATTACHMENT,MECHANISM & ASSY TO NEW REAR TAIL GATE	New	200.00	80.00
7	TO REMOVE/REFIX REVERSE SENSOR	New	120.00	60.00
8	TO REMOVE/REFIX INNER COMPARTMENT,REAR CHAIR & ETC	New	120.00	-
9	TO REMOVE/REFIX/REPLACE REAR TAIL GATE GLASS	New	150.00	120.00
10	UPHOLSTERY DETAILS CLEANING	New	220.00	-
Gross Labour Cost (S\$)			2,930.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >