



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Telok Blangah NPP
51 Telok Blangah Drive #01-118
SINGAPORE 100055
Tel No: 1800-2729999



T/20181015/2154

3 of 3

Report No. T/20181015/2154

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 WONG XIANG LONG, CLARENCE

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt YAN MINGSHENG DANIEL

Contact No.: 65476252

Signature Of Informant:

Date/Time:

15/10/2018 18:27

Classification Of Case:

Authentication Stamp



Signature: *Ch*

Singapore Police Force

Estimate

Tan Kah 97495749
WP
01/11/18 @ 330pm
Remy before print
18 days
sun@hkant.com

5/11/18
LS

CHINA TAIPING

Your Ref Vehicle No:
SKZ8200U (TP claim)

Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW 18
Date of loss: 13/10/2018
Our ref: LSA274TJS
Year: 2014

Qty	Description	List Price	Remarks
1.00	COVER, I-CAM	\$ 87.93	mis ✓
1.00	MOUNT I-CAM	\$ 29.34	mis ✓
4.00	SET OF MOUNTS FOR PDC SENSOR, FRONT	\$ 434.52	dis ✓
1.00	FRONT BUMPER GRILL PANEL	\$ 260.28	dis ✓
1.00	FRONT SEAL, ENGINE BONNET	\$ 137.43	?
8.00	FRONT BUMPER SCREW	\$ 80.00	dis ✓
4.00	FRONT BUMPER CLIP NUT	\$ 20.00	dis ✓
3.00	FRONT BUMPER FILLISTER HEAD SCREW	\$ 9.00	dis ✓
1.00	FRONT BUMPER LEFT TRIM GRILL	\$ 390.42	con ✓
1.00	FRONT BUMPER RIGHT TRIM GRILL	\$ 390.42	con ✓
14.00	FRONT BUMPER GRILL PANEL SCREW	\$ 42.00	dis ✓
1.00	FRONT BUMPER CARRIER	\$ 1,180.35	bt ✓
1.00	FRONT BUMPER LOWER MOUNT	\$ 749.16	mis ✓
1.00	FRONT LEFT ELEMENT	\$ 381.33	?
1.00	FRONT RIGHT ELEMENT	\$ 318.33	?
1.00	FRONT LOWER LEFT ELEMENT	\$ 269.73	?
1.00	FRONT LOWER RIGHT ELEMENT	\$ 269.73	?
2.00	FRONT LEFT AND RIGHT CONNECTOR	\$ 207.90	?
1.00	FRONT LEFT BUMPER SUPPORT	\$ 103.95	bt ✓
1.00	FRONT RIGHT BUMPER SUPPORT	\$ 103.95	bt ✓
1.00	FRONT TOP SPONGE	\$ 66.42	con ✓
1.00	FRONT BOTTOM SPONGE	\$ 66.42	mis ✓
1.00	FRONT LEFT SPONGE	\$ 47.07	mis ✓
1.00	FRONT RIGHT SPONGE	\$ 47.07	mis ✓
1.00	FOAM COMPONENT	\$ 38.16	?
2.00	FRONT LOWER MOUNT BOLT	\$ 10.00	dis ✓
2.00	FRONT EDGE PROTECTION	\$ 44.00	?
1.00	FRONT BONNET ENBLEM	\$ 125.10	dis ✓
1.00	FRONT CROSSLINK	\$ 715.23	bt ✓
2.00	FRONT CROSSLINK STOP BUFFER	\$ 46.98	dis ✓
1.00	FRONT LEFT ROD	\$ 43.02	bt ✓
1.00	FRONT RIGHT ROD	\$ 43.02	bt ✓
1.00	FRONT UPPER LEFT RADIATOR BRACKET	\$ 56.70	bt ✓
1.00	FRONT UPPER RIGHT RADIATOR BRACKET	\$ 56.70	bt ✓
2.00	FRONT SUPPORT BRACKET	\$ 69.30	?
2.00	FRONT SUPPORT PANEL BRACKET	\$ 346.68	?
2.00	FRONT LEFT AND RIGHT BRACE BRACKET	\$ 338.27	?
2.00	FRONT LEFT AND RIGHT HEADLAMP SUPPORT	\$ 549.18	bt ✓
2.00	FRONT LEFT AND RIGHT HEADLAMP LEVER	\$ 186.30	con ✓
7.00	FRONT SUPPORT HEAD SCREW	\$ 40.95	mis ✓

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16/18 S(138236)

CHINA TAIPING

Your Ref Vehicle No:

SKZ8200U (TP claim)

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW i5
Date of loss: 13/10/2018
Our ref: LSA274TJS
Year: 2014

4.00	FRONT C-CLIP NUT	\$	11.88	nd ✓
4.00	FRONT ISA SCREW	\$	24.84	nd ✓
6.00	FRONT BLIND RIVET NUT	\$	36.72	nd ✓
8.00	FRONT C-CLIP PLASTIC NUT	\$	14.40	nd ✓
2.00	FRONT LEVER TORX BOLT	\$	20.00	nd ✓
2.00	FRONT SUPPORT FLAT NUT	\$	29.88	nd ✓
1.00	FRONT WINDSHIELD	\$	2,600.00	X
1.00	FRONT WINDSHIELD TOP COVER	\$	93.60	X
10.00	FRONT WINDSHIELD BUMP STOP	\$	57.60	X
2.00	FRONT WINDSHIELD LEFT & RIGHT ROOF FRAME GASKET	\$	27.36	X
1.00	HEADLINING (roof lining)	\$	2,790.00	de ✓
1.00	FRONT WINDSHIELD COVER	\$	180.00	Cu ✓
2.00	FRONT LEFT AND RIGHT APRON COVER	\$	198.00	de ✓
3.00	FRONT WINDSHIELD COVER EXPANDING RIVET	\$	10.00	nd ✓
1.00	DASHBOARD INSTRUMENT PANNEL UPPER PART	\$	6,390.00	act ✓
1.00	FRONT UNDERHOOD SHIELD	\$	392.25	Cu ✓
2.00	FRONT LEFT AND RIGHT BOTTOM COVER	\$	280.90	th ✓
26.00	FRONT UNDER COVER BOLT	\$	36.54	nd ✓
2.00	FRONT LEFT AND RIGHT WHEELHOUSING <i>inner-steel</i>	\$	460.80	24-? , RH de ✓
2.00	FRONT REAR LEFT AND RIGHT WHEELHOUSING	\$	432.00	?
2.00	TOP LEFT AND RIGHT WHEEL ARCH COVER	\$	256.00	?
20.00	WHEELHOUSING PLASTIC NUT	\$	72.00	?
4.00	WHEELHOUSING HEX BOLT	\$	38.00	?
1.00	FRONT AIR DUCT	\$	180.00	?
1.00	FRONT BOTTOM AIR DUCT	\$	577.50	Cu ✓
1.00	FRONT LOWER LEFT AIR DUCT	\$	135.00	Cu ✓
1.00	FRONT LEFT BRAKE AIR DUCT	\$	72.00	de ✓
1.00	FRONT LOWER RIGHT AIR DUCT	\$	135.00	act ✓
1.00	FRONT RIGHT BRAKE AIR DUCT	\$	72.00	de ✓
1.00	FRONT UPPER EXHAUST AIR DUCT	\$	207.00	only ✓
1.00	FRONT LOWER SECTION AIR EXHAUST DUCT	\$	72.00	?
1.00	FRONT LOWER LEFT AIR-EXHAUST DUCT	\$	76.50	?
1.00	FRONT LOWER RIGHT AIR-EXHAUST DUCT	\$	76.50	?
4.00	FRONT BRAKE AIR DUCT HEX BOLT	\$	10.08	nd ✓
4.00	C-CLIP FOR PLASTIC NUT	\$	10.00	nd ✓
8.00	EXPANDING RIVET	\$	12.24	nd ✓
1.00	BATTERY TRAY	\$	210.00	?
4.00	FRONT PARKING SENSOR	\$	2,000.00	dis ✓
4.00	FRONT PARKING SENSOR RING	\$	34.00	nd ✓
1.00	FRONT BONNET	\$	3,964.35	bt ✓
1.00	FRONT LEFT BONNET HINGE	\$	134.00	bt ✓
1.00	FRONT RIGHT BONNET HINGE	\$	134.00	bt ✓
4.00	FRONT BOONRT HINGE SELF LOCKING COLLAR NUT	\$	8.00	nd ✓

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

CHINA TAIPING

Your Ref Vehicle No:

SKZ8200U (TP claim)

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW 1s
Date of loss: 13/10/2018
Our ref: LSA274TJS
Year: 2014

6.00	FRONT BONNET HINGE HEX BOLT WITH WASHER	\$	12.00	all ✓
1.00	FRONT BONNET AIR DUCT	\$	280.00	Car ✓
1.00	FRONT BONNET AIR DUCT GRILL	\$	147.90	+
8.00	FRONT BONNET EXPANDING RIVET	\$	12.00	all ✓
2.00	FRONT BONNET HINGE INTERMEDIATE PLATE ASSY	\$	10.00	bt ✓
1.00	FRONT BONNET SEAL	\$	99.00	mis ✓
1.00	FRONT BONNET SIDE SEAL	\$	82.35	nk ✓
1.00	FRONT LEFT AIR DUCT SEAL	\$	96.00	?
1.00	FRONT RIGHT AIR DUCT SEAL	\$	96.00	?
2.00	FRONT BONNET LOCK	\$	304.95	?
2.00	CATCH BRACKET	\$	73.18	bt ✓
2.00	TWIST PROTECTION	\$	18.30	de ✓
2.00	FRONT BONNET CABLE LEFT AND RIGHT	\$	440.00	?
2.00	EXPANDING RIVET	\$	4.00	?
2.00	ADJUSTER	\$	20.00	?
2.00	DISTANCE SENSOR rubber bracket	\$	10.00	✓
1.00	FRONT LEFT FENDER	\$	1,800.00	Car ✓
1.00	FRONT RIGHT FENDER	\$	1,800.00	Car ✓
1.00	FRONT LEFT SUPPORTING STRUT	\$	800.00	?
1.00	FRONT RIGHT SUPPORTING STRUT	\$	800.00	bt ✓
1.00	FRONT RIGHT DEFORMATION ELEMENT	\$	81.00	?
1.00	FRONT LEFT DEFORMATION ELEMENT	\$	81.00	?
1.00	REAR LEFT DEFORMATION ELEMENT	\$	80.00	?
1.00	REAR RIGHT DEFORMATION ELEMENT	\$	80.00	?
1.00	CENTER RIGHT DEFORMATION ELEMENT	\$	40.00	?
1.00	CENTER LEFT DEFORMATION ELEMENT	\$	40.00	?
2.00	GASKET	\$	10.00	?
1.00	FRONT LEFT FENDER SUPPORT	\$	40.00	?
1.00	FRONT RIGHT FENDER SUPPORT	\$	40.00	?
16.00	FRONT LEFT AND RIGHT FENDER SCREW	\$	96.00	?
20.00	Blind rivet nut, flat headed	\$	100.00	all ✓
2.00	Foam belt stick on	\$	40.00	all ✓
1.00	Seal, front side panel, left	\$	39.00	?
1.00	Seal, front side panel, left	\$	39.00	?
2.00	FRONT LEFT AND RIGHT HEADLAMP	\$	15,500.80	Car ✓
2.00	HEADLIGHT COVER	\$	86.40	des ✓
2.00	HEADLIGHT SINK LEFT AND RIGHT	\$	990.00	?
2.00	REPAIR KIT OF HEADLAMP	\$	378.00	all ✓
2.00	Control unit for front light electronics	\$	2,800.00	Car ✓ LH-CR-RH-?
2.00	Alignment element	\$	20.00	?
2.00	Repair kit for LWR servo motor	\$	150.00	all ✓
10.00	Countersunk screw	\$	40.00	all ✓
2.00	Control module, turn signal with gasket	\$	890.00	?

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

CHINA TAIPING

Your Ref Vehicle No:

SKZ8200U (TP claim)

Date: 22/10/2018

Vehicle No: SLX8977K

Model: BMW 1B

Date of loss: 13/10/2018

Our ref: LSA274TJS

Year: 2014

4.00	Flat nut	\$	40.00	nd ✓
2.00	GASKET	\$	20.00	nd ✓
1.00	FAN HOUSING WITH FAN MOTOR	\$	2,562.50	?
4.00	FAN HOUSING LOWER SEALING	\$	10.00	?
1.00	Radiator Top Inner	\$	1,890.00	?
1.00	Radiator Top Outer	\$	1,134.00	bt ✓
1.00	Radiator Lower Inner	\$	1,790.00	?
1.00	Radiator Lower Outer	\$	1,790.00	bt ✓
2.00	Radiator Left Module mount	\$	450.00	?
2.00	Radiator Right Module mount	\$	450.00	?
1.00	Radiator Lower Sealing	\$	250.00	?
1.00	Left Bracket for module	\$	240.00	?
1.00	Right Bracket for module	\$	240.00	?
1.00	Radiator Upper sealing	\$	250.00	?
4.00	Radiator Upper Sealing Screw self-tapping	\$	12.00	?
2.00	Fillister head screw	\$	10.00	?
2.00	Rubber Mounting	\$	50.00	?
2.00	Support rubber mounting	\$	60.00	?
6.00	Blind rivet nut, countersunk head	\$	40.00	?
1.00	Pipe, expansion tank-radiator	\$	90.00	?
1.00	Line from expansion tank - thermostat	\$	162.00	?
1.00	Line, connection for water pump	\$	220.00	?
1.00	Hose, expansion tank-return pipe	\$	160.00	?
1.00	Hose, expansion tank	\$	150.00	?
3.00	Clip	\$	12.00	?
4.00	Hose clamp	\$	30.00	?
1.00	Hose clamp	\$	10.00	?
1.00	Refrigerant line IWT	\$	650.00	?
1.00	Pressure hose assy compressor-condenser	\$	442.00	?
1.00	Suction pipe	\$	410.00	?
1.00	Pressure pipe	\$	620.00	?
6.00	Gasket ring	\$	120.00	?
1.00	Sealing cap for suction line	\$	8.00	?
1.00	Sealing cap for pressure line	\$	8.00	?
1.00	Pressure sensor	\$	180.00	?
1.00	A/C Condensor	\$	1,750.00	?
1.00	Front Left Wheel Rim	\$	4,880.00	X
1.00	Front Right Wheel Rim	\$	4,880.00	nt ✓
1.00	Wheel center cap with blue ring	\$	200.00	?
1.00	Wheel electr. module RDCI w/ screw valve	\$	500.00	?
1.00	Front Right Side Driveshaft	\$	4,050.00	?
1.00	Front Anti-roll bar	\$	680.00	?
2.00	Front Stabilizer link	\$	414.00	?

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16/18 S(128236)

Date: 22/10/2018

Vehicle No: SLX8977K

Model: BMW 18

Date of loss: 13/10/2018

Our ref: LSA274TJS

Year: 2014

CHINA TAIPING

Your Ref Vehicle No:

SKZ8200U (TP claim)

2.00	Front Absorber Left and Right	\$	4,000.00	24-4, 24-?
2.00	Front Absorber Spring Lower Pad	\$	60.00	?
2.00	Front Absorber Spring Top Pad	\$	68.00	?
6.00	Front Absorber Screw self-tapping	\$	60.00	?
2.00	Front Absorber Top Mounting	\$	760.00	?
2.00	Front Absorber Plug-in connection bracket	\$	34.00	?
1.00	Front axle support	\$	3,690.00	?
1.00	Front Axle Support Cross member	\$	558.00	?
12.00	Front Axle Support bolt with washer	\$	208.00	?
2.00	Front Right and Left Strut Arm	\$	1,500.00	?
2.00	Front Right and Left center Arm	\$	2,000.00	?
2.00	Front Right and Left Upper Arm	\$	1,808.30	?
2.00	Front Axle Mounting	\$	375.00	?
2.00	Front Headlamp Level Sensor	\$	480.00	?
1.00	Front Ringle Knuckle	\$	1,228.00	?
1.00	Front right wheel bearing with Hub	\$	696.00	?
1.00	Front Right and Left Wheel Speed Sensor	\$	640.00	?
1.00	At-steering box, electr TKP	\$	6,300.00	?
1.00	Front Right and Left Tie Rod	\$	1,280.00	?
1.00	Sprt steering wheel, leather, shift paddles	\$	2,800.00	?
1.00	Decor trim cover, steering wheel	\$	600.00	?
1.00	Cover for steering wheel, rear	\$	250.00	?
1.00	connecting line, steering wheel	\$	300.00	?
1.00	Airbag module, driver's side	\$	3,240.00	act
1.00	Front Left wiring harness, Live,	\$	468.00	?
1.00	Front Right wiring harness, Live	\$	540.00	?
1.00	SBK wiring harness	\$	72.00	?
1.00	Rain Sensor	\$	387.00	?
1.00	Steering Coil Spring cartridge	\$	480.00	?
1.00	Horn, high pitch	\$	158.40	one
1.00	Horn, low pitch	\$	158.40	act
2.00	Horn Screw	\$	10.00	one
1.00	Washer fluid reservoir	\$	225.00	del
1.00	Wash pump/fluid container	\$	112.35	?
1.00	Gasket	\$	12.00	*?
1.00	Strainer f wash pump	\$	14.00	?
1.00	Level sensor	\$	122.40	?
1.00	Hex bolt with washer	\$	5.00	one
2.00	Pipe support	\$	20.00	?
1.00	Cover, windshield	\$	180.00	one
1.00	Filler pipe for wash container	\$	120.00	?
1.00	Wiper Washer Tank Cover	\$	28.00	one
1.00	Hose, windshield washer	\$	80.00	?

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

CHINA TAIPING

Your Ref Vehicle No:
SKZ8200U (TP claim)

2.00	Wiper Nozzle
1.00	FRONT RIGHT SEAT BELT
1.00	Airbag for front passenger
1.00	Head airbag, right
3.00	Blind rivet nut, flat headed

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW 18
Date of loss: 13/10/2018
Our ref: LSA274TJS
Year: 2014

\$	615.00	?
\$	984.94	aut
\$	2,466.00	aut
\$	1,224.00	aut
\$	30.00	new

TOTAL: \$ 132,904.40
LESS 5 %: \$ 6,645.22
\$ 126,259.18

S/NET

Qty	Description	Unit Price	Remarks
1.00	FRONT BUMPER BODY KIT	\$ 15,000.00	Car
2.00	FRONT OVER FENDER BODY KIT	\$ 10,000.00	Car
1.00	FRONT WINDSCREEN SEALANT	\$ 120.00	X
1.00	FRONT PANEL SEALANT	\$ 160.00	new
1.00	WHEEL ALIGNMENT	\$ 200.00	✓120
1.00	FRONT WINDSCREEN SOLAR FIRM	\$ 600.00	X
1.00	TOWING FEE	\$ 200.00	? family receipt
TOTAL:		\$ 25,280.00	

LABOUR AND PAINT

Qty	Description	Unit Price	Remarks
1.00	LABOUR FOR REPAIR ON AFFECTED AREA	\$ 5,000.00	2500
1.00	SPRAY PAINT ON AFFECTED AREA	\$ 5,000.00	1500
1.00	CHECK WIRING	\$ 800.00	200
1.00	APPLY RUST PROOF ON AFFECTED PANEL	\$ 500.00	X
1.00	REMOVE & REFIT AFFECTED FRONT PORTION	\$ 800.00	500
1.00	REPROGRAMMING AND RESETTNG ON VEHICLE SYSTEM	\$ 1,000.00	200
1.00	TO REMOVE AND REFIT REAR WINDSCREEN	\$ 250.00	X
1.00	TO REMOVE AND REFIT REVERSE SENSOR	\$ 200.00	100
1.00	SUNDRIES	\$ 50.00	30

TOTAL: \$ 13,600.00

SUBTOTAL: \$ 165,139.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after estimate prepared by: TOH KHAR KIAN
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation.
- Third party survey is on a "without prejudice" basis.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and subject to final approval from Insurer.

Accepted by Repairer:

(b)

Estimate

Tan Jian 97495789
WP
01/11/18 @ 3:30pm
Remy before print
18 days
sun@hkauto.com



CHINA TAIPIING

Li Sheng Automobile Trading

Please arrange to survey at

30X N. Pandan Loop #01-06/18 S1282261

Date: 22/10/2018

Vehicle No: SLX8977K

Model: BMW ID

Date of loss: 13/10/2018

Our ref: LSA274TJS

Year: 2014

Your Ref Vehicle No:

5KZ8280U (TP claim)

Qty	Description	Unit Price	Remarks
1.00	COVER, I-CAM	\$	87.93 m/s ✓
1.00	MOUNT I-CAM	\$	29.34 m/s ✓
4.00	SET OF MOUNTS FOR PDC SENSOR, FRONT	\$	434.52 m/s ✓
1.00	FRONT BUMPER GRILL PANEL	\$	260.28 m/s ✓
1.00	FRONT SEAL, ENGINE BONNET	\$	137.43 ? - missing ✓
8.00	FRONT BUMPER SCREW	\$	80.00 m/s ✓
4.00	FRONT BUMPER CLIP NUT	\$	20.00 m/s ✓
3.00	FRONT BUMPER FILLISTER HEAD SCREW	\$	9.00 m/s ✓
1.00	FRONT BUMPER LEFT TRIM GRILL	\$	390.42 m/s ✓
1.00	FRONT BUMPER RIGHT TRIM GRILL	\$	390.42 m/s ✓
14.00	FRONT BUMPER GRILL PANEL SCREW	\$	42.00 m/s ✓
1.00	FRONT BUMPER CARRIER	\$	1,180.35 m/s ✓
1.00	FRONT BUMPER LOWER MOUNT	\$	749.16 m/s ✓
1.00	FRONT LEFT ELEMENT	\$	361.33 ? m/s ✓
1.00	FRONT RIGHT ELEMENT	\$	318.33 ? m/s ✓
1.00	FRONT LOWER LEFT ELEMENT	\$	269.73 ? m/s ✓
1.00	FRONT LOWER RIGHT ELEMENT	\$	269.73 ? m/s ✓
2.00	FRONT LEFT AND RIGHT CONNECTOR	\$	207.90 ? m/s ✓
1.00	FRONT LEFT BUMPER SUPPORT	\$	103.95 m/s ✓
1.00	FRONT RIGHT BUMPER SUPPORT	\$	103.95 m/s ✓
1.00	FRONT TOP SPONGE	\$	66.42 m/s ✓
1.00	FRONT BOTTOM SPONGE	\$	66.42 m/s ✓
1.00	FRONT LEFT SPONGE	\$	47.07 m/s ✓
1.00	FRONT RIGHT SPONGE	\$	47.07 m/s ✓
1.00	FOAM COMPONENT	\$	38.16 ? m/s ✓
2.00	FRONT LOWER MOUNT BOLT	\$	10.00 m/s ✓
2.00	FRONT EDGE PROTECTION	\$	44.00 ? m/s ✓
1.00	FRONT BONNET ENGLISH	\$	125.10 m/s ✓
1.00	FRONT CROSSLINK	\$	715.23 m/s ✓
2.00	FRONT CROSSLINK STOP BUFFER	\$	46.98 m/s ✓
1.00	FRONT LEFT ROD	\$	43.02 m/s ✓
1.00	FRONT RIGHT ROD	\$	43.02 m/s ✓
1.00	FRONT UPPER LEFT RADIATOR BRACKET	\$	56.70 m/s ✓
1.00	FRONT UPPER RIGHT RADIATOR BRACKET	\$	56.70 m/s ✓
2.00	FRONT SUPPORT BRACKET	\$	69.30 ? m/s ✓
2.00	FRONT SUPPORT PANEL BRACKET	\$	346.68 ? m/s ✓
2.00	FRONT LEFT AND RIGHT BRACE BRACKET	\$	338.22 ? m/s ✓
2.00	FRONT LEFT AND RIGHT HEADLAMP SUPPORT	\$	549.18 m/s ✓
2.00	FRONT LEFT AND RIGHT HEADLAMP LEVER	\$	186.30 m/s ✓
7.00	FRONT SUPPORT HEAD SCREW	\$	40.95 m/s ✓

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Bk K, Pandan Loop #01-16 /18 S(122236)

CHINA TRADING

Date: 13/10/2018

Vehicle No: SLX8977K

Model: BNV 1B

Date of loss: 13/10/2018

Our ref: LSA274TJS

Year: 2014

Your Ref Vehicle No:

SKZ8200U (TP claim)

4.00	FRONT C-CLIP NUT	\$	11.88	nd ✓
4.00	FRONT C-CLIP NUT	\$	24.84	nd ✓
6.00	FRONT RIVET RIVET NUT	\$	36.72	nd ✓
8.00	FRONT C-CLIP PLASTIC NUT	\$	14.40	nd ✓
2.00	FRONT LEVER TORX BOLT	\$	20.00	nd ✓
2.00	FRONT SUPPORT FLAT NUT	\$	29.88	nd ✓
1.00	FRONT WINDSHIELD	\$	2,600.00	X
1.00	FRONT WINDSHIELD TOP COVER	\$	93.60	X
10.00	FRONT WINDSHIELD BUMP STOP	\$	57.60	X
2.00	FRONT WINDSHIELD LEFT & RIGHT ROOF FRAME GASKET	\$	27.36	X
1.00	HEADLINING (roof lining)	\$	2,790.00	de ✓
1.00	FRONT WINDSHIELD COVER	\$	180.00	Cu ✓
2.00	FRONT LEFT AND RIGHT APRON COVER	\$	198.00	de ✓
3.00	FRONT WINDSHIELD COVER EXPANDING RIVET	\$	10.00	nd ✓
1.00	DASHBOARD INSTRUMENT PANNEL, UPPER PART	\$	6,390.00	act ✓
1.00	FRONT UNDERHOOD SHIELD	\$	392.35	nd ✓
2.00	FRONT LEFT AND RIGHT BOOTOM COVER	\$	240.90	nd ✓
26.00	FRONT UNDER COVER BOLT	\$	36.54	nd ✓
2.00	FRONT LEFT AND RIGHT WHEELHOUSING	\$	460.80	24-?, RH de ✓
2.00	FRONT REAR LEFT AND RIGHT WHEELHOUSING	\$	432.00	X n 7 ✓
2.00	TOP LEFT AND RIGHT WHEEL ARCH COVER	\$	256.00	de ✓
20.00	WHEELHOUSING PLASTIC NUT	\$	72.00	nd ✓
4.00	WHEEL HOUSING HEX BOLT	\$	38.00	X ✓
1.00	FRONT AIR DUCT	\$	180.00	de ✓
1.00	FRONT BOTTOM AIR DUCT	\$	577.50	nd ✓
1.00	FRONT LOWER LEFT AIR DUCT	\$	135.00	Cu ✓
1.00	FRONT LEFT BRAKE AIR DUCT	\$	72.00	de ✓
1.00	FRONT LOWER RIGHT AIR DUCT	\$	135.00	nd ✓
1.00	FRONT RIGHT BRAKE AIR DUCT	\$	72.00	de ✓
1.00	FRONT UPPER EXHAUST AIR DUCT	\$	267.00	nd ✓
1.00	FRONT LOWER SECTION AIR EXHAUST DUCT	\$	72.00	nd ✓
1.00	FRONT LOWER LEFT AIR-EXHAUST DUCT	\$	76.50	X n 7 ✓
1.00	FRONT LOWER RIGHT AIR-EXHAUST DUCT	\$	76.50	X n 7 ✓
4.00	FRONT BRAKE AIR DUCT HEX BOLT	\$	10.08	nd ✓
4.00	C-CLIP FOR PLASTIC NUT	\$	10.00	nd ✓
8.00	EXPANDING RIVET	\$	12.24	nd ✓
1.00	BATTERY TRAY	\$	210.00	X ✓
4.00	FRONT PARKING SENSOR	\$	2,000.00	nd ✓
4.00	FRONT PARKING SENSOR RING	\$	34.00	nd ✓
1.00	FRONT BONNET	\$	3,964.35	bt ✓
1.00	FRONT LEFT BONNET HINGE	\$	134.00	bt ✓
1.00	FRONT RIGHT BONNET HINGE	\$	134.00	bt ✓
4.00	FRONT BONNET HINGE SELF LOCKING COLLAR NUT	\$	8.00	nd ✓

Estimate



CHONGA TRADING

Li Sheng Automobile Trading

Please arrange to survey at

31k K, Pandan Loop #01-16 /18 S(128236)

Date: 2018/10/13

Vehicle No: SLD0977K

Model: BMW 18

Date of loss: 13/10/2018

Our ref: LSA274TJS

Year: 2014

Your Ref Vehicle No:

SKZ8200W (TP claim)

6.00	FRONT BONNET HINGE HEX BOLT WITH WASHER	\$	12.00	all
1.00	FRONT BONNET AIR DUCT	\$	280.00	all
1.00	FRONT BONNET AIR DUCT GRILL	\$	147.90	all
8.00	FRONT BONNET EXPANDING RIVET	\$	12.00	all
2.00	FRONT BONNET HINGE INTERMEDIATE PLATE ASSY	\$	10.00	all
1.00	FRONT BONNET SEAL	\$	99.00	all
1.00	FRONT BONNET SIDE SEAL	\$	82.35	all
1.00	FRONT LEFT AIR DUCT SEAL	\$	96.00	? all
1.00	FRONT RIGHT AIR DUCT SEAL	\$	96.00	? all
2.00	FRONT BONNET LOCK	\$	304.95	? all
2.00	CATCH BRACKET	\$	75.18	all
2.00	TWIST PROTECTION	\$	18.30	all
2.00	FRONT BONNET CABLE LEFT AND RIGHT	\$	440.00	all
2.00	EXPANDING RIVET	\$	8.00	? all
2.00	ADJUSTER	\$	20.00	all
2.00	DISTANCE SENSOR	\$	10.00	all
1.00	FRONT LEFT FENDER	\$	1,500.00	all
1.00	FRONT RIGHT FENDER	\$	1,800.00	all
1.00	FRONT LEFT SUPPORTING STRUT	\$	800.00	all
1.00	FRONT RIGHT SUPPORTING STRUT	\$	800.00	all
1.00	FRONT RIGHT DEFORMATION ELEMENT	\$	81.00	all
1.00	FRONT LEFT DEFORMATION ELEMENT	\$	81.00	all
1.00	REAR LEFT DEFORMATION ELEMENT	\$	80.00	all
1.00	REAR RIGHT DEFORMATION ELEMENT	\$	80.00	all
1.00	CENTER RIGHT DEFORMATION ELEMENT	\$	40.00	all
1.00	CENTER LEFT DEFORMATION ELEMENT	\$	40.00	all
2.00	GASKET	\$	10.00	all
1.00	FRONT LEFT FENDER SUPPORT	\$	40.00	all
1.00	FRONT RIGHT FENDER SUPPORT	\$	40.00	all
16.00	FRONT LEFT AND RIGHT FENDER SCREW	\$	96.00	all
2.00	FRONT LEFT AND RIGHT FENDER SCREW	\$	40.00	all
2.00	Seal, front side panel, left	\$	39.00	all
1.00	Seal, front side panel, left	\$	39.00	all
2.00	FRONT LEFT AND RIGHT HEADLAMP	\$	15,500.80	all
2.00	HEADLIGHT COVER	\$	86.40	all
2.00	HEADLIGHT SWK LEFT AND RIGHT	\$	900.00	all
2.00	REPAIR KIT OF HEADLAMP	\$	375.00	all
2.00	Control unit for front light electronics	\$	2,800.00	all
2.00	Alignment element	\$	20.00	all
2.00	Repair kit for LWR servo motor	\$	150.00	all
10.00	Consumable screw	\$	40.00	all
2.00	Control module, turn signal with gasket	\$	890.00	all

LH-X, RH-dis

LH-wo-RH-?

LH-X

Estimate



CHINA TAIPING

Your Ref Vehicle No:
SKZ8200U (TP claim)

1.00	Flat nut
2.00	GASKET
1.00	FAN HOUSING WITH FAN MOTOR
4.00	FAN HOUSING LOWER SEALING
1.00	Radiator Top Inner
1.00	Radiator Top Outer
1.00	Radiator Lower Inner
1.00	Radiator Lower Outer
2.00	Radiator Left Module mount
2.00	Radiator Right Module mount
1.00	Radiator Lower Sealing
1.00	Left Bracket for module
1.00	Right Bracket for module
1.00	Radiator Upper sealing
4.00	Radiator Upper Sealing Screw self tapping
2.00	Fillister head screw
2.00	Support Mounting
2.00	Support rubber mounting
6.00	Blind rivet nut, countersunk head
1.00	Pipe, expansion tank-radiator
1.00	Line from expansion tank - thermostat
1.00	Line connection for water pump
1.00	Hose, expansion tank-return pipe
1.00	Hose, expansion tank
3.00	Clip
4.00	Hose clamp
1.00	Hose clamp
1.00	Refrigerant line IWT
1.00	Pressure Hose Assy compressor-condenser
1.00	Suction pipe
1.00	Pressure pipe
2.00	Gasket ring
1.00	Sealing cap for suction line
1.00	Sealing cap for pressure line
1.00	Pressure sensor
1.00	A/C Condensor
1.00	Front Left Wheel Rim
1.00	Front Right Wheel Rim
1.00	Wheel center cap with blue ring
1.00	Wheel electr. module RDCI w/ screw valve
1.00	Front Right Side Driveshaft
1.00	Front Anti-roll bar
2.00	Front Stabilizer Link

Li Sheng Automobile Trading

Please arrange to survey at

88-4, Fuxin Loop 88-45-115-5128226

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW 116
Date of loss: 13/10/2018
Our ref: LSA274TJS
Year: 2014

€	20.00	20.00
\$	2,562.50	2,562.50
\$	10.00	10.00
\$	1,890.00	1,890.00
\$	1,134.00	1,134.00
\$	1,790.00	1,790.00
\$	1,790.00	1,790.00
\$	450.00	450.00
\$	450.00	450.00
\$	250.00	250.00
\$	240.00	240.00
\$	240.00	240.00
\$	250.00	250.00
\$	12.00	12.00
\$	10.00	10.00
\$	50.00	50.00
\$	60.00	60.00
\$	40.00	40.00
\$	90.00	90.00
\$	162.00	162.00
\$	220.00	220.00
\$	160.00	160.00
\$	160.00	160.00
\$	12.00	12.00
\$	30.00	30.00
\$	10.00	10.00
\$	650.00	650.00
\$	442.00	442.00
\$	410.00	410.00
\$	420.00	420.00
\$	120.00	120.00
\$	8.00	8.00
\$	8.00	8.00
\$	180.00	180.00
\$	1,750.00	1,750.00
\$	4,880.00	4,880.00
\$	4,880.00	4,880.00
\$	200.00	200.00
\$	500.00	500.00
\$	4,050.00	4,050.00
\$	680.00	680.00
\$	414.00	414.00

Estimate



Li Sheng Automobile Trading

Please arrange to survey at:
818 K, Pandan Loop #01-16 / 16 St (28236)

CHINA TAIPING

Your Ref Vehicle No:

SK7820017 (TP claim)

Date: 22/10/2018

Vehicle No: SLX8977K

Model: BMW 18

Date of loss: 13/10/2018

Chit ref: 15A274TJS

Year: 2014

2.00	Front Absorber Left and Right	\$	4,000.00	LH - 2, RH - 2 X un.
2.00	Front Absorber Spring Lower Pad	\$	60.00	X
2.00	Front Absorber Spring Top Pad	\$	68.00	X
6.00	Front Absorber Screw self-tapping	\$	60.00	X
2.00	Front Absorber Top Mounting	\$	760.00	X
2.00	Front Absorber Plug-in connection bracket	\$	34.00	X
1.00	Front Axle Support	\$	3,600.00	? b/ -
1.00	Front Axle Support Cross member	\$	588.00	X un.
12.00	Front Axle Support bolt with washer	\$	208.00	X un.
2.00	Front Right and Left Strut Arm	\$	1,500.00	X un.
2.00	Front Right and Left center Arm	\$	2,000.00	X un.
2.00	Front Right and Left Upper Arm	\$	1,808.30	X un.
2.00	Front Axle Mounting	\$	375.00	? n/ -
2.00	Front Wheel Hub	\$	486.00	X un.
1.00	Front Hinge Knuckle	\$	1,228.00	X un.
1.00	Front right wheel bearing with Hub	\$	696.00	b/ -
1.00	Front Right and Left Wheel Speed Sensor	\$	640.00	X
1.00	As-steering box, electr TKP	\$	6,300.00	b/ -
1.00	Front Right and Left Tie Rod	\$	1,280.00	? LH - X, RH - b/ -
1.00	Sprt steering wheel, leather, shift paddles	\$	2,800.00	? n/ -
1.00	Decor trim cover steering wheel	\$	600.00	? n/ -
1.00	Cover for steering wheel, rear	\$	250.00	X un.
1.00	connecting line, steering wheel	\$	300.00	X un.
1.00	Airbag module drivers side	\$	3,240.00	n/ -
1.00	Front Left wiring harness, Live	\$	468.00	? X un.
1.00	Front Right wiring harness, Live	\$	540.00	? n/ -
1.00	SBK wiring harness	\$	72.00	? n/ -
1.00	Rain Sensor	\$	567.00	X un.
1.00	Steering Coil Spring cartridge	\$	480.00	? n/ -
1.00	Horn, high pitch	\$	158.40	n/ -
1.00	Horn, low pitch	\$	158.40	n/ -
2.00	Horn Screw	\$	10.00	n/ -
1.00	Washer fluid reservoir	\$	225.00	? n/ -
1.00	Wash pump/fluid container	\$	112.35	? n/ -
1.00	Gasket	\$	12.00	? n/ -
1.00	Strainer wash pump	\$	14.00	? n/ -
1.00	Level sensor	\$	122.40	? n/ -
1.00	Heat sooth with washer	\$	5.00	n/ -
2.00	Pipe support	\$	20.00	X un.
1.00	Cover, windshield	\$	180.00	n/ -
1.00	Filter pipe for wash container	\$	120.00	X un.
1.00	Wiper Washer Tank Cover	\$	25.00	n/ -
1.00	Hose, windshield washer	\$	80.00	X un.

SUPPLEMENTARY



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW 18
Date of loss: 13/10/2018
Our ref: LSA274TIS
Year: 2014

CHINA TAIPING

Your Ker Vehicle No:
SKZ8200U (1P claim)

Qty	Description	List Price	Remarks
1.00	FRONT 1 CAM	\$ 1,164.16	cut ✓
1.00	BY PASS HOSE	\$ 269.64	ad ✓
2.00	BRACKET FOR MODULE LEFT AND RIGHT	\$ 821.76	ht ✓
1.00	WIPER RHS MOTOR WITH BRACKET	\$ 1,155.60	cut ✓
2.00	SOUND PROOF STICKER ON LEFT AND RIGHT FENDER	\$ 900.00	ht ✓
TOTAL:		\$ 4,311.16	
LESS 5%:		\$ 215.56	
		<u>\$ 4,095.60</u>	

Estimate prepared by: WINSON

Telephone: 97684247

Estimate

Taifeng 97495744
WP

01/11/18 @ 3:30pm

Passing before print

18 days

sun@hkan.com



Li Sheng Automobile Trading

Please arrange to survey at
Wu K. Pandan Loop #01-56 (18 S128256)

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW 18
Date of loss: 13/10/2018
Our ref: LSA274TJS
Year: 2014

CHINA TAIPIING

Your Ref Vehicle No:
SK28280U (TP claim)

Qty	Description	List Price	Remarks
1.00	COVER, 1-CAM	\$ 87.93	mis ✓
1.00	MOUNT 1-CAM	\$ 29.35	mis ✓
4.00	SET OF MOUNTS FOR PDC SENSOR, FRONT	\$ 434.52	dis ✓
1.00	FRONT BUMPER GRILL PANEL	\$ 260.28	dis ✓
1.00	FRONT REAL ENGINE BONNET	\$ 137.43	? - missing
8.00	FRONT BUMPER SCREW	\$ 80.00	mis ✓
4.00	FRONT BUMPER CLIP NUT	\$ 20.00	mis ✓
3.00	FRONT BUMPER FILLISTER HEAD SCREW	\$ 9.00	mis ✓
1.00	FRONT BUMPER LEFT TRIM GRILL	\$ 390.42	mis ✓
1.00	FRONT BUMPER RIGHT TRIM GRILL	\$ 390.42	mis ✓
14.00	FRONT BUMPER GRILL PANEL SCREW	\$ 42.00	mis ✓
1.00	FRONT BUMPER CARRIER	\$ 1,180.35	bt ✓
1.00	FRONT BUMPER LOWER MOUNT	\$ 749.16	mis ✓
1.00	FRONT LEFT ELEMENT	\$ 361.33	? bt ✓
1.00	FRONT RIGHT ELEMENT	\$ 318.33	? bt ✓
1.00	FRONT LOWER LEFT ELEMENT	\$ 269.73	? bt ✓
1.00	FRONT LOWER RIGHT ELEMENT	\$ 269.73	? bt ✓
2.00	FRONT LEFT AND RIGHT CONNECTOR	\$ 207.90	? bt ✓
1.00	FRONT LEFT BUMPER SUPPORT	\$ 103.98	bt ✓
1.00	FRONT RIGHT BUMPER SUPPORT	\$ 103.95	bt ✓
1.00	FRONT TOP SPONGE	\$ 66.42	mis ✓
1.00	FRONT BOTTOM SPONGE	\$ 66.42	mis ✓
1.00	FRONT LEFT SPONGE	\$ 47.07	mis ✓
1.00	FRONT RIGHT SPONGE	\$ 47.07	mis ✓
1.00	FOAM COMPONENT	\$ 38.16	? mis ✓
2.00	FRONT LOWER MOUNT BOLT	\$ 10.00	mis ✓
2.00	FRONT EDGE PROTECTION	\$ 44.00	? mis ✓
1.00	FRONT BONNET ENBLEM	\$ 125.30	mis ✓
1.00	FRONT CROSSLINK	\$ 715.23	bt ✓
2.00	FRONT CROSSLINK STOP BUFFER	\$ 46.98	mis ✓
1.00	FRONT LEFT ROD	\$ 43.02	bt ✓
1.00	FRONT RIGHT ROD	\$ 43.02	bt ✓
1.00	FRONT UPPER LEFT RADIATOR BRACKET	\$ 56.70	bt ✓
1.00	FRONT UPPER RIGHT RADIATOR BRACKET	\$ 56.70	bt ✓
2.00	FRONT SUPPORT BRACKET	\$ 69.30	? bt ✓
2.00	FRONT SUPPORT PANEL BRACKET	\$ 346.68	? bt ✓
2.00	FRONT LEFT AND RIGHT BRACE BRACKET	\$ 338.22	? bt ✓
2.00	FRONT LEFT AND RIGHT HEADLAMP SUPPORT	\$ 549.18	bt ✓
2.00	FRONT LEFT AND RIGHT HEADLAMP LEVER	\$ 186.30	mis ✓
7.00	FRONT SUPPORT HEAD SCREW	\$ 40.95	mis ✓

\$8402.29

Estimate



CHINA TATUNG

Li Sheng Automobile Trading

Please arrange to survey at

Blk K, Pandan Loop #01-16 / 18 S(128236)

Date: 13/10/2018

Vehicle No: SLX8977K

Model: BMW 118

Date of loss: 13/10/2018

Our ref: LSA274TJS

Year: 2014

Your Ref Vehicle No:

SKZ8200U (TP claim)

4.00	FRONT C-CLIP NUT	\$	11.88	net ✓
4.00	FRONT C-CLIP NUT	\$	24.84	net ✓
6.00	FRONT RIVET RIVET NUT	\$	36.72	net ✓
8.00	FRONT C-CLIP PLASTIC NUT	\$	14.40	net ✓
2.00	FRONT LEVER TORX BOLT	\$	20.00	net ✓
2.00	FRONT SUPPORT FLAT NUT	\$	29.88	net ✓
1.00	FRONT WINDSHIELD	\$	2,600.00	X
1.00	FRONT WINDSHIELD TOP COVER	\$	93.60	X
10.00	FRONT WINDSHIELD BOTTOM STOP	\$	57.60	X
2.00	FRONT WINDSHIELD LEFT & RIGHT ROOF FRAME GASKET	\$	27.36	X
1.00	HEADLINING (roof lining)	\$	2,790.00	de ✓
1.00	FRONT WINDSHIELD COVER	\$	180.00	de ✓
2.00	FRONT LEFT AND RIGHT APRON COVER	\$	198.00	de ✓
3.00	FRONT WINDSHIELD COVER EXPANDING RIVET	\$	10.00	net ✓
1.00	DASHBOARD INSTRUMENT PANNEL UPPER PART	\$	6,390.00	net ✓
1.00	FRONT UNDERHOOD SHIELD	\$	392.25	net ✓
2.00	FRONT LEFT AND RIGHT BOTTOM COVER	\$	280.90	net ✓
26.00	FRONT UNDER COVER BOLT	\$	36.54	net ✓
2.00	FRONT LEFT AND RIGHT WHEELHOUSING	\$	460.80	14-? , RH de ✓
2.00	FRONT REAR LEFT AND RIGHT WHEELHOUSING	\$	432.00	X net ✓
2.00	TOP LEFT AND RIGHT WHEEL ARCH COVER	\$	256.00	de ✓
20.00	WHEELHOUSING PLASTIC NUT	\$	72.00	net ✓
4.00	WHEELHOUSING HEX BOLT	\$	38.00	X
1.00	FRONT AIR DUCT	\$	180.00	de ✓
1.00	FRONT BOTTOM AIR DUCT	\$	577.50	net ✓
1.00	FRONT LOWER LEFT AIR DUCT	\$	135.00	net ✓
1.00	FRONT LEFT BRAKE AIR DUCT	\$	72.00	de ✓
1.00	FRONT LOWER RIGHT AIR DUCT	\$	135.00	net ✓
1.00	FRONT RIGHT BRAKE AIR DUCT	\$	72.00	de ✓
1.00	FRONT UPPER EXHAUST AIR DUCT	\$	207.00	net ✓
1.00	FRONT LOWER SECTION AIR EXHAUST DUCT	\$	72.00	net ✓
1.00	FRONT LOWER LEFT AIR-EXHAUST DUCT	\$	76.50	X net ✓
1.00	FRONT LOWER RIGHT AIR-EXHAUST DUCT	\$	76.50	X net ✓
4.00	FRONT BRAKE AIR DUCT HEX BOLT	\$	10.08	net ✓
4.00	C-CLIP FOR PLASTIC NUT	\$	10.00	net ✓
8.00	EXPANDING RIVET	\$	12.24	net ✓
1.00	BATTERY TRAY	\$	210.00	X
4.00	FRONT PARKING SENSOR	\$	2,000.00	de ✓
4.00	FRONT PARKING SENSOR RING	\$	34.00	net ✓
1.00	FRONT BONNET	\$	3,964.35	net ✓
1.00	FRONT LEFT BONNET HINGE	\$	134.00	net ✓
1.00	FRONT RIGHT BONNET HINGE	\$	134.00	net ✓
4.00	FRONT BONNET HINGE SELF LOCKING COLLAR NUT	\$	8.00	net ✓

\$18730.98

Estimate



CROWN TACONIC

Li Sheng Automobile Trading

Please arrange to survey at
31k K, Pandan Loop #01-16 / 18 S (128236)

Page: 1 of 1

Vehicle No: SLX8977K

Model: BMW 1s

Date of loss: 13/10/2018

Our ref: LSA274TJS

Year: 2014

Your Ref Vehicle No:

SKZ8200U (TP claim)

6.00	FRONT BONNET HINGE HEX BOLT WITH WASHER	\$	12.00	all
1.00	FRONT BONNET AIR DUCT	\$	280.00	all
1.00	FRONT BONNET AIR DUCT GRILL	\$	147.90	+
8.00	FRONT BONNET EXPANDING RIVET	\$	12.00	all
2.00	FRONT BONNET HINGE INTERMEDIATE PLATE ASSY	\$	10.00	bt
1.00	FRONT BONNET SEAL	\$	99.00	mis
1.00	FRONT BONNET SIDE SEAL	\$	82.35	all
1.00	FRONT LEFT AIR DUCT SEAL	\$	96.00	? all
1.00	FRONT RIGHT AIR DUCT SEAL	\$	96.00	? all
2.00	FRONT BONNET LOCK	\$	304.95	? bt
2.00	CATCH BRACKET	\$	73.18	bt
2.00	TWIST PROTECTION	\$	18.30	all
2.00	FRONT BONNET CABLE LEFT AND RIGHT	\$	440.00	all
2.00	EXPANDING RIVET	\$	4.00	? all
2.00	ADJUSTER	\$	20.00	all
2.00	DISTANCE SENSOR	\$	10.00	all
1.00	FRONT LEFT FENDER	\$	1,800.00	all
1.00	FRONT RIGHT FENDER	\$	1,800.00	all
1.00	FRONT LEFT SUPPORTING STRUT	\$	800.00	all
1.00	FRONT RIGHT SUPPORTING STRUT	\$	800.00	all
1.00	FRONT RIGHT DEFORMATION ELEMENT	\$	81.00	bt
1.00	FRONT LEFT DEFORMATION ELEMENT	\$	81.00	all
1.00	REAR LEFT DEFORMATION ELEMENT	\$	80.00	all
1.00	REAR RIGHT DEFORMATION ELEMENT	\$	80.00	all
1.00	CENTER RIGHT DEFORMATION ELEMENT	\$	40.00	all
1.00	CENTER LEFT DEFORMATION ELEMENT	\$	40.00	all
2.00	GASKET	\$	10.00	all
1.00	FRONT LEFT FENDER SUPPORT	\$	40.00	all
1.00	FRONT RIGHT FENDER SUPPORT	\$	40.00	all
16.00	FRONT LEFT AND RIGHT FENDER SCREW	\$	96.00	all
20.00	Blind rivet nut and washer	\$	100.00	all
2.00	Foam belt	\$	40.00	all
1.00	Seal, front side panel, left	\$	39.00	all
1.00	Seal, front side panel, right	\$	39.00	all
2.00	FRONT LEFT AND RIGHT HEADLAMP	\$	15,500.00	all
2.00	HEADLIGHT COVER	\$	86.40	all
2.00	HEADLIGHT SWIRL LEFT AND RIGHT	\$	990.00	? LH-X, RH-dis
2.00	REPAIR KIT OF HEADLAMP	\$	378.00	all
2.00	Control unit for front light electronics	\$	2,800.00	all LH-co-RH-?
2.00	Alignment element	\$	20.00	? all
2.00	Repair kit for LVR servo motor	\$	150.00	all
10.00	Control unit power	\$	40.00	all
2.00	Control module, turn signal with gasket	\$	990.00	? LH-X RH-all

\$24544.68

Estimate



CHINA TAIPING

Your Ref Vehicle No:
SKZ8200U (TP claim)

1.00	Flot nut
2.00	GASKET
1.00	FAN HOUSING WITH FAN MOTOR
4.00	FAN HOUSING LOWER SEALING
1.00	Radiator Top Inner
1.00	Radiator Top Outer
1.00	Radiator Lower Inner
1.00	Radiator Lower Outer
2.00	Radiator Left Module mount
2.00	Radiator Right Module mount
1.00	Radiator Lower Sealing
1.00	Left Bracket for module
1.00	Right Bracket for module
1.00	Radiator Upper sealing
4.00	Radiator Upper Sealing Screw with nut
2.00	Fillister head screw
2.00	Rubber Mounting
2.00	Support rubber mounting
6.00	Blind rivet nut, countersunk head
1.00	Pipe, expansion tank-radiator
1.00	Line from expansion tank - thermostat
1.00	Line connection for water pump
1.00	Hose, expansion tank-return pipe
1.00	Hose, expansion tank
3.00	Clip
4.00	Hose clamp
1.00	Hose clamp
1.00	Refrigerant line RWT
1.00	Pressure Hose w/assy compressor-condensor
1.00	Suction pipe
1.00	Pressure pipe
2 6.00	Gasket ring
1.00	Sealing cap for suction line
1.00	Sealing cap for pressure line
1.00	Pressure sensor
1.00	A/C Condensor
1.00	Front Left Wheel Rim
1.00	Front Right Wheel Rim
1.00	Wheel center cap with blue ring
1.00	Wheel electr. module RDCI w/ screw valve
1.00	Front Right Side Driveshaft
1.00	Front Anti-roll bar
2.00	Front Stabilizer Link

Li Sheng Automobile Trading

Please arrange to survey at

RR: C, Pandan Lemp, RR-24/34 (238234)

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW i5
Date of loss: 13/10/2018
Our ref: LSA274TJS
Year: 2014

\$	40.00	act
\$	20.00	act
\$	2,562.50	act
\$	10.00	act
\$	1,890.00	act
\$	1,134.00	act
\$	1,790.00	act
\$	1,790.00	act
\$	450.00	act
\$	450.00	act
\$	250.00	act
\$	240.00	act
\$	240.00	act
\$	250.00	act
\$	12.00	act
\$	10.00	act
\$	50.00	act
\$	60.00	act
\$	40.00	act
\$	90.00	act
\$	162.00	act
\$	220.00	act
\$	160.00	act
\$	150.00	act
\$	12.00	act
\$	30.00	act
\$	10.00	act
\$	650.00	act
\$	442.00	act
\$	410.00	act
\$	620.00	act
\$	120.00	act
\$	8.00	act
\$	8.00	act
\$	180.00	act
\$	1,750.00	act
\$	4,880.00	act
\$	4,880.00	act
\$	200.00	act
\$	500.00	act
\$	4,050.00	act
\$	680.00	act
\$	414.00	act

\$1930.50

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
818 K. Pandan Loop #01-16 / 18 S(128236)

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW 18
Date of loss: 13/10/2018
Unit ref: LBA274TJS
Year: 2014

CHINA TAIPING

Your Ref Vehicle No:
SKZ8200EJ (TP claim)

2.00	Front Absorber Left and Right	\$	4,000.00	24-12-18-Xun
2.00	Front Absorber Spring Lower Pad	\$	60.00	X
2.00	Front Absorber Spring Top Pad	\$	68.00	X
6.00	Front Absorber Screw self-tapping	\$	60.00	X
2.00	Front Absorber Top Mounting	\$	760.00	X
2.00	Front Absorber Plug-in connection bracket	\$	34.00	X
1.00	Front Axle Support	\$	3,600.00	?bt
1.00	Front Axle Support Cross member	\$	550.00	Xun
12.00	Front Axle Support bolt with washer	\$	208.00	Xun
2.00	Front Right and Left Strut Arm	\$	1,500.00	Xun
2.00	Front Right and Left center Arm	\$	2,000.00	Xun
2.00	Front Right and Left Upper Arm	\$	1,808.30	Xun
2.00	Front Axle Mounting	\$	375.00	?nc
2.00	Front Wheel Hub Sensor	\$	400.00	Xun
1.00	Front Angle Knuckle	\$	1,228.00	Xun
1.00	Front right wheel bearing with Hub	\$	695.00	bt
1.00	Front Right and Left Wheel Speed Sensor	\$	640.00	X
1.00	At-steering box, electr TKP	\$	6,300.00	bt
1.00	Front Right and Left Tie Rod	\$	1,280.00	? LH-X, RH-bt
1.00	Sprt steering wheel, leather, shift paddles	\$	2,800.00	?one
1.00	Decor trim (over steering wheel)	\$	600.00	?d's
1.00	Cover for steering wheel, rear	\$	250.00	Xun
1.00	connecting line, steering wheel	\$	300.00	Xun
1.00	Airbag module, driver's side	\$	3,240.00	act
1.00	Front Left wiring harness, Live	\$	468.00	?Xun
1.00	Front Right wiring harness, Live	\$	540.00	?for
1.00	SBK wiring harness	\$	72.00	?new
1.00	Ruin Sensor	\$	307.00	Xun
1.00	Steering Coil Spring carriage	\$	480.00	?act
1.00	Horn, high pitch	\$	158.40	one
1.00	Horn, low pitch	\$	158.40	act
2.00	Horn Screw	\$	10.00	one
1.00	Washer fluid reservoir	\$	225.00	de
1.00	Wash pump/fluid container	\$	112.35	?de
1.00	Gasket	\$	12.00	?no
1.00	Strainer wash pump	\$	14.00	?ne
1.00	Level sensor	\$	122.40	?his
1.00	Hex bolt with washer	\$	5.00	ne
2.00	Pipe support	\$	20.00	Xun
1.00	Cover, windshield	\$	180.00	one
1.00	Filler pipe for wash container	\$	120.00	Xun
1.00	Wiper Washer Tank Cover	\$	28.00	one
1.00	Hose, windshield washer	\$	80.00	Xun

\$21,078.55

Estimate



Li Sheng Automobile Trading

Please arrange to survey at

88, 2, Paldan Longren 1st/1st 9/10/2018

Date: 22/10/2018

Vehicle No. SLA0777K

Model: BMW 1s

Date of loss: 13/10/2018

Our ref: LSA274TJS

Year: 2014

\$ 645.00 X

\$ 984.94 act

\$ 2466.00 int

\$ 1,224.00 int

\$ 30.00 int

TOTAL: \$ 132,904.40

LESS 5 %: \$ 6,645.22

\$ 126,259.18

\$4704.94

92/15.36

27509.60

CHINA TAIPING

Your Ref Vehicle No:

SKZ8200U (TP claim)

2.00 Wiper Blade

1.00 FRONT RIGHT SEAT BELT / LHS also

1.00 Airbag for front passenger

1.00 Head airbag, right

3.00 Blind rivet nut, flat headed

SINET

Qty	Description
1.00	FRONT BUMPER BODY KIT
2.00	FRONT OVER FENDER BODY KIT
1.00	FRONT WINDSCREEN SEALANT
1.00	FRONT PANEL SEALANT
1.00	WHEEL ALIGNMENT
1.00	FRONT WINDSCREEN SOLAR FILM
1.00	TOWING FEE

Unit Price Remarks

\$ 15,000.00 car

\$ 10,000.00 car

\$ 120.00 X

\$ 100.00 act

\$ 200.00 120

\$ 600.00 X

\$ 200.00 ? family receipt

TOTAL: \$ 25,280.00

\$25430

380

1980

LABOUR AND PAINT

Qty	Description
1.00	LABOUR FOR REPAIR ON AFFECTED AREA
1.00	SPRAY PAINT ON AFFECTED AREA
1.00	CHECK WIRING
1.00	APPLY RUST PROOF ON AFFECTED PANEL
1.00	REMOVE & REPT AFFECTED FRONT PORTION
1.00	REPROGRAMMING AND RESETTNG ON VEHICLE SYSTEM
1.00	TO REMOVE AND REPT REAR WINDSCREEN
1.00	TO REMOVE AND REPT REVERSE SENSOR
1.00	SUNDRIES

Unit Price

\$ 5,000.00

\$ 5,000.00

\$ 800.00

\$ 500.00 X

\$ 800.00

\$ 1,000.00

\$ 250.00 X

\$ 200.00

\$ 50.00

TOTAL: \$ 13,600.00

SUBTOTAL: \$ 105,159.18

Total = 132,023.10

93369.60

Estimate prepared by: TOH KHAR KIAN

Telephone: 92967659

tohkh_90@hotmail.com

Pull chassis - 9200
Photo.

6

SUPPLEMENTARY



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW I8
Date of loss: 13/10/2018
Our ref: LSA274TIS
Year: 2014

CHINA TAIPING

Your Ref Vehicle No:
SKZ8200U (TP claim)

Qty	Description	List Price	Remarks
1.00	FRONT I CAM	\$ 1,164.16	cut ✓
1.00	BY PASS HOSE	\$ 269.64	ad ✓
2.00	BRACKET FOR MODULE LEFT AND RIGHT	\$ 821.76	ht ✓
1.00	WIPER RHS MOTOR WITH BRACKET	\$ 1,155.60	car ✓
2.00	SOUND PROOF STICKER ON LEFT AND RIGHT FENDER	\$ 900.00	nc ✓
TOTAL:		\$ 4,311.16	
LESS 5%:		\$ 215.56	
		\$ 4,095.60	

\$4311.16

Estimate prepared by: WINSON

Telephone: 97684247

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 5(128236)

CHINA TAIPING

Your Ref Vehicle No:
SKZ8200U (TP claim)

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW 18
Date of loss: 13/10/2018
Our ref: LSA274TJS
Year: 2014

Qty	Description	List Price	Remarks
1.00	COVER, I-CAM	\$ 87.93	mis ✓
1.00	MOUNT I-CAM	\$ 29.34	mis ✓
4.00	SET OF MOUNTS FOR PDC SENSOR, FRONT	\$ 434.52	dis ✓
1.00	FRONT BUMPER GRILL PANEL	\$ 260.28	dis ✓
1.00	FRONT SEAL, ENGINE BONNET	\$ 137.43	mis ✓
8.00	FRONT BUMPER SCREW	\$ 80.00	rec ✓
4.00	FRONT BUMPER CLIP NUT	\$ 20.00	rec ✓
3.00	FRONT BUMPER FILLISTER HEAD SCREW	\$ 9.00	rec ✓
1.00	FRONT BUMPER LEFT TRIM GRILL	\$ 390.42	mis ✓
1.00	FRONT BUMPER RIGHT TRIM GRILL	\$ 390.42	mis ✓
14.00	FRONT BUMPER GRILL PANEL SCREW	\$ 42.00	rec ✓
1.00	FRONT BUMPER CARRIER	\$ 1,180.35	bt ✓
1.00	FRONT BUMPER LOWER MOUNT	\$ 749.16	mis ✓
1.00	FRONT LEFT ELEMENT	\$ 381.33	bt ✓
1.00	FRONT RIGHT ELEMENT	\$ 318.33	bt ✓
1.00	FRONT LOWER LEFT ELEMENT	\$ 269.73	bt ✓
1.00	FRONT LOWER RIGHT ELEMENT	\$ 269.73	bt ✓
2.00	FRONT LEFT AND RIGHT CONNECTOR	\$ 207.90	bt ✓
1.00	FRONT LEFT BUMPER SUPPORT	\$ 103.95	bt ✓
1.00	FRONT RIGHT BUMPER SUPPORT	\$ 103.95	bt ✓
1.00	FRONT TOP SPONGE	\$ 66.42	mis ✓
1.00	FRONT BOTTOM SPONGE	\$ 66.42	mis ✓
1.00	FRONT LEFT SPONGE	\$ 47.07	mis ✓
1.00	FRONT RIGHT SPONGE	\$ 47.07	mis ✓
1.00	FOAM COMPONENT	\$ 38.16	mis ✓
2.00	FRONT LOWER MOUNT BOLT	\$ 10.00	rec ✓
2.00	FRONT EDGE PROTECTION	\$ 44.00	mis ✓
1.00	FRONT BONNET ENBLEM	\$ 125.10	rec ✓
1.00	FRONT CROSSLINK Radiator top panel	\$ 715.23	bt ✓
2.00	FRONT CROSSLINK STOP BUFFER	\$ 46.98	rec ✓
1.00	FRONT LEFT ROD	\$ 43.02	bt ✓
1.00	FRONT RIGHT ROD	\$ 43.02	bt ✓
1.00	FRONT UPPER LEFT RADIATOR BRACKET	\$ 56.70	bt ✓
1.00	FRONT UPPER RIGHT RADIATOR BRACKET	\$ 56.70	bt ✓
2.00	FRONT SUPPORT BRACKET	\$ 69.30	bt ✓
2.00	FRONT SUPPORT PANEL BRACKET	\$ 346.68	bt ✓
2.00	FRONT LEFT AND RIGHT BRACE BRACKET	\$ 338.22	bt ✓
2.00	FRONT LEFT AND RIGHT HEADLAMP SUPPORT	\$ 549.18	bt ✓
2.00	FRONT LEFT AND RIGHT HEADLAMP LEVER	\$ 186.30	mis ✓
7.00	FRONT SUPPORT HEAD SCREW	\$ 40.95	rec ✓

8402-29

Estimate



Li Sheng Automobile Trading

Please arrange to survey at
Blk K, Pandan Loop #01-16 /18 S(128236)

CHINA TAIPING

Your Ref Vehicle No:
SKZ8200U (TP claim)

Date: 22/10/2018
Vehicle No: SLX8977K
Model: BMW 18
Date of loss: 13/10/2018
Our ref: LSA274TJS
Year: 2014

4.00	FRONT C-CLIP NUT	\$	11.88	nei ✓
4.00	FRONT ISA SCREW	\$	24.84	nei ✓
6.00	FRONT BLIND RIVET NUT	\$	36.72	nei ✓
8.00	FRONT C-CLIP PLASTIC NUT	\$	14.40	nei ✓
2.00	FRONT LEVER TORX BOLT	\$	20.00	nei ✓
2.00	FRONT SUPPORT FLAT NUT	\$	29.88	nei ✓
1.00	FRONT WINDSHIELD	\$	2,600.00	X nn
1.00	FRONT WINDSHIELD TOP COVER	\$	93.60	X nn
10.00	FRONT WINDSHIELD BUMP STOP	\$	57.60	X nn
2.00	FRONT WINDSHIELD LEFT & RIGHT ROOF FRAME GASKET	\$	27.36	X nn
1.00	HEADLINING (roof lining)	\$	2,790.00	de ✓
1.00	FRONT WINDSHIELD COVER	\$	180.00	cu ✓
2.00	FRONT LEFT AND RIGHT APRON COVER	\$	198.00	de ✓
3.00	FRONT WINDSHIELD COVER EXPANDING RIVET	\$	10.00	nei ✓
1.00	DASHBOARD INSTRUMENT PANNEL UPPER PART	\$	6,390.00	de ✓
1.00	FRONT UNDERHOOD SHIELD	\$	392.25	cu ✓
2.00	FRONT LEFT AND RIGHT BOOTOM COVER	\$	280.90	tn ✓
26.00	FRONT UNDER COVER BOLT	\$	36.54	nei ✓ nn
2.00	FRONT LEFT AND RIGHT WHEELHOUSING	\$	230.40 460.80	LH - X, RH - de ✓
2.00	FRONT REAR LEFT AND RIGHT WHEELHOUSING	\$	432.00	X nn
2.00	TOP LEFT AND RIGHT WHEEL ARCH COVER	\$	256.00	de ✓
20.00	WHEELHOUSING PLASTIC NUT	\$	72.00	nei ✓
4.00	WHEELHOUSING HEX BOLT	\$	38.00	X nn
1.00	FRONT AIR DUCT	\$	180.00	de ✓
1.00	FRONT BOTTOM AIR DUCT	\$	577.50	C n ✓
1.00	FRONT LOWER LEFT AIR DUCT	\$	135.00	cu ✓
1.00	FRONT LEFT BRAKE AIR DUCT	\$	72.00	de ✓
1.00	FORNT LOWER RIGHT AIR DUCT	\$	135.00	cu ✓
1.00	FRONT RIGHT BRAKE AIR DUCT	\$	72.00	de ✓
1.00	FRONT UPPER EXHAUST AIR DUCT	\$	207.00	de ✓
1.00	FRONT LOWER SECTION AIR EXHAUST DUCT	\$	72.00	cu ✓
1.00	FRONT LOWER LEFT AIR-EXHAUST DUCT	\$	76.50	X nn
1.00	FRONT LOWER RIGHT AIR-EXHAUST DUCT	\$	76.50	X nn
4.00	FRONT BRAKE AIR DUCT HEX BOLT	\$	10.08	nei ✓
4.00	C-CLIP FOR PLASTIC NUT	\$	10.00	nei ✓
8.00	EXPANDING RIVET	\$	12.24	nei ✓
1.00	BATTERY TRAY	\$	210.00	X nn ✓
4.00	FRONT PARKING SENSOR	\$	2,000.00	dis ✓
4.00	FRONT PARKING SENSOR RING	\$	34.00	nei ✓
1.00	FRONT BONNET	\$	3,964.35	bt ✓
1.00	FRONT LEFT BONNET HINGE	\$	134.00	bt ✓
1.00	FRONT RIGHT BONNET HINGE	\$	134.00	bt ✓
4.00	FRONT BOONRT HINGE SELF LOCKING COLLAR NUT	\$	8.00	nei ✓

1873098