

ASS, REC, BY:

REF:

CS / CTU 8019674 / R11b

Special Instruction:

SURVAYOR

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTL

Date/Time:

29/10/2018 5:06pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 3821A

Insured:

SLJ 767E

at Workshop m/s

SK Automobile

Tel:

8121 0478

of

1 Soon Lee St #04-44

Policy No:

DMPCSN1767541700

Claim No:

9WM18D05085002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

30-10-2018

H.O.D. Endorsement:

Date/Time:

29-10-2018 5:31pm

Person Contacted:

An Xung

Vehicle

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLU 3821A - X

SLJ 767E - X

Wump Sum \$5400/- (Red: 9289.50', 63%)

Surveyor: Porn

REF:

52102

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 3821Aat Workshop m/s SK AUTOMOBILEof 1 BOOKLEST #04-44Insured: CTI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLU 3821A Yr Regn: 2017 / NOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra 1.6 G4S A.C (591)Colour: Red A/C: Insured / Std / NI / NASp. Reading: 11231 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM1H0841CMJWS70628

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEKENFront RearR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 24/10/18 D.O.I. 30/10/18Survey held at SK AUTOMOBILE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Rashid,pls check all parts prices

RECEIVED 09 APR 2019

Date/Time, File Pass to?

Blk Typist

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ 5400/-)TPDays Of Repair: 7Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Oct 2018		29 Oct 2018 17:06 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHEN DONG, ID: S8787019G		
Main Claimant:	SURESH KWAAR VEDULA		
Vehicle Reg. No.:	SLU3821A	Date of Loss:	24/10/2018 17:00 - :59
Claim Type:	TP / SNM18D05085C02	Policy/Cover Note No.:	DMPCSN1767541700 (Comprehensive)
Vehicle Reg. No. (Insured):	SLJ7617E	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	SK Automobile Pte Ltd (Pioneer) 1 Soon Lee Street #04-44/45, Pioneer Centre, 627605 Pioneer - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638985192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/11/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: JING XIONG KHOO <xionskauto@gmail.com>
Sent: Tuesday, 2 April 2019 10:59 AM
To: Denise Tay (LKKAUTO)
Cc: Rasul (LKKAUTO); Pioneer Workshop; Susan Koh; SK Admin
Subject: Re: SLU3821A AFTER PAINT PHOTOS
Attachments: SLU3821 MARKING ESTIMATE.pdf

Denise Tay/Rasul,

Vehicle No. : SLU3821A

Part (-20%) : \$ 4,648.00
S/Nett : \$ 4,20.00
Labour : \$ 1,940.00
Total : \$7,008.00
L/S (after -20%) : \$ 5,607.00

Refer to the above matter. and re- finalization

Kindly close the case at \$5,600.00

Denise Tay (LKKAUTO) <denisetay@lkkauto.com> 于 2019 年 4 月 2 日周二 上午 10:08 写道:

Dear Susan/Jing Xiong,

Please check and confirm on finalization amount

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Denise Tay (LKKAuto)

From: Susan Koh <susan@skauto.com.sg>
Sent: Monday, 8 April 2019 11:51 AM
To: Rasul (LKKAuto)
Cc: JING XIONG KHOO; Pioneer Workshop; SK Admin; Denise Tay (LKKAuto)
Subject: Re: SLU3821A AFTER PAINT PHOTOS

Dear Rasul

We confirm acceptance of Final COR at \$5,400.00 and 07 workdays.

THANK YOU

Best Regards
Susan
C/O SK Automobile Pte Ltd

On Mon, Apr 8, 2019 at 10:52 AM Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Xiong,

Kindly close at 5400


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: JING XIONG KHOO [<mailto:xiongskauto@gmail.com>]
Sent: Tuesday, 2 April, 2019 10:59 AM
To: Denise Tay (LKKAuto)

Denise Tay (LKKAuto)

From: JING XIONG KHOO <xiongskauto@gmail.com>
Sent: Friday, 4 January 2019 10:13 AM
To: Denise Tay (LKKAuto)
Cc: Sk Automobile; SK Admin; Susan Koh; Pioneer Workshop
Subject: Re: SLU 3821A / TP / DOA: 24/10/2018

Hi Denise,

On 27/11/2018 already sent calculation breakdowns & after paint photo for your surveyor mr rasu and remind him on 13/12/18 he no reply

Dear Mr. Rasul,
Please assist to finalize the case.

Vehicle No. : SLU3821A
D.O.A : 24/10/2018
Date Surveyed : 30/10/2018

Parts : 6,343.20 After less 20%
S/Nett : 420.00
Labour : 1,940.00
Total : 8,703.20
Total After Less 20% : 6,962.56

Can we close the case at \$ 6,950.00 ?

Please acknowledge finalization asap please

On Fri, 4 Jan 2019 at 09:24, Denise Tay (LKKAuto) <denisetay@lkkauto.com> wrote:

Dear Ah Xiong,

Can help me to check this case, vehicle has sent in for repair? If yes, Any finalization please forward

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Hyundai Elantra

Price Range

Depreciation

2017

Vehicle Type

Advanced Search

Home » Used Cars » Steven Mobile » Hyundai Elantra 1.6A GLS

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Hyundai Elantra 1.6A GLS

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$69,800 + \$90 → \$70,390**

Depreciation \$7,090 /yr

View models with similar depreciation

Reg Date 26-Oct-2017

(8yrs 11mths 28days COE left)

Manufactured 2017

Mileage 16,700 km (16.7k /yr)

Transmission Auto

Engine Cap 1,591 cc

Road Tax \$738 /yr

Power 93.8 kW (125 bhp)

View specs of the Hyundai Elantra (2016)

Curb Weight 1,345 kg

Features
 4 Cylinder Inline 16 Valve Dual CVT Engine, Multi Function Steering, Keyless Entry/Start, Auto Headlights, Retractable Side Mirrors, Cruise Control.

Accessories
 Standard Accessories, Leather Seats, Sports Rims, HUD, Front And Reverse Camera, Reverse Sensors, Driver Power Seat, White Daylight, Fog Lamps, HID.

Description
 1 Owner, Low Mileage, Low Dow Payment Only \$9,900 Monthly \$865 x 84 Fully Serviced, Beautiful Interior And Sleek Finish. Call To View And Test Drive. Bank Loan And In House Welcome.

COE \$42,902

OMV \$12,032

ARF \$12,032

Dereg Value \$47,636 as of today (change)

No. of Owners 1

Type of Veh Mid-Sized Sedan

Category PARF Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 23-Oct-2018 | Last Updated on: 27-Oct-2018

Tags: Hyundai Elantra, hyundai elantra, 2017 Hyundai Elantra, 2017 hyundai elantra, Hyundai, Elantra, elantra, Used Hyundai



Seller Information

Company	Steven Mobile » dealer's pricelist » 37 vehs sold 12 vehs available
Address	8 Kaki Bukit Avenue 4 #07-16 Search cars nearby this location
Location	Premier @ Kaki Bukit
Office No	63489909
Contact Person(s)	Steven 96788282

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Upfront Payment

» more Financial info

Transfer Fee \$25

Down Payment \$20,940 (change)

Maximum 70% Loan

1st Instalment \$703

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5210C
Vehicle Details	
Vehicle No.:	SLU3821A
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Oct 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	G4FGHU806355
Chassis No.:	KMHD841CMJU570625
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$12,019.00
Original Registration Date:	30 Nov 2017
First Registration Date:	30 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$12,019.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2027
PARF Rebate Amount:	\$9,014.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,791.00
COE Rebate Amount:	\$42,527.00
Total Rebate Amount:	\$51,541.00

The information contained herein is correct as at 27 Oct 2018

OK

\$ 70,390.00

\$ 51,541.00

\$ 18,849.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/10/2018 10:31
Date Of Accident	24/10/2018 17:40
Exact Location Of Accident	CHANGI SOUTH AVE 3 > PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU3821A
Insured/Policyholder	
Name Of Registered Owner	SURESH KUMAR VEDULA
NRIC No	S6865210C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81261945
Alternative Phone No	OTHERS-81261945

Vehicle Particulars

Manufacturer	HYUNDAI
Model	ELANTRA AD 1.6 GLS AT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098135851
Cover Note Number	

Driver

Name of Driver	SURESH KUMAR VEDULA
NRIC No	S6865210C
Date Of Birth	04/01/1968
Occupation	OUTDOOR
Date Of Driving Pass	28/06/2006
Driving Experience	12 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81261945
Fax Number	
Contact Number	OTHERS-81261945
Email Address	NOEMAIL

Address	16 ANG MO KIO CENTRAL 3 #10-25 GRANDEUR 8
Postcode	567748
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ7617E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	SURESH KUMAR VEDULA
Approximate Age	

Injuries Sustain

Injured person in which vehicle?

SLU3821A

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

16 ANG MO KIO CENTRAL 3 #10-25 GRANDEUR 8

Postcode

567748

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.




auth

IDAC KAKI BUKIT (VAC)
Reporting to: Mr. Peter Lim (Singapore)
Name: Singapore 415933
NRIC/FIN No.: Tel: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24-10-2018 at about 17:40hrs, I was travelling along Changi South Ave 3. Upon reaching the junction, I slow down & stop. While on stationary, all of a sudden I felt an impact from the rear. Then I realised a vehicle SLJ 7617E had collided onto my rear.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

26 OCT 2018
IDAC KAKI BUKIT(VAC)
23 KAKI BUKIT AVE 4
Singapore 415933
Reporting Centre
Tel: 67416897
Name: Fax: 67492305
NRIC/FIN No. Email: vackb@singnet.com.sg

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 30-Oct-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SLU3821A
ADDRESS	:	MODEL	: HYUNDAI ELANTRA
TEL. NO.	:	CHASSIS NO	: p=4648 SM=420 LB=1940
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT :		KUMAR98973736	
QUOTATION SUMMARY			7608 - 1401-20% 5607

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>274</i>	1	\$ 1,728.00	<i>1720</i> 1,728.00
2	BOOT LID REFLECTOR RH <i>X AN</i>	1	\$ 664.00	\$ 664.00
3	BOOT LID INNER LOCK <i>cut</i>	1	\$ 487.00	<i>208</i> 487.00
4	BOOT LID LOWER LOCK <i>X AN</i>	1	\$ 42.70	\$ 42.70
5	BOOT LID EMBLEM "ELANTRA" <i>new</i>	1	\$ 68.60	<i>78</i> 68.60
6	BOOT LID EMBLEM "S" <i>new</i>	1	\$ 45.00	\$ 45.00
7	BOOT LID LOGO <i>new</i>	1	\$ 37.40	<i>82</i> 37.40
8	BOOT LID INSULATOR <i>X AN</i>	1	\$ 387.00	\$ 387.00
9	BOOT LID HINGE <i>X AN</i>	2	\$ 132.00	\$ 264.00
10	BOOT LID WEATHERSTRIP <i>X AN</i>	1	\$ 254.00	\$ 254.00
11	BOOT LID DETECTOR SENSOR <i>RA</i>	<i>1pc</i>	\$ 325.00	\$ 650.00
12	TAILLAMP <i>2pc</i>	<i>1pc</i>	\$ 876.00	\$ 1,752.00
13	TAILLAMP PANEL RH <i>21</i>	1	\$ 380.00	<i>380</i> 380.00
14	REAR BUMPER <i>26</i>	1	\$ 678.00	\$ 678.00
15	REAR BUMPER LOWER <i>cut</i>	1	\$ 610.00	<i>280</i> 610.00
16	REAR BUMPER RETAINER <i>X AN</i>	2	\$ 54.50	\$ 109.00
17	REAR BUMPER BRACKET <i>AN</i>	2	\$ 25.00	\$ 50.00

1.748 1620
X
16270 174
X
48 68
33
30 50
X
X
165
515.70
193.70 250
505.40
228.70 280
X

18	REAR BUMPER REFLECTOR	CR ✓	1	\$	120.00	\$	120.00	58
19	REAR BUMPER REINFORCEMENT	PA ✓	1	\$	455.00	\$	455.00	315.70
20	REAR BUMPER SIDE COVER RH	cut ✓	1	\$	120.00	\$	120.00	45
21	REAR FENDER RH	repair	1	\$	954.00	\$	954.00	X
22	REAR FENDER COWLING RH	X n	1	\$	168.00	\$	168.00	X
23	REAR FENDER INNER TRIM RH	X n	1	\$	348.00	\$	348.00	X
24	REAR END PANEL	PA ✓	1	\$	680.00	\$	480 680.00	379
25	REAR END PANEL TOP GARNISH	CR ✓	1	\$	289.00	\$	289.00	105
26	REAR FLOOR PANEL TOP BOARD	X n	1	\$	445.00	\$	445.00	X
27	REAR EXHAUST PIPE	PA ✓	1	\$	980.00	\$	789 980.00	489.50

5503.80

20%

4403.04

5809.80
-20% 1161.00

4648

TOTAL PRICE

LESS 20%

SUB TOTAL PRICE

\$ 12,765.70

\$ 2,553.14

\$ 10,212.56

4368.80

20%

3495.04

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE X n	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP SET n	1	\$ 65.00	\$ 30 65.00
3	BOOT LID INSULATOR CLIP SET n	1	\$ 65.00	\$ 30 65.00
4	TAILLAMP CLIP SET n	1	\$ 32.00	\$ 15 32.00
5	TAILLAMP PANEL SEALANT n	1	\$ 80.00	\$ 30 80.00
6	REAR FENDER SEALANT n	1	\$ 120.00	\$ 20 120.00
7	REAR FENDER INNER COWLING CLIP SET X n	1	\$ 60.00	\$ 1 60.00
8	REAR FENDER SIDE INNER TRIM CLIP SET n	1	\$ 60.00	\$ 20 60.00
9	REAR END PANEL TOP GARNISH CLIP SET n	1	\$ 25.00	\$ 15 25.00
10	REAR END PANEL SEALANT n	1	\$ 120.00	\$ 60 120.00
11	REVERSE SENSOR SET n	1	\$ 250.00	\$ 200 250.00

TOTAL

\$ 927.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS.	\$ 1,500.00	750
2	TO SPRAY PAINT AFFECTED AREA.	\$ 1,500.00	900
3	TO APPLY TUFF COAT.	\$ 250.00	70
4	PERFORM REAR WIRING CHECK.	\$ 60.00	30
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	\$ 80.00	60

6	TRANSFER BOOT LID MECHANISM.	\$	80.00 40	
7	CONDUCT WATER LEAKAGE TEST.	\$	80.00 30	

8 Remove Refix Exhaust pipe
TOTAL

\$ ~~100~~ 60
\$ 3,550.00

1940 1940

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,139.56
TOTAL LABOUR COST : \$ 3,550.00
TOTAL REPAIR COST : \$ 14,689.56

14799.46

APPROVED DETAILS

EXCESS

NO. OF WORKING DAYS

RE-SURVEY

PART BY PART OR CUMULATIVE

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

7 day

30/10/18 @ 1630 hrs
RASHUL (LKK)
20010068

31/10/18

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3495.04
420.00
1940.00
5855.04
20%
4684.03
4/5 - 4,700

7 days

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: CHINA TAIPING	DATE	: 30-Oct-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SLU3821A
ADDRESS	:	MODEL	: HYUNDAI ELANTRA
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : KUMAR98973736			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>2 pt /</i>	1	\$ 1,728.00	\$ 1,728.00
2	BOOT LID REFLECTOR RH <i>X n</i>	1	\$ 664.00	\$ 664.00
3	BOOT LID INNER LOCK <i>cut /</i>	1	\$ 487.00	\$ 487.00
4	BOOT LID LOWER LOCK <i>X n</i>	1	\$ 42.70	\$ 42.70
5	BOOT LID EMBLEM "ELANTRA" <i>2 n</i>	1	\$ 68.60	\$ 68.60
6	BOOT LID EMBLEM "S" <i>2 n</i>	1	\$ 45.00	\$ 45.00
7	BOOT LID LOGO <i>2 n</i>	1	\$ 37.40	\$ 37.40
8	BOOT LID INSULATOR <i>X n</i>	1	\$ 387.00	\$ 387.00
9	BOOT LID HINGE <i>X n</i>	2	\$ 132.00	\$ 264.00
10	BOOT LID WEATHERSTRIP <i>X n</i>	1	\$ 254.00	\$ 254.00
11	BOOT LID DETECTOR SENSOR <i>1 RA /</i>	<i>1 pc</i>	\$ 325.00	\$ 650.00
12	TAILLAMP <i>2 RA /</i>	<i>1 pc</i>	\$ 876.00	\$ 1,752.00
13	TAILLAMP PANEL RH <i>2 n</i>	1	\$ 380.00	\$ 380.00
14	REAR BUMPER <i>2 n</i>	1	\$ 678.00	\$ 678.00
15	REAR BUMPER LOWER <i>cut /</i>	1	\$ 610.00	\$ 610.00
16	REAR BUMPER RETAINER <i>X n</i>	2	\$ 54.50	\$ 109.00
17	REAR BUMPER BRACKET <i>n</i>	2	\$ 25.00	\$ 50.00

11048
X
162.70
X
48
33
30
X
X
X
165
515.70
193.10
505.40
225.70
X
✓

18	REAR BUMPER REFLECTOR	CR1/	1	\$ 120.00	\$ 120.00
19	REAR BUMPER REINFORCEMENT	PA/	1	\$ 455.00	\$ 455.00
20	REAR BUMPER SIDE COVER RH	cut/	1	\$ 120.00	\$ 120.00
21	REAR FENDER RH	repair	1	\$ 954.00	\$ 954.00
22	REAR FENDER COWLING RH	X n1	1	\$ 168.00	\$ 168.00
23	REAR FENDER INNER TRIM RH	X n1	1	\$ 348.00	\$ 348.00
24	REAR END PANEL	PA/	1	\$ 680.00	\$ 680.00
25	REAR END PANEL TOP GARNISH	CR1/	1	\$ 289.00	\$ 289.00
26	REAR FLOOR PANEL TOP BOARD	X n1	1	\$ 445.00	\$ 445.00
27	REAR EXHAUST PIPE	PA/	1	\$ 980.00	\$ 980.00

TOTAL PRICE \$ 12,765.70
 LESS 20% \$ 2,553.14
SUB TOTAL PRICE \$ 10,212.56

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE	X n1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP SET	n1/	\$ 65.00	\$ 30 65.00
3	BOOT LID INSULATOR CLIP SET	n1/	\$ 65.00	\$ 30 65.00
4	TAILLAMP CLIP SET	n1/	\$ 32.00	\$ 15 32.00
5	TAILLAMP PANEL SEALANT	* n1/	\$ 80.00	\$ 30 80.00
6	REAR FENDER SEALANT	n1/	\$ 120.00	\$ 20 120.00
7	REAR FENDER INNER COWLING CLIP SET	X n1	\$ 60.00	\$ 1 60.00
8	REAR FENDER SIDE INNER TRIM CLIP SET	n1/	\$ 60.00	\$ 20 60.00
9	REAR END PANEL TOP GARNISH CLIP SET	n1/	\$ 25.00	\$ 15 25.00
10	REAR END PANEL SEALANT	n1/	\$ 120.00	\$ 60 120.00
11	REVERSE SENSOR SET	n1/	\$ 250.00	\$ 200 250.00

TOTAL \$ 927.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS.	\$ 1,500.00 750	
2	TO SPRAY PAINT AFFECTED AREA.	\$ 1,500.00 900	
3	TO APPLY TUFF COAT.	\$ 250.00 70	
4	PERFORM REAR WIRING CHECK.	\$ 60.00 30	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	\$ 80.00 60	

6	TRANSFER BOOT LID MECHANISM.	\$	80.00 40	
7	CONDUCT WATER LEAKAGE TEST.	\$	80.00 30	
8	Removed Refix Exhaust pipe	\$	100 60	
	TOTAL	\$	3,550.00	1940

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,139.56
TOTAL LABOUR COST : \$ 3,550.00
TOTAL REPAIR COST : \$ 14,689.56

APPROVED DETAILS

EXCESS
NO. OF WORKING DAYS : 7 days
RE-SURVEY :
PART BY PART OR LUMP :

DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

30/10/18 @ 1630 hrs
Rasul (LKK)
90010068

31/10/18

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3495.04
420.00
1940.00

5855.04
20%
4684.03
4/s - 4,700

7 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118019674/R1TBN2

Date: 10/04/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1767541700
Claimant Vehicle No :	SLU3821A	Insured Vehicle No :	SLJ7617E
Date of Loss:	24/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D05085C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU3821A	Engine No:	G4FGHU806355
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU570625
Reg. Date:	30/11/2017 (Man. Year: 2017)	Odometer:	11231 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,149.64	4,822.64	6,327.00	56.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	1,940.00	1,710.00	46.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,799.64	6,762.64	8,037.00	54.31
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	14,799.64	5,400.00	9,399.64	63.51
+ GST 7.00/7.00% (S\$)	1,035.97	378.00	657.97	63.51
Nett Amount (S\$)	15,835.61	5,778.00	10,057.61	63.51

INSPECTION

Date of Assignment:	29/10/2018	
Date Inspected:	30/10/2018	Inspected At:
		1 Soon Lee St #01-44
		Repairer: SK Automobile Pte Ltd (Toh Guan)
		48 Toh Guan Road East #01-121,
		Enterprise Hub
		Singapore 608586

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2019)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU3821A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	1,728.00 FL	*1,620.00 FL
2	1		*BOOT LID REFLECTOR RH	Not Necessary	664.00 FL	*- FL
3	1		*BOOT LID INNER LOCK	Cut	487.00 FL	*174.00 FL
4	1		*BOOT LID LOWER LOCK	Not Necessary	42.70 FL	*- FL
5	1		*BOOT LID EMBLEM ELANTRA	Necessary	68.60 FL	*68.00 FL
6	1		*BOOT LID EMBLEM S	Necessary	45.00 FL	*33.00 FL
7	1		*BOOT LID LOGO	Necessary	50.00 FL	*50.00 FL
8	1		*BOOT LID INSULATOR	Not Necessary	387.00 FL	*- FL
9	2		*BOOT LID HINGE	Not Necessary	264.00 FL	*- FL
10	1		*BOOT LID WEATHERSTRIP	Not Necessary	254.00 FL	*- FL
11	1		*BOOT LID DETECTOR SENSOR	Cracked (1 Pc only)	650.00 FL	*165.00 FL
		(2 Pcs)				
12	1		*TAILLAMP	Broken (1 Pc only)	1,752.00 FL	*515.70 FL
		(2 Pcs)				
13	1		*TAILLAMP PANEL RH	Bent	380.00 FL	*250.00 FL
14	1		*REAR BUMPER	Deformed	678.00 FL	*505.40 FL
15	1		*REAR BUMPER LOWER	Cut	610.00 FL	*280.00 FL
16	2		*REAR BUMPER RETAINER	Not Necessary	109.00 FL	*- FL
17	2		*REAR BUMPER BRACKET	Necessary	50.00 FL	*50.00 FL
18	1		*REAR BUMPER REFLECTOR	Cracked	120.00 FL	*58.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	455.00 FL	*315.20 FL
20	1		*REAR BUMPER SIDE COVER RH	Cut	120.00 FL	*45.00 FL
21	1		*REAR FENDER RH	Repair	954.00 FL	*- FL
22	1		*REAR FENDER COWLING RH	Not Necessary	168.00 FL	*- FL
23	1		*REAR FENDER INNER TRIM RH	Not Necessary	348.00 FL	*- FL
24	1		*REAR END PANEL	Bent	680.00 FL	*480.00 FL
25	1		*REAR END PANEL TOP GARNISH	Cracked	289.00 FL	*105.00 FL
26	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	445.00 FL	*- FL
27	1		*REAR EXHAUST PIPE	Bent	980.00 FL	*789.00 FL
28	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
30	1		*SET BOOT LID INSULATOR CLIP	Necessary	65.00 FS	*30.00 FS
31	1		*SET TAILLAMP CLIP	Necessary	32.00 FS	*15.00 FS
32	1		*TAILLAMP PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
33	1		*REAR FENDER SEALANT	Necessary	120.00 FS	*20.00 FS
34	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
35	1		*SET REAR FENDER SIDE INNER TRIM CLIP	Necessary	60.00 FS	*20.00 FS
36	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	25.00 FS	*15.00 FS
37	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*60.00 FS
38	1		*SET REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,705.30	5,923.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,555.66	1,100.66

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					11,149.64	4,822.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,500.00	750.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,500.00	900.00
3	TO APPLY TUFF COAT	New	250.00	70.00
4	PERFORM REAR WIRING CHECK	New	60.00	30.00
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	60.00
6	TRANFER BOOT LID MECHANISM	New	80.00	40.00
7	CONDUCT WATER LEAKAGE TEST	New	80.00	30.00
8	REMOVE & REFIX EXHAUST PIPE	New	100.00	60.00
Gross Labour Cost (S\$)			3,650.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >