

1952/10

INS. CASE OWNER:

CC 6 / CTI1801

LKK:

IDAC:

Surveyor:

marcus

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:

Fastech

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

2/11/18

14/1

12/11/18

24/11/18

9/9/19 - FILE PASS TO LIP TO CLOSE

G0H5087B-X

979498J-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)	☒	☐
After call ltr to OI:	☒	☐
Authorisation To Act:	☒	☐
Release Voucher:	☒	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☐	☐
Towing Invoice:	☐	☐
LTA / GIA:	☒	☐
Medical Bill:	☐	☐
PIR:	☐	☐
Mandate/Reject Instruction:	☐	☐
LOD	☒	☐
Payment Breakdown Form:	☐	☐
Post-Repair Photos:	☐	☐
Others:	☐	☐

PRELIMINARY ADVICE

Date/Time:

12/11/18

Sent By:

CJH

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

22/8/19

Confirm with:

Jason

Email ☒ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost: (w/bst)

SS 7062.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

560.00 (S 80 x 7 days)

Loss of Income (LOI):

SS

(S x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS 7624.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

SS

Name 1:

Fastech Auto Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Email ☐ Call ☐

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400

24/5/19

REF:

C74/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

8348W

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time Action / Instruction

21A28887

Veh No:

G3H/50873

Yr Regt:

6 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Car

Make:

Toyota hiace

2882

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

18903

T/Radio: Insured / Std / NI / NA

Eng/for:

G/No:

JTFH T02P300243023

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim: / STD A/Rim: or

Tyre Size:

F:

195 215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6

mm

R/Bal.

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

28/10/18

D.O.I.

29/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

☐

: Preli. Report

1)

Date/Time: File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation

) \$ - PS. (\$)

) Photo

) Other

TOTAL

8/11/18 L/S 6600 continued with the

(Red 8590.75/574)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI18019691/Upb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 29-10-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJY 2498J		Veh. Inspected	GBH 5087B
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	29/10/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/10/2018		Inspection Date	29/10/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 /

Tax Reg No : 20-0006262-D

Not Authorized
29/10/18
6600
6dy.

Qty Particular GBH 50873 Amount S\$

List Item :

1 pc	Rear boot
1 pc	Rear boot logo
1 pc	Rear boot outer handle
1 pc	Rear boot inner lock
1 pc	Rear boot lock stricker
1 pc	Rear boot sticker (hiace)
1 pc	Rear boot inner trim board
1 set	Rear boot inner trim board clips
1 pc	Rear boot weatherstrip
1 pc	Rear window inner seal
1 pc	Rear boot sticker (toyota)
2 pc	Rear tail lamp @ 352.30
2 pc	Rear tail lamp garnish @ 109.50
2 pc	Rear tail lamp hoousing panel @ 349.10
1 pc	Rear bumper
1 pc	Rear air vent nls
4 pc	Rear bumper lower support brackets @ 56.20
1 set	Rear bumper clips
1 pc	Rear end panel inner
1 pc	Rear end panel outer
1 pc	Rear end panel top steel plate
1 pc	Rear fender nls
1 pc	Rear spare tyre bracket
1 pc	Rear exhaust
List Item Total :	

body	\$	2,150.10
ner	\$	48.60
11	\$	241.10 X
20/5m	\$	395.60
11	\$	40.10 X
ner	\$	60.35
10/1	\$	288.30
ner	\$	45.00
ner	\$	292.30
ner	\$	45.00
ner	\$	35.20
nls	\$	704.60 12C
nls	\$	219.00 12C
nls	\$	698.20 12C
20/5	\$	596.20
215	\$	165.40
ner	\$	224.80
ner	\$	50.00
ner	\$	850.00
ner	\$	486.50
11	\$	228.10 X
ner	\$	1,452.20 X
ner	\$	263.10
ner	\$	971.00 X
\$		10,550.75

25%

6807.35

Special Nett Item :

8pax sticker
70 km/h sticker
1250 sticker
Rear windscreen sealant
Reverse sensor 1set
Rear end panel sealant
Rear REVERSE CAMERA
Rear floor panel insulator

ner	\$	20.00
ner	\$	20.00
ner	\$	20.00 X
ner	\$	50.00 40
ner	\$	280.00 200
ner	\$	50.00
ner	\$	500.00 300
ner	\$	200.00 X
\$		1,140.00

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 /

Tax Reg No : 20-0006262-D

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Qty	Particular	Policy No :	Amount S\$
-----	------------	-------------	------------

Labour Charge :

Remove and replace rear windscreen
Remove and replace rear reverse sensor
To check wiring
To spray rust proofing
Remove and replace tailgate mechanism
Labour for panel beating
To putty & spray painting
Labour charge total :

\$	150.00	120
\$	80.00	50
\$	50.00	30
\$	120.00	80
\$	100.00	60
\$	1,500.00	1200
\$	1,500.00	1000
\$	3,500.00	

8225.51
6620

E : Total Amount : \$ 15,190.75

FASTECH AUTO PTE LTD

LKK Auto Consultants hereby notify the Repairer of the following:
• To resurvey before spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62564561 FAX: (065) 62564315

Your ref: SNM18D05124C02
Our ref: CC6/CTI18019691/Upb3

Date: 12.11.2018

The Motor Claims Department
M/S China Taiping Insurance (Singapore) Pte. Ltd

Dear Sir/Madam

PRELIMINARY ADVICE OF VEHICLE NO.


GBH 5087B

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on
29.10.2018 at the premises of M/s Fastech Auto Pte Ltd
and have the following to report:-

Workshop Estimate Amount	: S\$	15,190.75
Revised Estimate Amount	: S\$	6,600.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	(est)
LTA Reimbursement Value	: S\$	(est)
Nett Value	: S\$	(est)

Description of Damage:
The vehicle sustained damages at the
REAR



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 06 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

> Back to OneMotoring**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 8348W

Vehicle Details

Vehicle No.: GBH5087B

Vehicle to be Exported: No

Intended Deregistration Date: 29 Oct 2018

Vehicle Make: TOYOTA

Vehicle Model: HIACE VAN TURBO 5DR MT

Primary Colour: White

Manufacturing Year: 2018

Engine No.: 1KD2805643

Chassis No.: JTFHT02P300243023

Maximum Power Output: -

Open Market Value: \$28,138.00

Original Registration Date: 27 Jun 2018

First Registration Date: 27 Jun 2018

Transfer Count: 0

Actual ARF Paid: \$1,407.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Jun 2028

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$29,901.00

COE Rebate Amount: \$28,887.00

Total Rebate Amount: \$28,887.00

The information contained herein is correct as at 29 Oct 2018

OK

Shu Pei (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Thursday, 1 November 2018 3:58 PM
To: Shu Pei (LKKAUTO)
Cc: Elaine Cheong
Subject: RE: Direct Settlement - Accident Involving SJY2498J (OI : CTI - SNM18D05124C02) AND GBH5087B (TP : LKK REF - CC6/CTI18019691/Upb3) on 28.10.2018
Attachments: leeSZ_SNM18D05124C01-SJY2498J-LKKDirectSettlementAccidentLtr_CLCR95.236.pdf; MCHM18140179-SJY2498J.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Elaine Cheong

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Tuesday, 30 October, 2018 6:25 PM
To: Claims Dept of CTI
Cc: Elaine Cheong; Lucas Lee; Hsiao Tong (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SJY2498J (OI : CTI - TBA) AND GBH5087B (TP : LKK REF - CC6/CTI18019691/Upb3) on 28.10.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle GBH 5087B at M/s Fastech Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Tel: 6389 6111 Fax: 6222 1033

Website: www.sg.cntaiping.com

Cy. Reg. No. 200208384E

Our Reference: **SNM18D05124/C01/8**

Date : **01 NOVEMBER 2018**

via Ordinary & Registered Mail

**KUEK TONY
BLK 318B YISHUN AVENUE 9
#13-138
SINGAPORE 762318**

Dear Sir / Madam

**ACCIDENT INVOLVING SJY2498J AND GBH5087B ON 28 OCTOBER 2018
ALONG AYE TOWARDS CHANGI**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **GBH5087B**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : HSIAO TONG

Ref : CC6/CTI18019691/UPB3

Contact No : 67423197

via Email : HSIAOTONG@LKKAUTO.COM

CC : Agent - (AN0365A) - HIGH POWER ENTERPRISE

F01/LKKDS-2013

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Monday, 4 February 2019 10:44 AM
To: 'claimsdept@sg.cntaiping.com'
Cc: Elaine Cheong; Admin A
Subject: <Seek Mandate>Direct Settlement - Accident Involving SJY2498J (OI : CTI - SNM18D05124C02) AND GBH5087B (TP : LKK REF - CC6/CTI18019691/Upb3) on 28.10.2018
Attachments: LKKInspection.pdf; LKKAdjustment1.pdf; LKK Survey Photos.pdf; LKK Resurvey Photos 1.pdf; LKK Resurvey Photos 2.pdf; TP LOD_GBH5087B.pdf

Your ref : **SNM18D05124C02**
Our ref : CC6/CTI18019691/Upb3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING SJY2498J(OI) AND GBH5087B(TP) ON 28/10/2018

We refer to the above matter.

This is a head-to-rear collision. We are of the view that liability is not in our insured driver's favour. We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "**FASTECH AUTO PTE LTD**" at **\$7,624.00(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 16,254.10	\$ 7,062.00
2. Loss of Use (7days x \$85.00)	\$ 595.00	\$ 560.00(7days x \$80.00)
3. LTA/ GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 16,824.10	<u>\$ 7,624.00</u>

**6days recommendation for repair + 1Sunday = 7days

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAUTO)
Sent: Monday, 12 November 2018 2:57 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18019691/Udb3s2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 16-09-2019		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJY 2498J	Veh. Inspected	GBH 5087B	
Policy No.	DMPCSN3003201702	Coverage (\$)	0.00	
Claim No.	SNM18D05124C02/8	Excess (\$)	0.00	
Assign From		Assign Date	29/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFHT02P300243023	Colour	WHITE	
Odometer	18903	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/10/2018	Inspection Date	29/10/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 5087B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	BADLY DENTED	2,150.10	2,150.10
1	REAR BOOT LOGO	NECESSARY	48.60	48.60
1	REAR BOOT OUTER HANDLE	NOT NECESSARY	241.10	-
1	REAR BOOT INNER LOCK	DENTED / JAMMED	395.60	395.60
1	REAR BOOT LOCK STRIKER	NOT NECESSARY	40.10	-
1	REAR BOOT STRIKER (HIACE)	NECESSARY	60.35	60.35
1	REAR BOOT INNER TRIM BOARD	TORN	288.30	288.30
1	SET REAR BOOT INNER TRIM BOARD CLIPS	NECESSARY	45.00	45.00
1	REAR BOOT WEATHERSTRIP	TWISTED	292.30	292.30
1	REAR WINDOW INNER SEAL	NECESSARY	45.00	45.00
1	REAR BOOT STICKER (TOYOTA)	NECESSARY	35.20	35.20
2	REAR TAIL LAMP @ \$352.30	N/S CRACKED	704.60	352.30
2	REAR TAIL LAMP GARNISH @ \$109.50	N/S TWISTED	219.00	109.50
2	REAR TAIL LAMP HOUSING PANEL @ \$349.10	N/S DENTED	698.20	349.10
1	REAR BUMPER	DISTORTED	596.20	596.20
1	REAR AIR VENT N/S	DISTORTED	165.40	165.40
4	REAR BUMPER LOWER SUPPORT BRACKETS @ \$56.20	BENT	224.80	224.80
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL INNER	BADLY DENTED	850.00	850.00
1	REAR END PANEL OUTER	BADLY DENTED	486.50	486.50
1	REAR END PANEL TOP STEEL PLATE	NOT NECESSARY	228.10	-
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	1,452.20	-
1	REAR SPARE TYRE BRACKET	BENT	263.10	263.10
1	REAR EXHAUST	TO REPAIR SEE LABOUR	971.00	-
	LESS 25% DISCOUNT		-	-1,701.84
			10,550.75	5,105.51
SPECIAL NETT ITEMS				
1	8PAX STICKER (SN)	NECESSARY	20.00	20.00
1	70KM/H STICKER (SN)	NECESSARY	20.00	20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	1250 STICKER (SN)	NOT FITTED	20.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR REVERSE CAMERA (SN)	SHORTED	500.00	300.00
1	REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	200.00	-
			1,140.00	630.00
	LABOUR			
	REMOVE AND REPLACE REAR WINDSCREEN.		150.00	120.00
	REMOVE AND REPLACE REAR REVERSE SENSOR.		80.00	50.00
	TO CHECK WIRING.		50.00	30.00
	TO SPRAY RUST PROOFING.		120.00	80.00
	TO REMOVE AND REPLACE TAILGATE MECHANISM.		100.00	60.00
	LABOUR FOR PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER N/S AND REAR EXHAUST.		1,500.00	1,200.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
			3,500.00	2,540.00
GRAND TOTAL			15,190.75	8,275.51
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,600.00

Report Ref No. CC6/CTI18019691/Udb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.