

ASS. REC. BY:

REF: CS/FCI 18019696/USD3 | 02
Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Luvane jaw

of

PER

Date/Time:

29/10/18 @ 6:19pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIL 2955A

Insured:

SHA 8079 X

at Workshop m/s

Prof Automotive

Tel:

9433 5558

of

10 kaki Bkt Rd 2 # 01-03 First East Centre

Policy No:

Claim No:

01800 7768 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

DS

D.O.A.

26/10/2018

CA / REV / REP. / REV 24 HRS

(up)

31/10/2018

H.O.D. Endorsement:

Date/Time:

9:20am @ 30/10/18

Person Contacted:

Edward

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
01/11/18	@ 15:18 p.m. revised PA to Luvane via email

Insurance No/Ref:

REF:

Ref/

ASSIGNMENT

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

5JL2955A

at Workshop no/s:

20th

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

28

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

20/11/2023

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

5JL2955A

Yr Regn:

17 08

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Jeep AXIO

1496

Colour:

Grey

A/C: Insured / Std / Nil / NA

Sp. Reading

16955

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

N2E1416097946

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

hankook

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

26/10/18

D.O.I.

31/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

renew 102 already LTA 14832

10/12/18 confirmed 21s \$5,000/- with Edward.

10/12/18 Confirmed 21s \$5,000/- @ 6 days with Marcus.
(\$5,889.20 Red - 54%)

MV - 28K

LTA - \$14,832.00

Net - \$13,168.00

Date/Time: File Pass to?

10/12/18

1)

Typist

Date/Time: File Return to?

2)

Report Format :

Lump Sum / I.B.I: \$ 5,000/- H/S

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation

1 S + PS \$

Photos

Others

TOTAL

170
50
50
90

360

RECEIVED 10 DEC 2018



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007768MFSH

Date: 01 November 2018

Our Ref: CS/FCII8019696/Usd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJL 2955A

Please be informed that we had conducted the inspection of the abovementioned vehicle on 31/10/2018 at the premises of M/s Profi Automotive and have the following to report:-

Workshop Estimate Amount	: S\$ 10,887.20
Revised Estimate Amount	: S\$ 7,068.15
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 5 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	29-10-2018	Our Ref No. D18007768MFSH
Accident Date	26-10-2018	Claim Type. Third Party
Insured Vehicle	SHA8079X	Third Party Vehicle. SJL2955A
Survey Location	10 kaki bukit road 2 #01-03First East centre	
Contact Person.	EDWARD OW	
Contact No.	94335558/ 94335558	Fax No. 66048454
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROFI AUTOMOTIVE	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 1 November 2018 3:18 PM
To: 'Lurene Jaw'; 'CWS Motor Claims'
Cc: SUR; assignments
Subject: RE: SURVEY ASSESSMENT - D18007768MFSH/1
Attachments: SJL 2955A - Preli Advise.pdf

Dear Lurene,

Enclosed preliminary revised of vehicle SJL 2955A.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 30 October 2018 10:32 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007768MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer arrange on 31/10/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 29 October 2018 6:18 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18007768MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Inchcape
Pre-Owned
6303 6303

FREE SERVICE & TYRE CREDITS
WHEN YOU PURCHASE A CAR FROM INCHCAPE-PREOWNED

PIT & GO
FREE SERVICE & TYRE CREDITS

VALUE **\$1,500**
FOR PURCHASES BELOW \$10K

PIT & GO
FREE SERVICE & TYRE CREDITS

VALUE **\$3,000**
FOR PURCHASES ABOVE \$10K



LEARN MORE
➔

Post an Advertisement

Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

1 Owner! Very Low Mileage! Cheapest Sporty Ride!



Sporty Yet Economy Ride!
Cheaper Than Taking Public Transport!
Direct Owner StarAd

PRIME MOTOR & LEASING

(SHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category

« Back (1 2 3) Next »

Sort by Date Posted

20 results/page

45 vehicles

axio

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	axio		Any	Any	2008	Any	Any	Any	Available
	Toyota	Corolla Axio 1.5M X (OPC) (New 5-yr COE)	\$24,800	\$4,960 /yr	11-Nov-2008	1,496 cc	89,800 km	Sedan	Available
New 5-years COE, One Owner To Avail Of This Great Deal, Call Us For Inquiries Or Visit Our Showroom For Viewing.									
Posted: 30-Oct-2018 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Axio 1.5A X (COE till 10/2023)	\$27,900	\$5,650 /yr	07-Oct-2008	1,496 cc	-	Sedan	Available
Elegant Silver, Spacious Sedan, Low Fuel Consumption, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-House Loan Packages Available.									
Prime Motor & Leasing									
Posted: 29-Oct-2018 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Axio 1.5A X (COE till 10/2023)	\$29,988	\$6,030 /yr	21-Oct-2008	1,496 cc	103,100 km	Sedan	Available
1 Owner, Low Mileage! New Paint, Pioneer DVD Player, Reverse Camera, New Leather Interior, No Repair Needed New Aircon, Full Servicing Done! New Auto Transmission Oil! All Good To Go! Must View To Bel...									
Posted: 29-Oct-2018 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									
	Toyota	Corolla Axio 1.5A X (COE till 10/2023)	\$27,800	\$5,580 /yr	24-Oct-2008	1,496 cc	126,458 km	Sedan	Available
New Arrival! New 5 Years COE! Cheapest In Town! Genuine Price! (Low Depreciation Of \$5570 Annually Only!) Low Mileage Of 12000km Clocked Annually! Very Mint Condition! Interior/Exterior Looks Like New...									
Posted: 28-Oct-2018 Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota									

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Corolla Axio 1.5A X (New 5-yr COE)

\$27,888

\$5,570 /yr

25-Nov-2008

1,496 cc

106,000 km

Sedan

Available

Free Servicing Upon Purchase! 1 Years Warranty Engine And Gearbox! 100% Loan Approval! Bank And In House Loan Available! Low Down Payment Available! No Gimmicks! Trade In Welcome! Priced Lowest In The...

Posted: 28-Oct-2018

Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota



Toyota Corolla Axio 1.5A X (COE till 09/2023)

\$29,800

\$6,090 /yr

23-Sep-2008

1,496 cc

107,000 km

Sedan

Available

Sporty Black, Well Maintained, Super Low Genuine Mileage Done. Well Groomed Inside Out. No Repairs Needed. Comes With 6 Months Warranty By Our In House Workshop. Free Island Wide Towing In Event Of Em...

PREMIUM AD

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6339J
Vehicle Details	
Vehicle No.:	SJL2955A
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	1NZD202399
Chassis No.:	NZE1416097946
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$13,420.00
Original Registration Date:	21 Nov 2008
First Registration Date:	21 Nov 2008
Transfer Count:	0
Actual ARF Paid:	\$13,420.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Nov 2018
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Nov 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,835.00
COE Rebate Amount:	\$14,832.00
Total Rebate Amount:	\$14,832.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 20 Nov 2018

OK

30 October 2018

Your Ref: Your insured SHA8079X

Our Ref: PA181004-SJL2955A

Accident Date: 26 October 2018

Vehicle No: SJL2955A

Make/Model: Toyota Axio 1.5X A

Name: Teng Boon Leng

Address: c/o 10 Kaki Bukit Road 2 #01-03 Singapore 417868

Not Alud
n/a
n/a \$5000/2
6th
31/10/18

S/NO	QTY	LISTED ITEM	AMOUNT (\$S)
01	1 pc	Rear Boot <i>not Alud</i>	1074.80
02	1 pc	Rear Boot Lock <i>not Alud</i>	307.80
03	1 pc	Rear Boot Lock Catch <i>in x</i>	94.50 X
04	1 pc	Rear Boot Rubber <i>to in</i>	232.40
05	1 pc	Rear Boot Emblem (AXIO) <i>not Alud</i>	70.60
06	1 pc	Rear Boot Emblem (X) <i>not Alud</i>	60.20
07	1 pc	Rear Boot Centre Logo <i>not Alud</i>	48.20
08	1 pc	Rear Boot Centre Garnish	202.40
09	2 pc	Rear Boot Centre Garnish Clip (8.50 X 2) <i>11 X</i>	17.00 X
10	2 pc	Rear Boot Hinge (107.40 X 2) <i>11 X</i>	214.80 X
11	1 pc	Rear Boot Inner Cover <i>in x</i>	440.80 X
12	11 pc	Rear Boot Inner Cover CLIP (6.50 X 11) <i>in x</i>	71.50 X
13	1 pc	Rear Spare Tire Panel <i>11 X</i>	946.20 X
14	1 pc	Rear Spare Tire Top Cover Board <i>not Alud</i>	678.60
15	1 pc	Rear End Panel <i>not Alud</i>	824.20
16	1 pc	Rear End Panel Top Garnish <i>not Alud</i>	274.40
17	2 pc	Rear End Panel Top Garnish Clip (12.90 X 2) <i>11 X</i>	25.80 X
18	2 pc	Rear Tail Lamp (437.40 X 2) <i>not Alud</i>	874.80
19	2 pc	Rear Tail Lamp Lower Bracket (121.60 X 2) <i>1/8 one 1/2</i>	243.20 1/2
20	2 pc	Rear Tail Lamp Panel (201.20 X 2) <i>not Alud</i>	402.40 X
21	2 pc	Rear Tail Lamp Gasket Seal (97.20 X 2) <i>not Alud</i>	194.40 X
22	2 pc	Rear Number Plate Lamp (86.20 X 2) <i>11 X</i>	172.40 X
23	1 pc	Rear Bumper <i>not Alud</i>	1074.80
24	2 pc	Rear Bumper Side Bracket (Big) (83.60 X 2) <i>not Alud</i>	167.20
25	2 pc	Rear Bumper Side Bracket (Small) (60.70 X 2) <i>not Alud</i>	121.40
26	2 pc	Rear Bumper Inner Bracket (81.60 X 2) <i>not Alud</i>	163.20 1/2
27	4 pc	Rear Bumper Lower Clip (12.90 X 4) <i>not Alud</i>	51.60
Listed Item Total			9049.60
*Less 25%			2262.40
			6787.20

5112.70
25%
3834.52

S/NO	QTY	SPECIAL NETT ITEM	AMOUNT (\$\$)
01	1 set	Rear Bumper Sensors <i>shunt 2025.11</i>	300.00
02	1 pc	Rear Number Plate <i>11x</i>	50.00
03	1 set	Rear Bumper Reverse Camera <i>shunt 300</i>	450.00
Special Nett Item Total			800.00

S/NO	LABOUR	AMOUNT (\$\$)
01	Panel Beating	1500.00
02	Check Wiring & Reset	100.00
03	Rust Proofing	100.00
04	Remove & Replace Rear Bumper Sensor	100.00
05	Spray Painting	1500.00
Labour Total		2700.00
Grand Total		10887.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18019696/Usd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8079X	Veh. Inspected	S JL 2955A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007768MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	29/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA AXIO (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	NZE1416097946	Colour	GREY	
Odometer	169551	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	HANKOOK	6 mm	
L/H Front Tyre	185/70 R14	HANKOOK	6 mm	
R/H Rear Tyre	185/70 R14	HANKOOK	6 mm	
L/H Rear Tyre	185/70 R14	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/10/2018	Inspection Date	31/10/2018	
Survey held at	PROFI AUTOMOTIVE BLK 10 KAKI BUKIT ROAD 2 #01-03 FIRST EAST CENTRE SINGAPORE 417868			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 2955A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	DENTED / BUCKLED	1,074.80	845.10
1	REAR BOOT LOCK	TWISTED	307.80	266.50
1	REAR BOOT LOCK CATCH	NOT NECESSARY	94.50	-
1	REAR BOOT RUBBER	TORN	232.40	232.40
1	REAR BOOT EMBLEM (AXIO)	NECESSARY	70.60	48.50
1	REAR BOOT EMBLEM (X)	NECESSARY	60.20	45.00
1	REAR BOOT CENTRE LOGO	NECESSARY	48.20	48.20
1	REAR BOOT CENTRE GARNISH	CRACKED	202.40	202.40
2	REAR BOOT CENTRE GARNISH CLIP @\$8.50	NOT NECESSARY	17.00	-
2	REAR BOOT HINGE @\$107.40	TO REPAIR SEE LABOUR	214.80	-
1	REAR BOOT INNER COVER	NOT NECESSARY	440.80	-
11	REAR BOOT INNER COVER CLIP @\$6.50	NOT NECESSARY	71.50	-
1	REAR SPARE TIRE PANEL	TO REPAIR SEE LABOUR	946.20	-
1	REAR SPARE TIRE TOP COVER BOARD	CRACKED	678.60	495.00
1	REAR END PANEL	BADLY DENTED	824.20	581.10
1	REAR END PANEL TOP GARNISH	TWISTED	274.40	274.40
2	REAR END PANEL TOP GARNISH CLIP @\$12.90	NOT NECESSARY	25.80	-
2	REAR TAIL LAMP @\$437.40	CRACKED	874.80	874.80
2	REAR TAIL LAMP LOWER BRACKET @\$121.60	N/S CRACKED	243.20	121.60
2	REAR TAIL LAMP PANEL @\$201.20	TO REPAIR SEE LABOUR	402.40	-
2	REAR TAIL LAMP GASKET SEAL @\$97.20	NOT NECESSARY	194.40	-
2	REAR NUMBER PLATE LAMP @\$86.20	NOT NECESSARY	172.40	-
1	REAR BUMPER	DISTORTED	1,074.80	655.90
2	REAR BUMPER SIDE BRACKET (BIG) @\$83.60	BENT	167.20	167.20
2	REAR BUMPER SIDE BRACKET (SMALL) @\$60.70	BENT	121.40	121.40
2	REAR BUMPER INNER BRACKET @\$81.60	N/S BENT	163.20	81.60
4	REAR BUMPER LOWER CLIP @\$12.90	NECESSARY	51.60	51.60

Report Ref No. CS/FCI18019696/Usd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,262.40	-1,278.18
			6,787.20	3,834.52
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER SENSORS (SN)	SHORTED	300.00	200.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER REVERSE CAMERA (SN)	SHORTED	450.00	300.00
			800.00	500.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BOOT HINGE,REAR SPARE TIRE PANEL AND REAR TAIL LAMP PANEL.		1,500.00	800.00
	CHECK WIRING & RESET.		100.00	30.00
	RUST PROOFING.		100.00	60.00
	REMOVE & REPLACE REAR BUMPER SENSOR.		100.00	50.00
	SPRAY PAINTING.		1,500.00	1,080.00
			3,300.00	2,020.00
	GRAND TOTAL		10,887.20	6,354.52
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00

Report Ref No. CS/FCI18019696/Usd3n2

MARKET VALUE: \$28,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,832.00=NETT VALUE: \$13,168.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.