

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKW5084Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR RH FRONT FENDER, RH REAR DOOR AND RENEW RH FRONT DOOR.	900.00	780
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	900.00	750
3	ZZ/003	REMOVE AND INSTALL RH FRONT DOOR MECHANISM.	80.00	/
4	ZZ/004	APPLY SEALANT TO RH FRONT DOOR.	100.00	/
TOTAL LABOUR CHARGES			----- 1980.00 -----	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKW5084Z

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1	SUNDRIES <i>new</i>	NPN			70.00 <i>20</i>
2	R/F FENDER ARC MLDG <i>cut</i>	63810-4EA0A	483.00	✓	
3	R//R DOOR LOWER PVC MLDG <i>cut</i>	82870-4EA0A	264.80	✓	
4	R/F DOOR LOWER PVC MLDG <i>cut</i>	80870-4EA0A	323.60	✓	
5	R/F DOOR TAPE <i>new</i>	80812-4EA0A	29.90	✓	
6	DOOR-FRONT RH <i>replaced</i>	H0100-4EAAA	1104.80	✓	
SUB TOTAL			2206.10	0.00	70.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			441.22	0.00	0.00
GRAND TOTAL			1764.88	0.00	70.00
OVERALL TOTAL			1834.88		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKW5084Z

TOTAL LABOUR CHARGES	1980.00
TOTAL SPARE PARTS CHARGES	1834.88

GRAND TOTAL	3814.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Adrian Lim
7/p 29/10/18
04 days.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.