

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412
Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

DATE

7/11/2018

VSKYBAM

M/SAIG

DEAR SIR / MADAM ESTIMATE REPAIR COST FOR GBF5856J

	TO SUPPLY :
1 1 PC	BONNET
2 1 PC	BONNET LOCK
3 1 PC	GRILLE
4 1 PC	GRILLE CLIPS
5 1 PC	BADGE
6 2PCS	HEADLAMP $466.40 \times 2 = 932.80$
7 1 PC	FRONT BUMPER 536.10
8 1 PC	FRONT BUMPER CLIPS
9 1 PC	FRONT BUMPER SIDE RETAINER
10 2PCS	FRONT BUMPER SIDE GARNISH
11 1 PC	FRONT BUMPER SPONGE 291.60
12 1 PC	FRONT BUMPER REINFORCEMENT
13 1 PC	SUPPORT PANEL
14 2PCS	HEADLAMP PANEL TOP
15 2PCS	HEADLAMP PANEL SIDE
16 1 PC	RADIATOR SIDE AIR GUIDE
17 1 PC	REAR BUMPER
18 1 PC	REAR BUMPER CLIPS
19 2PCS	REAR BUMPER RED REFLECTOR
20 1 PC	REAR END PANEL INNER
21 1 PC	REAR END PANEL OUTER
22 1 PC	REAR BUMPER SPONGE
23 2PCS	TAILLAMP
24 1 PC	TAILGATE 644.60
25 1 PC	REAR NISSAN LOGO
26 1 PC	REAR DOOR "DCi" STICKER
27 1 PC	REAR NISSAN " NV200"
28 1 PC	TAILGATE HINGE
29 1 PC	TALGATE CHECKER LH
30 1 PC	REAR DOOR WEATHERSTRIP
31 1 PC	RH DOOR
32 1 PC	REAR RH DOOR LOWER HINGE
33 1 PC	NUMBER PLATE GARNISH

Bul	\$	782.90	/
twl	\$	55.30	/
cre	\$	338.00	/
11	\$	45.00	X
11	\$	59.70	/
cre	\$	1,236.40	/
11	\$	589.70	/
11	\$	40.00	/
Bul	\$	44.00	/
11	\$	658.60	/
11	\$	320.80	/
11	\$	614.90	/
11	\$	507.50	/
11	\$	132.60	X
11	\$	102.40	X
11	\$	70.00	/
11	\$	624.80	/
11	\$	40.00	/
11	\$	110.00	X
11	\$	598.40	X
11	\$	122.40	/
11	\$	84.00	/
11	\$	504.20	1 PC 252.10
11	\$	1,281.10	/
11	\$	145.60	/
11	\$	68.90	/
11	\$	79.90	/
11	\$	198.20	X
11	\$	75.00	/
11	\$	106.90	/
11	\$	960.60	/
11	\$	99.10	X
11	\$	336.00	X

34	1 PC	RH DOOR RUBBER	<i>700</i>	\$ 57.00	✓
				\$ 11,089.90	
		LESS 10%		\$ (1,108.99)	
				\$ 9,980.91	
		SPECIAL NETT ITEMS			
35	1 PC	REVERSE SENSOR	<i>shutd</i>	\$ 280.00	<i>200</i>
36	<i>1</i> PC	SEALANT <i>for both glass</i>	<i>rec</i>	\$ 80.00	✓
37	1 PC	COMPANY ARTWORK	<i>rec</i>	\$ 880.00	<i>400</i>
38	1 PC	REAR "70 km/h"	<i>rec</i>	\$ 15.00	<i>10</i>
39	1 PC	AIRCON CONDENSER	<i>11</i>	\$ 658.20	<i>X</i>
40	1 PC	HORN	<i>11</i>	\$ 78.00	<i>X</i>
41	1 PC	RADIATOR	<i>1A</i>	\$ 684.70	<i>X</i>
		FRONT :			
42		SPRAY PAINTING		\$ 1,100.00	<i>600</i>
43		LABOUR CHARGE		\$ 880.00	<i>600</i>
44		WIRING CHECK		\$ 35.00	<i>20</i>
45		REMOVE AND RENEW AIRCON PARTS		\$ 160.00	<i>100</i>
		REAR :	<i>both</i>		
46		REMOVE & REFIT REAR WINDSCREEN		\$ 160.00	✓
47		TUFFCOAT	<i>1</i>	\$ 120.00	✓
48		RENEW REVERSE SENSOR		\$ 80.00	<i>50</i>
49		SPRAY PAINTING		\$ 1,250.00	<i>800</i>
50		LABOUR CHARGE		\$ 1,250.00	<i>900</i>
51		WIRING CHECK		\$ 50.00	<i>20</i>
52		TRANSFER DOOR FITTING		\$ 280.00	<i>100</i>
				<u>\$ 18,021.81</u>	
					<i>4760</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 8673.70
102
7806.33
460.00
11966.33