



# 樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref. SF/WSK/jw/SF-quo

30 October 2018

AIG - TP

SKQ 2892 X NISSAN LATIO

S\$

Spare Parts	front bumper <i>DE</i> ✓	470.00 nett
	Front bumper retainer <i>re</i> ✓	25.00 nett
	Front bumper clips @\$4.40 x 10 <i>re</i> ✓	44.00 nett
	Right front headlamp ?	390.00 nett
	Right front headlamp holder ?	30.00 nett
	Right front fog lamp ?	350.00 s.nett
	Right front fender <i>repair</i>	650.00 nett
	Right front fender cowling X	85.00 nett
	Right front fender cowling clips @\$4.40 x 8 pcs X	35.20 nett
		-----
		2,079.20

Labour To knock, straighten front inner panel, front lower panel, Frt side panel, right front wheelhouse, front support Panel, renew front bumper, front right headlamp, right Front fender and assembly.

~~900.00~~ *400*

To respray damaged parts.

~~750.00~~ *400*

-----  
S\$3,729.20  
=====

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Pass*

*49 900/008*

*3 days*

*48*

*31/10/18 @ 1145*

*Resurvey after repair*