

REF CS3/ III 18011908/Gsd3-1



SA/VOC/

ASSIGNMENT (Office)

Minimen Andrew Lim

III

Date/Time 06/08/2018

Estimated Cost

Bill to

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No GU 1733T

Insured SHB 7542B

at Workshop no/ Rhino Repairs

Tel 6254 8858

of 160 Sin Ming Drive #03-14

Policy No

Claim No

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A 04/06/18

04/07/2018 @ after 10am

CA / REV / REP. / REV 24 HRS /wp/

H.O.D. Endorsement

Date/Time 5:00pm 02/6/18

Person Contacted Dawn

Vehicle IN (OUT)

Date/Time	Action/Instruction (X) Estimate
	GU 1733T - NA / INCO90089641
	SHB 7542B - CCA / AXA 18010296 / Dpb3
	DCA - 25/1/2009
	DCA - 09/06/2018
07/18	After Repair
13/11/18	Confirmed L/S \$ 1,700/- @ 3days with Guo Qiang. (\$14,209.00 Red - 89%)

RECEIVED 19 NOV 2018.

14/11/2018.

160-160 =

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 19 November 2018 10:26 AM
To: rhinorepairsg@gmail.com
Cc: Admin-D (LKKAuto)
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Hi Dawn,

Final invoice and all supporting documents sent over to India International Insurance Pte Ltd

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: rhinorepairsg@gmail.com [mailto:rhinorepairsg@gmail.com]
Sent: Saturday, 17 November 2018 12:49 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Hi Shirely,

Confirm, \$1700 + 3 day loss of use.

Thank you.

Best Regards,

Dawn Sim



Rhino Rental Pte Ltd

160 Sin Ming Drive #03-14, Sin Ming Autocity Singapore 575722

Office: 6254 8858 Fax: 6250 9702 Email: sales@rhinorental.sg

Company/GST Registration No. 201325388E

Note: This is an original invoice and no hardcopy will be mailed out with effect as we are going paperless billing

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Wednesday, 14 November 2018 1:33 PM

To: rhinorepairsg@gmail.com

Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Hi Dawn,

Please confirm the final fig \$ 1,700.00 (lump sum) @ 3 days of repairs.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: rhinorepairsg@gmail.com [mailto:rhinorepairsg@gmail.com]

Sent: Friday, 9 November 2018 1:32 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Hi Nivitha,

Any updates?

Best Regards,

Dawn Sim



RhinoRental

Rhino Rental Pte Ltd

160 Sin Ming Drive #03-14, Sin Ming Autocity Singapore 575722

Office: 6254 8858 Fax: 6250 9702 Email: sales@rhinorental.sg

Company/GST Registration No. 201325388E

Note: This is an original invoice and no hardcopy will be mailed out with effect as we are going paperless billing

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Tuesday, 30 October 2018 2:07 PM

To: rhinorepairsg@gmail.com

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Dear Dawn,

Thank you for the email.

We'll check and revert to you shortly.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: rhinorepairsg@gmail.com [<mailto:rhinorepairsg@gmail.com>]

Sent: Tuesday, 30 October 2018 2:03 PM

To: 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Hi Nivitha,

I have send you the estimated repair cost on the 6 August 2018 and till now there is no respond from your side.

Please advise.

Thank you.

Best Regards,

Dawn Sim



Rhino Repairs Pte Ltd

160 Sin Ming Drive #03-14, Sin Ming Autocity Singapore 575722

Tel: 8666 4445 Fax: 6250 9702 Email: rhinorepairsg@gmail.com

Company Reg. No. 201600994N

From: rhinorepairsg@gmail.com <rhinorepairsg@gmail.com>

Sent: Thursday, 20 September 2018 5:54 PM

To: 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Hi Nivitha,

Will like to check with you If there is any updates on this case?

Please advise.

Thank you.

Best Regards,

Dawn Sim



Rhino Repairs Pte Ltd

160 Sin Ming Drive #03-14, Sin Ming Autocity Singapore 575722

Tel: 8666 4445 Fax: 6250 9702 Email: rhinorepairsg@gmail.com

Company Reg. No. 201600994N

From: rhinorepairssg@gmail.com <rhinorepairssg@gmail.com>

Sent: Monday, 6 August 2018 4:23 PM

To: 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Hi Nivitha,

Please find attachment estimated cost for your attention.

Best Regards,

Dawn Sim



Rhino Repairs Pte Ltd

160 Sin Ming Drive #03-14, Sin Ming Autocity Singapore 575722

Tel: 8666 4445 Fax: 6250 9702 Email: rhinorepairssg@gmail.com

Company Reg. No. 201600994N

From: Nivitha (LKK Auto) <admin-d@lkkauto.com>

Sent: Friday, 3 August 2018 1:34 PM

To: rhinorepairssg@gmail.com

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Dear Dawn,

You are most welcome.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: rhinorepairssg@gmail.com [mailto:rhinorepairssg@gmail.com]

Sent: Friday, 3 August 2018 1:29 PM

To: 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Hi Nivitha,

Noted ! Thank you so much for your help!

Best Regards,

Dawn Sim



Rhino Repairs Pte Ltd

160 Sin Ming Drive #03-14, Sin Ming Autocity Singapore 575722
Tel: 8666 4445 Fax: 6250 9702 Email: rhinorepairsg@gmail.com
Company Reg. No. 201600994N

From: Nivitha (LKK Auto) <admin-d@lkkauto.com>

Sent: Friday, 3 August 2018 1:26 PM

To: rhinorepairsg@gmail.com

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Dear Dawn,

I've informed my surveyor, later afternoon he will call to update you.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: rhinorepairsg@gmail.com [mailto:rhinorepairsg@gmail.com]

Sent: Friday, 3 August 2018 1:22 PM

To: 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Hi Nivitha,

Any updates on the estimated cost ?

Best Regards,

Dawn Sim



Rhino Repairs Pte Ltd

160 Sin Ming Drive #03-14, Sin Ming Autocity Singapore 575722
Tel: 8666 4445 Fax: 6250 9702 Email: rhinorepairsg@gmail.com
Company Reg. No. 201600994N

From: Nivitha (LKK Auto) <admin-d@lkkauto.com>

Sent: Friday, 6 July 2018 4:40 PM

To: rhinorepairsg@gmail.com

Cc: 'Motor Claim - III' <motorclaim@iii.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Dear Dawn,

Around 5 plus.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: rhinorepairsg@gmail.com [<mailto:rhinorepairsg@gmail.com>]
Sent: Friday, 6 July 2018 4:38 PM
To: 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>
Cc: 'Motor Claim - III' <motorclaim@iii.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Hi,

Can I check what time your surveyor will come down?

Please advise.

Best Regards,
Dawn Sim



Rhino Rental Pte Ltd

160 Sin Ming Drive #03-14, Sin Ming Autocity Singapore 575722
Office: 6254 8858 Fax: 6250 9702 Email: sales@rhinorental.sg
Company/GST Registration No. 201325388E

From: Nivitha (LKK Auto) <admin-d@lkkauto.com>
Sent: Friday, 6 July 2018 3:38 PM
To: rhinorepairsg@gmail.com
Cc: 'Motor Claim - III' <motorclaim@iii.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Dear Dawn,

Later my surveyor will come down for the post-repair photo taking.

BEST REGARDS,
G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]
Sent: Friday, 6 July 2018 3:34 PM
To: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Subject: FW: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

From: rhinorepairsg@gmail.com [<mailto:rhinorepairsg@gmail.com>]
Sent: 06 July, 2018 3:08 PM
To: Motor Claim - III <motorclaim@iii.com.sg>; 'Ruby Ong' <ruby@htapartners.com.sg>

Cc: sur@lkkauto.com; Sherini Pillai <sherini@iii.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Hi,

I will like to check with you if you can arrange your surveyor to drop by my workshop for the post-repair photo taking?

Best Regards,
Dawn Sim



Rhino Repairs Pte Ltd

160 Sin Ming Drive #03-14, Sin Ming Autocity Singapore 575722
Tel: 8666 4445 Fax: 6250 9702 Email: rhinorepairsg@gmail.com
Company Reg. No. 201600994N

From: rhinorepairsg@gmail.com <rhinorepairsg@gmail.com>

Sent: Thursday, 5 July 2018 5:52 PM

To: 'Motor Claim - III' <motorclaim@iii.com.sg>; 'Ruby Ong' <ruby@htapartners.com.sg>

Cc: sur@lkkauto.com; 'Sherini Pillai' <sherini@iii.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Importance: High

Hi,

Please get your surveyor to come down tomorrow morning for the post – repair inspection.

I will very much appreciate if you can reply to acknowledge with a time.

Thank you.

Best Regards,
Dawn Sim



Rhino Repairs Pte Ltd

160 Sin Ming Drive #03-14, Sin Ming Autocity Singapore 575722
Tel: 8666 4445 Fax: 6250 9702 Email: rhinorepairsg@gmail.com
Company Reg. No. 201600994N

From: rhinorepairsg@gmail.com <rhinorepairsg@gmail.com>

Sent: Wednesday, 4 July 2018 1:10 PM

To: 'Motor Claim - III' <motorclaim@iii.com.sg>; 'Ruby Ong' <ruby@htapartners.com.sg>

Cc: sur@lkkauto.com; 'Sherini Pillai' <sherini@iii.com.sg>

Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Hi,

Please advise what time is your surveyor coming down.

Thank you.

Best Regards,
Dawn Sim



Rhino Repairs Pte Ltd

160 Sin Ming Drive #03-14, Sin Ming Autocity Singapore 575722
Tel: 8666 4445 Fax: 6250 9702 Email: rhinorepairsg@gmail.com
Company Reg. No. 201600994N

From: rhinorepairsg@gmail.com <rhinorepairsg@gmail.com>
Sent: Tuesday, 3 July 2018 10:22 AM
To: 'Motor Claim - III' <motorclaim@iii.com.sg>; 'Ruby Ong' <ruby@htapartners.com.sg>
Cc: sur@lkkauto.com; 'Sherini Pillai' <sherini@iii.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Hi All,

The vehicle is in our workshop already, I will like to request for your surveyor to come down today instead of tomorrow before 5.30pm.

Please let me know if your surveyor can make it today.

Thank you.

Best Regards,
Dawn Sim



Rhino Repairs Pte Ltd

160 Sin Ming Drive #03-14, Sin Ming Autocity Singapore 575722
Tel: 8666 4445 Fax: 6250 9702 Email: rhinorepairsg@gmail.com
Company Reg. No. 201600994N

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 29 June 2018 4:00 PM
To: Ruby Ong <ruby@htapartners.com.sg>
Cc: rhinorepairsg@gmail.com; 'sur@lkkauto.com' <sur@lkkauto.com>; Sherini Pillai <sherini@iii.com.sg>
Subject: RE: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO.	:	GU1733T
III INSURED VEHICLE NO.	:	SHB7542B
DATE OF LOSS	:	04.06.2018

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor **LKK AUTO CONSULTANTS** to conduct the pre-repair survey.

This claim is handled by **PRIYA**.

Please let us have your client's **accident report and repair estimate** for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,

ANDREW LIM

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 227

S&P 'A-' (stable) rated Company

From: Ruby Ong [<mailto:ruby@htapartners.com.sg>]

Sent: Friday, 29 June, 2018 9:56 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: rhinorepairsg@gmail.com

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR GU1733T [OUR REF. TCL.MH.RO.50234.18.RR]

Importance: High

Your ref: SH 6383M

WITHOUT PREJUDICE

Our ref : TCL.MH.ro.50234.18.rr

29 June 2018

India International Insurance Pte Ltd

By Email Only

Motor Claims Department

64 Cecil Street

#04-02 IOB Building

Singapore 069428

VERY URGENT

Dear Sirs

CLAIMANT: RHINO RENTAL PTE LTD

ACCIDENT INVOLVING GU 1733T, SH 6383M & SHB 7542B ALONG CTE ON 4 JUNE 2018 @ ABOUT 0930HRS

We are instructed by Rhino Rental Pte Ltd to notify you of a road traffic accident on 4 June 2018 at about 0930hrs along CTE involving our client's vehicle registration number GU 1733T and vehicle registration number SH 6383M driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, our client propose to appoint **Victor Png of Appraisal VP Pte Ltd** as the single joint expert to carry out the pre-repair survey for GU 1733T.

Kindly make the necessary arrangements with the contact person. The details are as follows :

Venue : **Rhino Repairs Pte Ltd**
160 Sin Ming Drive
#03-14 Sin Ming Autocity
Singapore 575722

Contact Person : **Ms Dawn Sim (Tel: 6254 8858)**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313
www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including

the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.


If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Model : : NISSAN CABSTAR
 Vehicle No : GU1733T
 Workshop : Rhino Repair Pte Ltd

List of Damaged Parts

S/No	Qty	Description	Repairer's Amount (\$\$)	Adjuster's Amount (\$\$)
1	1	Rear tailgate / <i>done</i>	1,700.00	
2	1	Rear floor panel X	5,000.00	
3	1	Rear end panel X } <i>NN</i>	885.00	
4	1	Rear rh side gate X	3,000.00	
			10,585.00	0.00
			3,175.50	0.00
			7,409.50	0.00

Disc 30%

1190

Nett Item

S/No	Qty	Description	Repairer's Amount (\$\$)	Adjuster's Amount (\$\$)
5	1	Rear Tailgate "nissan"big red sticker X	100.00	
6	3	Rear tailgate hinge @60. each X	180.00	
7	1	Rear "nissan cab star"emblem sticker X	30.00	
8	2	Rear tail lamp (lh & rh) @250 <i>UH - CPA, MEX NN</i>	500.00	148.7
9	2	Rear tail lamp holder (lh & rh) @ \$100 X <i>NN</i>	200.00	
10	1	Rear no plate holder / <i>BT</i>	180.00	65.3
11	1	Rear no. plate lamp assy X	55.00	
12	3	Rear rh side gate hinge @60. each X	180.00	
13	1	Rear rh side gate lock X	200.00	
14	1	Rear rh lower tool box X	170.00	
15	1	Rear tow hock X	260.00	
			2,055.00	0.00
			205.50	0.00
			1,849.50	0.00

Disc 10%

244

192.6

Special Item

S/No	Qty	Description	Repairer's Amount (S\$)	Adjuster's Amount (S\$)
16	1	Rear reinforcement bar X	900.00	X
17	2	Rear reinforcement bar holder X	400.00	X
18	1	60 km/h sticker / MC	30.00	15
19	2	13 pax sticker X NH	30.00	X
20	2	Rear no plate / BT	40.00	15
			1,400.00	0.00
			1,400.00	0.00

10,659.00	0.00
-----------	------

30

Vehicle No
Workshop

GU1733T
Rhino Repair Pte Ltd

Labour Details for front

S/No	Description	Repairer's Amount (S\$)	Adjuster's Amount (S\$)
1	Check wiring system	250.00	30
2	Anti rust	500.00	X NN
3	Labour charge	2,500.00	300
4	Spray painting	2,000.00	400
Total Labour		5,250.00	0.00

730

ANNEX C

Repair Cost

S/No	Description	Repairer's Amount (S\$)	Adjuster's Amount (S\$)
1	Total Part Cost	10,659.00	0.00
2	Total Repair and Labour Cost	5,250.00	0.00
Total Repair		15,909.00	0.00

Repair Cost

\$15,909.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Repairer must be notified in writing if any
- is subject to final approval from Insurance Company

The repairs would require a period of 08 working days.

3 Days .

Acknowledged by Repairer
Signature:
Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref : CS3/III18011908/Gsd3e2-1	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Date : 21-11-2018	
			Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 7542B	Veh. Inspected	GU 1733T	
Policy No.		Coverage (\$)	0.00	
Claim No.	MCT18060110	Excess (\$)	0.00	
Assign From	ANDREW LIM	Assign Date	30/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN CABSTAR	c.c	3153	
Engine No.	HIDDEN	Year of Reg.	2001	
Chassis No.	JN1SF4F23Z0843020	Colour	SILVER	
Odometer	502621	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	SUMITOMO	5 mm	
L/H Front Tyre	195 R15	SUMITOMO	5 mm	
R/H Rear Tyre	155 R12	YOKOHAMA	5 mm	
L/H Rear Tyre	155 R12	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/06/2018	Inspection Date	04/07/2018	
Survey held at	RHINO REPAIRS-160 SIN MING DRIVE#03-14			
Repairer	-			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GU 1733T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	BUCKLED	1,700.00	1,700.00
1	REAR FLOOR PANEL	NOT NECESSARY	5,000.00	-
1	REAR END PANEL	NOT NECESSARY	885.00	-
1	REAR RH SIDE GATE	NOT NECESSARY	3,000.00	-
	LESS 30% DISCOUNT		-3,175.50	-510.00
			7,409.50	1,190.00
<u>NETT ITEMS</u>				
1	REAR TAILGATE "NISSAN" BIG RED STICKER (N)	NOT NECESSARY	100.00	-
3	REAR TAILGATE HINGE @\$60.00 (N)	NOT NECESSARY	180.00	-
1	REAR "NISSAN CAB STAR" EMBLEM STICKER (N)	NOT NECESSARY	30.00	-
2	REAR TAIL LAMP (LH&RH) @\$250.00 (N)	N/S CRACKED / O/S NOT NECESSARY	500.00	148.70
2	REAR TAIL LAMP HOLDER (LH&RH) @\$100.00 (N)	NOT NECESSARY	200.00	-
1	REAR NO PLATE HOLDER (N)	BENT	180.00	65.30
1	REAR NO. PLATE LAMP ASSY (N)	NOT NECESSARY	55.00	-
3	REAR RH SIDE GATE HINGE @\$60.00 (N)	NOT NECESSARY	180.00	-
1	REAR RH SIDE GATE LOCK (N)	NOT NECESSARY	200.00	-
1	REAR RH LOWER TOOL BOX (N)	NOT NECESSARY	170.00	-
1	REAR TOW HOCK (N)	NOT NECESSARY	260.00	-
	LESS 10% DISCOUNT		-205.50	-21.40
			1,849.50	192.60
<u>SPECIAL NETT ITEMS</u>				
1	REAR REINFORCEMENT BAR (SN)	NOT NECESSARY	900.00	-
2	REAR REINFORCEMENT BAR HOLDER (SN)	NOT NECESSARY	400.00	-
1	60KM/H STICKER (SN)	NECESSARY	30.00	15.00
2	13 PAX STICKER (SN)	NOT CHANGED	30.00	-
2	REAR NO PLATE (SN)	BENT	40.00	15.00
			1,400.00	30.00
<u>LABOUR</u>				
	CHECK WIRING SYSTEM.		250.00	30.00

Report Ref No. CS3/III18011908/Gsd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	ANTI RUST.	NOT NECESSARY	500.00	-
	LABOUR CHARGE.		2,500.00	300.00
	SPRAY PAINTING.		2,000.00	400.00
			5,250.00	730.00
GRAND TOTAL			15,909.00	2,142.60

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00
---	--	--	--	----------

Report Ref No. CS3/III18011908/Gsd3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

06/1/13) wof
ASS. REC. BY:

PRS
XRL

REF: III

ASSIGNMENT

From:

Date: 4/7/2018

Estimated Cost:

OR ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To/Inspect Vehicle No: GU 1733T

at Workshop n/s

Rhino Repairs

of 160 Sin Ming Drive # 03-14

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Down @ 6254 8858

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP, / 24 HRS ^{up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

64733T

Yr Regn:

2001, Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Cabstar 3/53

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

502621

T/Radio: Insured / Std / NI / NA

Eng/No:

JN1SF4F 23 20 84 302

C/No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ N/S / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R 15

R:

155 R 12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Sumitomo
(K)

Front

Rear

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

04-07-18

Survey held at

W/S

5:10pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

4/7/18

Submit PRS report

Date/Time: File Pass to?

19/1/18

1)

upst

Date/Time: File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 1,700/- 4/5)

80

80

10

120