

ESTIMATE TO REPAIR

VEHICLE NO. : GBC 1950 L
 MAKE : TOYOTA
 MODEL : HIACE 3.0 DX M
 YEAR : 2011
 CHASSIS NO : KDH2010070860

SURVEYOR NAME :
 DATE OF SURVEY : 01 NOV 2018
 TIME OF SURVEY :

DATE : 31-Oct-18
 DATE OF ACCIDENT : 26-Oct-18
 THIRD PARTY REF : SKU 9504 M / CHINA TAIPING

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	N/S Front Door			\$ 1,248.90	
1 pc	N/S Front Door Lock Pillar			\$ 589.10	
1 pc	N/S Rear Sliding Door			\$ 1,855.80	
1 pc	N/S Rear Sliding Door Rubber			\$ 387.10	
1 pc	N/S Rear Sliding Door Front Lock			\$ 311.50	
1 pc	N/S Rear Sliding Door Lock Switch			\$ 148.90	
				\$ 4,541.30	
				\$ 1,135.33	
	Less 25%			\$ 3,405.98	
1 pc	N/S Front Door Body Lettering	S.Nett		\$ 20.00	
	To putty and spray painting.			\$ 850.00	
	To transfer tailgate fittings.			\$ 100.00	
	Labour Charges.			\$ 700.00	
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
TG-RA/-	TOTAL				\$ 5,075.98

Not Authorised
 L1 Reg 8?
 7 days

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel: 65-64520893 Fax: 65-64589127 Website : www.LTM.sg
 Co. Reg No. 199307277D GST Reg No. M2-0019086-0