

INSURANCE

INS. CASE OWNED:

CC 6 /AIG1801

LKK

IDAC

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : \$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting It (1st)

Non-Reporting It (Cndy)

Non-Reporting It (Final)

Notification It (if non-pickup)

Call OI

After call It to OI

Documentation Check List: Handler Typist

Notification It (if non-pickup)

After call It to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others

Confirm by:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

\$

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOILA S/N No.

27

Repair Cost:

\$

4,333.50

Loss of Rental (LOR):

\$

(days)

Loss of Use (LOU):

\$

(5

x

days)

Loss of Income (LOI):

\$

1,000

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

\$

2. x y

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent)

Legal Cost:

\$

Total:

\$

5,335.50

Global Sum \$:

4,900. x x

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

4,900. x x

Name 1:

KANG

CAR REPAIRERS PTE LTD

Payee 2: (Strike if N.A.)

\$

Name 2:

x

Payee 3: (Strike if N.A.)

\$

x

Name 3:

x

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT 11/4/18

REF:

ASSIGNMENT

From _____ Date _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop no: _____

of _____

Insured _____

Policy No _____

Claims No _____

Sum Insured _____

Excess: _____

(Client's Record)

Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No SKD8751L Yr Regn 2012 Jan.

Type MC Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make

Toyota Uva

CC 1487

Colour

Silver

A/C Insured / Std / NI / NA

Sp Reading

63587

T/Radio: Insured / Std / NI / NA

Eng/No _____

C/No

MR053HY9305283427

Gen. Cond: Good / Fair / Poor / Burnt

Steering: OK / Jammed / Leaked / Burnt orBrake: OK / Jammed / Leaked / Burnt or

Modi: Nil / R/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / OKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A

26-10-18

D.O.I

29/10/18.

Survey held at

Keny.

Des. of Damages: Frt / Rep / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action Instruction

TP ALG.

\$4,050

26-10-18

27

28

29

30

31

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

48

49

50

51

52

53

54

55

56

57

58

59

60

61

62

63

64

65

66

67

68

69

70

71

72

73

74

75

76

77

78

79

80

81

82

83

84

85

86

87

88

89

90

91

92

93

94

95

96

97

98

99

100

101

102

103

104

105

106

107

108

109

110

111

112

113

114

115

116

117

118

119

120

121

122

123

124

125

126

127

128

129

130

131

132

133

134

135

136

137

138

139

140

141

142

143

144

145

146

147

148

149

150

151

152

153

154

155

156

157

158

159

160

161

162

163

164

165

166

167

168

169

170

171

172

173

174

175

176

177

178

179

180

181

182

183

184

185

186

187

188

189

190

191

192

193

194

195

196

197

198

199

200

201

202

203

204

205

206

207

208

209

210

211

212

213

214

215

216

217

218

219

220

221

222

223

224

225

226

227

228

229

230

231

232

233

234

235

236

237

238

239

240

241

242

243

244

245

246

247

248

249

250

251

252

253

254

255

256

257

258

259

260

261

262

263

264

265

266

267

268

269

270



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18019726/Ajb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 30-10-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 3621U	Veh. Inspected	SKD 8751L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	30/10/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/10/2018	Inspection Date	29/10/2018
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Kang Car Repairs Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 26/10/2018
TP Veh Reg No: SLX3621U

Estimate No: EST1800338
Date: 27 Oct 2018
Veh Reg No: SKD8751L
Make/Model: TOYOTA VIOS E M
Chassis No: MR053HY9305283427
Reg. Date: 16/01/2012
Your Ref No: SLX3621U

Joy

Estimate Repair Cost to Vehicle No :SKD8751L

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC REAR PANEL <i>replaced</i>	671.80	✓
2	1 PC REAR PANEL TRIM <i>replaced</i>	200.70	✓
3	1 PC BOOT LID <i>replaced</i>	584.20	✓
4	1 PC BOOT LID LOGO <i>new</i>	50.80	✓
5	1 PC BOOT LID "VIOS" EMBLEM <i>new</i>	46.60	✓
6	1 PC BOOTLID "E" EMBLEM <i>new</i>	36.80	✓
7	2 PCS BOOT LID HINGE <i>new</i>	114.00	✓
8	1 PC BOOT LID LOCK <i>new</i>	162.50	✓
9	1 PC BOOT LID LOCK CHECKER <i>new</i>	24.40	✓
10	1 PC BOOT LID RUBBER <i>new</i>	186.30	✓
11	1 PC SPARE TYRE COVER <i>new</i>	114.80	✓
12	1 PC SPARE TYRE RH SPONGE <i>replaced</i>	224.10	✓
13	1 PC SPARE TYRE LH SPONGE <i>new</i>	224.10	✓
14	1 PC REAR FENDER TRIM RH <i>new</i>	264.20	✓
15	1 PC TAIL LAMP RH <i>new</i>	409.90	325
16	1 PC TAIL LAMP PANEL RH <i>new</i>	114.80	✓
17	1 PC REAR BUMPER <i>replaced</i>	481.90	✓
18	2 PCS REAR BUMPER BRACKET <i>new</i>	134.80	✓
19	1 PC REAR BUMPER SIDE RETAINER RH <i>new</i>	113.90	✓
20	1 PC REAR BUMPER RH SMALL RETAINER <i>new</i>	48.40	✓
21	1 PC REAR BUMPER REFLECTOR - RH <i>replaced</i>	87.80	✓
22	1 PC EXHAUST PIPE <i>new</i>	634.10	✓
23	2 PCS EXHAUST PIPE MOUNTING <i>new</i>	39.60	✓
		4,970.50	
	Less 25%	1,242.63	3,727.92
	Special Net		
24	1 SET REAR PANEL TRIM CLIPS <i>new</i>	40.00	✓
25	1 PC BOOT LID NUMBER "293" STICKER <i>new</i>	35.00	✓
26	1 PC REAR NUMBER PLATE <i>new</i>	50.00	✓
27	1 SET REAR FENDER TRIM CLIPS RH <i>new</i>	48.00	✓

3969.7

2977.27

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 26/10/2018
TP Veh Reg No: SLX3621U

Estimate No: EST1800338
Date: 27 Oct 2018
Veh Reg No: SKD8751L
Make/Model: TOYOTA VIOS E M
Chasis No: MR053HY9305283427
Reg. Date: 16/01/2012
Your Ref No: SLX3621U

Estimate Repair Cost to Vehicle No :SKD8751L

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
28	2 PCS "L" PLATE BRACKET <i>Ne</i>	70.00 <i>50</i>	
29	1 PC "L" PLATE <i>Beit</i>	50.00 <i>✓</i>	
30	1 SET REAR BUMPER STICKER <i>neu</i>	195.00 <i>✓</i>	
31	1 SET REAR BUMPER CLIPS <i>pa</i>	48.00 <i>30</i>	
		536.00	536.00
	Labour		
32	1 TO CHECK WIRING <i>1760</i>	50.00 <i>30</i>	
33	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00 <i>80</i>	
34	1 TO REPLACE STICKER	100.00 <i>x</i>	
35	1 TO SPRAY UNDERSEAL	150.00 <i>50</i>	
36	1 (REAR) TO SPRAY PAINTING	1,300.00 <i>20</i>	
37	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,300.00 <i>20</i>	
		3,050.00	3,050.00
	<i>total: 5107.27</i>	Total	SS 7,313.92
	<i>4/5 H050</i>	Add GST @ 7%	511.97
		Total Amount Payable	SS 7,825.89

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND EIGHT HUNDRED TWENTY FIVE AND CENTS EIGHTY NINE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Kang Car Repairers Pte Ltd

Adrian Ly
2/5 29/10/18
06pm
AUTHORISED SIGNATURE

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1800338
Date: 27 Oct 2018
Veh Reg No: SKD8751L
Make/Model: TOYOTA VIOS E M
Chassis No: MR053HY9305283427
Reg. Date: 16/01/2012
Your Ref No: SLX3621U

Claim Type: Third Party
Accident Date: 26/10/2018
TP Veh Reg No: SLX3621U

Estimate Repair Cost to Vehicle No :SKD8751L

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1PC REAR PANEL <i>replaced</i>	671.80	✓
2	1PC REAR PANEL TRIM <i>replaced</i>	200.70	✓
3	1PC BOOT LID <i>replaced</i>	584.20	✓
4	1PC BOOT LID LOGO <i>new</i>	50.80	✓
5	1PC BOOT LID "VIOS" EMBLEM <i>new</i>	46.60	✓
6	1PC BOOTLID "E" EMBLEM <i>new</i>	36.80	✓
7	2PCS BOOT LID HINGE <i>new</i>	114.00	✓
8	1PC BOOT LID LOCK <i>found</i>	162.50	✓
9	1PC BOOT LID LOCK CHECKER <i>new</i>	24.40	✓
10	1PC BOOT LID RUBBER <i>new</i>	186.30	✓
11	1PC SPARE TYRE COVER <i>new</i>	114.80	✓
12	1PC SPARE TYRE RH SPONGE <i>replaced</i>	224.10	✓
13	1PC SPARE TYRE LH SPONGE <i>new</i>	224.10	✓
14	1PC REAR FENDER TRIM RH <i>new</i>	264.20	✓
15	1PC TAIL LAMP RH <i>new</i>	409.90	✓
16	1PC TAIL LAMP PANEL RH <i>new</i>	114.80	✓
17	1PC REAR BUMPER <i>replaced</i>	481.90	✓
18	2PCS REAR BUMPER BRACKET <i>new</i>	134.80	✓
19	1PC REAR BUMPER SIDE RETAINER RH <i>new</i>	113.90	✓
20	1PC REAR BUMPER RH SMALL RETAINER <i>new</i>	48.40	✓
21	1PC REAR BUMPER REFLECTOR - RH <i>new</i>	87.80	✓
22	1PC EXHAUST PIPE <i>replaced</i>	634.10	✓
23	2PCS EXHAUST PIPE MOUNTING <i>new</i>	39.60	✓
		4,970.50	
	Less 25%	1,242.63	3,727.92
	Special Net		
24	1SET REAR PANEL TRIM CLIPS <i>new</i>	40.00	✓
25	1PC BOOT LID NUMBER "293" STICKER <i>new</i>	35.00	✓
26	1PC REAR NUMBER PLATE <i>new</i>	50.00	✓
27	1SET REAR FENDER TRIM CLIPS RH <i>new</i>	48.00	✓

agreed
#4050/-
6 day
9/11/18
8

Adrian
pricing
325.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 26/10/2018
TP Veh Reg No: SLX3621U

Estimate No: EST1800338
Date: 27 Oct 2018
Veh Reg No: SKD8751L
Make/Model: TOYOTA VIOS E M
Chasis No: MR053HY9305283427
Reg. Date: 16/01/2012
Your Ref No: SLX3621U

Estimate Repair Cost to Vehicle No :SKD8751L

Quantity	Description	List Price	Amount
		SS	SS
28	2 PCS "L" PLATE BRACKET <i>Ne</i>	70.00 50 /	
29	1 PC "L" PLATE <i>Best</i>	50.00 /	
30	1 SET REAR BUMPER STICKER <i>Ne</i>	195.00 /	
31	1 SET REAR BUMPER CLIPS <i>m</i>	48.00 30 /	
		536.00	536.00
	Labour		
32	1 TO CHECK WIRING	50.00 30 /	
33	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	150.00 20 /	
34	1 TO REPLACE STICKER	100.00 *	
35	1 TO SPRAY UNDERSEAL	150.00 50 /	
36	1 (REAR) TO SPRAY PAINTING	1,300.00 20 /	
37	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,300.00 20 /	
		3,050.00	3,050.00
	Total		SS 7,313.92
	Add GST @ 7%		511.97
	Total Amount Payable		SS 7,825.89

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND EIGHT HUNDRED TWENTY FIVE AND CENTS EIGHTY NINE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

*after repair photo
taken by Andrian
with damaged
ex pipe
30/10/18*

Adrian L
L/S 29/10/18
06hys
AUTHORISED SIGNATURE

10 Sin Ming Drive Singapore 575701
Tel: 1800-CALL LTA (1800-2255 582) Fax: (65) 6553 5329

16 Jan 2012

Our ref 1601120101N004497389

COMFORTDELGRO DRIVING CENTRE PTE LTD
205 BRADDELL ROAD
SINGAPORE 579701



293

Dear Sir/Madam

**NOTIFICATION ON REGISTRATION OF VEHICLE AND ROAD TAX
(PLEASE DISPLAY THE ENCLOSED ROAD TAX DISC ON YOUR VEHICLE
WINDSCREEN)**

We wish to inform you that you have successfully registered vehicle SKD8751L on 16 Jan 2012. Enclosed is a validated road tax disc for the vehicle. Please display the said disc on your vehicle windscreen.

2. The details of the registration are as follows:

A) Owner Particulars

1. Name	: COMFORTDELGRO DRIVING CENTRE PTE LTD
2. Identification No. Type	: Company
3. Identification No.	: 199601882C
4. Place Of Passport Issue	: -
5. Registered Address	: 205 BRADDELL ROAD SINGAPORE 579701
6. Mailing Address	: -

B) Vehicle Particulars

1. Vehicle No.	: SKD8751L
2. Previous Vehicle No.	: -
3. Effective Date of Ownership	: 16 Jan 2012
4. Original Registration Date	: 16 Jan 2012
5. First Registration Date	: 16 Jan 2012
6. Vehicle Type	: M16 - For Instruction (Co) Car With 10 Years Lifespan
7. Vehicle Scheme	: Normal
8. Attachment 1	: No Attachment
9. Attachment 2	: -
10. Attachment 3	: -
11. Vehicle Make	: TOYOTA
12. Vehicle Model	: VIOS E MANUAL
13. Year of Manufacture	: 2011
14. Primary Colour	: Silver
15. Secondary Colour	: -
16. Passenger Capacity	: 4

17.	Chassis/Trailer Chassis No.	: MR053HY9305283427 / -
18.	Propellant	: Petrol
19.	Engine No./Motor No.	: 1NZY450515 / -
20.	Engine Capacity(cc)/Power Rating(kw)	: 1497 / -
21.	Unladen Weight(kg)	: 1075
22.	Maximum Laden Weight(kg)	: 1485
23.	Open Market Value	: \$10,216.00
24.	PARF Eligibility	: Yes
25.	PARF Eligibility Expiry Date	: 15 Jan 2022
26.	Minimum PARF Benefit	: \$5,108.00
27.	No. of Transfers	: 0
28.	IU Label No.	: -
29.	COE No.	: 2011080101000202C
30.	COE Expiry Date	: 15 Jan 2022
31.	COE Category	: A - Car (1600cc & below) & Taxi
32.	Quota Premium/Prevailing Quota Premium	: \$55,989.00
33.	Actual Quota Premium/PQP Paid	: \$55,989.00
34.	Actual ARF Paid	: \$10,216.00
35.	Vehicle Lifespan Expiry Date	: 15 Jan 2022
36.	Road Tax Amount	: \$684.00
37.	Road Tax Start Date	: 16 Jan 2012
38.	Road Tax End Date	: 15 Jan 2013
39.	Remarks	: This vehicle is eligible for PARF. The vehicle will be de-registered upon reaching its statutory lifespan on 15 Jan 2022. No COE renewal beyond that date will be allowed.

3. You may use your NRIC number and SingPass or User ID and Password (for non-Singaporeans/PRs) to login to <http://www.onemotoring.com.sg> and see the details of the above transaction. For ACRA-registered businesses and companies with EASY accounts, your authorised staff may also access the wide range of vehicle-related services via <http://www.onemotoring.com.sg> using EASY. If you do not have an EASY account, you can apply for it at <http://www.iras.gov.sg>. For non-Singaporeans/PRs who do not have a User Password, please contact us at 1800-CALL LTA (1800-2255 582) to request for a new password. Please note that a separate Transaction PIN is required for the following transactions via the Internet or at our Electronic Service Agents. Before you perform these transactions, please request for your Transaction PIN. You may find out more information on how to obtain your Transaction PIN and the documents needed (such as Board Resolution for companies and businesses, etc) via <http://www.onemotoring.com.sg> > LTA Information & Guidelines > Transaction PIN & User Account.

- a. Vehicle PIN - Transfer of Ownership and De-registration of Vehicle
- b. TCOE PIN - Transfer of TCOE (For Category C and E COE bid under individual)
- c. Rebate PIN - Transfer and Splitting of PARF/COE Rebate

4. We are pleased to inform you that the above vehicle will be included under your Road Tax GIRO scheme.

5. All new In-vehicle Units (IUs) are covered by a 5-year warranty against manufacturer's defect.



江氏修理汽車私人有限公司

KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

Our Ref : KCR1020188751AIG
Your Ref : SLX3621U

Date : 27 NOV 2018

WITHOUT PREJUDICE

AIG Asia Pacific Insurance Pte Ltd
C/O LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Paya Ubi Industrial Pk
Singapore 408933
Attention : Motor Claim Department

Dear Sirs,

Accident involving SKD8751L and SLX3621U on 26.10.2018 along Kaki Bukit Road 1.

We refer to the above accident. On our record showed that you are the insurer of motor vehicle SLX3621U.

We are instructed that the accident was caused by your insured's negligent driving and/or management of his vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense.

On behalf of and as authorized by M/S ComfortDelgro Driving Centre Pte Ltd, the owner of motor-vehicle no: SKD8751L, we submit their claim to you:

Cost of repairs (Inclusive of 7% GST)	\$ 4,333.50
Loss of use (10 days x \$120.00-Training vehicle)	\$ 1,200.00
GIA search	\$ 2.00
	<u>\$ 5,535.50</u>
	=====

Our claim for loss of use is as follows :-

<u>No of days</u>	<u>Date</u>	<u>Remarks</u>
	26.10.18	Date of Accident/ Reporting
1	27.10.18	Saturday
2	28.10.18	} Sunday
3	29.10.18	} Surveyed by LKK Auto
4	30.10.18	} Day 1 of repair
5	31.10.18	} Day 2
6	01.11.18	} Day 3
7	02.11.18	} Day 4
8	03.11.18	} Sunday
9	04.11.18	} Day 5

<u>No of days</u>	<u>Date</u>	<u>Remarks</u>
<u>10</u>	05.11.18	<u>1 Day 6</u>
10 days		6 days as recommended

Enclosed herewith are copies of the following documents in support of our client's claim:

- 1) Tax invoice no: KCR-INV1800718
- 2) GIA report and certificate insurance of SKD8751L
- 3) GIA search fee & invoice
- 4) Vehicle registration details

We hope to receive your early reply soon.

Thank you.

Yours faithfully,

KANG CAR REPAIRERS PTE LTD



.....

Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Friday, 8 February 2019 12:02 PM
To: 'lkguan118@gmail.com'
Cc: Admin A; CS A Team
Subject: ACCIDENT INVOLVING SLX 3621U AND SKD 8751L ON 26/10/2019

Our ref: CC6/AIG18019726/Ajb3

LEE KHUAY GUAN

Policy Holder

Dear Sir,

ACCIDENT INVOLVING SLX 3621U AND SKD 8751L ON 26/10/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

As spoken, based on the accident report and accident scenario, liability is down against us.

You are aware that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (and 20% for commercial vehicles) upon next renewal due to this Third Party claim.

We understand that you wish to privately settle to protect your NCD, as requested, please be informed of the following:

	THIRD PARTY CLAIMED	OUR REVISED TO OFFER TO CLAIMANT
Cost of Repairs	\$ 7,825.89 (estimate submitted)	\$ 4,333.50 (with GST)
Loss of Use	\$ 1,200.00 (\$120 x 10 days)	\$ 800.00 (\$100 x 8 days)
LTA Search Fee	\$ 2.00	\$ 2.00
TOTAL	\$ 9,027.89	\$ 5,135.50

\$5,135.50 – Payable to Third-Party claimant (if above to offer is accepted) and \$363.80 – For surveyor's fee.

Please let us know of your decision whether or not you are keen to privately settle for the reinstatement of your NCD within 7 days from the date of this e-mail. Otherwise, we will proceed accordingly for an amicable settlement of this claim.

If you need any clarification, please do not hesitate to contact the undersigned.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)



I, COMFORTDELGRO DRIVING CENTRE PTE LTD ("the third party claimant")
of 205 UBI AVE 4 SINGAPORE 408805 (address),
owner of SKD8751L (vehicle no.) hereby authorize
KANG CAR REPAIRERS PTE LTD

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SKD8751L that was
damaged pursuant to the accident which occurred on 26.10.2018 (date) along
KAKI BUKIT ROAD 1 (location)
involving vehicle no/s SLX3621U ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 25 day of March (month) 20 19 (year)


Khaw Sim Leon,
Office Assistant
Operations Division


Signed by "the third party claimant"

KANG CAR REPAIRERS PTE. LTD.

Signed by "the workshop"

This Discharge Voucher applies strictly for Claimant's claim for personal injury / property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may manifest arising directly or indirectly from this accident. This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, KANG CAR REPAIRERS PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$4,900.00 (Global Sum) for vehicle no. SKD 8751L, that was damaged pursuant to the accident which occurred on 26/10/2018 (date) along KAKI BUKIT (location) involving vehicle no/s SLX 3621U. This is pursuant to the inspection conducted on 29/10/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner COMFORTDELGRO DRIVING CENTRE PTE LTD ("the third party claimant") of vehicle no. SKD 8751L, make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKD 8751L (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 25 (day) of March (month) **2019** (year)


Signed by appointed surveyor

KANG CAR REPAIRERS PTE. LTD.


Signed by "the workshop" (with chop)



江氏修理汽車私人有限公司

KANG CAR REPAIRERS PTE LTD

1 KAKI BUKIT AVE 6 #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883
TEL: 67477636, 67473005 FAX: 67485071 Email: kangcar@singnet.com.sg
Co. Reg. No. 201300201N GST Reg. No. 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120

TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department
Your Ref No: SLX3621U
Claim Type: Third Party
Accident Date: 26/10/2018
TP Veh Reg No: SLX3621U

Final No: KCR-INV1800718
Claim No: EST1800338
Date: 23 Nov 2018
Policy No: M489523
Veh Reg No: SKD8751L
Make/Model: TOYOTA VIOS E M
Chassis No: MR053HY9305283427
Engine No:
Reg. Date: 16/01/2012

Tax Invoice to Vehicle No :SKD8751L

PAGE:1

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>

As recommended by surveyor to proceed repair at total cost/lumpsum cost	S\$ 4,050.00
Add GST @ 7%	283.50
Total Amount payable	<u>S\$ 4,333.50</u>

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND THREE HUNDRED THIRTY THREE AND CENTS FIFTY ONLY

For Kang Car Repairers Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735**TAX INVOICE**

Our Ref No: GR-18-166488

Date of Request: 26/10/2018

Your Ref No: Online Purchase

Kang Car Repairers Pte Ltd
No 1 Kaki Bukit Ave 6
#02-06 AutoBay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 26/10/2018
Enquiry By Yee Mei Cheng
TP Vehicle No. SLX3621U
Accident Date 26/10/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Oct 2018 Edit Reg		29 Oct 2018 00:00 Edit Adj Rpt	S\$4,050.00 Edit Estimates	S\$4,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LEE KHUAY GUAN, ID: S1105111A								
Main Claimant:	COMFORTDELGRO DRIVING CENTRE PTE LTD, Co. Reg. No.: 199601882C								
Vehicle Reg. No.:	SKD8751L	Date of Loss:	26/10/2018 09:00 - :59 [81 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4671204330SG	Policy/Cover Note No.:	1800041486 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLX3621U	Policy No. (Claimant):	M489523						
		Excess:							
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3551 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (31/10/2018): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKD8751L (4671204330SG)**
[SLX3621U]

TP

COMFORTDELGRO DRIVING CENTRE PTE LTD

Oct 26 2018 9:00AM

[LEE KHUAY GUAN]

Kang Car Repairers Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Letters/Correspondences														1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown											1	Edit			
Photos/Images														3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
2	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
3	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
4	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
5	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
6	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
7	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
8	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
9	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
10	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
11	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
12	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
13	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
14	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
15	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
16	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
17	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
18	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
19	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
20	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
21	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
22	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
23	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
24	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
25	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
26	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
27	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
28	04/01/19 09:44	General View											1	Load JPG	<input checked="" type="checkbox"/>		
29	04/01/19 09:44	Reinspection Photo											1	Load JPG	<input checked="" type="checkbox"/>		
30	04/01/19 09:44	Reinspection Photo											1	Load JPG	<input checked="" type="checkbox"/>		
31	04/01/19 09:44	Reinspection Photo											1	Load JPG	<input checked="" type="checkbox"/>		
32	04/01/19 09:44	Reinspection Photo											1	Load JPG	<input checked="" type="checkbox"/>		
33	04/01/19 09:44	Reinspection Photo											1	Load JPG	<input checked="" type="checkbox"/>		
34	04/01/19 09:44	Reinspection Photo											1	Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	04/01/19 09:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/10/18 12:19	TP_GIA_REPORT	Load PDF	
2	17/04/19 09:48	WORKSHOP INVOICE	Load PDF	
3	17/04/19 09:48	AUTHORISATION TO ACT FORM	Load PDF	
4	17/04/19 09:48	Release Voucher	Load PDF	
5	17/04/19 09:48	GIA SEARCH	Load PDF	
6	17/04/19 09:48	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	31/10/18 10:35	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLX3621U (Insd veh)	Model:	TOYOTA VIOS 1.5 E (M)
	SKD8751L (TP veh)		
Date of Accident:	26/10/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	7,825.84
Final Repair Cost	:	\$	4,900.00
Loss of Use	:	\$	10.00 days at \$100.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	4,900.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Kang Car Repairers Pte Ltd	:	\$ 4,900.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

17 Apr
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18019726/AJB3Q2

Date: 17/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800041486

Claimant Vehicle No: SKD8751L Insured Vehicle No: SLX3621U

Date of Loss: 26/10/2018 Nature of Claim: TP Claim No: 4671204330SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD8751L	Engine No:	1NZY450515
Make & Model:	TOYOTA VIOS, 1.5 E (M)	Chassis No:	MR053HY9305283427
Reg. Date:	16/01/2012 (Man. Year: 2011)	Odometer:	163587 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,263.87	3,347.27	916.60	21.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,760.00	1,290.00	42.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,313.87	5,107.27	2,206.60	30.17
Approved Total (Overridden) (S\$)		4,050.00		
(S\$)	7,313.87	4,050.00	3,263.87	44.63
+ GST 7.00/7.00% (S\$)	511.97	283.50	228.47	44.63
Nett Amount (S\$)	7,825.84	4,333.50	3,492.34	44.63
+ Loss of Use (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,335.50		
Global Sum Settlement (S\$)		4,900.00		

INSPECTION

Date of Assignment: 29/10/2018
Date Inspected: 29/10/2018 Inspected At:

Kang Car Repairers Pte Ltd (HQ)
No 1 Kaki Bukit Ave 6, #02-06
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR PANEL	Dented	671.80 FL	*671.80 FL
2	1		*REAR PANEL TRIM	Deformed	200.70 FL	*200.70 FL
3	1		*BOOT LID	Buckled	584.20 FL	*584.20 FL
4	1		*BOOT LID LOGO	Necessary	50.80 FL	*50.80 FL
5	1		*BOOT LID VIOSEMBLEM	Necessary	46.60 FL	*46.60 FL
6	1		*BOOT LID E EMBLEM	Necessary	36.80 FL	*36.80 FL
7	2		*BOOT LID HINGE	Not Necessary	114.00 FL	*- FL
8	1		*BOOT LID LOCK	Damaged	162.50 FL	*162.50 FL
9	1		*BOOT LID LOCK CHECKER	Not Necessary	24.40 FL	*- FL
10	1		*BOOT LID RUBBER	Cut	186.30 FL	*186.30 FL
11	1		*SPARE TYRE COVER	Cut	114.80 FL	*114.80 FL
12	1		*SPARE TYRE RH SPONGE	Deformed	224.10 FL	*224.10 FL
13	1		*SPARE TYRE LH SPONGE	Not Necessary	224.10 FL	*- FL
14	1		*REAR FENDER TRIM RH	Not Necessary	264.20 FL	*- FL
15	1		*TAIL LAMP RH	Cut	409.90 FL	*325.00 FL
16	1		*TAIL LAMP PANEL RH	Repair	114.80 FL	*- FL
17	1		*REAR BUMPER	Deformed	481.90 FL	*481.90 FL
18	2		*REAR BUMPER BRACKET	Not Necessary	134.80 FL	*- FL
19	1		*REAR BUMPER SIDE RETAINER RH	Necessary	113.90 FL	*113.90 FL
20	1		*REAR BUMPER RH SMALL RETAINER	Necessary	48.40 FL	*48.40 FL
21	1		*REAR BUMPER REFLECTOR -RH	Cracked	87.80 FL	*87.80 FL
22	1		*EXHAUST PIPE	Bent	634.10 FL	*634.10 FL
23	2		*EXHAUST PIPE MOUNTING	Not Necessary	39.60 FL	*- FL
24	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*10.00 FS
25	1		*BOOT LID NUMBER PLATE 293STICKER	Necessary	35.00 FS	*35.00 FS
26	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
27	1		*SET REAR FENDER TRIM CLIPS RH	Not Necessary	48.00 FS	*- FS
28	2		*LPLATE BRACKET	Necessary	70.00 FS	*50.00 FS
29	1		*LPLATE	Bent	50.00 FS	*50.00 FS
30	1		*SET REAR BUMPER STICKER	Necessary	195.00 FS	*195.00 FS
31	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,506.50	4,339.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,242.63	992.43
Total Parts (\$\$)	4,263.87	3,347.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIX REAR EXHAUST PIPE	New	150.00	80.00
3	TO REPLACE STICKER	New	100.00	0.00
4	TO SPRAY UNDERSEAL	New	150.00	50.00
5	(REAR) TO SPRAY PAINTING	New	1,300.00	800.00
6	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	1,300.00	800.00
Gross Labour Cost (\$\$)			3,050.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >