

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

Not Authorized
d/s
7 day
31/10/18
Take the money

GBF9938E Toyota Dyna

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear tailgate assy <i>Subs</i>	\$ 1,697.00 ✓
2	4	Rear tailgate hinges <i>11</i>	\$ 260.00 X
3	1	Rear tailgate left top lock <i>Ref</i>	\$ 248.00 ✓
4	1	Rear tailgate right top lock <i>Ref</i>	\$ 248.00 ✓
5	1	Rear tailgate left lower lock hinge <i>11</i>	\$ 176.00 X
6	1	Rear tailgate right lower lock hinge <i>11</i>	\$ 176.00 X
7	2	Rear tailgate left rubber stopper <i>11</i>	\$ 38.00 X
8	2	Rear tailgate right rubber stopper <i>11</i>	\$ 38.00 X
9	1	Rear tailgate left rubber stopper bracket <i>11</i>	\$ 58.00 X
10	1	Rear tailgate right rubber stopper bracket <i>11</i>	\$ 58.00 X
11	1	Rear tailgate lower panel <i>Subs</i>	\$ 1,675.00 ✓
12	2	Rear tailgate reflector <i>M/S cm</i>	\$ 166.00 PC
13	1	Rear left taillamp <i>11</i>	\$ 662.00 X
14	1	Rear right taillamp <i>11</i>	\$ 662.00 X
15	1	Rear left taillamp bracket <i>11</i>	\$ 125.00 X
16	1	Rear right taillamp bracket <i>11</i>	\$ 125.00 X
17	2	Rear no plate lamp <i>11</i>	\$ 80.00 X
18	1	Rear no plate support bracket <i>11</i>	\$ 120.00 X
19	1	Rear lower floor panel <i>11</i>	\$ 3,630.00 X
20	6	Rear left cabin rubber mounting <i>11</i>	\$ 680.00 X
21	6	Rear right cabin rubber mounting <i>11</i>	\$ 680.00 X
22	1	Rear spare tyre bracket carrier <i>11</i>	\$ 380.00 X
23	1	Rear spare tyre lock holder <i>11</i>	\$ 360.00 X
			\$ 12,342.00
Less 25%			\$ 3,085.50
			\$ 9,256.50

Special Nett Items

1	1	Rear tailgate '70km/h' sticker <i>11</i>	\$ 30.00 10
2	1	Rear tailgate '6pax' sticker <i>11</i>	\$ 30.00 10
3	1	Rear tailgate 'Dyna' sticker <i>11</i>	\$ 30.00 ✓
4	1	Rear tailgate >1500kg sticker <i>11</i>	\$ 30.00 20
5	1set	Rear tailgate red sticker <i>11</i>	\$ 80.00 X
6	1set	Rear tailgate advertisement sticker <i>11</i>	\$ 100.00 50
7	1set	Rear spare tyre <i>11</i>	\$ 650.00 X
8	1	Rear towing inner panel <i>11</i>	\$ 650.00 X
9	1	Rear left top railing <i>11</i>	\$ 1,600.00 X
10	1	Rear right top railing <i>11</i>	\$ 1,600.00 X
11	1	Rear no plate <i>11</i>	\$ 80.00 20
			\$ 4,880.00

Total parts

\$ 14,136.50

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

GBF9938E Toyota Dyna

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper assy <i>DD/used ✓</i>	\$ 1,212.00
2	2	Front bumper bracket <i>L X</i>	\$ 230.00
3	1	Front bumper reinforcement <i>?</i>	\$ 496.00
4	1	Front grille assy <i>cm ✓</i>	\$ 368.00
5	1	Front panel assy <i>S-130 ✓</i>	\$ 1,296.00
6	2	Front panel bracket <i>NS X</i>	\$ 183.00
7	1	Front panel centre logo <i>cm ✓</i>	\$ 105.00
8	1	Front left corner panel <i>R X</i>	\$ 183.00
9	1	Front right corner panel <i>L X</i>	\$ 183.00
10	1	Front left headlamp <i>?</i>	\$ 1,176.00
11	1	Front right headlamp <i>cm ✓</i>	\$ 1,176.00
12	1	Front headlamp wire harness <i>11X</i>	\$ 450.00
13	1	Front horn <i>?</i>	\$ 86.00
14	1	Front left step garnish <i>11X</i>	\$ 276.00
15	1	Front right step garnish <i>11X</i>	\$ 276.00
16	1	Front wiper panel <i>DD/used ✓</i>	\$ 873.00
17	2	Front wiper nozzle <i>11X</i>	\$ 157.00
18	2	Front wiper arm <i>cm ✓</i>	\$ 136.00
19	2	Front wiper blade <i>11X</i>	\$ 106.00
20	1	Front wiper linkage with motor assy <i>?</i>	\$ 393.00
21	2	Front wiper nozzle grommet <i>?</i>	\$ 68.00
22	1	Front left wing mirror <i>11X</i>	\$ 579.00
23	1	Front right wing mirror <i>11X</i>	\$ 493.00
24	1	Front left wing mirror motor assy <i>11X</i>	\$ 550.00
25	1	Front cabin assy <i>11X</i>	\$ 8,850.00
26	1	Front dashboard panel assy <i>?</i>	\$ 1,278.00
27	1	Front dashboard centre console <i>11X</i>	\$ 699.00
28	1	Front dashboard glove box <i>11X</i>	\$ 205.00
29	1	Front towing hook <i>11X</i>	\$ 179.00
30	1	Front air-con condenser assy <i>?</i>	\$ 1,410.00
31	1	Front evaporator coil with blower assy <i>?</i>	\$ 2,659.00
			<u>\$ 26,331.00</u>
Less 25%			<u>\$ 6,582.75</u>
			<u>\$ 19,748.25</u>

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

GBF9938E Toyota Dyna

			Estimated Parts Price	
No	Qty	Parts Description		
<u>Special Nett Items</u>				
1	6	Front grille clips <i>all</i>	\$ 20.00	✓
2	1	Front panel sealant <i>all</i>	\$ 80.00	50
3	1	Front panel Dyna sticker <i>all</i>	\$ 60.00	✓
4	8	Front wiper panel clips <i>all</i>	\$ 30.00	x
5	1	Front left fog lamp <i>11</i>	\$ 280.00	x
6	1	Front right fog lamp <i>11</i>	\$ 280.00	x
7	1	Front air-con gas	\$ 80.00	7
8	1	Front no plate <i>one</i>	\$ 80.00	20
			<u>\$ 910.00</u>	
Total parts			\$ 20,658.25	

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522

GBF9938E Toyota Dyna

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,600.00 900
2	To putty and spray painting front portion.	\$ 1,600.00 800
3	To check wiring and focus front headlamp.	\$ 50.00 20
4	To apply anti rust proofing to front affected area.	\$ 120.00 60
5	To remove and install air-con system to facilitate the repair and refill gas.	\$ 180.00 100
6	To remove and install front dashboard panel to facilitate the repair.	\$ 350.00 160
7	To remove and install front cabin assy to facilitate the repair.	\$ 17650.00 x
8	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,600.00 900
9	To putty and spray painting rear portion.	\$ 1,600.00 900
10	To check rear lighting and wiring.	\$ 50.00 20
11	To apply anti rust proofing to rear affected area.	\$ 120.00 60
12	To remove and install both rear tailgate lock.	\$ 180.00 x
13	To remove and install rear cabin assy to facilitate the repair.	\$ 17650.00 x
14	Towing service.	\$ 150.00 x
Total labour :		\$ 8,800.00

Total parts : \$ 34,794.75
Total labour : \$ 8,800.00
Total repair cost : \$ 43,594.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: