

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Arrange for Service
Owner coming
07 NOV 2018 @ 0830am
owner L LOK

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLG5280X

Chassis No : JHMRU1830GX200560

Model : HRV LX-SIN CVT YM 2016

Owner's Name : JUNAINAH BINTE MOHAMED ALFIA

Ins Policy No. : 18-MV008781-R02

Date of Accident : 24/10/2018

Document No. : SQT18004643 **Page** 1

Date : 29. Oct 2018

Customer No. : WZI007

Svc Advisor : ARY CHUA WAI NGE

Engine No : L15B4530562

Date | Time : 29. Oct 2018 6:13:36 PM

Surveyor Name :

Survey Date : DID : +65 6846 5673
HP : +65 8100 6306

Authorisation Date : *hence notify*

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

TP DIRECT SETTLEMENT (J/NO:)
OWNER: JUNAINAH BINTE MOHAMED ALFIA
OWNER INSURER: TOKIO MARINE INSURANCE LTD
ACC DATE: 24/10/2018@20.30PM
SURVEYED BY:
REF NO:
TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD
TP VEH: SH6945S (HYUNDAI/140/BLUE-TAXI)

91505-TM8-003	CLIP,BUMPER	10	2.00	25	15.00	1.05	16.05
33552-T7A-J01	LAMP UNITL.	1	428.70	25	321.52	22.51	344.03
74450-T7A-J01ZQ	PROTECTORL.RR.WHEEL ARCH	1	165.40	25	124.05	8.68	132.73
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	92.30	25	69.22	4.85	74.07
71598-T7A-J00	SPACER,L.RR.BPR S	1	19.20	25	14.40	1.01	15.41
04715-T7A-900ZZ	FACE,RR.BUMPER	1	463.70	25	347.77	24.34	372.11
Sum Item					891.96	62.44	954.40

BOSUN	SUNDRIES	1	60.00	20	60.00	4.20	64.20
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	140.00	100	140.00	9.80	149.80
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	180.00	140	180.00	12.60	192.60
BKRP21S	STRAIGHTEN ALIGN RR PANEL RR L FENDER & RENEW	1	1680.00	600	1680.00	117.60	1797.60
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	1800.00	675	1800.00	126.00	1926.00
Sum Labor					3860.00	270.20	4,130.20

Survey By

Date & Time

Excess

Status

Total Amount 4,751.96 332.64 5,084.60

Total (Inclusive of GST) **5,084.60**

Caro Carl.

07/11/18

3 Days.

before paint photos.

1717.67