



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM)

#04-04 Singapore 757047

Tel: 65 6493 1924

Fax: 65 6493 1928

VEHICLE REPAIR ESTIMATE

Insurance Company: AIG Asia Pacific Insurance Pte Ltd

Address: 78 Shenton Way #07-16 Singapore 079120

Telephone: 6419 3000 Fax: 6835 7416

Email: claimsurvey@aig.com.sg

Make/ Model : NISSAN NV350

Date: 29/10/2018

Chassis No : JNIUC4E2620001815

Vehicle No: PC2925M

Date/Time of Accident : 24/10/2018 13:10

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	FRONT BUMPER	1	\$ 584.70	10%	\$ 526.23
2	FRONT BUMPER FOG LAMP LH	1	\$ 320.80	10%	\$ 288.72
3	FRONT BUMPER SIDE RETAINER	2	\$ 348.40	10%	\$ 313.56
4	FRONT BUMPER FOG LAMP COVER LH	1	\$ 167.50	10%	\$ 150.75
5	FRONT HEAD LAMP	1	\$ 458.60	10%	\$ 412.74
6	FRONT HEAD LAMP LOWER BRACKET LH	1	\$ 145.70	10%	\$ 131.13
7	FRONT DOOR STEP GARNISH LH	1	\$ 92.50	10%	\$ 83.25
8	FRONT WASHER TANK	1	\$ 262.10	10%	\$ 235.89
9	FRONT INNER COOLER LH	1	\$ 752.60	10%	\$ 677.34
10	FRONT INNER COOLER COVER LH	1	\$ 151.50	10%	\$ 136.35

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT BUMPER CLIP	8	\$ 36.00	\$ 36.00
2	FRONT DOOR STEP GARNISH CLIP LH	4	\$ 18.00	\$ 18.00
Total Special Items Cost				\$ 3,009.96

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 800.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 400.00

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TOWING	
TO REMOVE & REFIX REAR WINDSCREEN	
TO TUFFCOAT AFFECTED AREA	\$ 50 250.00
TO REPLACE FRONT WINDSCREEN	
TO REPLACE ENGINE MOUNTING/ GEAR BOX MOUNTING	
TO REMOVE/ REPLACE AIRCON CONDENSOR, VACUUM, TOP UP AIRCON GAS COMPUTERIZED	
TO REMOVE/ REFIT/ REPLACE DASHBOARD	
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	
TO REMOVE/ REPLACE FRONT UNDERCARRIAGE	
TO REMOVE/ REFIT WIRING CHECKS	
TO REMOVE/REFIT/ ADJUST BRAKE FOUR WHEELS	
TO REMOVE/ REPLACE REAR SILENCER BOX	
TO REMOVE/ REPLACE REVERSE SENSORS	
TO RESET ALL AIRBAG NECESSARY SYSTEM	
TO REMOVE & REPLACE ALL NECESSARY AIR BAG	
TO REMOVE AND REPLACE ROOF-TOP LINING	
TO REMOVE AND REPLACE INNER COOLER	\$ 100.00
Total Others Cost	\$ 350.00
GRAND TOTAL	\$ 4,959.96



CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua
 Job Title: Account Assistant
 Direct Contact: 65 8322 7418
 Email: jeslyn@carzauto.com.sg

N/A 2 LKK

29/10/18

LIS

3 DAYS

- CHECK ITEM(S) PHOTO

- AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: