



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

### ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info	
Ms NG MUI SIANG (HUANG MEICHAN)  8 Upper Serangoon Crescent #16-22 Singapore 534032  Contact No Mobile: 96946108Cheung	Cust No/Name	/Ms NG MUI SIANG (HUANG MEICHAN)
	Reg No/Reg Date	SGB2385H / 17/06/201
	Date In/Mileage	/ 0
	Chassis No	JMYXTGF3WFZ001998
	Engine No	4B12PM3627
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F27)
	Colour/Trim	W01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	29/10/2018/ 11:21		465 / Tay Jian Ye	32515
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	TO RENEW REAR BUMPER, TAILGATE, WELD AND CUT END PANEL				1650 2750.00
E PNT88000	TO REMOVE AND REFIT REAR WINDSCREEN				240.00
E PNT88000	TO TRANSFER REAR TAILGATE TRIM, MECHANISM, TO NEW PART				200 225.00
E PNT88000	TO REMOVE AND REFIT REAR END PANEL TRIM AND FENDER REAR TRIM TO FACILITATE				200 225.00
E PNT88000	TO TRANSFER REAR PARKING SENSOR TO NEW PART				60 90.00
E PNT98000	PAINT WORK SPRAY REAR BUMPER, TAILGATE, END PANEL				1260 1680.00
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30 50.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				200.00
M SUNDRY	TO APPLY ANTI CORROSION				40 80.00
M SUNDRY	TO APPLY BODY SEALANT				60 80.00
M SUNDRY	TO APPLY REAR WINDSCREEN SEALANT				80.00
M SUNDRY	TO SUPPLY C&C LOGO				50.00
M SUNDRY	TO SUPPLY MIVEC LOGO				50.00
M SUNDRY	TO SUPPLY PARKING SENSOR				220.00
M SUNDRY	SUNDRIES				30.00
M REINFORCEMENT,RR BUMPER,LH		1.00	78.00	00.00	? 78.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

### ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Ms NG MUI SIANG (HUANG MEICHAN)	Cust No/Name /Ms NG MUI SIANG (HUANG MEICHAN)
8 Upper Serangoon Crescent	Reg No/Reg Date SGB2385H / 17/06/201
#16-22	Date In/Mileage / 0
Singapore 534032	Chassis No JMYXTGF3WFZ001998
Contact No Mobile: 96946108Cheung	Engine No 4B12PM3627
	Make/Model MIT/OUTLANDER 2.4 CVT AWD (F27)
	Colour/Trim W01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	29/10/2018/ 11:21		465 / Tay Jian Ye	32515		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	REINFORCEMENT,RR BUMPER,RH	?		1.00	78.00	00.00	78.00
M	BRKT,R/BMPR FACE SIDE,LH	ne		1.00	12.00	00.00	12.00
M	BRKT,R/BMPR FACE SIDE,RH	ne		1.00	12.00	00.00	12.00
M	FACE,RR BUMPER	ne		1.00	1053.00	00.00	1053.00
M	EXTENSION,RR BUMPER	ne		1.00	511.00	00.00	511.00
M	GARNISH,RR BUMPER SIDE,LH REFLECTOR	sca		1.00	73.00	00.00	73.00
M	REFLECTOR,TAIL LAMP,LH	?		1.00	170.00	00.00	170.00
M	GARNISH,RR BUMPER SIDE,RH REFLECTOR	sca		1.00	73.00	00.00	73.00
M	REFLECTOR,TAIL LAMP,RH	?		1.00	170.00	00.00	170.00
M	PANEL,RR END	ne - repair		1.00	0.00	00.00	
M	PANEL ASSY,TAILGATE	ne		1.00	1060.00	00.00	1060.00
M	W/STRIP,TAILGATE OPENING	ne		1.00	211.00	00.00	211.00
M	DAM,TAILGATE,UPR	ne		1.00	12.00	00.00	12.00
M	DAM,TAILGATE SIDE	ne		2.00	27.00	00.00	54.00
M	DAM,TAILGATE,LWR	ne		1.00	41.00	00.00	41.00
M	STOPPER,WINDSHIELD GLASS	ne		2.00	3.00	00.00	6.00
M	FASTENER,WINDSHIELD	ne		4.00	6.00	00.00	24.00
M	MARK,OUTLANDER	ne		1.00	94.00	00.00	94.00
M	CARRIER,SPARE TIRE	?		1.00	251.00	00.00	251.00
M	BOLT,SPARE TIRE CARRIER	?		1.00	32.00	00.00	32.00

SURVEYOR NAME: Ram - Hp 90010068SURVEYOR SIGNATURE: R1DATE: 13/11/18 @ 0920REMARKS: 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and confirmed &amp; accepted by Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nett 10,065.00  
7% GST on 10065.00 704.55  
Total Payable 10,769.55

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.