

111 1
Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

1/5*6000

GBH1143Z Toyota Hiace

1	1	Rear bumper assy	Dis 688.10	\$	1,260.00	/
2	2	Rear bumper bracket	Set	\$	172.00	/
3	1	Rear bumper inner beam	Set	\$	287.00	/
4	1	Rear tailgate assy	S-6500	\$	2,062.00	/
5	1	Rear tailgate lock mechanism	Jan	\$	266.00	/
6	1	Rear tailgate lock catch	11	\$	62.00	X
7	2	Rear tailgate hinges	11	\$	162.00	X
8	2	Rear tailgate damper	11	\$	375.00	X
9	1	Rear tailgate weatherstrip	twl	\$	288.00	/
10	1	Rear tailgate inner board	Delcom	\$	190.00	/
11	1	Rear tailgate centre logo	ren	\$	69.00	/
12	1	Rear tailgate super GL emblem	ren	\$	74.00	/
13	1	Rear tailgate hiace emblem	ren	\$	68.00	/
14	1	Rear tailgate windscreen glass moulding	ren NS	\$	295.00	X
15	1	Rear tailgate lock actuator	8m	\$	189.00	/
16	1	Rear tailgate top garnish	11	\$	280.00	X
17	2	Rear tailgate side garnish	11	\$	220.00	X
18	1	Rear tailgate outer chrome garnish	11	\$	276.00	X
19	1	Rear tailgate lock cylinder	11	\$	191.00	X
20	1	Rear left taillamp	cm 668.10	\$	785.00	/
21	1	Rear right taillamp	11	\$	785.00	X
22	1	Rear left taillamp lower panel	11	\$	109.00	X
23	1	Rear right taillamp lower panel	11	\$	109.00	X
24	1	Rear wiper blade assy	11	\$	166.00	X
25	1	Rear wiper motor assy	11	\$	476.00	X
26	1	Rear wiper spray nozzle	11	\$	109.00	X
27	1	Rear windscreen glass assy	11	\$	2,010.00	X
28	1	Rear spare tyre carrier	Set	\$	376.00	/
29	1	Rear end lower panel	S-6500	\$	1,274.00	/
30	1	Rear exhaust muffler assy	11	\$	2,400.00	X
31	2	Rear exhaust muffler rubber mounting	11	\$	38.00	X
				\$	15,423.00	
Less 25%				\$	3,855.75	6671.2
				\$	11,567.25	25% 1003.40

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

GBH1143Z Toyota Hiace

<u>Special Nett Items</u>			
1	10	Rear bumper clips <i>me</i>	\$ 50.00 ✓
2	12	Rear tailgate inner board clips <i>me</i>	\$ 30.00 —
3	4	Rear tailgate outer chrome garnish clips <i>11</i>	\$ 20.00 X
4	1	Rear tailgate '70km/h' sticker <i>me</i>	\$ 30.00 10
5	1	Rear tailgate >1000kg sticker <i>me</i>	\$ 30.00 ✓
6	1 set	Rear tailgate advertisement sticker <i>NN NF</i>	\$ 80.00 X
7	1	Rear third brake lamp <i>NN NF</i>	\$ 350.00 X
8	6	Rear tailgate top garnish clips <i>11</i>	\$ 30.00 X
9	6	Rear tailgate side garnish clips <i>11</i>	\$ 30.00 X
10	1	Rear windscreen glass sealant <i>me</i>	\$ 80.00 40
11	1	Rear view camera <i>11</i>	\$ 300.00 2
12	1	Rear bumper reverse sensor <i>shd</i>	\$ 250.00 200
13	1	Rear no plate <i>scr</i>	\$ 60.00 20
			\$ 1,340.00 —
Total Parts			
			\$ 12,907.25 380

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To disclose damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

GBH1143Z Toyota Hiace

1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$	1,800.00	900
2	To putty and spray painting rear portion.	\$	1,800.00	900
3	To check rear lighting and wiring.	\$	50.00	20
4	To remove and install rear tailgate lock mechanism.	\$	80.00	60
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$	150.00	X
6	To apply anti rust proofing to rear affected area.	\$	120.00	80
7	To remove and install rear windscreen glass to facilitate the repair.	\$	140.00	120
8	To remove and install rear bumper reverse sensor.	\$	80.00	50
9	To remove and install rear view camera.	\$	80.00	X
10	To remove and install rear exhaust muffler assy.	\$	150.00	X
11	Towing service.	\$	120.00	X

Total labour : \$ 4,570.00

Total parts : \$ 12,907.25

Total labour : \$ 4,570.00

Total repair cost : \$ 17,477.25

Not Allocated
Lkm
L/S 36000
Sdy.
31/10/18
Theright Allocated