

1 November 2018

Auto & General Insurance (Singapore) Pte. Limited

190 Clemenceau Avenue #03-01 Singapore Shopping Centre Singapore 239924

Attention: Ms Julie Mangubat

SCENE INVESTIGATION REPORT

(Confidential and privileged for use by Insurers and their appointed representatives)

YOUR REFERENCE : C10002188/JM

OUR REFERENCE : BDI/MC/18-1055

SITUATION OF LOSS : Lorong 23 Geylang, in front of premises of 1 Sims

Lane and in vicinity of lamp post no. 10

DATE & TIME OF ACCIDENT : 28 October 2018 (Sunday) @ 1500 hrs

NATURE OF ACCIDENT : The Insured Vehicle had suddenly stalled as the

Insured attempted to travel past a road which was

inundated with water.

SCENE INSPECTION

- The accident has been verified to have occurred along Lorong 23 Geylang, in front of the premises of 1 Sims Lane and in the vicinity of lamp post no. 10.
- The stretch of road comprises of an unmarked single lane but it was observed to be a dual carriageway.
- The height of the road hump near to where the Insured Vehicle had stalled was measured to be about 9cm (0.09m).



Photo 1: Shows a streetdirectory.com map extract of the accident scene.





Co. Reg No. : 201312008M 7030 Ang Mo Kio Avenue 5 #08 - 03, Northstar @ AMK, Singapore 569880 Tel : +65 6904 4922 Fax : +65 6904 4922





Photo 4: Shows a general view of the road in the Insured Vehicle's travel direction.



A-PAC Investigation Solutions Pte Ltd








Photo 6: Shows the raised level of water at the time the Insured Vehicle had stalled.



A-PAC Investigation Solutions Pte Ltd





Photo 7: Shows the height measurement of the road hump.

Co. Reg No. : 201312008M 7030 Ang Mo Kio Avenue 5 #08 - 03, Northstar @ AMK, Singapore 569880 Tel : +65 6904 4922 Fax : +65 6904 4922





Photo 8: Shows the height measurement of the road hump.

Co. Reg No. : 201312008M 7030 Ang Mo Kio Avenue 5 #08 - 03, Northstar @ AMK, Singapore 569880 Tel : +65 6904 4922 Fax : +65 6904 4922