

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5717Y

AAD1810-252

Not Notarized
11 Sep @ 4300h

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

/SHC 5717Y
 VF1ABL15AUC281611
 RENAULT
 LATITUDE
 22.10.18
EQ

PART		LIST	
1	DOOR PANEL REAR RH	\$	<i>11</i> 2,844.66
1	DOOR GUIDE REAR RH	\$	<i>12</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>11</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>11</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>12</i> 203.06
1	DOOR LOCK REAR RH	\$	<i>11</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>11</i> 126.49
1	DOOR HANDLE CAP REAR RH	\$	<i>12</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>12</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>12</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>12</i> 133.60
1	DOOR REGULATOR REAR RH	\$	<i>12</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>12</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>12</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>12</i> 6.31
1	DOOR FINISHER REAR RH	\$	<i>12</i> 423.10
1	DOOR MOULDING REAR RH	\$	<i>12</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>12</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>12</i> 6.91
1	DOOR CASING REAR RH	\$	<i>12</i> 1,509.06
1	DOOR WATER SHIELD REAR RH	\$	<i>12</i> 30.39
1	DOOR CASING CLIP	\$	<i>12</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>12</i> 48.74
1	DOOR FINISHER INNER REAR RH	\$	<i>12</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>12</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>12</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>12</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>12</i> 20.33
1	DOOR GRAB HANDLE REAR RH	\$	<i>12</i> 210.96

X

Trans-cab Auto Services Pte Ltd**AAD1810-252**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5717Y

1	DOOR BLIND REAR RH	\$	Sn	741.80	} X
1	DOOR WHEATHESTRIP REAR RH	\$	Sn	410.66	
1	DOOR SEAL REAR RH	\$	Sn	162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	Sn	229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	Sn	334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	Sn	115.64	} ✓
1	FENDER PANEL REAR RH	\$	Bn	3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	Sn	671.45	X
1	WHEELARCH REAR RH	\$	Sn	543.47	X
1	DOOR MIRROR ASSY RH	\$	Sn	1,483.40	X
1	ROCKER PANEL INNER GARNISH RH	\$	Sn	466.51	X
1	ROCKER PANEL INNER RH	\$	N	1,024.79	X
1	ROCKER PANEL CENTER RH	\$	N	990.25	X
1	BUMPER COVER REAR	\$	Bn	1,108.46	✓
1	BUMPER LOWER REAR	\$	Sn	768.84	} X
1	BUMPER BRACKET CTR REAR	\$	Sn	113.47	
1	BUMPER BRACKET SIDE RH REAR	\$	Sn	135.97	
1	BUMPER RETAINER RH REAR	\$	Sn	44.99	
1	BUMPER BEAM REAR	\$	N	777.52	
1	BUMPER BEAM BRACKET RH REAR	\$	N	225.95	} ✓
TOTAL		\$		23,576.90	
10%		\$		2,357.69	
		\$		21,219.21	

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	Nn	300.00	60sn
1	DOOR CHECK BOLT	\$	Nn	22.69	} X
1	DOOR GUIDE SCREW	\$	Nn	10.85	
1	DOOR HINGE BOLT	\$	Nn	10.85	
1	DOOR HINGE NUT RH	\$	Nn	14.60	
1	DOOR CHECK BOLT	\$	Nn	22.69	
1	DOOR CHECK NUT	\$	Nn	3.75	
1	DOOR LOCK SCREW L70Y	\$	Nn	6.12	} ✓
1	DOOR CATCH SCREW L70Y	\$	Nn	10.06	
1SET	PARKING AID	\$	Nn	700.00	✓
1SET	REAR BUMPER CLIP	\$	Nn	66.00	✓
1SET	BUMPER BRACKET CTR CLIP	\$	Nn	33.00	✓

Trans-cab Auto Services Pte Ltd

AAD1810-252

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5717Y

1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn 10.00	} X
1SET	BUMPER RETAINER RH CLIP RR	\$	nn 20.00	
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	nn 10.00	
1SET	BUMPER RETAINER CLIP LH RR	\$	nn 20.00	
1SET	BUMPER LOWER REAR RIVET	\$	nn 22.00	
1SET	BUMPER LOWER REAR CLIP	\$	nn 66.00	
1	RIGHT REAR TYRE	\$	sn 330.00	
1	RIGHT REAR TYRE RIM	\$	sn 380.00	

TOTAL	\$	2,058.63
--------------	-----------	-----------------

TOTAL PARTS	\$	23,277.84
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	7001
Putty and spray painting of the affected portion.	\$	4,500.00	6601
To rust-proofing of the affected areas.	\$	170.00	301
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	109
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X

Trans-cab Auto Services Pte Ltd

AAD1810-252

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5717Y

To transfer of Rear door fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ *nn* 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X**TOTAL** \$ 12,010.00**Over All Total** \$ 35,287.84**LUMP SUM (REPAIR DAY)****15 DAYS***5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: