

Not Authored
 11 Sep 8?
 Murray After Rain



NUR FAJRINA BEE BTE ABD AZIZ
 BLK 662 #23-20
 BUFFALO ROAD
 SINGAPORE 210662

File No : SH/2018/13910/012/TP
 Date : 29-October-2018

21 days

Estimated cost of repair for vehicle no: SKA7191A MAZDA 1.5 ATV

Accident involving vehicle no: SKA7191A & SJR1369S on 25-October-2018

Description	Quantity	List Price
Rear bumper	1	\$ <i>Rt</i> 450.00 ✓
Bumper clips @ set	1	\$ <i>nc</i> 18.00 ✓
RH rear bumper retainer	1	\$ <i>Dis</i> 20.00 ✓
LH rear bumper retainer	1	\$ <i>Di</i> 20.00 ✓
RH tail lamp	1	\$ <i>mgcm</i> 215.00 ✓
LH tail lamp	1	\$ <i>mgcm</i> 215.00 ✓
Rear bumper reinforcement	1	\$ <i>Rt</i> 135.00 ✓
Rear body end panel	1	\$ <i>Rt</i> 190.00 ✓
Rear bumper no. plate lamps @ set	1	\$ <i>mt</i> 145.00 ✓
Tail door	1	\$ <i>Rt</i> 480.00 ✓
Tail door emblem	1	\$ <i>nc</i> 28.00 ✓
Tail door badge 'Mazda 2'	1	\$ <i>nc</i> 45.00 ✓
Tail door top inner lock	1	\$ <i>n</i> 145.00 X
Tail door bottom inner lock	1	\$ <i>n</i> 28.00 X
Rear body end panel inner tiem garnish	1	\$ <i>nc</i> 115.00 ✓
Rear spare tyre floor panel	1	<i>Rt/Brn</i> \$ 450.00 ✓
RH rear bumper and wheel duct garnish	1	\$ 65.00 ?
LH rear bumper and wheel duct garnish	1	\$ 65.00 ?
Rear spare tyre top tiem board	1	\$ 220.00 ?
RH rear compartment wheel tiem board (to check)	1	\$ 240.00 ?
LH rear compartment wheel tiem board (to check)	1	\$ 240.00 ?
Front bumper	1	<i>CM</i> \$ <i>/Brn</i> 450.00 ✓
Grille	1	\$ <i>CM</i> 85.00 ✓
Grille emblem	1	\$ <i>nc</i> 55.00 ✓
Front susupport panel	1	\$ <i>CM</i> 280.00 ✓
Front susupport top cover	1	\$ <i>nc</i> 85.00 ✓
LH air cleaner air duct	1	\$ <i>nc</i> 135.00 ✓
Bonnet lock	1	\$ <i>Rt</i> 90.00 ✓
RH head lamp	1	<i>mgcm</i> \$ 420.00 ✓
LH head lamp	1	<i>mgcm</i> \$ 420.00 ✓
Front bumper center air grille	1	\$ <i>SL</i> 85.00 X
Front bumper reinforcement	1	\$ 220.00 ?
Front bumper reinforcement insulator spongh	1	\$ 85.00 ?
Radiator	1	\$ 450.00 ?
Radiator assy	1	\$ 360.00 ?
Air condensor	1	\$ 350.00 ?

NUR FAJRINA BEE BTE ABD AZIZ

BLK 662 #23-20
BUFFALO ROAD
SINGAPORE 210662

File No : SH/2018/13910/012/TP

Date : 29-October-2018

Estimated cost of repair for vehicle no: SKA7191A MAZDA 1.5 ATV

Accident involving vehicle no: SKA7191A & SJR1369S on 25-October-2018

Description	Quantity	List Price
Air condensor aluminium gas pipe	1	\$ 185.00 7
Air condensor 'H' gas pipe	1	\$ 160.00 7
		\$ 7,444.00
Add 15%		\$ 1,116.60
		\$ 8,560.60
Rear bumper parking sensor	1	SN \$ <i>CMA</i> 260.00 <i>200sn</i>
Rear windscreen sealant	1	SN \$ <i>me</i> 60.00 <i>40sn</i>
Rear w/s inner sealant rubber	1	SN \$ <i>me</i> 28.00 ✓
Rear number plate	1	SN \$ <i>CMA</i> 45.00 ✓
Front number plate	1	SN \$ <i>CMA</i> 45.00 ✓
Radiator coolant water	1	SN \$ <i>me</i> 35.00 <i>20sn</i>
To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality.	1	\$ 60.00 ✓
Towing charges	1	\$ 80.00 <i>501</i>
To respray paint front accident and repair areas.	1	\$ <i>700</i> 750.00 <i>6501</i>
To respray paint rear accident and repair areas.	1	\$ 1,100.00 <i>1000</i>
To remove and reinstall rear windscreen.	1	\$ 150.00 <i>1201</i>
To remove and check engine, gearbox, radiator, engine & gearbox mountings, intake and exhaust manifold & for damage and reinstall components and check engine running functionality.	1	\$ 180.00 <i>801</i>
Labour charges to remove front damaged parts, check , jack out RH and LH front chassis member, repair and panel beating, RH and LH front fender, Bonnet and pull out front damaged panel, renew and install adjust front body bonnet, door bumper alignment.	1	\$ 850.00 <i>6501</i>
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	1	\$ 65.00 <i>401</i>
Labour charges to remove rear damaged parts, jack out RH and LH rear chassis member, compartment floor panel, body and cut out floor panel, rear body end panel, repair and panel beating, rewinding, renew install and adjust rear chassis, body tail door bumper alignment.	1	\$ 1,500.00 <i>1400</i>

NUR FAJRINA BEE BTE ABD AZIZBLK 662 #23-20
BUFFALO ROAD
SINGAPORE 210662

File No : SH/2018/13910/012/TP

Date : 29-October-2018

Estimated cost of repair for vehicle no: SKA7191A MAZDA 1.5 ATV**Accident involving vehicle no: SKA7191A & SJR1369S on 25-October-2018**

Description	Quantity	List Price
		\$ 13,768.60

T/Party: EQ INSURANCE COMPANY LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: