

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

Not Allowed
above
take photo after
open
24h.
16/11/18

M/S : LONPAC INSURANCE BHD
300, Beach Road, #17-04/07
THE CONCOURSE
Singapore 199555

TEL: 62507388 FAX: 62963767
ATTN: Motor Claim Department
Your Ref No: 18/LP/TP-217 (10)
Claim Type: Third Party

Estimate No: EST0004465
Date: 30 Oct 2018
Policy No: 1800020693
Veh Reg No: SLU1053M
Make/Model: TOYOTA CHR

Reg. Date: 30/08/2017

Estimate Repair Cost to Vehicle No :SLU1053M


Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Parts				
1 FRT BUMPER		1 PC	1,350.00	
2 FRT BUMPER RETAINER LH		1 PC	75.00	
3 FRT BUMPER CLIP		10 PC	20.00	
4 LH HEADLAMP		1 PC	800.00	
			2,245.00	
	Add 15%		336.75	2,581.75
Labour				
5 WIRE CHECKING		1 UNIT	30.00	
6 LABOUR CHARGE		1 UNIT	200.00	
7 SPRAY PAINTING		1 UNIT	200.00	
				430.00

Amount Before Excess S\$ 3,011.75

Add GST @ 7% 210.82

Total Amount payable S\$ 3,222.57

TOTAL: SINGAPORE DOLLAR THREE THOUSAND TWO HUNDRED TWENTY TWO AND CENTS FIFTY SEVEN ONLY



For SME Motor Pte Ltd

AUTHORISED SIGNATURE