



凱摩哆服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 30/10/2018

Attn: The Motor Claims Department

Your Insured veh no : GZ 2865 M

AIG ASIA PACIFIC INSURANCE PTE LTD.

78 Shenton Way

07-16 Chartis Building

Singapore 079120

Dear Sir / Madam

LKK Auto Consultants hence notify the Repairer of the following:

WITHOUT PREJUDICE after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Resurvey is on a "Without Prejudice" basis (By Email Only)
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Estimate Cost repair Bill To Nissan NV200 NO GBH 916 S & GZ 2865 M on 24/10/2018 @08:05:00

To Supply :-

1pc	Rear boot cover LH <i>Dented</i>	\$ 1,281.10 ✓
1pc	Rear boot cover hinge top <i>3 new</i>	\$ 115.00 +
1pc	Rear boot cover hinge lower	\$ 115.00 +
1pc	Rear boot cover NV200 emblem <i>new</i>	\$ 79.90 ✓
1pc	Rear boot cover inner rubber <i>new</i>	\$ 98.00 +
1pc	Rear bumper <i>Deformed</i>	\$ 624.80 ✓
1pc	Rear bumper lamp <i>new</i>	\$ 55.00 +
1pc	70km/h <i>new</i>	\$ 10.00 ✓
1pc	Rear boot cover lock <i>new</i>	\$ 115.00 +
1pc	Rear boot cover "Nissan" logo <i>new</i>	\$ 60.00 ✓
1set	Reverse sensor <i>Damaged</i>	\$ 280.00 - 200 (SN)
1pc	Rear glass sealant <i>new</i>	\$ 60.00 ✓
		\$ 2,893.80
Less		10% \$ 289.38
		\$ 2,604.42

To dismantle and replace of the accident damaged parts, including heat/weld, cut-off, knocking, straighten, repair, adjust and reshape of same.

\$ ~~480.00~~ 350

To putty, apply primer & spray paint on the affected portion.

790 \$ ~~580.00~~ 300

To check wiring functions.

\$ ~~60.00~~ 30

To remove reverse sensor.

\$ ~~80.00~~ 50

labour charge to remove & refix windscreen.

\$ ~~100.00~~ 60

\$ 3,904.42

Adrian Lim
2/5 02/11/18

042mp

total: 2894.22
(P/P) ✓