

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1800339
Date: 29 Oct 2018
Veh Reg No: SKU4904A
Make/Model: TOYOTA VELLFIRE2.5X
CVT
Chasis No: AGH300015873
Reg. Date: 30/07/2015
Your Ref No: SLL4999L

Claim Type: Third Party
Accident Date: 26/10/2018
TP Veh Reg No: SLL4999L

Xiao Tong

Estimate Repair Cost to Vehicle No :SKU4904A

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>Dented</i>	1,637.30	✓
2	1 PC BOOTLID LOGO <i>new</i>	59.30	✓
3	1 PC BOOT LID "VELLFIRE" EMBLEM <i>new</i>	68.70	✓
4	1 PC BOOT LID LAMP RH <i>new</i>	547.70	+
5	1 PC BOOT LID LAMP LH <i>cracked</i>	547.70	✓
6	1 PC REAR NUMBER PLATE LAMP <i>new</i>	160.20	+
7	1 PC BOOT LID CHROME <i>new cracked</i>	768.90	465.80
8	1 PC REAR WINDSCREEN RUBBER <i>new</i>	78.10	✓
9	2 PCS BOOT LID HINGE <i>new</i>	119.20	+
10	2 PCS BOOT LID SHOCK ABSORBER <i>new</i>	663.40	+
11	1 PC BOOT LID LOCK <i>Damaged</i>	763.90	584.40
12	1 PC BOOT LID LOCK CHECKER <i>new</i>	48.70	+
13	1 PC BOOT LID RUBBER <i>new</i>	368.90	✓
14	2 PCS BOOTLID STOPPER MOUNTING <i>new</i>	16.00	+
15	1 PC BOOT LID TRIM <i>Dented</i>	673.60	✓
16	1 PC BOOT LID HOLDING HANDLE <i>new</i>	38.70	+
17	1 PC TAIL LAMP LH <i>new</i>	542.70	+
18	1 PC TAIL LAMP - RH <i>new</i>	542.70	+
19	1 PC TAIL LAMP LOWER PANEL LH <i>Dented</i>	360.70	✓
20	1 PC REAR PANEL <i>Dented</i>	725.50	✓
21	1 PC REAR PANEL TRIM <i>Dented</i>	232.90	✓
22	1 PC SPARE TYRE PANEL TRIM <i>new</i>	667.70	+
23	1 PC SPARE TYRE COVER RH <i>Dented</i>	424.70	✓
24	1 PC SPARE TYRE COVER LH <i>Dented</i>	424.70	✓
25	1 PC SPARE TYRE CENTRE COVER <i>Dented</i>	288.70	✓
26	1 PC REAR FENDER TRIM LH <i>cracked</i>	986.70	798
27	1 PC REAR FENDER TRIM RH <i>cracked</i>	986.70	798
28	4 PCS REVERSE SENSORS <i>Damaged</i>	1,526.40	500
29	1 PC REAR LH SEAT BRACKET <i>new</i>	366.70	+

1pc " antenne sensor - 169.60 ✓
Dented

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1800339
Date: 29 Oct 2018
Veh Reg No: SKU4904A
Make/Model: TOYOTA VELLFIRE2.5X
CVT
Chasis No: AGH300015873
Reg. Date: 30/07/2015
Your Ref No: SLL4999L

Claim Type: Third Party
Accident Date: 26/10/2018
TP Veh Reg No: SLL4999L

Estimate Repair Cost to Vehicle No :SKU4904A

Quantity	Description	List Price	Amount
		SS	SS
30	1 PC REAR LH SEAT BRACKET TOP GARNISH <i>Del d</i>	202.80	✓
31	1 PC REAR RH SEAT BRACKET <i>Ne n</i>	366.70	✓
32	1 PC REAR RH SEAT BRACKET TOP GARNISH <i>Del d</i>	202.80	✓
33	1 PC REAR SEAT BRACKET CENTRE TRAY <i>Del d</i>	288.40	✓
34	1 PC REAR SEAT BRACKET CENTRE TRAY HARDBOARD <i>Del d</i>	199.70	✓
35	1 PC REAR BUMPER <i>Del d</i>	1380.40	
36	2 PCS REAR BUMPER BRACKET <i>LH Rnted</i>	184.60	92.30
37	2 PCS REAR BUMPER SIDE RETAINER <i>ne</i>	11704.20	138.40
38	2 PCS REAR BUMPER SMALL RETAINER <i>ne</i>	85.60	✓
39	1 PC REAR BUMPER REFLECTOR - LH <i>can d</i>	8778.15	54.10
40	1 PC REAR BUMPER REFLECTOR - RH <i>Ne n</i>	54.10	✓
41	1 PC REAR TOWING COVER <i>Del d</i>	25.70	✓
		16,544.90	
	Less 25%	4,136.23	12,408.81
	Special Net		
42	1 PC REAR NUMBER PLATE <i>ne n</i>	50.00	✓
43	1 PC REAR NUMBER PLATE BASE <i>ne n</i>	50.00	✓
44	1 PC REAR WINDSCREEN SEAL <i>3 ne</i>	60.00	30
45	1 PC REAR WINDSCREEN SEALANT <i>190</i>	60.00	30
46	1 SET BOOT LID TRIM CLIPS <i>ne</i>	80.00	30
47	1 SET REAR PANEL TRIM CLIPS <i>ne</i>	48.00	10
48	1 SET REAR FENDER LH TRIM CLIPS <i>ne</i>	60.00	30
49	1 SET REAR FENDER TRIM CLIPS RH <i>ne</i>	60.00	30
50	1 SET REAR BUMPER CLIPS <i>ne</i>	60.00	30
51	1 PC REVERSE CAMERA <i>ne n</i>	480.00	✓
		1,008.00	1,008.00
	Labour		
52	1 TO CHECK WIRING	50.00	30
53	1 TO REMOVE AND REFIT REVERSE SENSOR	100.00	60
54	1 TO REMOVE AND REFIT REVERSE CAMERA	100.00	50

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1800339
Date: 29 Oct 2018
Veh Reg No: SKU4904A
Make/Model: TOYOTA VELLFIRE2.5X
CVT
Chasis No: AGH300015873
Reg. Date: 30/07/2015
Your Ref No: SLL4999L

Claim Type: Third Party
Accident Date: 26/10/2018
TP Veh Reg No: SLL4999L

Estimate Repair Cost to Vehicle No :SKU4904A

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
55	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 ✓	
56	1 TO SPRAY UNDERSEAL	200.00 60	
57	1 (REAR) TO SPRAY PAINTING	1,800.00 1200	
58	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,000.00 1200	
59	1 TO REMOVE AND REFIT SEAT CUSHION 2900	800.00 100	
60	1 TO REMOVE AND REFIT INNER TRIM	200.00 80	
		5,370.00	5,370.00
Total			S\$ 19,172.99
Add GST @ 7%			1,342.11
Total Amount Payable			<u>S\$ 20,515.10</u>

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND FIVE HUNDRED FIFTEEN AND CENTS TEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

total 11868.15
2/s 9.5K.

9.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: