

6 AUG 1977, HAZARD

1KF

IMP

ASSIGNMENT
29/10/18

Date / Time: 29/10/18
Registered in Meritmen: 2/11/18

Pre-assign / CCU / FTE

GRA 4863X



Insured Vehicle No.:
Name of Insured: CHAN Hing motor co. p/l

Claim No.:
Policy No.:

Insured Tel No.:
Excess Sec II :SS
HP: 27/10/18
D.O.A:

Make / Model:
Place of Accident: Tampines Ave 4

Is driver the owner? (YES / NO)
If NO, Driver Name / Age: Siew Heng HAO, Brandon
Driver Tel No.:
Nature of Accident:
(VL: YES / NO)

GI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Insured Liability: % Final? Yes / No

CPH 8988H



INSRS:
WSP:
Tel: Chin Meng
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time	STAGE	DATE / PIC
8/11/18	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call GI:	26.10.18
	After call ltr to GI:	
20.10.18	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup):	
10/7/19	After call ltr to GI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: S\$ (days) Reduction: % Email: Call:

FINAL SETTLEMENT Date/Time: 29/8/19 Confirm with: Chin Meng Motors Email: Call:

Final Liability: % (Agreed / Assessed) BOLA S/N No. 27 If NO or B 28, Ass. Lia:

Repair Cost: S\$ 12100.00 * OLD REPAIR EXCEED TP

Loss of Rental (LOR): S\$ 1080.00 (9 days) x \$120

Loss of Use (LOU): S\$ - (\$ x days)

Loss of Income (LOI): S\$ - (\$ x days)

LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search: S\$ 7.45

Medical: S\$ -

Disbursement: S\$ - (e.g. Tow/Independent)

Legal Cost: S\$ -

Total: S\$ 13187.45 Global Sum S\$:

FINAL PAYMENT Date/Time: Confirm with: Email: Call:

Payee 1: S\$ 13187.45 Name: Chin Meng Motors

Payee 2: (Strike if N.A.) S\$ Name 2:

Payee 3: (Strike if N.A.) S\$ Name 3:

COPY SENT
31/9/19

- 1) Claim status: ☒ Non-Report/Private Settle
- 2) Report Format: ☒ P
- 3) Survey fee: \$320

CH 340

Adrian

ASSIGNMENT

29/12/10

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SDH8988H. Yr Regn: 2010 Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 730Li cc 2996.

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading 245135 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAKB22040CN74740

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 245/50R18

R: 245/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 29/10/18

Survey held at Chin Meng.

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG.

43 - \$12100 (Red \$ 8548.25 / 41%)

MV: 70K.

PV: 56.2K

Nett: 13.8K

+2216

Date/Time, File Pass to?

Date/Time, File Return to?

1)

7)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

振明摩哆

CHIN MENG MOTORS

1 Kall Bukit Ave 6, #01-40/63 Autobay@Kall Bukit, Singapore 417883

Tel: 6747-4810 Fax: 6745-5018

cmmotors@singnet.com.sg

Our Ref: EST341/18/TP

Your Ref: TP claim against GBA4863X

27-Oct-18

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#08-16

Singapore 409179

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to BMW 730Li no: SDH8988H

Date of accident: 27-10-2018

Parts supply:

- 1 pc Boot *vented*
- 1 pc Boot emblem - Logo *3m*
- 1 pc Boot emblem - 730Li *3m*
- 1 pc Boot centre garnish (chrome) assy *cut*
- 1 pc Boot reverse camera *new Dmgd*
- 1 pc Boot inner lock *Dmgd*
- 1 pc Boot insulator *new*
- 2 pcs Boot lamps @\$480.50 *RH cut*
- 2 pcs Boot lamp side rubber @\$105.95 *LH missing*
- 2 pcs Boot lamp top garnish (chrome) @\$83.85 *2 cut*
- 2 pcs Boot hinges @\$182.60 *Best*
- 1 pc Boot weatherstrip *cut*
- 1 pc Boot inner switch (open & close) *new*
- 2 pcs Taillamps @\$721.50 *LH cancelled, RH 2nd*
- 2 pcs Taillamp side garnish @\$83.85 *LH cut, RH new*
- 2 pcs Taillamp lower brackets @\$65.50 *2nd Dmgd*
- 2 pcs Taillamp clips @\$12.50 *new*
- 1 pc Rear bumper *Distorted*
- 1 pc Rear bumper tow cover *2nd*
- 2 pcs Rear bumper reflectors @\$45.80 *2nd - L & R*
- 4 pcs Rear bumper PDC sensor @\$236.85 *2 pieces dmgd*
- 4 pcs Rear bumper PDC sensor holders @\$58.60 *new*
- 1 pc Rear bumper reinforcement *Best*
- 2 pcs Rear bumper side garnish (retainers) @\$192.15 *LH Dmgd*
- 1 pc Rear bumper centre inner garnish *Distorted*
- 2 pcs Rear bumper brackets @\$192.15 *cancelled*
- 2 pcs Rear bumper absorbers @\$141.85 *new*
- 1 pc Rear bumper lower lip *Distorted*
- 1 pc Rear end panel *Distorted*
- 1 pc Rear end panel garnish *Distorted*
- 4 pcs Rear end panel garnish clips @\$7.50 *new*
- 1 pc Rear L/h fender inner trim board *new*
- 1 pc Rear ~~LH~~ spare tyre board *Distorted*

ESTIMATE

~ 11,800 TBC

Asher.

SS	1,987.90	✓
	69.50	✓
	61.05	✓
	485.60	✓
	681.10	<i>350/50</i>
	311.85	✓
	160.50	✓
	961.00	<i>480.50</i>
	211.90	<i>109.95</i>
	167.70	<i>83.85</i>
	365.20	✓
	191.65	✓
	524.20	✓
	1,443.00	✓
	167.70	<i>83.85</i>
	131.00	<i>65.50</i>
	25.00	✓
	1,571.15	✓
	50.65	✓
	91.60	<i>48.80</i>
	947.40	<i>473.30</i>
	234.40	✓
	800.80	✓
	384.30	<i>192.15</i>
	113.50	✓
	384.30	✓
	283.70	✓
	285.60	✓
	903.85	✓
	178.85	✓
	20.00	<i>10</i>
	368.45	✓
	537.50	✓
	15,111.90	

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Re: Estimated cost of repair to BMW 730Li no: SDH8988H

Date of accident: 27-10-2018

Parts supply:

Balance b/f:

- 1 pc Rear lower cover *2ch*
1 pc Exhaust muffler *2ch*
2 pcs Exhaust muffler @ \$66.80 *Best*
1 pc Neck restraint sensor unit *Activated*
1 pc Driver's neck restraint unit *Activated*
1 pc Front pax neck restraint unit *Activated*

1381145 SN: 880
12430.30

15,111.90
189.50 ✓
2,136.55 ✓
133.60 ✓
385.50 ✓
895.50 ✓
895.50 ✓
<u>19,748.05</u>
Less 10%: (1,974.81)

S/Nett Items

- 1 pc Rear no. plate with cover (S/Nett) *2ch*

45.00 *

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To respray affected part.

To remove and refit front both assy assy to replace neck restraint unit

To reset fault code after repair.

To check wirings.

2380

1,200.00 / 1000
1,200.00 / 1000
300.00 250
100.00 ✓
30.00 ✓
<u>SS 20,648.25</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary detail(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
H/S 29/10/18.
09 Pags.
Total 15190.30
L/S 12.11C.


> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4221G
Vehicle Details	
Vehicle No.:	SDH8988H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Oct 2018
Vehicle Make:	B.M.W.
Vehicle Model:	730LI AT ABS D/AB 2WD 4DR NAV HID SR
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	11317602N52B30AF
Chassis No.:	WBAKB22040CN74740
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$71,112.00
Original Registration Date:	29 Dec 2010
First Registration Date:	29 Dec 2010
Transfer Count:	0
Actual ARF Paid:	\$71,112.00
Intended PARF Rebate Particulars	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2020
PARF Rebate Amount:	\$42,667.00
Intended COE Rebate Particulars	
COE Expiry Date:	28 Dec 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$64,900.00
COE Rebate Amount:	\$13,509.00
Total Rebate Amount:	\$56,176.00

The information contained herein is correct as at 29 Oct 2018

OK



► **SEARCH** 730 Price Range Depreciation 2011 Vehicle Type Search View All Advanced Search

► **Used Car Comparison**

— Comparing 3 Vehicles —

BMW 7 Series 730Li Sunroof

BMW 7 Series 730Li Sunroof

BMW 7 Series 730Li Sunroof



Clear All

Add all to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

Back to search result

Use search bar above to set to compare.

CAR DETAILS

Price	\$70,000	\$70,800	\$70,800	-
Instalment	\$2,082	\$1,959	\$1,959	-
Registration Date	03-Dec-2010	01-Feb-2011	24-Feb-2011	-
Manufactured	2010	2010	2010	-
Mileage	-	55,641 km	130,000 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	2,996 cc	2,996 cc	2,996 cc	-
Road Tax	\$2,382 /yr	\$2,382 /yr	\$2,382 /yr	-
Power	190.0 kW (254 bhp)	190.0 kW (254 bhp)	190.0 kW (254 bhp)	-
Curb Weight	1,855 kg	1,855 kg	1,855 kg	-
Features	3.0L BMW Twin Turbo Charged Engine, 321 BHP, 6 Speed Automatic, ABS, Airbags, Traction Control, Cruise Control, Auto HID Headlights And Rain Sensors.	Powered By 3L Inline 6 Cylinders Engine Producing 258Bhp 310NM Of Torque, 6-Speed Automatic, ABS, DSC, DTC, Adaptive HID Headlights.	Powered By 3L Inline 6 Cylinders Engine Producing 258Bhp 310NM Of Torque, 6-Speed Automatic, ABS, DSC, DTC, Adaptive HID Headlights.	-
Accessories	Sports Rims, Electric Leather Seats With Memory, Built In Audio System With I-Drive/Assist Parking, Reverse Sensors, Rear DVD Screen, Fog Lights.	Comfort Seats With Memory, Reverse Camera, Soft Close Door, Navigation, Daytime Running Lights, Comfort Access.	Comfort Seats With Memory, Reverse Camera, Soft Close Door, Navigation, Daytime Running Lights, Comfort Access.	-
Description	Very Well Maintained Agent Unit. Original Color Grey, Wrapped In White! Factory Fitted Interior. No Repairs Needed. Best Deal In Town. High Loan Available! Call Now To View! Viewing Is Strictly By Appointment Only.	Best Condition 730Li In The Market, Please Make Your Way To Look At The Others Before Coming Doen To Confirm The Purchase.Fully Maintained By PML From Day One So Genuine Mileage. M Performance Kitted With 22"DPE Wheel,M-carbon Steering Wheel,So Much Value In This Unit.Bank Loan/In House Loan And Trade In Available. Call Friends Auto Traders Your Trusted Dealership And Drive Home Your BMW 7 Series	Replaced Front And Rear Suspension And Airmatic Pumps. Replaced Mounting, New Headlights. Gearbox Overhaul And Valve Body Done In August. Infra-Tint Platinum Solar Film. Fully Serviced At PML. Revol Ceramic Paint Protection. Superb Condition. Strictly Via Appointment.	-
COE	\$46,001	\$67,009	\$75,789	-
OMV	\$72,216	\$70,376	\$70,809	-
ARF	\$72,216	\$70,376	\$70,809	-
Depreciation	\$16,170 /yr	\$15,760 /yr	\$15,230 /yr	-
No. of Owners	3	3	3	-
Type of Vehicle	Luxury	Luxury	Luxury	-
Category	PARF Car	PARF Car, Premium Ad Car, Low Mileage Car	PARF Car, Premium Ad Car	-
Availability	Available	Available	Available	-

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7725211H



Name

LEE YEN LING

李彦霖

Race

CHINESE

Date of birth

13-09-1977

Sex

F

S7725211H

Country of birth

SINGAPORE

*Ind Pkly
AIG*

REPUBLIC OF SINGAPORE DRIVING LICENCE



Control Number S77252

Name

LEE YEN LING (LI
YANLING)

Birth Date: 13 Sep 1977

Issue Date: 02 Jan 2003



000088542A



4106534

NRIC No: S7725211H



Date of issue

26-09-2007

295 BEDOK SOUTH AVENUE 3 #15-01
SINGAPORE 469296

NRIC No: S7725211H

Date: 26/07/2010

No: 8513626

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

02 Jan 2003



Licence No: S7725211H

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: CMM201/19/TP

Your Ref: TP claim against GBA4863X

19-Jun-19

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16

Singapore 079120

Attn: Motor Claims Department

Dear Sir/Ms,

Accident Involving SDH8988H and GBA4863X on 27-10-2018 at Tampines Ave 4.

We refer to the above matter. The accident was caused solely by the negligence of your insured and as a result, our client had incurred the following cost and losses:-

Cost of Repair (Surveyed by your surveyor):	S\$	12,100.00
Rental 09 days @\$120.00 :		1,080.00
GIA search fee:		7.45
	S\$	<u>13,187.45</u>

Enclosed are copies of following documents for your perusal:

- (X) Repair bill
- (X) Letter of authorisation
- (X) GIA report
- (X) Photocopy of driver's IC & DL
- (X) GIA search fee



Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 28 December 2018 9:33 AM
To: 'KELVIN.LEE@KIANHUAMOTOR.COM.SG'
Subject: ACCIDENT INVOLVING GBA 4863X AND SDH 8988H ON 27/10/2018

Our Ref: CC6/AIG18019777/Aea3

28 DEC 2018

KIAN HUA MOTOR COMPANY PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING GBA 4863X AND SDH 8988H ON 27/10/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: Ashersng@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, GAN CHEE SIONG ("the third party claimant")
of 295 BEDOK SOUTH AVE 3 #U-01 S469296 (address),
owner of SDH8988H (vehicle no.) hereby authorize
CHIN MENG MOTORS

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SDH8988H that was
damaged pursuant to the accident which occurred on 27/10/12 (date) along
JUNCTION OF TAMPINES AVE 4 (location)
involving vehicle no/s GBA4863X ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 19th day of JUNE (month) 20 12 (year)



Signed by "the third party claimant"



Signed by "the workshop"

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, CHIN MENG MOTORS ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$ 12,100.00** (Repair Cost), **S\$ 1080.00** (Loss of rental/use), **7.45** (Disbursement), for vehicle no. **SDH8988H** that was damaged pursuant to the accident which occurred on **27-10-2018** (date) along **TAMPINES AVE 4** (location) involving vehicle no/s **GBA4863X**. This is pursuant to the inspection conducted on **29/10/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **GAN CHEE SIONG** ("the third party claimant") of vehicle no. **SDH8988H** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SDH8988H** (vehicle no.) as a result of the accident.


We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 29th (day) of August (month) 2019 (year)


LWP

Signed by appointed surveyor



Signed by "the workshop" (with chop)

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: CMM201/19/TP

Your Ref: TP claim against GBA4863X

19-Jun-19

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16

Singapore 079120

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Final cost of repair to BMW 730i no: SDH8988H

Date of accident: 27-10-2018

Total cost of repair and labour charge incurred for dismantling and replacement for parts of the above mentioned vehicle etc as recommended in nett as lump sum by surveyor.

Total lump sum: SS 12,100.00

Dollars: Twelve thousand and one hundred only.

A handwritten signature in black ink, appearing to be 'Xun' or similar, with a stylized flourish at the end.



DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1
SINGAPORE 798125
TEL: 6383 2661 FAX: 6484 2836
REG. NO. 430058/000

Chin Meng

No. 19692

Date.

5/11/18

OFFICIAL RECEIPT

Received from

Lee Yen Ling

the sum of Dollars

One thousand eighty only

being Payment Of

SKF 4340E

(27/10/18 - 5/11/18)

DAWN ENTERPRISES

\$

1080/-

Cash/Cheque No.



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

Chin May
SOH 8988D

Nº 36198

RENTAL AGREEMENT

DATE 27/10/18

HIRER'S PARTICULARS

Name Lee Yen Ling
Address 295 Bedok South Ave 3
#15-01
S469296
772511H
I/C or Passport No. 772511H Country _____
Occupation _____
Date of Birth _____ Age _____
Driving Licence No. _____ Date Passed _____
Tel: (HP) 90219788 (Residence) _____

DRIVER'S PARTICULARS

Name _____
Address _____
I/C or Passport No. _____ Country _____
Occupation _____
Date of Birth _____ Age _____
Driving Licence No. _____ Date Passed _____
Tel: (Office) _____ (Residence) _____

IMPORTANT NOTES:

1. No Insurance Coverage if the driver is below 24yrs old or less than 2 years driving licence
2. This vehicle is licensed to carry 2000 passengers only
3. Hirer is liable to pay first \$ 2000 as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
4. For usage to Malaysia subject to higher excess all claims of \$55,000.00 and different rental rate
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
6. No refund will be given for vehicle returns early.
7. No refund will be given for petrol left in vehicle.
8. Hirer is liable to pay all parking fee and traffic summonses.
9. Vehicles to be return during office hour only.
10. No Service on Public Holiday and Sunday.

CHARGES

9 Day at \$ 120.00 per days \$ 1080.00
Day at \$ _____ per week
Day at \$ _____ per month

TOTAL AMOUNT \$ 1080.00

AMOUNT PAID \$ 1080.00

BALANCE DUE

Days Extension From _____ To _____

Amount Deposit (refundable) \$ _____

SCHEDULE

MODEL

SKF 4340E

T/A/H/L

Date

Time

Mileage

27/10/18

5/11/18

FROM

27/10/18

TO

5/11/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

Hirer's Signature

Driver/Guarantor's Signature

DAWN ENTERPRISES

[> Back to OneMotoring](#)


Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 27 Oct 2018 / 12:02:50

Receipt Date/Time : 27 Oct 2018 / 12:02:50

Tax Invoice/Receipt

Receipt No. : ITNET-00000-181027-000560

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBA4863X				
As at 27 Oct 2018/10:00:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - GBA4863X Enquiry Fee 20181027120130408989	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx0994	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING


















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Oct 2018 Edit Reg		29 Oct 2018 00:00 Edit Adj Rpt	S\$12,100.00 Edit Estimates	S\$12,100.00 View Rpt		Pending for Survey Report Cancel Case






























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	KIAN HUA MOTOR COMPANY PTE LTD , Co. Reg. No.: 200106569G								
Main Claimant:	GAN CHEE SIONG , ID: S2764221G								
Vehicle Reg. No.:	SDH8988H	Date of Loss:	27/10/2018 09:00 - :59 [93 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3813640581SG	Policy/Cover Note No.:	1800078396 (Third Party Only)						
Vehicle Reg. No. (Insured):	GBA4863X	Policy No. (Claimant):	D17MTPV01016104						
		Excess:							
Repairer:	Chin Meng Motors (HQ) 1 Kaki Bukit Ave 6 #01-40/63, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 4810								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/11/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> AIG_SG_EXPRESS (05/08/2019): Alert - Adj Mandate Approved (S\$13187.45) - SDH8988H - Claim Handler: Kesaval, J... 									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDH8988H (3813640581SG)
 [GBA4863X]
 TP
 GAN CHEE SIONG
 Oct 27 2018 9:00AM
 [KIAN HUA MOTOR COMPANY PTE LTD]
 Chin Meng Motors

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<div></div>	<div></div>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown													1	Edit				
Photos/Images															3 per page		<div></div>	<div></div>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	12/12/18 14:04	General View													1	Load JPG	<div></div>			
2	12/12/18 14:04	General View													1	Load JPG	<div></div>			
3	12/12/18 14:04	General View													1	Load JPG	<div></div>			
4	12/12/18 14:04	General View													1	Load JPG	<div></div>			
5	12/12/18 14:04	General View													1	Load JPG	<div></div>			
6	12/12/18 14:04	General View													1	Load JPG	<div></div>			
7	12/12/18 14:04	General View													1	Load JPG	<div></div>			
8	12/12/18 14:04	General View													1	Load JPG	<div></div>			
9	12/12/18 14:04	General View													1	Load JPG	<div></div>			
10	12/12/18 14:04	General View													1	Load JPG	<div></div>			
11	12/12/18 14:04	General View													1	Load JPG	<div></div>			
12	12/12/18 14:04	General View													1	Load JPG	<div></div>			
13	12/12/18 14:04	General View													1	Load JPG	<div></div>			
14	12/12/18 14:04	General View													1	Load JPG	<div></div>			
15	12/12/18 14:04	General View													1	Load JPG	<div></div>			
16	12/12/18 14:04	General View													1	Load JPG	<div></div>			
17	12/12/18 14:04	General View													1	Load JPG	<div></div>			
18	12/12/18 14:04	General View													1	Load JPG	<div></div>			
19	12/12/18 14:04	General View													1	Load JPG	<div></div>			
20	12/12/18 14:04	General View													1	Load JPG	<div></div>			
21	12/12/18 14:04	General View													1	Load JPG	<div></div>			
22	12/12/18 14:04	General View													1	Load JPG	<div></div>			
23	12/12/18 14:04	General View													1	Load JPG	<div></div>			
24	12/12/18 14:04	General View													1	Load JPG	<div></div>			
25	12/12/18 14:04	General View													1	Load JPG	<div></div>			
26	12/12/18 14:04	General View													1	Load JPG	<div></div>			
27	12/12/18 14:04	General View													1	Load JPG	<div></div>			
28	12/12/18 14:04	General View													1	Load JPG	<div></div>			
29	12/12/18 14:04	General View													1	Load JPG	<div></div>			
30	12/12/18 14:04	General View													1	Load JPG	<div></div>			
31	12/12/18 14:04	General View													1	Load JPG	<div></div>			
32	12/12/18 14:04	General View													1	Load JPG	<div></div>			
33	12/12/18 14:04	General View													1	Load JPG	<div></div>			
34	12/12/18 14:04	General View													1	Load JPG	<div></div>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	12/12/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/12/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/12/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/12/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/12/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/12/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/12/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/12/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/12/18 14:04	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	12/12/18 14:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/11/18 11:58	TP GIA REPORT	 Load PDF	
2	28/12/18 09:35	LETTER TO OI	 Load PDF	
3	22/07/19 14:18	RENTAL RECEIPT	 Load PDF	
4	22/07/19 14:18	LTA SEARCH	 Load PDF	
5	30/07/19 10:51	TP ESTIMATE - MARKED	 Load PDF	
6	04/09/19 14:44	WORKSHOP INVOICE	 Load PDF	
7	04/09/19 14:44	AUTHORISATION TO ACT FORM	 Load PDF	
8	04/09/19 14:44	Release Voucher	 Load PDF	
9	04/09/19 14:44	LOD	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/11/18 09:29	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBA4863X (Insd veh)	Model:	BMW 730LI 3.0 AT ABS D/AB
	SDH8988H (TP veh)		2WD 4DR NAV HID SR (A)
Date of Accident:	27/10/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	20,648.24	
Final Repair Cost	: \$	12,100.00	
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$	1,080.00	9 days
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	13,187.45	

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____(%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 27

BOLA Liability: 100 _____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Chin Meng Motors	: \$	13,187.45
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

04 Sep
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18019777/ADA3Q2

Date: 04/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800078396

Claimant Vehicle No : SDH8988H

Insured Vehicle No : GBA4863X

Date of Loss: 27/10/2018

Nature of Claim:

TP

Claim No: 3813640581SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDH8988H

Make & Model: BMW 730LI, 3.0 AT ABS D/AB 2WD 4DR NAV HID SR (A)

Engine No: 11317602N52B30AF

Reg. Date: 29/12/2010 (Man. Year: 2010)

Chassis No: WBAKB22040CN74740

Colour: Black

Odometer: 245135 km

Engine Capacity: 2996 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50 R18

Rear Tyre Size: 245/50 R18

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,818.24	12,810.30	5,007.94	28.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	2,380.00	450.00	15.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,648.24	15,190.30	5,457.94	26.43
Approved Total (Overridden) (S\$)		12,100.00		
Nett Amount (S\$)	20,648.24	12,100.00	8,548.24	41.40
+ Car Rental (9.0 x S\$120.00/day) (S\$)		1,080.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		13,187.45		

INSPECTION

Date of Assignment: 29/10/2018

Date Inspected: 29/10/2018 Inspected At:

Chin Meng Motors (HQ)
1 Kaki Bukit Ave 6 #01-40/63, Autobay @
Kaki Bukit
Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT	Dented	1,987.90 FL	*1,987.90 FL
2	1		*BOOT EMBLEM -LOGO	Necessary	69.50 FL	*69.50 FL
3	1		*BOOT EMBLEM -730LI	Necessary	61.05 FL	*61.05 FL
4	1		*BOOT CENTRE GARNISH (CHROME) ASSY	Cut	485.60 FL	*485.60 FL
5	1		*BOOT REVERSE CAMERA	Damaged	612.99 FS	*380.00 FS
6	1		*BOOT INNER LOCK	Damaged	311.85 FL	*311.85 FL
7	1		*BOOT INSULATOR	Not Necessary	160.50 FL	*- FL
8	1		*BOOT LAMPS	N/S Cut	961.00 FL	*480.50 FL
9	1		*BOOT LAMP SIDE RUBBER	N/S Missing	211.90 FL	*109.95 FL
10	1		*BOOT LAMP TOP GARNISH (CHROME)	N/S Cut	167.70 FL	*83.85 FL
11	2		*REAR HINGES	Bent	365.20 FL	*365.20 FL
12	1		*BOOT WEATHERSTRIP	Cut	191.65 FL	*191.65 FL
13	1		*BOOT INNER SWITCH (OPEN & CLOSE)	Not Necessary	524.20 FL	*- FL
14	2		*TAILLAMPS	Cracked	1,443.00 FL	*1,443.00 FL
15	1		*TAILLAMP SIDE GARNISH	N/S Cut / O/S Not Necessary	167.70 FL	*83.85 FL
16	1		*TAILLAMP LOWER BRACKETS	N/S Damaged	131.00 FL	*65.50 FL
17	2		*TAILLAMP CLIPS	Necessary	25.00 FL	*25.00 FL
18	1		*REAR BUMPER	Distorted	1,571.15 FL	*1,571.15 FL
19	1		*REAR BUMPER TOW COVER	Deformed	50.65 FL	*50.65 FL
20	1		*REAR BUMPER REFLECTORS	N/S Cracked	91.60 FL	*45.80 FL
21	1		*REAR BUMPER PDC SENSOR	Damaged (2 PCS ONLY)	947.40 FL	*473.30 FL
22	4		*REAR BUMPER PDC SENSOR HOLDERS (4 PCS)	Not Necessary	234.40 FL	*- FL
23	1		*REAR BUMPER REINFORCEMENT	Bent	800.80 FL	*800.80 FL
24	1		*REAR BUMPER SIDE GARNISH (RETAINERS)	N/S Damaged	384.30 FL	*192.15 FL
25	1		*REAR BUMPER CENTRE INNER GARNISH	Distorted	113.50 FL	*113.50 FL
26	2		*REAR BUMPER BRACKETS	Cracked	384.30 FL	*384.30 FL
27	2		*REAR BUMPER ABSORBERS	Not Necessary	283.70 FL	*- FL
28	1		*REAR BUMPER LOWER LIP	Deformed	285.60 FL	*285.60 FL
29	1		*REAR END PANEL	Dented	903.85 FL	*903.85 FL
30	1		*REAR END PANEL GARNISH	Deformed	178.85 FL	*178.85 FL
31	4		*REAR END PANEL GARNISH CLIPS	Necessary	30.00 FL	*10.00 FL
32	1		*REAR L/H FENDER INNER TRIM BOARD	Not Necessary	368.45 FL	*- FL
33	1		*REAR SPARE TYRE BOARD	Deformed	537.50 FL	*537.50 FL
34	1		*REAR LOWER COVER	Deformed	189.50 FL	*189.50 FL
35	1		*EXHAUST MUFFLER	Not Necessary	2,136.55 FL	*- FL
36	2		*EXHAUST MUFFLER	Bent	133.60 FL	*133.60 FL
37	1		*NECK RESTRAINT SENSOR UNIT	Activated	385.50 FL	*385.50 FL
38	1		*DRIVERS NECK RESTRAINT UNIT	Activated	895.50 FL	*895.50 FL
39	1		*FRONT PAX NECK RESTRAINT UNIT	Activated	895.50 FL	*895.50 FL
40	1		*REAR NO.PLATE WITH COVER	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **19,724.94** **14,191.45**
 - List Item Discount on L Items 10.00/10.00% (\$\$) **1,906.70** **1,381.15**

Total Parts (\$\$) **17,818.24** **12,810.30**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS AS MENTIONED ABOVE ETC	New	1,200.00	1,000.00
2	TO RESPRAY AFFECTED PART	New	1,200.00	1,000.00
3	TO REMOVE AND REFIT FRONT BOTH ASSY TO REPLACE NECK RESTRAINT UNIT	New	300.00	250.00
4	TO RESET FAULT CODE AFTER REPAIR	New	100.00	100.00
5	TO CHECK WIRINGS	New	30.00	30.00
Gross Labour Cost (S\$)			2,830.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >