

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: EST341/18/TP

Your Ref: TP claim against GBA4863X

27-Oct-18

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#08-16

Singapore 409179

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to BMW 730Li no: SDH8988H

Date of accident: 27-10-2018

Parts supply:

- 1 pc Boot *vented*
1 pc Boot emblem - Logo *3m*
1 pc Boot emblem - 730Li *3m*
1 pc Boot centre garnish (chrome) assy *cut*
1 pc Boot reverse camera *new* *Dungd*
1 pc Boot inner lock *Dungd*
1 pc Boot insulator *new*
2 pcs Boot lamps @\$480.50 *LH cut*
2 pcs Boot lamp side rubber @\$105.95 *LH missing*
2 pcs Boot lamp top garnish (chrome) @\$83.85 *2H cut*
2 pcs Boot hinges @\$182.60 *Best*
1 pc Boot weatherstrip *cut*
1 pc Boot inner switch (open & close) *new*
2 pcs Taillamps @\$721.50 *LH cut, RH cut*
2 pcs Taillamp side garnish @\$83.85 *LH cut, RH new*
2 pcs Taillamp lower brackets @\$65.50 *2H cut*
2 pcs Taillamp clips @\$12.50 *new*
1 pc Rear bumper *distorted*
1 pc Rear bumper tow cover *cut*
2 pcs Rear bumper reflectors @\$45.80 *2H cut 2*
4 pcs Rear bumper PDC sensor @\$236.85 *2 pieces dungd*
4 pcs Rear bumper PDC sensor holders @\$58.60 *new*
1 pc Rear bumper reinforcement *Best*
2 pcs Rear bumper side garnish (retainers) @\$192.15 *LH Rungd*
1 pc Rear bumper centre inner garnish *distorted*
2 pcs Rear bumper brackets @\$192.15 *cut*
2 pcs Rear bumper absorbers @\$141.85 *new*
1 pc Rear bumper lower lip *cut*
1 pc Rear end panel *vented*
1 pc Rear end panel garnish *cut*
4 pcs Rear end panel garnish clips @\$7.50 *new*
1 pc Rear L/h fender inner trim board *new*
1 pc Rear *new* spare tyre board *behind*

ESTIMATE

~ 11 800 TBC

Asher.

S\$	1,987.90	✓
	69.50	✓
	61.05	✓
	485.60	✓
	681.10	<i>380/50</i>
	311.85	✓
	160.50	✓
	961.00	<i>480.50</i>
	211.90	<i>109.95</i>
	167.70	<i>83.85</i>
	365.20	✓
	191.65	✓
	524.20	✓
	1,443.00	✓
	167.70	<i>83.85</i>
	131.00	<i>65.50</i>
	25.00	✓
	1,571.15	✓
	50.65	✓
	91.60	<i>45.80</i>
	947.40	<i>473.30</i>
	234.40	✓
	800.80	✓
	384.30	<i>192.15</i>
	113.50	✓
	384.30	✓
	283.70	✓
	285.60	✓
	903.85	✓
	178.85	✓
	30.00	<i>10</i>
	368.45	✓
	537.50	✓
	15,111.90	

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883

Tel: 6747-4810 Fax: 6745-5018

cmmotors@singnet.com.sg

Re: Estimated cost of repair to BMW 730Li no: SDH8988H

Date of accident: 27-10-2018

Parts supply:

Balance b/f:

1 pc Rear lower cover *Reh*

1 pc Exhaust muffler *Reh*

2 pcs Exhaust muffler @\$66.80 *Best*

1 pc Neck restraint sensor unit *Activated*

1 pc Driver's neck restraint unit *Activated*

1 pc Front pax neck restraint unit *Activated*

13811.45 SN: 880
12430.30

15,111.90	
189.50	✓
2,136.55	✗
133.60	-
385.50	-
895.50	✓
895.50	✓
19,748.05	
Less 10%:	(1,974.81)

S/Nett Items

1 pc Rear no. plate with cover (S/Nett) *Reh*

45.00 *

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To respray affected part.

To remove and refit front both assy assy to replace neck restraint unit

To reset fault code after repair.

To check wirings.

2380

1,200.00	1000
1,200.00	1000
300.00	250
100.00	✓
30.00	✓
S\$ 20,648.25	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
H/s 29/10/18.

09 Pags.

total: 1519030

L/S: 12.11C.