

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLK6006U
Chassis No : JHMRC1880GC206736
Model : ODYSSEY 2.4 EX-S 16YM
Owner's Name : LIM HSU AN
Ins Policy No. :
Date of Accident : 28/10/2018

Document No. : SQT18004647
Date : 29. Oct 2018
Customer No. : WZA006
Svc Advisor :
Engine No : K24W72012860
Date | Time : 29. Oct 2018 7:42:33 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:LIM HSE AN OWNER INSURER:LIBERTY INSURANCE ACC DATE:28/10/2018 SURVEYED BY: DATE: REF NO: TP INSURER:AXA INSURANCE TP VEH:SKE 3659 Z						
04715-T6A-000ZZ	FACERR.BUMPER	1 <i>ly</i>	527.00	25	395.25	27.67	422.92
71502-T6A-003ZD	FACER.RR.BUMPER GARNISH	1 <i>x</i>	75.30	25	56.47	3.95	60.42
71507-T6A-003ZB	FACEL.RR.BUMPER GARNISH	1 <i>x</i>	75.30	25	56.47	3.95	60.42
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1 <i>new</i>	18.70	25	14.02	0.98	15.00
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1 <i>new</i>	18.70	25	14.02	0.98	15.00
91505-TM8-003	CLIP,BUMPER	9 <i>new</i>	2.00	25	13.50	0.95	14.45
68100-T6A-Q10ZZ	TAILGATE COMP	1 <i>bt</i>	1049.80	25	787.35	55.11	842.46
74440-T6A-003	WEATHERSTRIPTAILGATE	1 <i>?</i>	115.10	25	86.32	6.04	92.36
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1 <i>?</i>	172.10	25	129.07	9.03	138.10
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1 <i>?</i>	225.90	25	169.42	11.86	181.28
74827-T0A-A00	STOPPERTAILGATE	2 <i>?</i>	3.50	25	5.25	0.37	5.62
66100-T6A-Q00ZZ	PANEL COMP,REAR	1 <i>?</i>	451.70	25	338.77	23.71	362.48
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2 <i>new</i>	17.60	25	26.40	1.85	28.25
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1 <i>new</i>	16.60	25	12.45	0.87	13.32
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1 <i>new</i>	16.60	25	12.45	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD	4 <i>new</i>	3.90	25	11.70	0.82	12.52
73225-TM8-000	RUBBER A WINDSHIELD DAM	1 <i>new</i>	3.60	25	2.70	0.19	2.89
73226-SZW-000	DAMPERSTD 5X5	2 <i>new</i>	8.30	25	12.45	0.87	13.32
76711-T6A-003	CAPPIVOT	1 <i>new</i>	4.70	25	3.52	0.25	3.77
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2 <i>new</i>	60.00		120.00	8.40	128.40
Sum Item					<u>2267.58</u>	<u>158.72</u>	<u>2,426.30</u>

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLK6006U

Chassis No : JHMRC1880GC206736

Model : ODYSSEY 2.4 EX-S 16YM

Owner's Name : LIM HSU AN

Ins Policy No. :

Date of Accident : 28/10/2018

Document No. : SQT18004647

Date : 29. Oct 2018

Customer No. : WZA006

Svc Advisor :

Engine No : K24W72012860

Date | Time : 29. Oct 2018 7:42:33 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1 ³⁰	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1 ¹⁰⁰	120.00		120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT END PANEL	1 [?]	120.00		120.00	8.40	128.40
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1 ²⁸⁰	380.00		380.00	26.60	406.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1 ✓	380.00		380.00	26.60	406.60
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA(N)	1 ✓	380.00		380.00	26.60	406.60
BOMISC1	RESET & CALLBRATE SMART ENTRY SYSTEM(N)	1 ✓	450.00		450.00	31.50	481.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1 ⁵⁶⁰	800.00		800.00	56.00	856.00
BODAMKIT	WINDSCREEN DAM KIT.	1 ¹⁵⁰	180.00		180.00	12.60	192.60
BG02R	REPLACE RR. WINDSCREEN.(N)	1 ✓	560.00		560.00	39.20	599.20
BKRP02M	CUT OFF & RENEW RR PANEL. RENEW ALL DAMAGE PARTS.	1 ¹⁶⁸⁰	7000.00		7000.00	490.00	7490.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1 ⁹⁰⁰	4500.00		4500.00	315.00	4815.00
Sum Labor					14970.00	1,047.90	16,017.90

Survey By

Date & Time

Excess

Status

Signature

Total Amount 17,237.58 1,206.62 18,444.20

Total (Inclusive of GST) **18,444.20**

Resurvey before paint.
Sur @ Kuantan. u n.
5 days.

Printed on 21/11/2018 9:08:53 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: