

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

30-Oct-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6346 C

1 pc	Front bumper Deformed	\$	531.00
1 pc	Front bumper emblem Nec	\$	44.00
2 pcs	Front bumper o/s & o/s side retainer @ \$16.00 n/s x o/s <input checked="" type="checkbox"/> Cra	\$	32.00
2 pcs	Front bumper o/s & o/s upper bracket @ \$16.00 <input checked="" type="checkbox"/> svc	\$	32.00
2 pcs	Front bumper o/s & o/s support bracket @ \$16.00 <input checked="" type="checkbox"/> svc	\$	32.00
1 pc	Front o/s fender Bent	\$	384.00
1 pc	Front o/s fender inner shield Cra	\$	120.00
1 pc	Washer tank <input checked="" type="checkbox"/> svc	\$	47.00
1 pc	Washer tank motor <input checked="" type="checkbox"/> svc	\$	48.00
1 pc	Wheel cover Grazed	\$	116.00
		\$	1,386.00
		Less 10%	\$ 138.60
		\$	1,247.40

S/NETT

1 pc	Front bumper clips nec	\$	48.00
1 set	Front o/s fender inner shield clips nec	\$	24.00
1 pc	Front o/s fender stickers <input checked="" type="checkbox"/> nn	\$	30.00
	Towing Fee	\$	50.00 <input checked="" type="checkbox"/>
	Sundry	\$	50.00 20
	To check wheel alignment	\$	80.00 <input checked="" type="checkbox"/> nn
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same etc	\$	400 650.00
	To putty and spray painting on front bumper, front o/s fender	\$	400.00 560
	To apply rustproofing on the repaired and replaced panels.	\$	80.00 30
		\$	2,659.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

L/sum \$1,600.00 / 3 repair days

Ka Lun 10/10/18
30/10/18 1330 hrs.
3 Days
L/S
After Repair photo