SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3 Pioneer Road North #01-18 Singapore 628457 Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Our Ref:

Date :

25/3/2019

ATTN:THE MOTOR CLAIMS DEPT
AXA INSURANCE (SINGAPORE) PTE LTD

SUPPLEMENTARY ESTIMATE COST OF REPAIR

Vehicle Reg No.	YN9341L	Model / Year	MIT. F	EB21
Date of Accident		Policy No.		
Type of Claim	OWN DAMAGE	Prepared By	SHARON	
Survey By		Chassis No.		
S/NO Description		Qty Unit Price	Ar	mount
1 TO KNOCK FRT PANEL REAR PANEL			\$	150.00
	TO PUTTY & SPRAY PAINTING ON FRT PANEL RR PAN			250.00
The state of the s			\$	400.00