



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD18017069/T1vbs2-1

6 TEMASEK BOULEVARD  
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 15-11-2018



Code : FWD

### 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SGJ 4270A	Veh. Inspected	SJP 3488D
Policy No.	PNPV2018-00009223	Coverage (\$)	0.00
Claim No.	1201800011739	Excess (\$)	0.00
Assign From	LIONEL TAN	Assign Date	30/10/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALLION	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	NZT2603032904	Colour	RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70R14	DUNLOP	6 mm
L/H Front Tyre	185/70R14	DUNLOP	6 mm
R/H Rear Tyre	185/70R14	DUNLOP	6 mm
L/H Rear Tyre	185/70R14	DUNLOP	6 mm

### 4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.
--

### 5. General Information

Accident Date	17/09/2018	Inspection Date	02/11/2018
Survey held at	KEPPEL FELS NORTH GATE 5 PIONEER SECTOR WALK		
Repairer	TK CAR REPAIRS		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------