



CarCrafters Singapore Pte Ltd

48 Toh Guan Road East

#05-155, Enterprise Hub

Singapore 608586

## Repair Estimate

Tel: 6267 9916

Fax: 6267 9313

www.carcrafters.sg

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way #27-01 AXA Tower Singapore 058716

Our Client

GUNNAR STAUTLAND KOLOEN

Date : 30/10/2018

Vehicle Num : SJA1436X

Make/Model : VW SHARAN 2.0 TSI AT 7NE14H3

Chassis No : WVVZZZ7NEV014305

Accident Date : 27 October 2018 @ 2150Hrs

| S/N           | PARTS                                                       | QTY | PRICE       | TOTAL                    |
|---------------|-------------------------------------------------------------|-----|-------------|--------------------------|
| 1             | Rear Bumper <i>re /</i>                                     | 1   | \$ 720.00   | \$ 720.00                |
| 2             | Rear Lower Spoiler <i>CRA /</i>                             | 1   | \$ 158.00   | \$ 158.00                |
| 3             | Attachment Strip <i>?</i>                                   | 1   | \$ 108.00   | \$ 108.00                |
| 4             | Rear Foam Insert <i>?</i>                                   | 1   | \$ 78.00    | \$ 78.00                 |
| 5             | RH Bumper Guide Piece <i>new /</i>                          | 1   | \$ 47.00    | \$ 47.00                 |
| 6             | Rear Towing Cap <i>cut /</i>                                | 1   | \$ 42.00    | \$ 42.00                 |
| 7             | Rear Reinforcement <i>?</i>                                 | 1   | \$ 470.00   | \$ 470.00                |
| 8             | Rear Hatch Door <i>repair</i>                               | 1   | \$ 1,800.00 | \$ 1,800.00              |
| 9             | Rear Weather Strip <i>new /</i>                             | 1   | \$ 196.00   | \$ 196.00                |
| TOTAL PARTS   |                                                             |     |             | \$ 3,619.00              |
| MISCELLANEOUS |                                                             |     |             |                          |
| 1             |                                                             | 1   |             |                          |
| LABOUR        |                                                             |     |             |                          |
| 1             | To remove/ replace/ refit rear bumper & other affected area |     |             | \$ 450 <del>600.00</del> |
| 2             | To putty & respray rear bumper                              |     |             | \$ 500 <del>600.00</del> |
| 3             | To check accident affected wiring system & recover.         |     |             | \$ 50.00                 |
| TOTAL         |                                                             |     |             | \$ 4,869.00              |
| GST 7%        |                                                             |     |             | \$ 340.83                |
|               |                                                             |     |             | \$ 5,209.83              |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: