



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Ref: CC4/ASM18019806/Kga3q2 Date: 01/04/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 4425X	Veh. Inspected	SGX 2961D	
Policy No.	P1794110	Coverage (\$)	0.00	
Claim No.	S8M01113	Excess (\$)	0.00	
Assign From		Assign Date	31/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HARRIER (A)	c.c	1986	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZSU600078503	Colour	METALLIC BLACK	
Odometer	42245 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R19	MICHELIN	4 mm	
L/H Front Tyre	235/55 R19	MICHELIN	4 mm	
R/H Rear Tyre	235/55 R19	MICHELIN	8 mm	
L/H Rear Tyre	235/55 R19	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S & O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/10/2018	Inspection Date	31/10/2018	
Survey held at	160 SIN MING DRIVE# 06-02			
Repairer	MBM WHEELPOWER PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			11 Working Days	