

MBM WHEELPOWER PTE LTD

Your Ref: SJH4425X

Our Ref: SGX2961D

To: AXA

CC

Fax

Not Autharised
1.B.1, 6/1 day & ?
11 days

Date: 30/10/2018

From: Stephanie

Fax: 64525333

Contact: 86865188

Make / Model: TOYOTA HARRIER 2.0 ELEGANCE
AT ABS D/AIRBAG 2WD

Chassis No.: ZSU600078503

Engine No.: 3ZRB784734

Year of Make: 2016

Accident Date: 28 October 2018


ESTIMATE FOR VEHICLE NO. : SGX2961D

DESCRIPTION

QTY

List Price

BONNET	1	\$	<i>Bu</i> 2,290.00 ✓
BONNET INSULATOR	1	\$	<i>Return</i> 895.00 ✓
BONNET INSULATOR CLIPS	10	\$	<i>Me</i> 60.00 ✓
BONNET HINGE LH	1	\$	<i>Bu</i> 115.00 ✓
BONNET HINGE RH	1	\$	<i>Dir</i> 115.00 ✓
BONNET LOCK	1	\$	<i>Bu</i> 166.00 ✓
BONNET STRIKER	1	\$	120.00 ?
BONNET CHROME MOULDING	1	\$	<i>Mit</i> 295.00 ✓
FRONT SUPPORT PANEL	1	\$	<i>Bu</i> 1,385.00 ✓
FRONT SUPPORT PANEL TOP GARNISH	1	\$	<i>CM</i> 460.00 ✓
FRONT SUPPORT PANEL TOP GARNISH CLIPS	10	\$	<i>Me</i> 60.00 ✓
FRONT BUMPER SUPPORT (5202948010)	1	\$	290.00 ?
FRONT BUMPER SUPPORT PANEL BRACKET LH	1	\$	<i>Bu</i> 225.00 ✓
FRONT BUMPER SUPPORT PANEL BRACKET RH	1	\$	225.00 ?
HEADLAMP LH	1	\$	<i>Br</i> 3,403.00 ✓
HEADLAMP RH	1	\$	<i>CM</i> 3,403.00 ✓
FRONT BUMPER (BODY KIT)	1	\$	<i>Br</i> 4,363.00 ✓
FRONT BUMPER CLIPS	15	\$	<i>Me</i> 90.00 ✓
FRONT BUMPER SIDE RETAINER LH	1	\$	<i>CM</i> 105.00 ✓
FRONT BUMPER SIDE RETAINER RH	1	\$	<i>Dir</i> 105.00 ✓
FRONT BUMPER SIDE BRACKET LH	1	\$	<i>Mit</i> 139.00 ✓
FRONT BUMPER SIDE BRACKET RH	1	\$	139.00 ?
RADIATOR GRILLE WITH SEAL HOOD	1	\$	<i>Mit</i> 890.00 ✓
RADIATOR GRILL CLIPS	10	\$	<i>Me</i> 60.00 ✓



mbm wheelpower

	QTY		List Price
FRONT BUMPER LOWER GRILLE	1	\$	CM 315.00 ✓
FRONT BUMPER GUARD (5241148020)	1	\$	CRM 390.00 ✓
FRONT BUMPER FOG LAMP LH	1	\$	M17 580.00 ✓
FRONT BUMPER FOG LAMP GARNISH LH	1	\$	M17 115.00 ✓
FRONT BUMPER FOG LAMP RH	1	\$	M17 580.00 ✓
FRONT BUMPER FOG LAMP GARNISH RH	1	\$	115.00 ?
FRONT BUMPER REINFORCEMENT	1	\$	B1 600.00 ✓
FRONT BUMPER SPONGE CENTER	1	\$	CRM 205.00 ✓
FRONT BUMPER SPONGE LH	1	\$	M17 96.00 ✓
FRONT BUMPER SPONGE RH	1	\$	M17 96.00 ✓
HORNS @ \$165 EACH	2	\$	330.00 ?
RADIATOR ASSY	1	\$	2,150.00 ?
AIRCON CONDENSER	1	\$	1,500.00 ?
FAN SHROUD	1	\$	SL 350.00 X
FAN MOTOR	1	\$	SL 685.00 X
MOTOR FAN (1636128200)	1	\$	SL 210.00 X
MOTOR FAN NO. 2 (1636128210)	1	\$	SL 280.00 X
FRONT LH FENDER	1	\$	B1 1,382.00 ✓
FRONT LH FENDER INNERSHIELD	1	\$	CM 532.00 ✓
FRONT LH FENDER INNERSHIELD CLIPS	10	\$	RM 60.00 ✓
FRONT RH FENDER	1	\$	B1 1,382.00 ✓
FRONT RH FENDER INNERSHIELD	1	\$	Return 532.00 ✓
FRONT RH FENDER INNERSHIELD CLIPS	10	\$	RM 60.00 ✓
FRONT FENDER SEAL LH	1	\$	95.00 ?
FRONT FENDER SEAL RH	1	\$	95.00 ?
FRONT DRIVE SHAFT	1	\$	R 2,466.00 X
FRONT LH SHOCK ABSORBER	1	\$	805.00 ?
FRONT LH WHEEL HUB WITH BEARING	1	\$	686.00 ?
FRONT LH KNUCKLE ARM	1	\$	682.00 ?
FRONT LH LOWER ARM	1	\$	795.00 ?
FRONT LH STABILIZER LINK	1	\$	SL 226.00 X
FRONT STABILIZER BAR	1	\$	SL 402.00 X
FRONT LH TIE ROD END	1	\$	225.00 ?
FRONT RH SHOCK ABSORBER	1	\$	805.00 ?
FRONT RH WHEEL HUB WITH BEARING	1	\$	686.00 ?
FRONT RH KNUCKLE ARM	1	\$	682.00 ?
FRONT RH LOWER ARM	1	\$	795.00 ?
FRONT RH STABILIZER LINK	1	\$	SL 226.00 X
FRONT LH RIM	1	\$	SL 2,343.00 ✓
FRONT RH RIM	1	\$	RM 2,343.00 ✓
FRONT RH TIE ROD END	1	\$	225.00 ?

(Wheel Alignment)

	QTY		List Price
FRONT CROSS MEMBER ASSY (5120112442)	1	\$	3,017.00 ?
FRONT CROSS MEMBER REINFORCEMENT RH (5110742020)	1	\$	<i>n</i> 320.00 <i>x</i>
FRONT CROSS MEMBER REINFORCEMENT LH (5110842020)	1	\$	<i>n</i> 320.00 <i>x</i>
FRONT CROSS ASSY (5710442070)	1	\$	1,120.00 ?
Total:	\$		51,302.00
LESS 25%	\$		(12,825.50)
Parts Total:	\$		38,476.50

SPECIAL NETT

BODY SEALANT	1	\$	<i>n</i> 80.00 <i>301</i>
COOLANT	1	\$	<i>n</i> 80.00 <i>301n</i>
FRONT NUMBER PLATE WITH HOLDER	1	\$	<i>n</i> 50.00 <i>851</i>
FRONT LH TYRE	1	\$	<i>n</i> 500.00 <i>x</i>
FRONT RH TYRE	1	\$	500.00 ?
TOWING FEE	1	\$	(Bill) 120.00 ?

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	2,100.00 <i>11001</i>
TO REMOVE & INSTALL AIRCON COMPONENT INCLUDING CHARGE UP GAS	\$	150.00 <i>1001</i>
TO REMOVE & INSTALL RADIATOR ASSY	\$	100.00 <i>501</i>
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$	80.00 <i>2</i>
TO CONDUCT CHASSIS ALIGNMENT ON CAR O LINER	\$	500.00 <i>2501</i>
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$	200.00 <i>1201</i>
TO REMOVE & REFIT FRONT LH & RH SUSPENSION	\$	500.00 ?
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	120.00 <i>301</i>
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	2,100.00 <i>14001</i>
Total:	\$	45,656.50
7% GST:	\$	3,195.96
Grand Total:	\$	48,852.46

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mbm wheelpower pte ltd

160 SIN MING DRIVE #06-02

SIN MING AUTOCITY

t62628888 f64525333

Company Registration Number : 200204110W