

Mr. Lim

REF:

LPC

ASSIGNMENT

m:

Date: 31.10.2018

Veh No:

SDZ 9002 B

Yr Regn:

10 Sep 2015

Estimated Cost:

Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SDZ 9002 B

Make:

Honda Vezel

C.C. 1496

at Workshop m/s

Ryder Auto

Colour:

Blue

A/C: Insured / Std / NI / NA

of

Blk 1 Kaki Bukit Ave 6 #01-56

Sp. Reading

47353

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

L1584021838

Policy No.

C/No:

RU11101835

Claims No.

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or


(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / ☒ S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

Tyre Size:

F: 215/60/16

R: 215/60/16

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal.

6 mm

R/Bal.

6 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal.

6 mm

L/Bal.

6 mm

Est. Repairs: 4 days Res.: Yes or No

D.O.A.

28/10/18

D.O.I.

31/10/18

Lum Sum: % 3 Val.: Yes or No

Survey held at

Ryder Auto

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

M V 64,000/2

P V 46,700/2

N V 14,300/2

L/S \$ 5,700 200 (5,200)

R(\$ 2,430.43/30%)

TGLim

Nil

5/11/18

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))