

Ryder Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883
 Email: ryderautoworkshop@gmail.com
 Fax: 64815390

ESTIMATE OF REPAIR

(Without Prejudice)

Veh # : SDZ9002B Model : HONDA VEZEL 1.5X CVT

Date Of Accident: 28/10/2018 3P : SLR4064C (Lonpac)

Location : LIM CHU KANG RD OPPOSITE BUS STOP NO: B16

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
	<u>List Items</u>				
1 pc	Rear bumper		900.00	1,240.00	DDV
10 pcs	Rear bumper clips			52.00	NECV
1 pc	Rear bumper insulator			380.00	NEC
2 pcs	Rear bumper o/s & n/s retainer		?/	84.00	BTV
2 pcs	Rear bumper o/s & n/s reflector		?/	190.00	CRV
2 pcs	Rear bumper o/s & n/s corner clips			220.00	NECV
1 pc	Rear tail-gate		1100.00	1,750.00	DDV
1 pc	Rear tail-gate weather-strip		? -	265.00	AITV
1 pc	Rear tail-gate emblem			75.00	NECV
1 pc	Rear tail-gate VEZEL emblem		56.00	85.00	NECV
1 pc	Rear tail-gate inner trim		300.00	395.00	DDV
12 pcs	Rear tail-gate inner trim clips			63.00	NECV
2 pcs	Rear tail-gate o/s & n/s stopper			20.00	NNX
1 pc	Rear tail-gate buzzer		150.00	380.00	CRV
1 pc	Rear tail-gate lock (Upper)			280.00	DDV
1 pc	Rear tail-gate lock (Lower)			44.80	BTV
1 pc	Rear tail-gate lower panel		600.00	780.00	DDV
1 pc	Rear tail-gate lower panel inner trim		?	290.00	CRV
5 pcs	Rear tail-gate lower panel inner trim clips			28.00	NECV
1 pc	Rear window moulding		?	90.00	NNX
14 pcs	Rear window moulding clips		?	87.00	NNX
1 pc	Rear window inner seal			50.00	NNX
	Sub-Total			6,848.80	
	After -20%			5,479.04	

Ryder Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883
Email: ryderautoworkshop@gmail.com
Fax: 64815390

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
	<u>Special Nett Items</u>			60.00	NE LV
1 pc	Rear windscreen sealant			45.00	NEC NNX
1 pc	Rear regn. no. plate			29.00	BRN
1 pc	Rear regn. no. plate bracket			380.00	CUT ✓
1 set	Rear reverse sensor		200.00		
	Sub-Total			514.00	
	<u>Labour</u>				
1	To dismantle rear damaged welding and straighten		800.00	1,800.00	1300
2	To spray painting		800.00	1,600.00	400
3	To remove and refit rear windscreen			200.00	100
4	To remove and replace rear reverse sensor			120.00	60.00
5	To remove and replace rear tail-gate			150.00	NNX
6	To check wiring			100.00	50.00
7	To re-seal anti-rust			200.00	60.00
	Sub-Total			4,170.00	
	Total			10,163.04	
	After -20%			8,130.43	

Chan

Chan San Choon
Director
DipCE, AAE MIMI, MSAE(Aust)

5 days

5/11/18

4s 5700/2.16

Not Authorised

Quotation mark - photo

TG Lim

LKK Auto Consultants