

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorised

ESTIMATE

AXA Insurance Singapore Pte Ltd

8 Shenton Way,

#27-01/02 AXA Tower

Singapore 068811

Attn: Motor Claims Department

11 Sep 87
Resurvey After Paint
18 days

Date : 30/10/2018
Vehicle No : SKW849A
Veh Make/Model : Toyota Corolla Altis 1.6L
YOM : 2015 (16/10/2015)
Chassis No : MR053REH104539492
Date of Accident : 28/10/2018

No	Qty	Description	Amount \$
List Items:-			
1	1	Front windscreen glass	\$ <i>Sm</i> 1,359.60 <i>X</i>
2	1	Front windscreen glass moulding	\$ <i>Mc</i> 143.50 <i>✓</i>
3	1	Windshield cowl cover	\$ <i>Det</i> 613.70 <i>✓</i>
4	1	Front side panel protector (LH)	\$ 63.77 <i>?</i>
5	1	Front side panel protector (RH)	\$ 63.77 <i>?</i>
6	1	Bonnet	\$ <i>Bj</i> 1,226.60 <i>✓</i>
7	2	Bonnet hinge	\$ <i>Bj</i> 131.60 <i>✓</i>
8	1	Bonnet lock	\$ <i>Bj</i> 131.80 <i>✓</i>
9	1	Bonnet lock control cable	\$ <i>45.95</i> 4,545.00 <i>?</i>
10	1	Bonnet lock brace panel	\$ <i>Bj</i> 146.80 <i>✓</i>
11	1	Bonnet insulator pad	\$ <i>Sm</i> 265.80 <i>X</i>
12	10	Bonnet insulator pad clip	\$ <i>Mc</i> 52.00 <i>✓</i>
13	1	Bonnet seal	\$ <i>Sm</i> 53.60 <i>X</i>
14	2	Bonnet stopper	\$ <i>Mc</i> 30.00 <i>✓</i>
15	1	Bonnet stand	\$ <i>M/S</i> 58.30 <i>✓</i>
16	1	Bonnet stand clip	\$ <i>M/S</i> 13.79 <i>✓</i>
17	1	Front RH door	\$ <i>R</i> 1,224.10 <i>X</i>
18	1	Front RH door triangle garnish	\$ <i>D/S</i> 43.30 <i>✓</i>
19	1	Front LH fender	\$ <i>Bu</i> 889.60 <i>✓</i>
20	1	Front LH fender "VVTI" emblem	\$ <i>Mc</i> 34.70 <i>✓</i>
21	1	Front LH fender splash shield	\$ <i>CM</i> 203.10 <i>✓</i>
22	10	Front LH fender splash shield clip	\$ <i>Mc</i> 58.00 <i>✓</i>
23	1	Front RH fender	\$ <i>Bu</i> 889.60 <i>✓</i>
24	1	Front RH fender "VVTI" emblem	\$ <i>Mc</i> 34.70 <i>✓</i>
25	1	Front RH fender splash shield	\$ <i>CM</i> 203.10 <i>✓</i>
26	10	Front RH fender splash shield clip	\$ <i>Mc</i> 58.00 <i>✓</i>
27	1	Front RH fender side panel protector	\$ <i>Bj</i> 98.30 <i>✓</i>
28	1	Radiator grille side air guide	\$ <i>CM</i> 106.80 <i>✓</i>
29	1	LH head lamp	\$ <i>An</i> 2,880.80 <i>✓</i>
30	1	RH headlamp	\$ <i>M/S</i> 2,880.80 <i>✓</i>
Balance b/f			\$ 18,474.53

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date : 30/10/2018
Vehicle No : SKW849A
Veh Make/Model : Toyota Corolla Altis 1.6L
YOM : 2015 (16/10/2015)
Chassis No : MR053REH104539492
Date of Accident : 28/10/2018

No	Qty	Description	Amount \$
		Balance c/f	\$ 18,474.53
31	1	Front grille assy	\$ 631.80
32	1	Front bumper	\$ 627.54
33	1	Front bumper grille	\$ 147.30
34	1	Front bumper fog lamp (LH)	\$ 300.90
35	1	Front bumper fog lamp (RH)	\$ 300.90
36	1	Front bumper fog lamp cover (LH)	\$ 99.01
37	1	Front bumper fog lamp cover (RH)	\$ 99.01
38	2	Front bumper side retainer	\$ 177.00
39	10	Front bumper clip	\$ 58.00
40	1	Front bumper reinforcement	\$ 386.60
41	1	Front bumper sponge	\$ 178.30
42	1	Support panel assy	\$ 1,112.70
43	1	Support panel top garnish	\$ 78.60
44	6	Support panel top garnish clip	\$ 34.80
45	2	Airbag sensor	\$ 1,745.24
46	1	Washer tank	\$ 183.60
47	1	Washer tank motor	\$ 240.80
48	1	Washer tank cap	\$ 20.40
49	1	Radiator spare tank	\$ 161.50
50	1	Air-con condenser assy	\$ 1,121.91
51	2	Air-con condenser top bushing	\$ 31.00
52	2	Air-con condenser bottom bushing	\$ 31.00
53	1	Air-con discharge hose	\$ 506.00
54	1	Air-con suction hose	\$ 444.50
55	1	Radiator	\$ 1,764.80
56	1	Radiator return hose	\$ 384.90
57	1	Radiator return hose T-joint	\$ 88.00
58	1	Radiator top hose	\$ 40.10
59	1	Radiator bottom hose	\$ 42.30
		Balance b/f	\$ 29,513.04

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date : 30/10/2018
Vehicle No : SKW849A
Veh Make/Model : Toyota Corolla Altis 1.6L
YOM : 2015 (16/10/2015)
Chassis No : MR053REH104539492
Date of Accident : 28/10/2018

No	Qty	Description	Amount \$
		Balance c/f	\$ 29,513.04
60	1	Fan blade	\$ 147.90
61	1	Fan motor	\$ 453.90
62	1	Fan cowling	\$ CMF 218.01
63	1	Air cleaner box assy	\$ 964.40
64	1	Air cleaner hose	\$ 112.20
65	1	Air cleaner inlet	\$ 162.20
66	1	Air intake resonator	\$ 101.40
67	1	Battery tray	\$ 139.40
68	1	ABS pump	\$ 4,957.70
69	1	Thermostat cover	\$ 50.13
70	1	Engine mounting (rear)	\$ 225.40
71	1	Engine mounting (front)	\$ Dir 205.40
72	1	Engine mounting (LH)	\$ 226.50
73	1	Engine mounting (RH)	\$ 358.90
74	1	Engine mounting bracket (front)	\$ 190.08
75	1	Engine under cover (center)	\$ CM 531.70
76	1	Engine under cover (LH)	\$ CM 76.40
77	1	Engine under cover (RH)	\$ CM 76.40
78	1	Front side member sub-assy (LH)	\$ 816.60
79	1	Front side member sub-assy (RH)	\$ 816.60
80	1	Engine mounting member sub-assy (center)	\$ Dir 400.90
81	1	Lower arm (LH)	\$ 602.10
82	1	Lower arm (RH)	\$ 602.10
83	1	Gearbox housing	\$ CMF 1,200.00
		Total - List Item	\$ 43,149.36
		Less 25%	\$ 10,787.34
		Total	\$ 32,362.02

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

AXA Insurance Singapore Pte Ltd
8 Shenton Way,
#27-01/02 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Date : 30/10/2018
Vehicle No : SKW849A
Veh Make/Model : Toyota Corolla Altis 1.6L
YOM : 2015 (16/10/2015)
Chassis No : MR053REH104539492
Date of Accident : 28/10/2018

[illegible]

25m
 ?
 X
 201
 30m
 ?
 50m
 60m
 X
 X
 X
 ?

