

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : AXA INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTHQ/TP/1810/019
Policy No:	5045308884-08	Date of Loss:	19/10/2018
Vehicle Reg. No.:	SJY3545A	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SKS8199C
Any Injuries?	no	Contact No:	
Insured/Claimant:	NUR FARHANA BINTE MUSTAFA	Driver:	MOHAMAD HAZMIN BIN ALI

Make/Model:	Toyota, Vios - MR053HY9	Vehicle Reg. Date:	25/08/2010
Vehicle Colour:	RED	Engine Number:	1NZY130773
Chassis No:	MR053HY9305177430	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss HEAD ON

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	2,575.10
Miscellaneous Items	70.00
Labour	390.00
Paintwork Labour	600.00
Towing	0.00
Gross Total(\$\$):	3,635.10
GST 7.00%(\$\$):	254.46
Nett Amount(\$\$):	3,889.56

This claim is handled by: Shaun Toh L M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Allowed
L/K
L/K
the p/b. After
31/10/18

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	BONNET <i>✓</i>	200.00	200.00	+10.00	220.00
2	1	BONNET HINGE LH <i>17X</i>	22.00	22.00	+10.00	24.20
3	1	BONNET HINGE RH <i>17X</i>	22.00	22.00	+10.00	24.20
4	1	FRONT BUMPER <i>713</i>	150.00	150.00	+10.00	165.00
5	1	FRONT BUMPER SIDE RETAINER LH <i>Set</i>	25.00	25.00	+10.00	27.50
6	1	FRONT BUMPER SIDE RETAINER RH <i>Set</i>	25.00	25.00	+10.00	27.50
7	1	FRONT BUMPER EMBLEM <i>ner</i>	25.00	25.00	+10.00	27.50
8	1	FRONT GRILLE CHROME <i>220</i>	110.00	110.00	+10.00	121.00
9	1	FRONT BUMPER CENTRE AIR GRILLE <i>7m</i>	45.00	45.00	+10.00	49.50
10	1	FRONT BUMPER BRACKET LH <i>Set</i>	45.00	45.00	+10.00	49.50
11	1	FRONT BUMPER BRACKET RH <i>Set</i>	45.00	45.00	+10.00	49.50
12	1	FRONT BUMPER REINFORCEMENT <i>7m</i>	90.00	90.00	+10.00	99.00
13	1	FRONT BUMPER INNER SPONGE <i>NTX</i>	45.00	45.00	+10.00	49.50
14	1	FRONT FENDER LH <i>2X</i>		0.00	+10.00	0.00
15	1	FRONT FENDER RH <i>2X</i>		0.00	+10.00	0.00
16	1	FRONT BUMPER LOWER SPOILER <i>De/cu</i>	250.00	250.00	+10.00	275.00
17	1	BONNET LOCK <i>7m</i>	42.00	42.00	+10.00	46.20
18	1	FRONT SUPPORT PANEL <i>DO/Seal</i>	280.00	280.00	+10.00	308.00
19	1	FRONT HEADLAMP LH <i>?</i>	140.00	140.00	+10.00	154.00
20	1	FRONT HEADLAMP RH <i>?</i>	140.00	140.00	+10.00	154.00
21	1	FRONT BUMPER INNER ABSORBER <i>NTX</i>	60.00	60.00	+10.00	66.00
22	1	AIR CON CONDENSER <i>?</i>	160.00	160.00	+10.00	176.00
23	1	RADIATOR <i>?</i>	180.00	180.00	+10.00	198.00
24	1	FRONT SUPPORT PANEL SIDE GARNISH LH <i>?</i>	25.00	25.00	+10.00	27.50
25	1	FRONT SUPPORT PANEL SIDE GARNISH RH <i>?</i>	25.00	25.00	+10.00	27.50
26	1	FRONT BUMPER REINFORCEMENT STAY <i>Right</i>	95.00	95.00	+10.00	104.50
27	1	FRONT BUMPER REINFORCEMENT STAY <i>Left</i>	95.00	95.00	+10.00	104.50
		RH				

Total Parts (S\$) 2,575.10

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT NUMBER PLATE <i>Set</i>	30.00 <i>20</i>	30.00	0.00	30.00
2	1	FRONT WEEKEND SEAL <i>ner</i>	20.00 <i>16.05</i>	20.00	0.00	20.00
3	1	FRONT BUMPER CLIP <i>ner</i>	20.00	20.00	0.00	20.00

Sub Total (S\$) 70.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove & Refit air-con compressor, air-con motor, condenser, pipes & vacuum, including refilling of gas.	60.00	60.00 <i>✓</i>	0.00	60.00
2	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00 <i>20</i>	0.00	30.00
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and	300.00	300.00 <i>✓</i>	0.00	300.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
		Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.				
			Gross Labour Cost (\$\$)			390.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	600.00	600.00	0.00	600.00
			Gross Labour Cost (\$\$)			600.00

< END OF ESTIMATES >