



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

Page 1 / 2
CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

LOW HOCK BENG
BLK 327 JURONG EAST ST 31 #08-170
SINGAPORE 600327

Attention : Motor Claim Department
Contact : 93291903

Estimate : ES003315

Date : 29/10/2018
Vehicle Num. : SJV4015Y
Make/Model : HYUNDAI AVANTE
Chassis/Eng# : KMH DU41BMAU897457
Accident Date : 26/10/2018
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	BOOTLID LOGO		23.30
2.	1	BOOTLID EMBLEM AVANTE		29.40
3.	1	BOOTLID EMBLEM		21.20
4.	1	RH TAILLAMP		288.50
5.	1	REAR BUMPER		447.00
6.	1	REAR BUMPER REINFORCEMENT		270.00
7.	1	REAR BUMPER SPONGE		129.30
8.	1	REAR END PANEL		580.90
List TotalS\$:				1,789.60
20.00% Discount S\$:				357.92
				1,431.68
SPECIAL NETT ITEMS :				
1.	1	REAR BUMPER SPOILER		600.00
2.	1	REVERSE SENSOR		200.00
Special Nett Total S\$:				800.00
LABOUR :				
TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING				100.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

LOW HOCK BENG
BLK 327 JURONG EAST ST 31 #08-170
SINGAPORE 600327

Attention : Motor Claim Department
Contact : 93291903

Page 2 / 2
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003315

Date : 29/10/2018
Vehicle Num. : SJV4015Y
Make/Model : HYUNDAI AVANTE
Chassis/Eng# : KMH DU41BMAU897457
Accident Date : 26/10/2018
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO RUST PROOF ON ACCIDENT DAMAGED PARTS		120.00
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER		1,400.00
		TO CUT OUT /REWELD REAR END PANEL, REPAIR SPARE TYRE		
		PANEL, REAR FENDERS, REAR CHASSIS INCLUDES KNOCKING		
		& REPLACEMENT OF PARTS		750.00
		Labour Total S\$:		2,370.00

E. & O.E.

Total S\$: 4,601.68

for FALCON AIR AUTO SERVICES PTE LTD



FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

Enquire Vehicle Insurer**Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name**

SGK3916Y 26 Oct 2018 / 18:45:00 Successful

A12

AXA INSURANCE PTE LTD

[Previous](#) [OK](#)**Thank you**

Ng Jacqueline has successfully logged out.

Your last login date and time was 27 Oct 2018, 11:30:04.

To return to ONE.MOTORING, please click [here](#)For security reasons, please **CLEAR YOUR CACHE** after each session.**Session Transaction History**

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(S\$)	Log Date/Time
1	Vehicle	SGK3916Y	-	18.32 Insurance Enquiry (GIRO Payment)	7.49	27 Oct 2018 / 11:31:37