

Surveyor:

MPB

DOI:

ASSIGNMENT

31.10.18

Date / Time:

30/10/18

Registered in Meritline:

31.10.18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SH8434L

Name of Insured:

CTP2

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

29.10.18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SKK 81485



INSRS:

WSP:

Tel:

Liability:

RMKS:

Prime Auto claims.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SKK 81485 - X ;
SH8434L, 11/10/18 20:23/18 ; 1st claim

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup)

Call CR:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

FIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

31.10.18

Seek response for liability.

Pending for OI word to remove liability.

25.1.19

III inform that received word from insurer, will submit w/f.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

S\$

(Agreed / Assessed) BOLA S/N No.:

na.

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle / TP

2) Report Format:

TP

3) Survey fee:

7280

25.1.19

Signature: *[Signature]*

REF: III

623911

ASSIGNMENT

From: Date: 31-10-2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKK 8148S

at Workshop m/s Prime Auto

of 6 Benoi Place

Insured

Policy No

Claims No:

Sum Insured


Excess:

(Client's Record)

Make of Veh:

(Policy Condition) 12pm

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKK 8148S Yr Regn: 2013 / May

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf A71-Y cc 139X

Colour: BLACK A/C: Insured / Std / NI / NA

Sp. Reading: 108 477 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZ2ANZDW110679

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ R/Rim / STD A/Rim or

Tyre Size: F: 225/40ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 29/10/18 D.O.I: 31/10/18

Survey held at PRIME AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

4/3 FR

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

01/11/18 refer to email, request limit 1K only. K.I.U first. workshop not continue to repair

MARKET VALUE : \$ 47,500
LTA B. RESERVE : \$ 46,305
NET VALUE : \$ 1,195

4/5: \$1,000 (RED: \$8,184.38 90%)

PLS INCLUDE IN MEDIAN REPORT TO

Date/Time: File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1 \$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6239H
Vehicle Details	
Vehicle No.:	SKK81485
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Nov 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	GOLF A7 1.4 TSI AT BMT 5G14JZ SR HID
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	CHP113429
Chassis No.:	WVWZZZAUZDW110679
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$29,096.00
Original Registration Date:	16 May 2013
First Registration Date:	16 May 2013
Transfer Count:	1
Actual ARF Paid:	\$17,735.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 May 2023
PARF Rebate Amount:	\$12,414.00
Intended COE Rebate Details	
COE Expiry Date:	15 May 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$74,689.00
COE Rebate Amount:	\$33,891.00
Total Rebate Amount:	\$46,305.00

The information contained herein is correct as at 01 Nov 2018

OK

47,500
46,305
1,195

Rasul (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Thursday, 1 November, 2018 9:24 AM
To: 'Alice Leong'
Subject: SKK 8148S

Hi Alice,

As spoken, repair limit to repair this vehicle is 1K only

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 31.10.2018

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SKK8148S VOLKSWAGEN GOLF 1.4 (2013)

To Supply

1) 1pc	Front bumper <i>DE</i>	\$	1,237.92
2) 1set	Front bumper clip <i>na</i>	\$	34.50
3) 1pc	Front bumper left retainer <i>na</i>	\$	30.53
4) 1pc	Front bumper fog lamp garnish <i>8mm</i>	\$	147.14
5) 1pc	Front bumper lower center chrome garnish <i>? X 5mm</i>	\$	370.47
6) 1pc	Front bumper left sensor <i>na</i>	\$	240.18
7) 1pc	Left front fender <i>na</i>	\$	629.91
8) 1pc	Left front fender cowling <i>cut</i>	\$	272.49
9) 1pc	Left front fender cowling clip <i>na</i>	\$	46.00
10) 1pc	Left head lamp <i>cut</i>	\$	2,248.65
11) 1pc	Left headlamp nozzle	\$	192.34
12) 1pc	Left front shock absorber <i>8mm</i>	\$	366.79
13) 1pc	Left front wheel nuckle <i>8mm</i>	\$	709.49
14) 1pc	Left front lower arm <i>8mm</i>	\$	426.36
15) 1pc	Wiper washer tank <i>8mm</i>	\$	232.93

Sub total parts	\$	7,185.70
Less: 10% discount	\$	718.57
	\$	6,467.13

To Supply S.Nett Parts

1) 1pc	Left front sport rim 18" <i>cut</i>	\$	<i>8mm</i> 1,629.45 <i>prize</i>
2) 1pc	Left front tyre <i>cut</i>	\$	<i>210</i> 300.00 <i>70%</i>
3) 1pc	Front no. plate <i>X 1A</i>	\$	38.00

Sub total S.Nett Parts	\$	1,967.45
------------------------	----	----------

L/charges

- | | | |
|--|----|-----------------------|
| -1) To tuff kote | \$ | 50.00 30 |
| 2) To remove & fit left front tyre, replace sport rim and tyre & balance tyre | \$ | 50.00 |
| 3) To focus left front head lamp | \$ | 50.00 30 |
| 4) To remove left front suspension, replace shock absorber, nuckle & lower arm | \$ | 400.00 150 |
| 5) To computerize wheel alignment | \$ | 80.00 60 |
| 6) To remove front bumper, front bumper fog lamp garnish, left front fender, replace the above parts. Align & adjust front bumper & front bumper fog lamp garnish | \$ | 600.00 400 |
| 7) To putty, respray painting front bumper, left front fender. To polish | \$ | 600.00 400 |

Sub total L/charges	\$	1,350.00
Estimated Grand total	\$	9,784.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before respray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Farid
Hp 90010068

5 days

43

31/10/18 @ 1220

Resurvey after repair

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Tuesday, 30 October, 2018 5:13 PM
To: Pei Yee; 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: aliceleong@primeautoclaims.com; Pooi Chin Han Daniel
Subject: RE: PRI REQUEST TO ACCIDENT ON 29.10.2018 INVOLVING SKK8148S & SH8434L
Attachments: img-181030140011.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKK8148S and let us have your report urgently.

This claim will be handled by Ms Daniel.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

30.10.2018 @ 5:31pm
Pei Yee veh not in.

From: Pei Yee [mailto:peiyee@primeautoclaims.com]
Sent: 30 October, 2018 2:06 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: aliceleong@primeautoclaims.com
Subject: PRI REQUEST TO ACCIDENT ON 29.10.2018 INVOLVING SKK8148S & SH8434L
Importance: High

Hi

The above referred

Our client's GIA report enclosed for your retention. Please arrange PRI on urgent basis.

Please inform surveyor to avoid 1230-1330pm lunch hour.

*We select LKK Auto Consultants Pte. Ltd ; Vehicle will be check in at 1200hrs noon on tomorrow (31.10.2018), owner waiting.

***Please arrange PRI soonest possible due to loss of income and loss of rental per day count.**

Thank you.

Thank you & Best regards,

Pei Yee

Prime Auto Claims Service Pte. Ltd.
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

A member of the Prime Group

Disclaimer: This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.



Virus-free. www.avast.com

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Nov 2018 Edit Reg		30 Oct 2018 00:00 Edit Adj Rpt	S\$1,000.00 Edit Estimates	S\$1,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	HO CHUN HWEE, ID: S8626239H								
Vehicle Reg. No.:	SKK8148S	Date of Loss:	29/10/2018 12:00 - :59 [65 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18100914	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SH8434L	Policy No. (Claimant):	2017-V0102703-VDP-E002						
		Excess:							
Repairer:	Prime Auto Claims Service Pte Ltd (HQ) 6 Benoi Place, 629927 Pioneer - Tel: 68610908								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]								
Claimant's Insurer:	Great Eastern General Insurance Limited (HQ) - Tel: +65 248 2888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 12/11/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• III_SG (02/11/2018): Alert - Adj Mandate Approved (S\$0.00) - SKK8148S - Claim Handler: Pooi Chin Han ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKK8148S (MCT18100914)
[SH8434L]
TP
HO CHUN HWEE
Oct 29 2018 12:00PM
[COMFORT TRANSPORTATION PTE LTD]
Prime Auto Claims Service Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	23/01/19 17:42	Odometer Reading					Load JPG	☒	
2	23/01/19 17:42	Chassis Number					Load JPG	☒	
3	23/01/19 17:42	General View					Load JPG	☒	
4	23/01/19 17:42	General View					Load JPG	☒	
5	23/01/19 17:42	General View					Load JPG	☒	
6	23/01/19 17:42	General View					Load JPG	☒	
7	23/01/19 17:42	General View					Load JPG	☒	
8	23/01/19 17:42	General View					Load JPG	☒	
9	23/01/19 17:42	General View					Load JPG	☒	
10	23/01/19 17:42	General View					Load JPG	☒	
11	23/01/19 17:42	General View					Load JPG	☒	
12	23/01/19 17:42	General View					Load JPG	☒	
13	23/01/19 17:42	General View					Load JPG	☒	
14	23/01/19 17:42	General View					Load JPG	☒	
15	23/01/19 17:42	General View					Load JPG	☒	
16	23/01/19 17:42	General View					Load JPG	☒	
17	23/01/19 17:42	General View					Load JPG	☒	
18	23/01/19 17:42	General View					Load JPG	☒	
19	23/01/19 17:42	General View					Load JPG	☒	
20	23/01/19 17:42	General View					Load JPG	☒	
21	23/01/19 17:42	General View					Load JPG	☒	
22	23/01/19 17:42	General View					Load JPG	☒	
23	23/01/19 17:42	General View					Load JPG	☒	
24	23/01/19 17:42	General View					Load JPG	☒	
25	23/01/19 17:42	General View					Load JPG	☒	
26	23/01/19 17:42	General View					Load JPG	☒	
27	23/01/19 17:42	General View					Load JPG	☒	
28	23/01/19 17:43	General View					Load JPG	☒	
29	23/01/19 17:43	General View					Load JPG	☒	
30	23/01/19 17:43	General View					Load JPG	☒	
31	23/01/19 17:43	General View					Load JPG	☒	
32	23/01/19 17:43	General View					Load JPG	☒	
33	23/01/19 17:43	General View					Load JPG	☒	
34	23/01/19 17:43	General View					Load JPG	☒	
35	23/01/19 17:43	General View					Load JPG	☒	
36	23/01/19 17:43	General View					Load JPG	☒	
37	23/01/19 17:43	General View					Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/01/19 17:43	General View	 Load JPG	☒
39	23/01/19 17:43	General View	 Load JPG	☒
40	23/01/19 17:43	General View	 Load JPG	☒
41	23/01/19 17:43	General View	 Load JPG	☒
42	23/01/19 17:43	General View	 Load JPG	☒
43	23/01/19 17:43	General View	 Load JPG	☒
44	23/01/19 17:43	General View	 Load JPG	☒
45	23/01/19 17:43	Reinspection Photo	 Load JPG	☒
46	23/01/19 17:43	Reinspection Photo	 Load JPG	☒
47	23/01/19 17:43	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/10/18 15:11	TP GIA REPORT	 Load PDF	
2	31/10/18 15:11	ACKNOWLEDGEMENT EMAIL TO III DD 30.10.2018	 Load PDF	
3	01/11/18 18:37	TP ESTIMATE - MARKED	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	01/11/18 09:09	Singapore Accident Statement	 Load PDF	
2	23/01/19 16:35	Letter of Demand from Third Party TPD LOD FROM TOMMY CHOO, MARK GO LLC	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No.199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18019828/R1EA3Q2

Date: 28/01/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No: SKK8148S Insured Vehicle No: SH8434L
 Date of Loss: 29/10/2018 Nature of Claim: TP Claim No: MCT18100914

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKK8148S
 Make & Model: VOLKSWAGEN GOLF, 1.4 (A7) TSI (A) Engine No: CHP113429
 Reg. Date: 16/05/2013 (Man. Year: 2013) Chassis No: WWWZZZAUZDW110679
 Colour: Black Odometer: 108477 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,434.58	4,476.16	3,958.42	46.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	970.00	860.00	46.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,264.58	5,446.16	4,818.42	46.94
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	10,264.58	1,000.00	9,264.58	90.26
+ GST 7.00/7.00% (S\$)	718.52	70.00	648.52	90.26
Nett Amount (S\$)	10,983.10	1,070.00	9,913.10	90.26
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 30/10/2018
 Date Inspected: 31/10/2018 Inspected At: Prime Auto Claims Service Pte Ltd (HQ)
 6 Benoi Place
 Singapore 629927
 Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$47,500.00

LTA REIMBURSEMENT VALUE (RV) : \$46,305.00

NETT VALUE : \$1,195.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2019)
Parts: 144	VOLKSWAGEN GOLF 1.4 (A7) TSi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKK8148S)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,237.92 FL	*1,237.92 FL
2	1		*SET FRONT BUMPER CLIP	Necessary	34.50 FL	*34.50 FL
3	1		*FRONT BUMPER LEFT RETAINER	Necessary	30.53 FL	*30.53 FL
4	1		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	147.14 FL	*- FL
5	1		*FRONT BUMPER LOWER CENTER CHROME GARNISH	Serviceable	370.47 FL	*- FL
6	1		*FRONT BUMPER LEFT SENSOR	Necessary	240.18 FL	*240.18 FL
7	1		*LEFT FRONT FENDER	Buckled	629.91 FL	*629.91 FL
8	1		*LEFT FRONT FENDER COWLING	Cut	272.49 FL	*272.49 FL
9	1		*LEFT FRONT FENDER COWLING CLIP	Necessary	46.00 FL	*46.00 FL
10	1		*LEFT HEAD LAMP	Scratched	2,248.65 FL	*2,248.65 FL
11	1		*LEFT HEAD LAMP NOZZLE	Not Necessary	192.34 FL	*- FL
12	1		*LEFT FRONT SHOCK ABSORBER	Not Necessary	366.79 FL	*- FL
13	1		*LEFT FRONT WHEEL NUCKLE	Not Necessary	709.49 FL	*- FL
14	1		*LEFT FRONT LOWER ARM	Not Necessary	426.36 FL	*- FL
15	1		*WIPER WASHER TANK	Not Necessary	232.93 FL	*- FL
16	1		*LEFT FRONT SPORT RIM 18	Not Necessary	1,629.45 FS	*- FS
17	1		*LEFT FRONT TYRE (70%)	Cut	300.00 FS	*210.00 FS
18	1		*FRONT NO PLATE	Not Necessary	38.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,153.15	4,950.18
- List Item Discount on L Items 10.00/10.00% (\$\$)	718.57	474.02
Total Parts (\$\$)	8,434.58	4,476.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TUFF KOTE	New	50.00	30.00
2	TO REMOVE & FIT LEFT FRONT TYRE ,REPLACE SPORT RIM AND TYRE & BALANCE TYRE	New	50.00	50.00
3	TO FOCUS LEFT FRONT HEAD LAMP	New	50.00	30.00
4	TO REMOVE LEFT FRONT SUSPENSION ,REPLACE SHOCK ABSORBER ,NUCKLE & LOWER ARM	New	400.00	0.00
5	TO COMPUTERIZE WHEEL ALIGNMENT	New	80.00	60.00
6	TO REMOVE FRONT BUMPER ,FRONT BUMPER FOG LAMP GARNISH ,LEFT FRONT FENDER ,REPLACE THE ABOVE PARTS.ALIGN & ADJUST FRONT BUMPER & FRONT BUMPER FOG LAMP GARNISH	New	600.00	400.00
7	TO PUTTY,RESPRAY PAINTING FRONT BUMPER ,LEFT FRONT FENDER .TO POLISH	New	600.00	400.00
Gross Labour Cost (\$\$)			1,830.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >