



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 31.10.2018

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SKK8148S VOLKSWAGEN GOLF 1.4 (2013)

To Supply

1) 1pc	Front bumper <i>De ✓</i>	\$	1,237.92
2) 1set	Front bumper clip <i>na ✓</i>	\$	34.50
3) 1pc	Front bumper left retainer <i>na ✓</i>	\$	30.53
4) 1pc	Front bumper fog lamp garnish <i>?</i>	\$	147.14
5) 1pc	Front bumper lower center chrome garnish <i>?</i>	\$	370.47
6) 1pc	Front bumper left sensor <i>na ✓</i>	\$	240.18
7) 1pc	Left front fender <i>na ✓</i>	\$	629.91
8) 1pc	Left front fender cowling <i>cut ✓</i>	\$	272.49
9) 1pc	Left front fender cowling clip <i>na ✓</i>	\$	46.00
10) 1pc	Left head lamp <i>sc ✓</i>	\$	2,248.65
11) 1pc	Left headlamp nozzle <i>?</i>	\$	192.34
12) 1pc	Left front shock absorber <i>?</i>	\$	366.79
13) 1pc	Left front wheel nuckle <i>?</i>	\$	709.49
14) 1pc	Left front lower arm <i>?</i>	\$	426.36
15) 1pc	Wiper washer tank <i>?</i>	\$	232.93

Sub total parts	\$	7,185.70
Less: 10% discount	\$	718.57
	\$	6,467.13

To Supply S.Nett Parts

1) 1pc	Left front sport rim 18" <i>sc ✓</i>	\$	<i>?</i> 1,629.45 <i>price</i>
2) 1pc	Left front tyre <i>cut ✓</i>	\$	<i>210</i> 300.00 <i>70%</i>
3) 1pc	Front no. plate <i>X</i>	\$	38.00

Sub total S.Nett Parts	\$	1,967.45
------------------------	----	----------

L/charges

- | | | |
|--|----|------------------------|
| 1) To tuff kote | \$ | 50.00 30 |
| 2) To remove & fit left front tyre, replace sport rim and tyre & balance tyre | \$ | 50.00 / |
| 3) To focus left front head lamp | \$ | 50.00 30 |
| 4) To remove left front suspension, replace shock absorber, nuckle & lower arm | \$ | 400.00 150? |
| 5) To computerize wheel alignment | \$ | 80.00 60 |
| 6) To remove front bumper, front bumper fog lamp garnish, left front fender, replace the above parts. Align & adjust front bumper & front bumper fog lamp garnish | \$ | 600.00 400 |
| 7) To putty, respray painting front bumper, left front fender. To polish | \$ | 600.00 400 |

Sub total L/charges	\$	1,350.00
Estimated Grand total	\$	<u>9,784.58</u>

Farid
Hp 90010068

5 days

43

31/10/18 @ 1220

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: