

Surveyor:

KSC

DOI:

ASSIGNMENT

30.10.18

Date / Time:

20/10-18

Registered in Merime:

31.10.18

Pre-assign / CCU / FTE

SLQ 8938 F



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

27/10/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L YES / NO)

Insured Liability: %

Final 7 Yes / No

SHB 7806 R

INSRS:
WSP:
Tel:
Liability:
RMKS:

Trans-Cab

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

LINA 15/3/19

After call ltr to OI:

LINA 3/4/19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Repair Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45

S\$ 8,750

(9

days) Reduction:

83

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Wai Yin

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

11a

If NO or B 28, Ass. Lis:

Repair Cost:

(4/455)

S\$ 9,362.50

Loss of Rental (LOR):

S\$ 1,237.25

(13

days) x \$ 98.25

Loss of Use (LOU):

S\$

-

(5

x

days)

Loss of Income (LOI):

S\$

-

(5

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

S\$

7.45

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/Independent)

Legal Cost

S\$

-

Total:

S\$ 10,647.20

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

10,647.20

Name 1:

TRANS-CAB

SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: ☒ Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$320

COPY SENT
17/11/2020

ASS. REC. BY:

REF:

AIGI

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S14B7806R

Yr Regn:

00, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Epica

c.c.

1,991

Colour:

White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng No:

C/No:

KL1LA89RTBB 107393

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

3

mm

L/Bal.

9

mm

D.O.A.

27/10/18

D.O.I.

30/10/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

cls body & N/S RM

The UIC / Chassis frame / Body structure affected due to collision.

Date / Time

Action / Instruction

31/10 File pass to Catherine, battery Plot.

CLIS \$ 87750 / Fed \$ 41,639.16 / 83 %

9 days + 1 PH (deep wall) + 1 Sunday + 2 PRS = 13 days

Date/Time, File Pass to?



Prel. Report

1)

Date/Time, File Return to?



Final Report

2)

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S - RS \$

Fixed

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Trans-cab Auto Services Pte Ltd

AAD1810-276

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7806R

Not Authorized
6/1 Sing & ? 7/12/18
Book Value ? \$8,750

Vehicle No.:

SHB 7806R

Chassis No.:

KL1LA69RJB107393

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

27.10.18

Third Party Insurer :

AIG

PART**LIST**

1	1	Front Bumper	\$	7 1,202.00	✓
2	1	Front Bumper Lower Absorber	\$	SL 180.00	X
3	1	Front Bumper Reinforcement	\$	R 356.00	X
4	1	Front Bumper Retainer RH	\$	SL 102.00	X
5	1	Front Bumper Retainer LH	\$	CM 102.00	✓
6	1	Front Bumper Lower Grille	\$	SL 78.00	X
7	1	Front Bumper Lower Stiffener	\$	DI 134.37	✓
8	1	Front Bumper Bracket LH	\$	R 10.00	X
9	1	Front Bumper Bracket RH	\$	R 10.00	X
10	1	Bumper Fog Lamp Cover RH	\$	SL 32.40	X
11	1	Bumper Fog Lamp Cover LH	\$	MIT 32.40	✓
12	1	Headlamp LH	\$	SL 816.00	X
13	1	Headlamp LH inner panel	\$	R 611.16	X
14	1	Front Shock Absorber Assy RH	\$	SL RT 216.17	X
15	1	Front Shock Absorber Top Mounting RH	\$	SL RT 48.32	X
16	1	Front Lower Arm RH	\$	SL RT 283.00	X
17	1	Front Knuckle Arm RH	\$	SL RT 230.00	X
18	1	Front Hub Unit	\$	SL RT 376.00	X
19	1	Front Disc Brake RH	\$	157.55	?
20	1	Front Strut Bar Bracket RH	\$	235.01	?
21	1	Front Stabilizer Bar	\$	234.00	?
22	1	Front Stabilizer Bar Link RH	\$	51.79	?
23	1	Front Stabilizer Bar Bracket RH	\$	105.75	?
24	1	Front Stabilizer Bar Bush RH	\$	66.00	?
25	1	Front Beam A - Impact RH	\$	214.00	?
26	1	Front Lower Arm LH	\$	RT 283.00	✓
27	1	Front Shock Absorber Assy LH	\$	RT 216.17	✓

Trans-cab Auto Services Pte Ltd

AAD1810-276

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7806R

28	1	Front Shock Absorber Top Mounting LH	\$	Bz	48.32	✓
29	1	Front Knuckle Arm LH	\$	Bz	230.00	—
30	1	Front Hub Unit	\$	Sm	376.00	X
31	1	Front Disc Brake LH	\$	Sm	157.55	X
32	1	Front Strut Bar Bracket LH	\$	N	235.01	X
33	1	Front Stabilizer Bar	\$	Sm	234.00	X
34	1	Front Stabilizer Bar Link LH	\$	Bz	51.79	✓
35	1	Front Stabilizer Bar Bracket LH	\$		105.75	? N N
36	1	Front Stabilizer Bar Bush LH	\$		66.00	? N N
37	1	Front Beam A - Impact LH	\$	N	214.00	} X
38	1	Interm Axle Shaft (Centre)	\$	N	241.14	
39	1	Horn Unit (Low Tone)	\$	Sm	53.46	
40	1	Horn Unit (High Tone)	\$	Sm	53.46	
41	1	Front Support Panel Assy	\$	N	1,222.32	
42	1	Front brace panel	\$	N	134.37	
43	1	Windscreen Washer Tank (Reservoir A-W/Shield)	\$	Sm	62.00	
44	1	Windscreen Washer Tank Motor (Pump Wswa)	\$	Sm	51.00	
45	1	TANK, WIPER HOSE	\$	Sm	21.00	
46	1	Windscreen Washer Tank - Filler Neck	\$	Sm	4.80	
47	1	Radiator Grille (Grille A-Rad)	\$	Sm	367.00	
48	1	Radiator Grille Top Cover	\$	Sm	45.02	
49	1	Fan Blade(A/C)	\$	Sm	536.00	
50	1	Fan Blade(Radiator)	\$	Sm	634.00	
51	1	Aircon Condenser	\$	Sm	600.00	
52	1	Aircon hose - condenser to compressor	\$	Sm	450.00	
53	1	Aircon hose - compressor to evaporator	\$	Sm	624.00	
54	1	Aircon hose - condenser to evaporator	\$	Sm	580.00	
55	1	Aircon compressor - pump	\$	Sm	1,847.95	
56	1	Aircon compressor bracket	\$	N	245.30	
57	1	Aircon condensor bottom bushing	\$	Sm	119.00	
58	1	Air Cleaner Assembly (Cleaner A-Air)	\$	Sm	112.00	
59	1	Air Filter (element A-Air Cleaner)	\$	Sm	39.00	
60	1	Air-cleaner intake duct	\$	Sm	89.25	
61	1	Air-cleaner intake duct hose (top)	\$	Sm	75.85	
62	1	Air intake resonator top (square)	\$	Sm	14.52	
63	1	Air intake resonator (beside fender)	\$	Sm	20.01	

Trans-cab Auto Services Pte Ltd

AAD1810-276

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7806R

64	1	Air intake resonator hose (bottom)	\$	Sm	60.90	X
65	1	Air intake resonator tank top bracket	\$	Sm	45.00	X
66	1	Resonator A-A/CL	\$	Bu	137.00	✓
67	1	Front Fender LH	\$	Bu	837.60	✓
68	1	Front Fender Liner LH	\$	MV	47.00	✓
69	1	Fender Insulation LH	\$	Sm	39.00	X
70	1	Front Fender Inner Wheel House Panel LH	\$	R	1,437.00	X
71	1	Front Door RH	\$	Bu	1,133.00	✓
72	1	Front Door Glass Guide RH Chrome Moulding	\$	Sm	60.00	✓
73	1	Front Door Outer Moulding	\$	Bu	220.00	✓
74	1	Front Door Outer Handle	\$	Sm	125.00	X
75	1	Front Door Handle Support	\$	Sm	3.00	X
76	1	Front Door outer handle inner seal	\$	Sm	89.15	X
77	1	Front Door outer key lock	\$	Sm	25.00	X
78	1	Front Door Hinge Upper	\$	R	65.00	X
79	1	Front Door Hinge Lower	\$	R	65.00	X
80	1	Front Door inner lock	\$	Tu	586.00	✓
81	1	Front Door Inner Lock Latch RH	\$	R	206.00	X
82	1	Front Door Check / Arrestor	\$	Sm	67.50	X
83	1	Front Door Weatherstrip RH	\$	Sm	138.79	X
84	1	Front Door glass channel weatherstrip	\$	Sm	160.00	X
85	1	Front Door inner trim board	\$	Sm	455.69	X
86	1	Front Door window glass	\$	Sm	456.12	X
87	1	Front Door Power Window Motor (Master) RH	\$	Tu	284.97	✓
88	1	Front Door power window motor switch	\$	Sm	145.00	X
89	1	Front Door Window Regulator Gear RH	\$	Bu	84.58	✓
90	1	Front Door Outer Pillar Panel RH	\$	R	715.00	X
91	1	Front Door Pillar Inner Panel RH	\$	R	850.00	X
92	1	Front Door Center Pillar Panel RH	\$		698.15	? ^{NN}
93	1	Front Side View Mirror Assy RH	\$	Sm	1,191.00	X ^X
94	1	Rear Door RH (Panel A-RR DR LH)	\$	Bu	1,133.00	✓
95	1	Rear door weatherstrip - Inner	\$	Sm	41.40	X
96	1	Rear door weatherstrip - 2nd Frame	\$	Sm	25.90	X
97	1	Rear door top hinge	\$	Bu	35.00	✓
98	1	Rear door bottom hinge	\$	Bu	35.00	✓
99	1	Rear door inner lock	\$	Tu	425.00	✓

Trans-cab Auto Services Pte Ltd**AAD1810-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7806R

100	1	Rear door check / arrestor	\$	Sn	65.00	
101	1	Rear door lock striker / latch	\$	Sn	206.00	
102	1	Rear Door Inner Lock Latch RH	\$	Sn	206.00	
103	1	Rear door outer weatherstrip moulding	\$	Sn	85.00	
104	1	Rear Door Glass Guide RH Chrome Moulding	\$	Sn	60.00	
105	1	Rear Door Outer Moulding	\$	Sn	220.00	
106	1	Rear Door Outer Handle	\$	Sn	125.00	
107	1	Rear Door Handle Support	\$	Sn	3.00	
108	1	Rear Door outer handle inner seal	\$	Sn	89.15	
109	1	Rear Door outer key lock	\$	Sn	25.00	
110	1	Rear Door Weatherstrip RH	\$	Sn	138.79	
111	1	Rear Door glass channel weatherstrip	\$	Sn	160.00	
112	1	Rear Door inner trim board	\$	Sn	455.69	
113	1	Rear Door window glass	\$	Sn	456.12	
114	1	Rear Door Power Window Motor (Master) RH	\$	Th	284.97	✓
115	1	Rear Door power window motor switch	\$	Sn	145.00	X
116	1	Rear Door Window Regulator Gear RH	\$	By	84.58	—
117	1	Rear Door Outer Pillar Panel RH	\$	n	715.00	X
118	1	Rear Door Pillar Inner Panel RH	\$	n	850.00	X
119	1	Rear Door Center Pillar Panel RH	\$		698.15	? X NH
120	1	Side Rocker Panel Garnish RH	\$	nd	236.40	✓
121	1	Front Side View Mirror Assy LH	\$	Sn	1,191.00	X
122	1	Rear Fender RH	\$	n	1,145.00	X
123	1	Rear Fender Inner Trim RH	\$	Sn	418.44	X
124	1	Front Side Rocker Panel Garnish RH	\$	Sn	236.40	X
125	1	Front Side Rocker Panel Outer RH	\$	n	600.00	X
126	1	Front Side Rocker Panel Inner RH	\$	n	519.30	X
144	1	Front Side Rocker Panel Garnish LH	\$	cm Sn	236.40	✓
145	1	Front Side Rocker Panel Outer LH	\$	n	600.00	X
146	1	Front Side Rocker Panel Inner LH	\$	n	519.30	X
147	1	Rear Bumper	\$	n	1,202.00	X

TOTAL	\$	40,443.40
10%	\$	4,044.34
	\$	36,399.06

Trans-cab Auto Services Pte Ltd

AAD1810-276

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7806R

Special Nett

1	1 Set	Front Bumper Fastener Clip	\$	nn	24.00	✓
2	1 Set	Radiator Grille clip	\$	nn	35.00	X
3	1 Set	Radiator Grille Top Cover Clip	\$	nn	10.00	X
4	1 Set	Louver Cowl Top clip	\$	nn	30.00	X
5	1 Set	Front Fender Liner clip LH	\$	nn	30.00	X
6	1 Set	Front Fender Liner clip RH	\$	nn	30.00	X
7	1	Front Fender RR Bracket RH	\$	nn	7.10	X
8	1	Front left tyre	\$	nn	220.00	30/55
9	1	Front Tyre Rim LH	\$	nn	350.00	50/55
10	1	Front door sticker 'Trans-cab'	\$	nn	80.00	60/55
11	1Set	Rear Fender Inner Trim Clip RH	\$	nn	30.00	X
12	1	Rear door sticker '6555-3333'	\$	nn	80.00	60/55
13	1	Front right door sticker 'Trans-cab'	\$	nn	80.00	60/55
14	1	Front left door sticker 'Trans-cab'	\$	nn	80.00	X
15	2	Front Windscreen Sealant	\$	nn	100.00	X
16	1	Front Windscreen Inner Sponge Seal	\$	nn	100.00	X
17	1Set	Rear Bumper Fastener Clip	\$	nn	44.00	X
18	1Set	Rear Fender Inner Trim Clip RH	\$	nn	30.00	X
19	1Set	Rear Bumper End Dust Cover Clip	\$	nn	30.00	X

TOTAL	\$	1,390.10
--------------	-----------	-----------------

TOTAL PARTS	\$	37,789.16
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	40/
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	1400/
Putty and spray painting of the affected portion.	\$	4,500.00	1400/

Trans-cab Auto Services Pte Ltd**AAD1810-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7806R

Towing Fees.	\$	120.00	50%
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	200%
To check steering geometry and computer wheel alignment	\$	220.00	60%
To rust-proofing of the affected areas.	\$	170.00	90%
To transfer of tire, rim and on wheel balancing.	\$	170.00	} 20%
To transfer of tire, rim and on wheel balancing.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	<i>Repair</i> 220.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	340.00	60%
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 340.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	180.00	60%
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1810-276**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7806R

To transfer of bonnet fittings, attachment and
perform water seepage test.

\$ *~ 170.00* X

To Remove And Refit Front W/Screen Glass To Facilitate
Bodywork Repair.

\$ *~ 440.00* X**TOTAL** \$ **12,600.00****Over All Total** \$ **50,389.16****Repair Days (Lump Sum)***15 DAYS**9 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary part(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	5HB7806R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Oct 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1456952K
Chassis No.:	KL1LA69RJ88107393
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,578.00
Original Registration Date:	28 Aug 2012
First Registration Date:	28 Aug 2012
Transfer Count:	0
Actual ARF Paid:	\$14,578.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Aug 2020
PARF Rebate Amount:	\$9,475.00

Intended COE Rebate Details

COE Expiry Date:	27 Aug 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$48,892.00
COE Rebate Amount:	\$11,171.00
Total Rebate Amount:	\$20,646.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Oct 2018

OK

Khanchna (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Monday, 26 August 2019 12:14 PM
To: Khanchna (LKK Auto)
Subject: FW: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Best Regards,

Cecilia Chong | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Cecilia Chong (LKK Auto)
Sent: Friday, 12 April 2019 3:40 PM
To: Yee Chee Kiong <yeeck3@hotmail.sg>
Subject: RE: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Dear Mr Yee,

Regarding about speeding issue, we are not able to do anything about it. As we are just a loss adjuster and assessor firm appointed by your vehicle insurance company on property damage. Therefore we only base on motor accident guidelines to see who have the right of way to settle the matter. Moreover third party is driving on straight road and you are actually turning to main road and have to be assure that the road is clear before you can turn in to the main road. Hope you can understand. Thanks

Best Regards,

Cecilia Chong | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yee Chee Kiong [mailto:yeeck3@hotmail.sg]
Sent: Friday, 12 April 2019 3:33 PM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Subject: RE: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Hi Cecilia

Due to the taxi travelling in high speed on slope up road which is about 50 meters away. The sudden surfaced taxi in high speed resulted the accident. the road speed limit on this part of the road is below 70. The impact of the taxi's damages had explained it was a fast moving vehicle. In addition, the taxi driver did not pay attention to the road condition or he engrossed in conversation with his passenger whilst driving. Regards

Yee Chee Kiong

From: Cecilia Chong (LKK Auto) [CeciliaChong@lkkauto.com]

Sent: Friday, April 12, 2019 2:25 PM
To: Yee Chee Kiong
Subject: RE: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Dear Yee Chee Kiong,

After viewing the video footage, the liability is really not in our favour. As you are making a turn to the main road. Under the Motor Accident guideline, the liability is down, under BOLA S9a. And as seen in the video footage, Third Party is already coming close to you before you accelerate your vehicle.

Thanks

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | <mailto:BevanLim@lkkauto.com%7C> fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yee Chee Kiong [mailto:yeeck3@hotmail.sg]

Sent: Friday, 12 April 2019 2:07 PM

To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

Subject: Re: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Yee Chee Kiong has shared a OneDrive file with you. To view it, click the link below.

[https://r1.res.office365.com/owa/prem/images/dc-mpg_20.png]<https://1drv.ms/u/s!Alr1skaMHn4woDAHrumdk-oTwEDS>

REC_2018_10_27_11_49_31_F_Trim.mp4<https://1drv.ms/u/s!Alr1skaMHn4woDAHrumdk-oTwEDS>

Hi Cecilia

Due to file is too large, I uploaded to cloud. Let me know if it is able to open.
Grateful if you could help resume my NCB to 50%.

Yee Chee Kiong

From: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com<mailto:CeciliaChong@lkkauto.com>>

Sent: Thursday, April 11, 2019 2:07 PM

To: Yee Chee Kiong

Subject: RE: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Dear Mr Yee,

I unable to open the video clip from your Mircrosoft word. Kindly please attached the video clip file in the email. Thanks

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong @lkkauto.com | <mailto:BevanLim@lkkauto.com%7C> fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yee Chee Kiong [mailto:yeeck3@hotmail.sg]

Sent: Thursday, 11 April 2019 1:43 PM

To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com<mailto:CeciliaChong@lkkauto.com>>

Subject: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Yee Chee Kiong has shared a OneDrive file with you. To view it, click the link below.

[https://r1.res.office365.com/owa/prem/images/dc-docx_20.png]<https://1drv.ms/w/s!Alr1skaMHn4woC_faQnru4K5G3fx>

Accident SLQ8938K 3a 1.docx<https://1drv.ms/w/s!Alr1skaMHn4woC_faQnru4K5G3fx>

Dear Cecilia Chong

I refer to your letter CC3/AIG18019829/Kha3 dd 3 April 2019.

I enclose the letter with photos to Jeffrey Say Kiat Ng on 14 January 2019 for your reference.

Yours sincerely

Yee Chee Kiong

Print Received Message

This mail is associated with :

***SHB7806R (8108080374SG)
[SLQ8938K]**

TP

TRANS-CAB SERVICES PTE LTD

Oct 27 2018 11:00AM

[YEE CHEE KIONG]

Trans-cab Auto Services Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 22/11/2019 10:09 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10348.20) - SHB7806R - Claim Handler: Foo, Chit Yan

Approved:10348.20:COR \$9,362.50 rental \$978.25 LTA \$7.45 Total 10,348.20 LOI claimed under BI.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 25 November 2019 3:27 PM
To: Ng Wai Yin; claims@transcab.com.sg
Cc: Admin A
Subject: Offer - Mva between SHB 7806R & SLQ 8938K (AIG) on 27/10/2018

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 9,362.50
2. Loss of Rental (13 days x \$75.25)	\$ 978.25
3. LTA/GIA Search Fee	\$ 7.45
TOTAL	\$ 10,348.20

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 26 November 2019 9:22 AM
To: Khanchna (LKK Auto)
Cc: Admin A; claims@transcab.com.sg
Subject: RE: Offer - Mva between SHB 7806R & SLQ 8938K (AIG) on 27/10/2018 -- AAD1810-276
Attachments: AAD1810-276 - RENTAL LETTER.pdf

WITHOUT PREJUDICE

Dear Khanchna

Refer to the below offer making to us, I realize that we had submitted wrong amount for the rental rate.

Actual rental rate should be \$98.25 instead of \$75.25.

Enclosed is our rental letter for your investigation.

Hope you can review this offer and let us have your revised of the rental rate.

Thank You

Best Regards,

Ng Wai Yin

Finance Department

TEL: 6603 1265 Ext.308

**** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg*

TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63

Singapore 569111

Tel: 6287 6666 Fax: 6287 7764

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]
Sent: Monday, 25 November, 2019 3:27 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; claims@transcab.com.sg
Cc: Admin A <admin-a@lkkauto.com>
Subject: Offer - Mva between SHB 7806R & SLQ 8938K (AIG) on 27/10/2018

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

Re seek on LOR

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	31 Oct 2018 15:18	Cim Veh Model Changed	(204923) CHEVROLET EPICA 2.0 2.0DSL AT ABS D/AB 2WD 4DR TUR (A).	[A] HOW MEI KWAN
2	31 Oct 2018 15:18	Cim Created	Reg No: SHB7806R. Acct Date: 2018/10/27. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Trans-cab Auto Services Pte Ltd ()	[A] HOW MEI KWAN
3	31 Oct 2018 15:18	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
4	31 Oct 2018 15:18	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/12	[A] HOW MEI KWAN
5	31 Oct 2018 15:18	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
6	31 Oct 2018 15:18	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
7	31 Oct 2018 15:19	Label Added	(23):Express.	[A] HOW MEI KWAN
8	31 Oct 2018 15:19	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] HOW MEI KWAN
9	22 Oct 2019 11:22	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
10	22 Oct 2019 11:22	Cim Dtl Modified	JPJ Reg. Date: -> 2012/08/28.	[A] Elaine Kuan Hwa Meen
11	22 Oct 2019 11:22	Cim Details Notified		[A] Elaine Kuan Hwa Meen
12	05 Nov 2019 10:22	Adj Mandate Request	CurReq:10998.20:BOLA 11 a - Insured making U-turn. Liability down against Insured. **9 days recommendation for repair + 1 Sundays + 2 PRS + 1 PH = 13 days	[A] Khanchna Pothura
13	22 Nov 2019 10:08	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/11/12	[I] Loh, Chee-Heng
14	22 Nov 2019 10:08	Adj Mandate Set	Approved:10998.20.	[I] Loh, Chee-Heng
15	22 Nov 2019 10:09	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/11/12. Mandate Remarks: COR \$9,362.50 rental \$978.25 LTA \$7.45 Total 10,348.20 LOI claimed under BI.	[I] Loh, Chee-Heng
16	22 Nov 2019 10:09	Adj Mandate Set	Approved:10348.20:COR \$9,362.50 rental \$978.25 LTA \$7.45 Total 10,348.20 LOI claimed under BI.	[I] Loh, Chee-Heng
17	03 Dec 2019 14:12	Adj Mandate Request	CurReq:10647.20:Third party submitted amended Loss of Rental supporting documents and is re-seeking LOR for \$98.25.	[A] Khanchna Pothura

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No.	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Billable)	Ref 1	Ref 2	Amount
2257182	26 Aug 2019 11:39:52	Video Upload	Motor	AIG Asia Pacific Insurance Pte. Ltd.	AIG Asia Pacific Insurance Pte. Ltd. (SG)	SHB7806R	Khanchna Pothura	xx.xx
2320911	22 Oct 2019 11:22:44	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SHB7806R	SLQ8938K	11.77

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 21 January 2020 8:38 AM
To: 'Ng Wai Yin'
Cc: Admin A
Subject: RE: Offer - Mva between SHB 7806R & SLQ 8938K (AIG) on 27/10/2018 -- AAD1810-276

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 9,362.50
2. Loss of Rental (13 days x \$98.25)	\$ 1,277.25
3. LTA/GIA Search Fee	\$ 7.45
TOTAL	\$ 10,647.20

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Wishing you a Happy and Prosperous Lunar New Year



Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 23 December 2019 2:19 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: FW: Offer - Mva between SHB 7806R & SLQ 8938K (AIG) on 27/10/2018 -- AAD1810-276

Khanchna (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Monday, 26 August 2019 12:14 PM
To: Khanchna (LKK Auto)
Subject: FW: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Best Regards,
Cecilia Chong | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Cecilia Chong (LKK Auto)
Sent: Friday, 12 April 2019 3:40 PM
To: Yee Chee Kiong <yeeck3@hotmail.sg>
Subject: RE: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Dear Mr Yee,

Regarding about speeding issue, we are not able to do anything about it. As we are just a loss adjuster and assessor firm appointed by your vehicle insurance company on property damage. Therefore we only base on motor accident guidelines to see who have the right of way to settle the matter. Moreover third party is driving on straight road and you are actually turning to main road and have to be assure that the road is clear before you can turn in to the main road. Hope you can understand. Thanks

Best Regards,
Cecilia Chong | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yee Chee Kiong [mailto:yeeck3@hotmail.sg]
Sent: Friday, 12 April 2019 3:33 PM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Subject: RE: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Hi Cecilia

Due to the taxi travelling in high speed on slope up road which is about 50 meters away. The sudden surfaced taxi in high speed resulted the accident. the road speed limit on this part of the road is below 70. The impact of the taxi's damages had explained it was a fast moving vehicle. In addition, the taxi driver did not pay attention to the road condition or he engrossed in conversation with his passenger whilst driving. Regards

Yee Chee Kiong

From: Cecilia Chong (LKK Auto) [CeciliaChong@lkkauto.com]

Sent: Friday, April 12, 2019 2:25 PM
To: Yee Chee Kiong
Subject: RE: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Dear Yee Chee Kiong,

After viewing the video footage, the liability is really not in our favour. As you are making a turn to the main road. Under the Motor Accident guideline, the liability is down, under BOLA S9a. And as seen in the video footage, Third Party is already coming close to you before you accelerate your vehicle.

Thanks

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | <mailto:BevanLim@lkkauto.com%7C> fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yee Chee Kiong [mailto:yeeck3@hotmail.sg]

Sent: Friday, 12 April 2019 2:07 PM

To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

Subject: Re: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Yee Chee Kiong has shared a OneDrive file with you. To view it, click the link below.

[https://r1.res.office365.com/owa/prem/images/dc-mpg_20.png]<https://1drv.ms/u/s!Alr1skaMHn4woDAHrumdk-oTwEDS>

REC_2018_10_27_11_49_31_F_Trim.mp4<https://1drv.ms/u/s!Alr1skaMHn4woDAHrumdk-oTwEDS>

Hi Cecilia

Due to file is too large, I uploaded to cloud. Let me know if it is able to open.

Grateful if you could help resume my NCB to 50%.

Yee Chee Kiong

From: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com<mailto:CeciliaChong@lkkauto.com>>

Sent: Thursday, April 11, 2019 2:07 PM

To: Yee Chee Kiong

Subject: RE: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Dear Mr Yee,

I unable to open the video clip from your Mircrosoft word. Kindly please attached the video clip file in the email. Thanks

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong @lkkauto.com | <mailto:BevanLim@lkkauto.com%7C> fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yee Chee Kiong [mailto:yeeck3@hotmail.sg]

Sent: Thursday, 11 April 2019 1:43 PM

To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com<mailto:CeciliaChong@lkkauto.com>>

Subject: Accident Involving SLQ8938K & SHB7806R On 27 October 2018

Yee Chee Kiong has shared a OneDrive file with you. To view it, click the link below.

[https://r1.res.office365.com/owa/prem/images/dc-docx_20.png]<https://1drv.ms/w/s!Alr1skaMHn4woC_faQnru4K5G3fx>

Accident SLQ8938K 3a 1.docx<https://1drv.ms/w/s!Alr1skaMHn4woC_faQnru4K5G3fx>

Dear Cecilia Chong

I refer to your letter CC3/AIG18019829/Kha3 dd 3 April 2019.

I enclose the letter with photos to Jeffrey Say Kiat Ng on 14 January 2019 for your reference.

Yours sincerely

Print Received Message

This mail is associated with :

***SHB7806R (8108080374SG)
[SLQ8938K]**

TP

TRANS-CAB SERVICES PTE LTD

Oct 27 2018 11:00AM

[YEE CHEE KIONG]

Trans-cab Auto Services Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 15/01/2020 11:47 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10647.20) - SHB7806R - Claim Handler: Foo, Chit Yan

Approved:10647.20:COR \$9,362.50 Rental \$1,179-1,277.25 LTA \$7.45 Total 10,548.95-10,647.20 LOI claimed under BI. *Subj to Final Repair Bill, Rental Agreement, LTA Search Bill in order

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Oct 2018 Edit Reg		30 Oct 2018 00:00 Edit Adj Rpt	S\$8,750.00 Edit Estimates	S\$8,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	YEE CHEE KIONG, ID: S0166508A		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHB7806R	Date of Loss:	27/10/2018 11:00 - :59 [73 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8108080374SG	Policy/Cover Note No.:	1700027062 (Comprehensive) Coverage: 26/07/2018 - 25/07/2019
Vehicle Reg. No. (Insured):	SLQ8938K	Policy No. (Claimant):	VPX/P1680520
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd () No 2 Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 12/11/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)





































- AIG_SG_EXPRESS (15/01/2020): Alert - Adj Mandate Approved (S\$10647.20) - SHB7806R - Claim Handler: Foo, Chit ...
- AIG_SG_EXPRESS (22/11/2019): Alert - Adj Mandate Approved (S\$10348.20) - SHB7806R - Claim Handler: Foo, Chit ...
- AIG_SG_EXPRESS (22/11/2019): Alert - Adj Mandate Approved (S\$10998.20) - SHB7806R - Claim Handler: Foo, Chit ...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB7806R (8108080374SG)
[SLQ8938K]
TP
TRANS-CAB SERVICES PTE LTD
Oct 27 2018 11:00AM
[YEE CHEE KIONG]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser <input type="button" value="v"/>	
Video				
			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/08/19 11:39	Video - Accident (Insured)	 Load MP4	
Letters/Correspondences				
			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	 Edit	
Photos/Images				
			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
2	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
3	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
4	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
5	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
6	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
7	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
8	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
9	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
10	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
11	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
12	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
13	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
14	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
15	26/08/19 11:43	Chassis Number	 Load JPG <input checked="" type="checkbox"/>	
16	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
17	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
18	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
19	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
20	26/08/19 11:43	General View	 Load JPG <input checked="" type="checkbox"/>	
21	26/08/19 11:44	General View	 Load JPG <input checked="" type="checkbox"/>	
22	26/08/19 11:44	General View	 Load JPG <input checked="" type="checkbox"/>	
23	26/08/19 11:44	General View	 Load JPG <input checked="" type="checkbox"/>	
24	26/08/19 11:44	General View	 Load JPG <input checked="" type="checkbox"/>	
25	26/08/19 11:44	General View	 Load JPG <input checked="" type="checkbox"/>	
26	26/08/19 11:44	General View	 Load JPG <input checked="" type="checkbox"/>	
27	26/08/19 11:44	General View	 Load JPG <input checked="" type="checkbox"/>	
Documentation				
			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/10/18 18:24	TP ESTIMATE - MARKED	 Load PDF	
2	31/10/18 18:24	TP GIA REPORT	 Load PDF	
3	26/08/19 11:42	LETTER TO OI	 Load PDF	
4	05/11/19 10:17	TP LOD, FINAL REPAIR INVOICE, LTA SEARCH, RENTAL SUPPORTING DOCS	 Load PDF	
5	03/12/19 14:08	AMENDED RENTAL LETTER	 Load PDF	
6	09/01/20 09:12	Email from Third party workshop	 Load PDF	
7	18/02/20 11:46	WORKSHOP INVOICE	 Load PDF	
8	18/02/20 11:46	AUTHORISATION TO ACT FORM	Load PDF	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
9	18/02/20 11:46	Release Voucher		Load PDF
10	18/02/20 11:46	RENTAL RECEIPT		Load PDF
11	18/02/20 11:46	RENTAL MILEAGE		Load PDF
12	18/02/20 11:46	LTA SEARCH		Load PDF
13	18/02/20 11:46	LOD		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	01/11/18 11:00	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLQ8938K (Insd veh)	Model:	CHEVROLET EPICA 2.0
	SHB7806R (TP veh)		2.0DSL AT ABS D/AB 2WD
Date of Accident:	27/10/2018		4DR TUR (A)

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	53,916.40
Final Repair Cost	:	\$	9,362.50
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,277.25 13 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	10,647.20

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Trans-cab Auto Services Pte Ltd	:	\$ 10,647.20
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

18 Feb
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18019829/KKA3Q2

Date: 18/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700027062
 Claimant SHB7806R Insured Vehicle No: SLQ8938K
 Vehicle No: SHB7806R
 Date of Loss: 27/10/2018 Nature of Claim: TP Claim No: 8108080374SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB7806R
 Make & Model: CHEVROLET EPICA, 2.0 2.0DSL AT ABS D/AB 2WD 4DR TUR (A) Engine No: Z20S1456952K
 Reg. Date: 28/08/2012 (Man. Year: 2011) Chassis No: KL1LA69RJBB107393
 Colour: Red/White Odometer: 0 km
 Engine Capacity: 1991 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Giti 3 mm Rear Left Side: Giti 9 mm
 Front Right Side: Giti 9 mm Rear Right Side: Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,789.16	7,610.49	30,178.67	79.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,600.00	3,380.00	9,220.00	73.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,389.16	10,990.49	39,398.67	78.19
Approved Total (Overridden) (S\$)		8,750.00		
(S\$)	50,389.16	8,750.00	41,639.16	82.64
+ GST 7.00/7.00% (S\$)	3,527.24	612.50	2,914.74	82.64
Nett Amount (S\$)	53,916.40	9,362.50	44,553.90	82.64
+ Car Rental (13.0 x S\$98.25/day) (S\$)		1,277.25		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,647.20		

INSPECTION

Date of Assignment: 30/10/2018
 Date Inspected: 30/10/2018 Inspected At: Trans-cab Auto Services Pte Ltd
 No 2 Ang Mo Kio Street 63
 Singapore 569111
 Estimated Period of Repair: 9.0 days

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,202.00 FL	*1,202.00 FL
2	1		*FRONT BUMPER LOWER ABSORBER	Serviceable	180.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	356.00 FL	*- FL
4	1		*FRONT BUMPER RETAINER RH	Serviceable	102.00 FL	*- FL
5	1		*FRONT BUMPER RETAINER LH	Cracked	102.00 FL	*102.00 FL
6	1		*FRONT BUMPER LOWER GRILLE	Serviceable	78.00 FL	*- FL
7	1		*FRONT BUMPER LOWER STIFFENER	Distorted	134.37 FL	*134.37 FL
8	1		*FRONT BUMPER BRACKET LH	Repair	10.00 FL	*- FL
9	1		*FRONT BUMPER BRACKET RH	Repair	10.00 FL	*- FL
10	1		*BUMPER FOG LAMP COVER RH	Serviceable	32.40 FL	*- FL
11	1		*BUMPER FOG LAMP COVER LH	Missing	32.40 FL	*32.40 FL
12	1		*HEADLAMP LH	Serviceable	816.00 FL	*- FL
13	1		*HEADLAMP LH INNER PANEL	Repair	611.16 FL	*- FL
14	1		*FRONT SHOCK ABSORBER ASSY RH	Serviceable	216.17 FL	*- FL
15	1		*FRONT SHOCK ABSORBER TOP MOUNTING RH	Serviceable	48.32 FL	*- FL
16	1		*FRONT LOWER ARM RH	Serviceable	283.00 FL	*- FL
17	1		*FRONT KNUCKLE ARM RH	Serviceable	230.00 FL	*- FL
18	1		*FRONT HUB UNIT	Serviceable	376.00 FL	*- FL
19	1		*FRONT DISC BRAKE RH	Not Necessary	157.55 FL	*- FL
20	1		*FRONT STRUT BAR BRACKET RH	Not Necessary	235.01 FL	*- FL
21	1		*FRONT STABILIZER BAR	Not Necessary	234.00 FL	*- FL
22	1		*FRONT STABILIZER BAR LINK RH	Not Necessary	51.79 FL	*- FL
23	1		*FRONT STABILIZER BAR BRACKET RH	Not Necessary	105.75 FL	*- FL
24	1		*FRONT STABILIZER BAR BUSH RH	Not Necessary	66.00 FL	*- FL
25	1		*FRONT BEAM A -IMPACT RH	Not Necessary	214.00 FL	*- FL
26	1		*FRONT LOWER ARM LH	Bent	283.00 FL	*283.00 FL
27	1		*FRONT SHOCK ABSORBER ASSY LH	Bent	216.17 FL	*216.17 FL
28	1		*FRONT SHOCK ABSORBER TOP MOUNTING LH	Bent	48.32 FL	*48.32 FL
29	1		*FRONT KNUCKLE ARM LH	Bent	230.00 FL	*230.00 FL
30	1		*FRONT HUB UNIT	Serviceable	376.00 FL	*- FL
31	1		*FRONT DISC BRAKE LH	Serviceable	157.55 FL	*- FL
32	1		*FRONT STRUT BAR BRACKET LH	Repair	235.01 FL	*- FL
33	1		*FRONT STABILIZER BAR	Serviceable	234.00 FL	*- FL
34	1		*FRONT STABILIZER BAR LINK LH	Bent	51.79 FL	*51.79 FL
35	1		*FRONT STABILIZER BAR BRACKET LH	Not Necessary	105.75 FL	*- FL
36	1		*FRONT STABILIZER BUSH LH	Not Necessary	66.00 FL	*- FL
37	1		*FRONT BEAM A- IMPACT LH	Repair	214.00 FL	*- FL
38	1		*INTERM AXLE SHAFT (CENTRE)	Repair	241.14 FL	*- FL
39	1		*HORN UNIT (LOW TONE)	Serviceable	53.46 FL	*- FL
40	1		*HORN UNIT (HIGH TONE)	Serviceable	53.46 FL	*- FL
41	1		*FRONT SUPPORT PANEL ASSY	Repair	1,222.32 FL	*- FL
42	1		*FRONT BRACE PANEL	Repair	134.37 FL	*- FL
43	1		*WINDSCREEN WASHER TANK (RESERVOIR A-W/SHIELD)	Serviceable	62.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*WINDSCREEN WASHER TANK MOTOR (PUMP WSWA)	Serviceable	51.00 FL	*- FL
45	1		*TANK,WIPER HOSE	Serviceable	21.00 FL	*- FL
46	1		*WINDSCREEN WASHER TANK -FILLER NECK	Serviceable	4.80 FL	*- FL
47	1		*RADIATOR GRILLE (GRILLE A-RAD)	Serviceable	367.00 FL	*- FL
48	1		*RADIATOR GRILLE TOP COVER	Serviceable	45.02 FL	*- FL
49	1		*FAN BLADE (A/C)	Serviceable	536.00 FL	*- FL
50	1		*FAN BLADE (RADIATOR)	Serviceable	634.00 FL	*- FL
51	1		*AIRCON CONDENSER	Serviceable	600.00 FL	*- FL
52	1		*AIRCON HOSE -CONDENSER TO COMPRESSOR	Serviceable	450.00 FL	*- FL
53	1		*AIRCON HOSE -COMPRESSOR TO EVAPORATOR	Serviceable	624.00 FL	*- FL
54	1		*AIRCON HOSE -CONDENSER TO EVAPORATOR	Serviceable	580.00 FL	*- FL
55	1		*AIRCON COMPRESSOR -PUMP	Serviceable	1,847.95 FL	*- FL
56	1		*AIRCON COMPRESSOR BRACKET	Repair	245.30 FL	*- FL
57	1		*AIRCON COMPRESSOR BOTTOM BUSHING	Serviceable	119.00 FL	*- FL
58	1		*AIR CLEANER ASSEMBLY (CLEANER A-AIR)	Serviceable	112.00 FL	*- FL
59	1		*AIR FILTER (ELEMENT A-AIR CLEANER)	Serviceable	39.00 FL	*- FL
60	1		*AIR-CLEANER INTAKE DUCT	Serviceable	89.25 FL	*- FL
61	1		*AIR-CLEANER INTAKE DUCT HOSE (TOP)	Serviceable	75.85 FL	*- FL
62	1		*AIR INTAKE RESONATOR TOP (SQUARE)	Serviceable	14.52 FL	*- FL
63	1		*AIR INTAKE RESONATOR (BESIDE FENDER)	Serviceable	20.01 FL	*- FL
64	1		*AIR INTAKE RESONATOR HOSE (BOTTOM)	Serviceable	60.90 FL	*- FL
65	1		*AIR INTAKE RESONATOR TANK TOP BRACKET	Serviceable	45.00 FL	*- FL
66	1		*RESONATOR A-A/CL	Broken	137.00 FL	*137.00 FL
67	1		*FRONT FENDER LH	Bent	837.60 FL	*837.60 FL
68	1		*FRONT FENDER LINER LH	Missing	47.00 FL	*47.00 FL
69	1		*FENDER INSULATION LH	Serviceable	39.00 FL	*- FL
70	1		*FRONT FENDER INNER WHEEL HOUSE PANEL LH	Repair	1,437.00 FL	*- FL
71	1		*FRONT DOOR RH	Bent	1,133.00 FL	*1,133.00 FL
72	1		*FRONT DOOR GLASS GUIDE RH CHROME MOULDING	Serviceable	60.00 FL	*- FL
73	1		*FRONT DOOR OUTER MOULDING	Buckled	220.00 FL	*220.00 FL
74	1		*FRONT DOOR OUTER HANDLE	Serviceable	125.00 FL	*- FL
75	1		*FRONT DOOR HANDLE SUPPORT	Serviceable	3.00 FL	*- FL
76	1		*FRONT DOOR OUTER HANDLE INNER SEAL	Serviceable	89.15 FL	*- FL
77	1		*FRONT DOOR OUTER KEY LOCK	Serviceable	25.00 FL	*- FL
78	1		*FRONT DOOR HINGE UPPER	Repair	65.00 FL	*- FL
79	1		*FRONT DOOR HINGE LOWER	Repair	65.00 FL	*- FL
80	1		*FRONT DOOR INNER LOCK	Jammed	586.00 FL	*586.00 FL
81	1		*FRONT DOOR INNER LOCK LATCH RH	Repair	206.00 FL	*- FL
82	1		*FRONT DOOR CHECK /ARRESTOR	Serviceable	67.50 FL	*- FL
83	1		*FRONT DOOR WEATHERSTRIP RH	Serviceable	138.79 FL	*- FL
84	1		*FRONT DOOR GLASS CHANNEL WEATHERSTRIP	Serviceable	160.00 FL	*- FL
85	1		*FRONT DOOR INNER TRIM BOARD	Serviceable	455.69 FL	*- FL
86	1		*FRONT DOOR WINDOW GLASS	Serviceable	456.12 FL	*- FL
87	1		*FRONT DOOR POWER WINDOW MOTOR (MASTER) RH	Jammed	284.97 FL	*284.97 FL
88	1		*FRONT DOOR POWER WINDOW MOTOR SWITCH	Serviceable	145.00 FL	*- FL
89	1		*FRONT DOOR WINDOW REGULATOR GEAR RH	Bent	84.58 FL	*84.58 FL
90	1		*FRONT DOOR OUTER PILLAR PANEL RH	Repair	715.00 FL	*- FL
91	1		*FRONT DOOR PILLAR INNER PANEL RH	Repair	850.00 FL	*- FL
92	1		*FRONT DOOR CENTER PILLAR PANEL RH	Not Necessary	698.15 FL	*- FL
93	1		*FRONT SIDE VIEW MIRROR ASSY RH	Serviceable	1,191.00 FL	*- FL
94	1		*REAR DOOR RH (PANEL A-RR DR LH)	Bent	1,133.00 FL	*1,133.00 FL
95	1		*REAR DOOR WEATHERSTRIP -INNER	Serviceable	41.40 FL	*- FL
96	1		*REAR DOOR WEATHERSTRIP -2ND FRAME	Serviceable	25.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
97	1		*REAR DOOR TOP HINGE	Bent	35.00 FL	*35.00 FL
98	1		*REAR DOOR BOTTOM HINGE	Bent	35.00 FL	*35.00 FL
99	1		*REAR DOOR INNER LOCK	Jammed	425.00 FL	*425.00 FL
100	1		*REAR DOOR CHECK /ARRESTOR	Serviceable	65.00 FL	*- FL
101	1		*REAR DOOR LOCK STRIKER /LATCH	Serviceable	208.00 FL	*- FL
102	1		*REAR DOOR INNER LOCK LATCH RH	Serviceable	208.00 FL	*- FL
103	1		*REAR DOOR OUTER WEATHERSTRIP MOULDING	Serviceable	85.00 FL	*- FL
104	1		*REAR DOOR GLASS GUIDE RH CHROME MOULDING	Serviceable	60.00 FL	*- FL
105	1		*REAR DOOR OUTER MOULDING	Serviceable	220.00 FL	*- FL
106	1		*REAR DOOR OUTER HANDLE	Serviceable	125.00 FL	*- FL
107	1		*REAR DOOR HANDLE SUPPORT	Serviceable	3.00 FL	*- FL
108	1		*REAR DOOR OUTER HANDLE INNER SEAL	Serviceable	89.15 FL	*- FL
109	1		*REAR DOOR OUTER KEY LOCK	Serviceable	25.00 FL	*- FL
110	1		*REAR DOOR WEATHERSTRIP RH	Serviceable	138.79 FL	*- FL
111	1		*REAR DOOR GLASS CHANNEL WEATHERSTRIP	Serviceable	160.00 FL	*- FL
112	1		*REAR DOOR INNER TRIM BOARD	Serviceable	455.69 FL	*- FL
113	1		*REAR DOOR WINDOW GLASS	Serviceable	456.12 FL	*- FL
114	1		*REAR DOOR POWER WINDOW MOTOR (MASTER)RH	Jammed	284.97 FL	*284.97 FL
115	1		*REAR DOOR POWER WINDOW MOTOR SWITCH	Serviceable	145.00 FL	*- FL
116	1		*REAR DOOR WINDOW REGULATOR GEAR RH	Bent	84.58 FL	*84.58 FL
117	1		*REAR DOOR OUTER PILLAR PANEL RH	Repair	715.00 FL	*- FL
118	1		*REAR DOOR PILLAR INNER PANEL RH	Repair	850.00 FL	*- FL
119	1		*REAR DOOR CENTER PILLAR PANEL RH	Not Necessary	698.15 FL	*- FL
120	1		*SIDE ROCKER PANEL GARNISH RH	Dented	236.40 FL	*236.40 FL
121	1		*FRONT SIDE VIEW MIRROR ASSY LH	Serviceable	1,191.00 FL	*- FL
122	1		*REAR FENDER RH	Repair	1,145.00 FL	*- FL
123	1		*REAR FENDER INNER TRIM RH	Serviceable	418.44 FL	*- FL
124	1		*FRONT SIDE ROCKER PANEL GARNISH RH	Serviceable	236.40 FL	*- FL
125	1		*FRONT SIDE ROCKER PANEL OUTER RH	Repair	600.00 FL	*- FL
126	1		*FRONT SIDE ROCKER PANEL INNER RH	Repair	519.30 FL	*- FL
127	1		*FRONT SIDE ROCKER PANEL GARNISH LH	Cracked	236.40 FL	*236.40 FL
128	1		*FRONT SIDE ROCKER PANEL OUTER LH	Repair	600.00 FL	*- FL
129	1		*FRONT SIDE ROCKER PANEL INNER LH	Repair	519.30 FL	*- FL
130	1		*REAR BUMPER	Repair	1,202.00 FL	*- FL
131	1		*SET FRONT BUMPER FASTENER CLIP	Necessary	24.00 FS	*24.00 FS
132	1		*SET RADIATOR GRILEL CLIP	Not Necessary	35.00 FS	*- FS
133	1		*SET RADIATOR GRILEL TOP COVER CLIP	Not Necessary	10.00 FS	*- FS
134	1		*SET LOUVER COWL TOP CLIP	Not Necessary	30.00 FS	*- FS
135	1		*SET FRONT FENDER LINER CLIP LH	Not Necessary	30.00 FS	*- FS
136	1		*SET FRONT FENDER LINER CLIP RH	Not Necessary	30.00 FS	*- FS
137	1		*FRONT FENDER RR BRACKET RH	Repair	7.10 FS	*- FS
138	1		*FRONT LEFT TYRE (30%)	Punctured	220.00 FS	*66.00 FS
139	1		*FRONT TYRE RIM LH	Bent	350.00 FS	*50.00 FS
140	1		*FRONT DOOR STICKER TRANS-CAB	Bent	80.00 FS	*60.00 FS
141	1		*SET REAR FENDER INNER TRIM CLIP RH	Not Necessary	30.00 FS	*- FS
142	1		*REAR DOOR STICKER 6555-3333	Necessary	80.00 FS	*60.00 FS
143	1		*FRONT RIGHT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
144	1		*FRONT LEFT DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
145	2		*FRONT WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
146	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
147	1		*SET REAR BUMPER FASTENER CLIP	Not Necessary	44.00 FS	*- FS
148	1		*SET REAR FENDER INNER TRIM CLIP RH	Not Necessary	30.00 FS	*- FS
149	1		*SET REAR BUMPER END DUST COVER CLIP	Not Necessary	30.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.				Sub Total (S\$)	41,833.50	8,420.55
				- List Item Discount on L Items 10.00/10.00% (S\$)	4,044.34	810.06
				Total Parts (S\$)	37,789.16	7,610.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	40.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	4,500.00	1,400.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	1,400.00
4	TOWING FEES	New	120.00	50.00
5	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	200.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	80.00
7	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	90.00
8	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING }	New	170.00	20.00
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING }	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	340.00	60.00
12	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	340.00	0.00
13	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	60.00
14	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
15	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
16	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
17	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
18	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	440.00	0.00
Gross Labour Cost (\$\$)			12,600.00	3,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >