

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 48960
Date Estimated : 31/10/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Vickneshwaran s/o Thangavelu
878 Woodlands Avenue 9
#05-296

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 730878

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE
SGB5312Z	E948511	23/12/2011	116iA/5	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To repalce rear bumper and attachments include making good the tail end panel and knocking out dents caused by the accident	1700.00		1,700.00 ✓
To spray paint rear bumper and tail end panel	1603.00		1,603.00 ✓
To supply rear emboss number plate	83.00		83.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00 ✓
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00 ✓
# To remove old PDC assembly, replace damaged parts, reconnect to new bumper include conducting checks for proper function	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER CARRIER	394.90	1.00		394.90 ✓
DECORATIVE STRIP (LINE URBAN)	110.00	1.00		110.00 ✓
REAR BUMPER PRIMED (LINES)	924.75	1.00		924.75 ✓
SET MOUNTS PDC SENSOR REAR *	62.95	1.00		62.95 ✓
# NUMBER PLATE LIGHT LED *	23.80	1.00		23.80 ✓
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05 ✓

SUPPLEMENTARY ITEMS

Total Labour :	3,996.00
Total Parts :	1,569.45
Total Labour & Parts :	5,565.45
Deduction for Excess :	0.00
Total Repair Costs less Excess:	5,565.45
GST @7%:	389.58
Grand Total :	5,955.03