

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 633Y**AAD1810-281***Not Authorised*
11 Sep @ 1830h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 633Y

VF1ABL15AUC278283

RENAULT

LATITUDE

27.10.18

**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Buclina</i>	1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>ndul Cor</i>	768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sh</i>	113.47	}
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sh</i>	135.97	
5	1 BUMPER RETAINER RH REAR	\$	<i>Sh</i>	44.99	
6	1 BUMPER REFLECTOR RH	\$	<i>Sh</i>	43.61	
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sh</i>	135.97	
8	1 BUMPER RETAINER LH REAR	\$	<i>Sh</i>	44.99	
9	1 BUMPER REFLECTOR LH	\$	<i>Sh</i>	43.61	
10	1 BUMPER BEAM REAR	\$	<i>Sh</i>	777.52	
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Sh</i>	225.95	
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Sh</i>	225.95	
13	1 OUTER PANEL REAR (End Panel)	\$	<i>Sh</i>	1,471.77	} X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sh</i>	404.56	
15	1 TAILLAMP RH	\$	<i>Sh</i>	552.55	
16	1 TAILLAMP PANEL RH	\$	<i>Sh</i>	986.70	
17	1 TAILLAMP LH	\$	<i>Sh</i>	552.55	
18	1 TAILLAMP PANEL LH	\$	<i>Sh</i>	986.70	
19	1 BOOT REAR	\$	<i>Sh</i>	2,872.68	
20	1 BOOT FINISHER	\$	<i>Sh</i>	470.06	
21	1 BOOT WHEATERSTRIP	\$	<i>Sh</i>	323.05	
22	1 BOOT REFLECTOR LAMP LH	\$	<i>Sh</i>	493.35	
23	1 BOOT REFLECTOR LAMP RH	\$	<i>Sh</i>	493.35	
24	1 BOOT BADGE 'RENAULT'	\$	<i>Sh</i>	225.36	
25	1 BOOT BADGE	\$	<i>Sh</i>	225.36	
26	1 BOOT STRUT LH	\$	<i>Sh</i>	276.08	
27	1 BOOT STRUT RH	\$	<i>Sh</i>	276.08	
28	1 BOOT HINGE LH	\$	<i>Sh</i>	367.84	
29	1 BOOT HINGE RH	\$	<i>Sh</i>	367.84	

Trans-cab Auto Services Pte Ltd**AAD1810-281**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 633Y

30	1 BOOT INNER TRIM	\$	586.45	X
31	1 BOOT SWITCH	\$	168.13	X
32	1 BOOT LOCK	\$	202.67	X
33	1 BOOT LOCK CATCH	\$	74.40	X

TOTAL	\$	16,046.87
10%	\$	1,604.69
	\$	14,442.19

Special Nett

1	1SET PARKING AID	\$	See	700.00	X
2	1SET REAR BUMPER CLIP	\$	nn	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	nn	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	—
10	1 BOOT STICKER "Trans-cab"	\$	nn	80.00	} X
11	1 BOOT STICKER "6555-3333"	\$	nn	80.00	
12	1 EXHAUST MOUNTING REAR	\$	See	17.82	
13	2 REAR WINDSCREEN SEALANT	\$	nn	80.00	
14	1 WINDSCREEN MOULDING	\$	See	100.00	
15	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	

TOTAL	\$	1,404.82
--------------	-----------	-----------------

TOTAL PARTS	\$	15,847.01
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *2201*

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 3,000.00 *2001*

Trans-cab Auto Services Pte Ltd**AAD1810-281**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 633Y

To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 602
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00 X
To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X

TOTAL \$ 8,510.00**Over All Total \$ 24,357.01****LUMP SUM (REPAIR DAY)****10 DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date: