

CITY CAB PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHB 3474R

MAKE :

MODEL : HYUNDAI i40

DATE 31/10/2018

LONPAC-45

TS

1225

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X repair</i>			\$ 553.00
	Rear Bumper Clip 10 pcs <i>X 2</i>			\$ 22.00
	Rear Bumper Bracket <i>X su</i>		\$ 35.60	\$ 71.20
	Rear Bumper Sponge <i>X su</i>			\$ 103.50
	Rear Bumper Under Cover <i>X su</i>			\$ 228.00
	SUB TOTAL			\$ 977.70
	LESS 20%			\$ 195.54
	DISCOUNTED TOTAL			\$ 782.16
	Rear Bumper Advertisement Logo <i>— me</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>— me</i>		\$ 100.00	\$ 200.00
				\$ 250.00
	Labour Charge			
	Panel Beating			\$ 400.00 <i>100</i>
	Spray Painting Charge			\$ 250.00 <i>200</i>
	TOTAL LABOUR			\$ 650.00
	ESTIMATE TOTAL			\$ 1,682.16
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

Kalina 16/11/18

31/10/18 1600hrs

2 Pys

45

After Repair p Lts

UK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to negotiation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date: