

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1242/2018/NK
Date : 02-Nov-18

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : M/S Premium Automobiles Pte Ltd
Address : 55 Ubi Road
Singapore 408699
Telephone : Ms See : Hp 97508652
Type of Claim : Third Party Claims
Policy No. : 1800094625
Vehicle No : **SLV 2599 T**
Model Code : Audi A5 SB 2.0 TFS.
Model / Year : Dec-17
Engine No : CVK051373
Chassis No : WAUZZZF57JA052061
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Oct-18
Place of Accident : Along Somerset Rd

Tanpin 97425719
-wp'
9/11/18
Resurvey before print.
sure theland.com
5 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 2599 T

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper. To repair rhs rear fender. Reorganise crash management components. Reinstall all parts removed.	\$ 1,400.00 1050.	
3	To respray rear bumper and rhs rear fender.	\$ 1,600.00 1400.	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 3,552.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLV 2599 T**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 2,190.00	de ✓
2	REAR BUMPER FIXING PARTS	\$ 142.00	rec ✓
3	REAR BUMPER SECURING STRIPS	\$ 191.00	?
4	RERA BUMPER CHROME TRIM	\$ 878.00	ant ✓
5	REAR BUMPER INNER CLIPS	11 \$ 407.00	?
6	REAR BUMPER OUTER CLIPS	4 \$ 148.00	?
7	REAR LIGHT REFLECTOR LH / RH	2 \$ 74.00	LH-X, RH ant ✓
8	REAR BUMPER GUIDE SECTION UPPER / LOWER RH	2 \$ 56.00	?
9	REAR REINFORCEMENT BEAM	\$ 786.00	X
11	REAR BUMPER SENSOR INNER / OUTER	\$ 211.00	?
12	REAR BUMPER SEAL RING	4 \$ 14.00	rec ✓
13	SUNDRIES	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 5,397.00	
TOTAL LABOUR CHARGES		\$ 3,552.00	
GRAND TOTAL		\$ 8,949.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant