

ASS. REC. BY:

REF:

CS/CTI18019845/Tlg d301

Special Instruction:

Surveyor:

Menimen

From (Person):

Irene Tay

ASSIGNMENT (Office)

of CTI

Date/Time:

31/10/18 @ 2:10pm

Estimated Cost:

Bill to:

OD: TP/ WS/TP RES/ OD RES/ EVA/ INV/ MV/CS

To Inspect Vehicle No:

GBA 7936A

Insured:

at Workshop m/s

Sng Ah Tee

Tel:

6268 6183

of

Blk 3 pioneer Rd North # 01-18

Policy No:

DMCVSN 3040451800

Claim No:

SNM18D05134C01

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

26/10/2018

CA /

REV

/ REP. / REV 24 HRS

01/11/2018

H.O.D. Endorsement:

Date/Time:

3:37pm @ 31/10/18

Person Contacted:

Juye

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBA 7936A-X
07/11/18 @ 5:22pm	revert to Irene Tay via Menimen. (pending COR).
08/11/18 @ 10:15am	2nd revert to Irene Tay via Menimen. Complainer undertake US \$600.
09/11/18 @ 10:20am	Alfred Toh informed CTR B ex: \$500 via Menimen.
09/11/18 @ 11:01am	informed Janica CTR not more than US \$600 & ex: \$500.
15/3/19 @ 4:17pm	confirmed with Sharon US \$6000, 6 days. CRed \$3716, 28%.

Surveys

Tanph

REF: C11

CS/CTU8019815/T1d3

ASSIGNMENT

WE 2022 CLK

From:

Date: 01/11/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBA 7936A

at Workshop m/s Sng Ah Tee

of Blk 3, Pioneer Rd North #01-18

Insured:

Policy No.

Claims No.


Sum Insured: Excess: \$500.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$24K

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

GBA 7936A

Yr Regn:

2008 Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Urvan

3.0

c.c

2953

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

255422

T/Radio:

Insured / Std / NI / NA

Eng/No:

JN1MG4E25 267 80435

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/115

B2 / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

01/11/18

Survey held at

Sng Ah Tee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit \$6000

RECEIVED 18 MAR 2019

Date/Time, File Pass to?

1) 18/3 11:40

Date/Time, File Return to?

2)

☐

: Preli. Report

☐

: Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\$ + RS. \$1

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Report Format :

MER-00

Lump Sum / L.B.I. (\$

6000

220

220

**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2018 Sendback Est	30 Oct 2018 16:12 \$8,246.00	31 Oct 2018 14:10 Assign				New Assignment Cancel Case

Main   Reference   Claim Details   Documents   Show All

### CLAIM SUBFOLDER DETAILS

Insured:	CONCEPTS.SG, Co. Reg. No.: 53040541E		
Vehicle Reg. No.:	GBA7936A	Date of Loss:	26/10/2018 16:00 - :59 [129 Months From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D05134C01	Policy/Cover Note No.:	DMCVSN3040451800 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/11/2018]		
Driver/Custodian:	TAN EE LING ,EVELYN (37 / Female), NRIC: S8104016H, Tel: +6596545955		
Adj Asg. Remarks:	revert		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)

Compose Case Mail

### ALL ASSOCIATED TASKS

[View All](#)

## Search Tasks

[Create New Task](#)

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAuto)

---

**From:** Sharon Sng <sharon@sngahtee.com>  
**Sent:** Friday, 15 March 2019 4:17 PM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** RE: GBA7936A - FINALISE (LIMIT REPAIR \$6K BEFORE EXCESS \$500) PART 2

Hi Shiau chan

confirm....

Best Regards

---

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457  
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



*-Please note that all offer/acceptance is made without prejudice.-*

---

**From:** Shiau Chan (LKKAuto) <siewsc@lkkauto.com>  
**Sent:** Friday, March 15, 2019 11:36 AM  
**To:** Sharon Sng <sharon@sngahtee.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: GBA7936A - FINALISE (LIMIT REPAIR \$6K BEFORE EXCESS \$500) PART 2

Dear Sharon,

WITHOUT PREJUDICE

Offer Lump Sum \$6,000.00 before excess \$500.00 & GST and 6 repair days.

Kindly confirm.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Sharon Sng <sharon@sngahtee.com>  
**Sent:** Friday, 1 March 2019 6:25 PM  
**To:** Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** GBA7936A - FINALISE (LIMIT REPAIR \$6K BEFORE EXCESS \$500) PART 2

**Shiau Chan (LKKAuto)**

---

**From:** Do-Not-Reply <do-not-reply@merimen.com>  
**Sent:** Friday, 15 March 2019 11:40 AM  
**To:** do-not-reply@merimen.com  
**Cc:** SUR  
**Subject:** OD VEHICLE GBA 7936A (YOUR REF: SNM18D05134C01)

This mail is associated with :  
**GBA7936A (SNM18D05134C01)**

OD  
Oct 26 2018 4:00PM  
[CONCEPTS.SG]  
Sng Ah Tee Motor & Panel Service Pte Ltd

Dear Irene,

We have received supplementary \$1,470.00 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is within authorisation limit.

Thanks & Regards,

Shiau Chan (Ms)  
LKK Auto Consultants Pte Ltd  
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



**AVG**

This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 9 November 2018 11:01 AM  
**To:** ADMIN SAT  
**Cc:** SUR  
**Subject:** VEHICLE GBA 7936A (DOA: 26/10/2018)

Dear Janice,

As instructed by our client, please proceed to repair the insured vehicle GBA 7936A at repair cost not more than Lump Sum \$6,000.00 (Excess \$500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	30 Oct 2018 13:02	<b>Clm Veh Model Changed</b>	(201385) NISSAN URVAN 3.0 D (M).	[R] JOYCE TAN LAI CHIN
2	30 Oct 2018 13:02	<b>Clm Created</b>	Reg No: GBA7936A, Policy No: DMCVSN3040451800, Acct Date: 2018/10/26, Claim Type: OD, Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer), Created from SAS:MSAT18139550	[R] JOYCE TAN LAI CHIN
3	30 Oct 2018 16:12	<b>Clm Submitted</b>	8246.00.	[R] Janice Chang Siew Yin
4	31 Oct 2018 14:10	<b>Clm Registration Modified</b>	Excess: -> 500.00.	[I] Ong Chin Kiat
5	31 Oct 2018 14:10	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):revert	[I] Ong Chin Kiat
6	31 Oct 2018 14:10	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/11/12	[I] Ong Chin Kiat
7	31 Oct 2018 14:10	<b>Adj Mandate Set</b>	Approved:0.00.	[I] Ong Chin Kiat
8	31 Oct 2018 15:47	<b>Assignment 1st Accessed</b>		[A] Nivitha Govindasamy
9	31 Oct 2018 17:12	<b>Adj Adjuster Assigned</b>	[None] -> MOHD TAUFIKH BIN HAMID	[A] Nivitha Govindasamy
10	02 Nov 2018 16:37	<b>Adj Rpt Initiated</b>		[A] SHIAU CHAN
11	02 Nov 2018 17:21	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2018/11/12	[A] SHIAU CHAN
12	02 Nov 2018 17:22	<b>Adj Mandate Request</b>	Cur.Req:0.00:DAMAGES CONSISTENT. PENDING REPAIR COST FROM REPAIRER.	[A] SHIAU CHAN
13	07 Nov 2018 09:13	<b>Adj Mandate Request Cancelled</b>		[A] SHIAU CHAN
14	08 Nov 2018 10:14	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2018/11/12	[A] SHIAU CHAN
15	08 Nov 2018 10:15	<b>Adj Mandate Request</b>	Cur.Req:6000.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. REPAIRER WILLING TO UNDERTAKE THE REPAIR COST NOT MORE THAN LUMP SUM \$6,000.00. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
16	09 Nov 2018 10:20	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2018/11/12. Mandate Remarks: Proceed to authorize repairs at \$6,000.00 BEFORE Excess of \$500.00	[I] Alfred Toh
17	09 Nov 2018 10:20	<b>Adj Mandate Set</b>	Approved:6000.00:Proceed to authorize repairs at \$6,000.00 BEFORE Excess of \$500.00Reinsp:Adj decides.	[I] Alfred Toh

Date From



Date To



Audit Type

None

Go

### ACTIVITY

[31/10/2018 17:12] Nivitha Govindasamy:

Please be informed repairer agreed survey on 01/11/2018.

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1960239	30/10/2018 13:02	Motor	Sng Ah Tee Motor & Panel Service Pte Ltd (HQ)	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	GBA7936A		xx.xx
1964934	02/11/2018 16:37	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBA7936A		10.70

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 08 Nov 2018

**Preliminary Advice**

Vehicle No	: GBA7936A	Accident Date	: 26/10/2018
Make	: NISSAN URVAN	Policy No.	: DMCVSN3040451800
Assignment Date	: 31/10/2018	Excess	: S\$500.00
Date of Inspection	: 01/11/2018	Est. Duration of Repair	: 7.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,246.00
Revised Amount	:S\$	4,000.00
Check Items (Estimated)	:S\$	4,020.00
Total	:S\$	8,020.00

Lump Sum Repair	:S\$	6,400.00
-----------------	------	----------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	24,000.00
COE / PARF Rebate	:S\$	17,181.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,819.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : REPAIRER WILLING TO UNDERTAKE THE REPAIR COST NOT MORE THAN LUMP SUM \$6,000.00.



**Note: This document has not been finalised.**

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 02 Nov 2018

### Preliminary Advice

Vehicle No	: GBA7936A	Accident Date	: 26/10/2018
Make	: NISSAN URVAN	Policy No.	: DMCVSN3040451800
Assignment Date	: 31/10/2018	Excess	: S\$500.00
Date of Inspection	: 01/11/2018	Est. Duration of Repair	: 7.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,246.00
Revised Amount	:S\$	4,000.00
Check Items (Estimated)	:S\$	4,020.00
Total	:S\$	8,020.00

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	24,000.00
COE / PARF Rebate	:S\$	17,181.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,819.00

### Remarks

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : PENDING REPAIR COST FROM REPAIRER.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Business  
Owner ID: 0541E

### Vehicle Details

Vehicle No.: GBA7936A  
Vehicle to be Exported: No  
Intended Deregistration Date: 31 Oct 2018  
Vehicle Make: NISSAN  
Vehicle Model: URVAN PANEL LWB 3.0 5DR 5MT AIRBAG 2WD  
Primary Colour: Blue  
Manufacturing Year: 2007  
Engine No.: ZD30153494K  
Chassis No.: JN1MG4E25Z0780435  
Maximum Power Output: -  
Open Market Value: \$24,954.00  
Original Registration Date: 26 Jan 2008  
First Registration Date: 26 Jan 2008  
Transfer Count: 2  
Actual ARF Paid: \$1,248.00

### Intended PARF Rebate Details

PARF Eligibility: No  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 31 Oct 2022  
COE Category: C - Goods Vehicle & Bus  
COE Period(Years): 5  
PQP Paid: \$21,477.00  
COE Rebate Amount: \$17,181.00  
**Total Rebate Amount: \$17,181.00**

### Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 29 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/10/2018 12:21
Date Of Accident	26/10/2018 16:00
Exact Location Of Accident	ALONG CTE BEFORE EXIT BRADDELL RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBA7936A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CONCEPTS.SG
Co Reg No	53040541E
Email Address	EVELYN@CONC6PT.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-96545955
<b>Vehicle Particulars</b>	
Manufacturer	NISSAN
Model	URVAN-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3040451800
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN EE LING ,EVELYN
NRIC No	S8104016H
Date Of Birth	13/01/1981
Occupation	OUTDOOR
Date Of Driving Pass	08/02/2001
Driving Experience	17 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96545955
Fax Number	
Contact Number	
Email Address	EVELYN@CONC6PT.COM.SG

Address	1, BUKIT BATOK CRE, #05-23,WEGA PALZA
Postcode	658064
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CASEY CHEN LI SHIAU GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

#### Circumstances of Accident

ON 26/10/2018 AT ABOUT 1600 HRS. WHILE I WAS TRAVELLING ALONG CTE BEFORE EXIT BRADDELL RD. MY VEHICLE HAVE TWO CAR DISTANCE WITH VEHICLE C. VEHICLE B SUDDENLY CUT IN FROM RIGHT LANE AND APPLY EMERGENCY BRAKE . I COULDN'T STOP IN TIME AND COLLIDED ONTO REAR LEFT PORTION OF VEHICLE B. VEHICLE B HAVEN'T FULLY IN THE LANE.VEHICLE B HAD COLLIDED ONTO RIGHT PORTION OF VEHICLE C.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ7652E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJX6562K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A **14 DAYS TIMEFRAME** FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

122-Printed Sketch Plan Form\_V3

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to circumstances

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time: \*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

☒ Claim own policy  
☐ Claim third party  
☐ Claim OD / TP at other works hop  
☐ For record purpose

Policy No. \_\_\_\_\_  
Insurer Ching Veh. No. GBA7936A

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

## Sng Ah Tee Motor &amp; Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

## PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN3040451800	Date of Loss:	26/10/2018
Vehicle Reg. No.:	GBA7936A	Driveable?	
Driver Age/Info:	37 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CONCEPTS.SG		
Driver:	TAN EE LING ,EVELYN		

Make/Model:	NISSAN URVAN, 3.0 D (M)	Vehicle Reg. Date:	26/01/2008
Vehicle Colour:	BLUE		
Engine No:	ZD30153494K	Chassis No:	JN1MG4E25Z0780435
Odometer:	5 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	9

Description of Accident/Loss

ON 26/10/2018 AT ABOUT 1600 HRS. WHILE I WAS TRAVELLING ALONG CTE BEFORE EXIT BRADDELL RD. MY VEHICLE HAVE TWO CAR DISTANCE WITH VEHICLE C. VEHICLE B SUDDENLY CUT IN FROM RIGHT LANE AND APPLY EMERGENCY BRAKE . I COULDN'T STOP IN TIME AND COLLIDED ONTO REAR LEFT PORTION OF VEHICLE B. VEHICLE B HAVEN'T FULLY IN THE LANE.VEHICLE B HAD COLLIDED ONTO RIGHT PORTION OF VEHICLE C.

Present Location: SNG AH TEE MOTOR &amp; PANEL SERVICE PTE LTD (PIONEER)

## COST OF CLAIMS

Parts	
Miscellaneous Items	
Labour	
Paintwork Labour	
Towing	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

<b>Gross Total (S\$)</b>	<b>8,246.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>577.22</b>
<b>Nett Amount (S\$)</b>	<b>8,823.22</b>

Tan Ah Tee 9745741 01/11/18  
Ex \$500 2550  
Repair Not Authorise  
Resurvey after repair.  
6-7 days

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

9716



**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 30 Oct 2018)**Parts:** N/A NISSAN URVAN 3.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBA7936A)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	bt — *15.00 FS
2	1		*FRT BUMPER	0.00	0.00	de — *280.00 F
3	2		*FRT BUMPER SIDE RETAINER	0.00	0.00	we — *130.00 F
4	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	bt — *155.00 F
5	1		*FRT FOGLAMP (RH)	0.00	0.00	clb — *245.00 F
6	1		*FRT FOGLAMP COVER(RH)	0.00	0.00	de — *65.00 F
7	1		*FRT HEADLAMP (RH)	0.00	0.00	cr — *220.00 F
8	1		*FRT GRILLE EMBLEM	0.00	0.00	cr — *50.00 F
9	1		*FRT GRILLE	0.00	0.00	cr — *230.00 F
10	1		*FRT SIGNAL LAMP (RH)	0.00	0.00	cr — *55.00 F
11	1		*FRT HORN	0.00	0.00	bt — *75.00 F
12	1		*FRT PANEL	0.00	0.00	bt — *550.00 F
13	1		*FRT CORNER PANEL (RH)	0.00	0.00	bt — *240.00 F
14	1		*FRT PANEL INNER PANEL (RH)	0.00	0.00	na X *240.00 F X
15	1		*AIR CON CONDENSER ASSY	0.00	0.00	na X *780.00 F X
16	1		*INTERCOOLER	0.00	0.00	bt 2 *1,400.00 F ✓
17	1		*AIR CON BLOWER ASSY	0.00	0.00	cr — *1,300.00 F ✓
18	1		*FRT DOOR ROC STICKER (RH)	0	0.00	we — *20.00 FS
19	1		*FRT WINDSCREEN MOULDING	0.00	0.00	we — *80.00 F
20	1		*FRT WINDSCREEN SEALANT	0	0.00	we — *40.00 FS
21	1		*ERP BRACKET	0	0.00	na X *26.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)****6,196.00**

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO CHECK WIRING	New	30.00
2	TO REMOVE & REFIX FRT WINDSCREEN	New	120.00
3	TO TOP UP AIR CON GAS	New	100.00
4	TO REMOVE & REFIX FRT DASHBOARD	New	200.00
5	TO KNOCK FRT DOOR (RH), WELD, REMOVE & REPLACE ABOVE PARTS	New	800.00
6	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS	New	800.00
Gross Labour Cost (\$\$)			2,050.00

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

**REPAIR DETAILS****Reference****Part Source:** (Last Synchronised: 01 Mar 2019)**Parts:** N/A NISSAN URVAN 3.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Sng Ah Tee Motor & Panel Service Pte Ltd/GBA7936A/01/03/2019 18:01**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.*Supplementary***Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*RADIATOR	0.00	0.00	*480.00 F <i>bt</i>
2	1		*RADIATOR FAN BLADE	0.00	0.00	*105.00 F <i>ora</i>
3	2		*ENGINE MOUNTING	0.00	0.00	*150.00 F <i>de</i>
4	1		*RADIATOR FAN CLUTCH	0.00	0.00	*300.00 F <i>dis</i>
5	1		*FRT HEADLAMP PANEL RH	0.00	0.00	*210.00 F <i>bt</i>
6	1		*RADIATOR FAN COWLING	0.00	0.00	*115.00 F <i>ora</i>
7	2		*FRT BUMPER BRACKET	0.00	0.00	*110.00 F <i>bt</i>

F=Franchise part.

**Total Parts (S\$)****1,470.00**

Sng Ah Tee Motor & Panel Service Pte Ltd/GBA7936A/01/03/2019 18:01. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

10/3/2018

Estimate Report

accept \$6k (Ls)  
on 8/11/18

## Sng Ah Tee Motor &amp; Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18  
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

## PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSN3040451800	Date of Loss:	26/10/2018
Vehicle Reg. No.:	GBA7936A	Driveable?	
Driver Age/Info:	37 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CONCEPTS.SG		
Driver:	TAN EE LING ,EVELYN		
Make/Model:	NISSAN URVAN, 3.0 D (M)	Vehicle Reg. Date:	26/01/2008
Vehicle Colour:	BLUE		
Engine No:	ZD30153494K	Chassis No:	JN1MG4E25Z0780435
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	9		

Description of Accident/Loss

ON 26/10/2018 AT ABOUT 1600 HRS. WHILE I WAS TRAVELLING ALONG CTE BEFORE EXIT BRADDELL RD. MY VEHICLE HAVE TWO CAR DISTANCE WITH VEHICLE C. VEHICLE B SUDDENLY CUT IN FROM RIGHT LANE AND APPLY EMERGENCY BRAKE . I COULDN'T STOP IN TIME AND COLLIDED ONTO REAR LEFT PORTION OF VEHICLE B. VEHICLE B HAVEN'T FULLY IN THE LANE.VEHICLE B HAD COLLIDED ONTO RIGHT PORTION OF VEHICLE C.

Present Location:

SNG AH TEE MOTOR &amp; PANEL SERVICE PTE LTD (PIONEER)

## COST OF CLAIMS

	Amount
Parts	6,196.00
Miscellaneous Items	0.00
Labour	2,050.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>8,246.00</b>
<b>+ GST 7.00% (S\$)</b>	<b>577.22</b>
<b>Nett Amount (S\$)</b>	<b>8,823.22</b>

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

Limit Lum Sum  
\$6000

## REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 30 Oct 2018)

Parts: N/A NISSAN URVAN 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBA7936A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE	0	0.00	bt ✓ *15.00 FS
2	1		*FRT BUMPER	0.00	0.00	de ✓ *280.00 F
3	2		*FRT BUMPER SIDE RETAINER	0.00	0.00	ne ✓ *130.00 F
4	1		*FRT BUMPER REINFORCEMENT	0.00	0.00	bt ✓ *155.00 F
5	1		*FRT FOGLAMP (RH)	0.00	0.00	clg ✓ *245.00 F
6	1		*FRT FOGLAMP COVER(RH)	0.00	0.00	de ✓ *65.00 F
7	1		*FRT HEADLAMP (RH)	0.00	0.00	cr ✓ *220.00 F
8	1		*FRT GRILLE EMBLEM	0.00	0.00	cr ✓ *50.00 F
9	1		*FRT GRILLE	0.00	0.00	cr ✓ *230.00 F
10	1		*FRT SIGNAL LAMP (RH)	0.00	0.00	cr ✓ *55.00 F
11	1		*FRT HORN	0.00	0.00	bt ✓ *75.00 F
12	1		*FRT PANEL	0.00	0.00	bt ✓ *550.00 F
13	1		*FRT CORNER PANEL (RH)	0.00	0.00	bt ✓ *240.00 F
14	1		*FRT PANEL INNER PANEL (RH)	0.00	0.00	1 ? *240.00 F
15	1		*AIR CON CONDENSER ASSY	0.00	0.00	? *780.00 F
16	1		*INTERCOOLER	0.00	0.00	? *1,400.00 F ✓
17	1		*AIR CON BLOWER ASSY	0.00	0.00	? *1,300.00 F ✓
18	1		*FRT DOOR ROC STICKER (RH)	0	0.00	ne ✓ *20.00 FS
19	1		*FRT WINDSCREEN MOULDING	0.00	0.00	ne ✓ *80.00 F
20	1		*FRT WINDSCREEN SEALANT	0	0.00	ne ✓ *40.00 FS
21	1		*ERP BRACKET	0	0.00	x *26.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)

\$6076.00

6,196.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

Smet \$741

Radiator bt ✓ \$480

Radiator fan blade cr ✓ \$105.

Engine mty de ✓ \$75 x 2. (SET).  
22/11/18

SUMMARY.

- RADIATOR FAN (W/TH) — \$300
- FRT HEADLAMP PANEL (RH) — \$210
- RADIATOR FAN (ONLY) — \$15.
- FRT BUMPER BRACKET (x2) — \$55.

10/30/2018

Estimate Report

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING	New	30.00
2	TO REMOVE & REFIX FRT WINDSCREEN	New	120.00
3*	TO TOP UP AIR CON GAS <i>NEC item</i>	New	100.00 ✓
4 X	TO REMOVE & REFIX FRT DASHBOARD	New	200.00
5	TO KNOCK FRT DOOR (RH), WELD, REMOVE & REPLACE ABOVE PARTS	New	800.00
6	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS	New	800.00
Gross Labour Cost (\$\$) <i>1650</i>			2,050.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

*total \$8270/-*

*less 70% : \$5789/-  
 ~\$6600/- 4/5  
 before exam \$500/-  
 OK? pls revert.  
 Summ 1/2/2019*

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2018 <a href="#">Sendback Est</a>	30 Oct 2018 16:12 <b>S\$8,246.00</b>	31 Oct 2018 14:10 <a href="#">Edit Adj Rpt</a>	<b>S\$6,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$6,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
Supp #1	01 Mar 2019 17:59	01 Mar 2019 18:01 <b>S\$1,470.00</b>	01 Mar 2019 18:01			(Combined)	<b>Combined with Main</b> <a href="#">Uncombine Suppl.</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:	<b>CONCEPTS.SG</b> , Co. Reg. No.: 53040541E		
Vehicle Reg. No.:	<b>GBA7936A</b>	Date of Loss:	26/10/2018 16:00 - :59 [129 Months From LTA Reg Date (Man Yr)]
Claim Type:	<b>OD / SNM18D05134C01</b>	Policy/Cover Note No.:	DMCVSN3040451800 (Comprehensive)
		Excess:	S\$500.00
Repairer:	<b>Sng Ah Tee Motor &amp; Panel Service Pte Ltd (Pioneer)</b> Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Irene Tay Hui Ping</b> - 638986192]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 12/11/2018]		
Driver/Custodian:	TAN EE LING ,EVELYN (37 / Female) , NRIC: S8104016H, Tel: +6596545955 Email: evelyn@conc6pt.com.sg		
Adj Asg. Remarks:	revert		

**ASSOCIATED MAIL RECEIVED**
[View All](#)
[Compose Case Mail](#)

- CHINA\_TAIPING (09/11/2018): Alert - Adj Mandate Approved (S\$6000.00) - GBA7936A - Claim Handler: Irene Tay H...

**ALL ASSOCIATED TASKS**
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**GBA7936A (SNM18D05134C01)**

**OD**



















































**Oct 26 2018 4:00PM**

**[CONCEPTS.SG]**

**Sng Ah Tee Motor & Panel Service Pte Ltd**















Upload Documents			Upload Photos			Compose New Letter			View <span>View in Browser</span>		
Video									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)							Thumbnail	Print	
1	29/10/18 13:50	Video - Accident [Linked Accident Report Documents]							Load MP4		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)							Thumbnail	Print	
1	29/10/18 13:55	Accident Statement							Load HTM		
2	30/10/18 16:12	Repairer Estimates							Load HTM		
3	01/03/19 18:01	Repairer Estimates Suppl. #1							Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	02/11/18 17:21	Adjuster Immediate Advice							Load HTM		
2	08/11/18 10:14	Adjuster Immediate Advice							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
2	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
3	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
4	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
5	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
6	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
7	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
8	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
9	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
10	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
11	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
12	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
13	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
14	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
15	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
16	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
17	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
18	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
19	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
20	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
21	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
22	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
23	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
24	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
25	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
26	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	
27	09/11/18 10:12	General View							Load JPG	<input checked="" type="checkbox"/>	



Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
28	09/11/18 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
29	09/11/18 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
30	09/11/18 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
31	09/11/18 10:12	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
32	09/11/18 10:12	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
33	09/11/18 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
34	09/11/18 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
35	09/11/18 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
36	09/11/18 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
37	09/11/18 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
38	09/11/18 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
39	09/11/18 10:12	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/03/19 11:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	15/03/19 11:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	15/03/19 11:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	15/03/19 11:32	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
78	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
79	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
80	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
81	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
82	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
83	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
84	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
85	15/03/19 11:33	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>	
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	30/10/18 13:28	E-filed GIA report	 Load PDF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	02/11/18 16:48	ESTIMATE	 Load PDF		
2	19/03/19 14:26	Supplementary	 Load PDF		

## Linked Accident Report Documents

Video				View	View in Browser
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	29/10/18 13:50	Video - Accident	 Load MP4		
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	29/10/18 13:55	Accident Statement	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	29/10/18 13:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
2	29/10/18 13:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
3	29/10/18 13:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
4	29/10/18 13:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
5	29/10/18 13:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
6	29/10/18 13:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
7	29/10/18 13:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
8	29/10/18 13:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
9	29/10/18 13:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
10	29/10/18 13:45	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>	
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	29/10/18 13:31	Sketch Plan	 Load TIF		
2	29/10/18 13:51	IC,CI,DL	 Load TIF		

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Repairer

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

Our File No: CS/CTI18019845/T1QD3E2

Date: 19/03/2019

### REFERENCE

Insured/Claimant: CONCEPTS.SG Policy No: DMCVSN3040451800  
Date of Loss: 26/10/2018 Nature of Claim: OD Claim No: SNM18D05134C01

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA7936A**  
Make & Model: NISSAN URVAN, 3.0 D (M) Engine No: ZD30153494K  
Reg. Date: 26/01/2008 (Man. Year: 2007) Chassis No: JN1MG4E25Z0780435  
Colour: Blue Odometer: 255422 km  
Engine Capacity: 2953 cc  
Market Value/New Car Price: S\$24,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15  
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,666.00	6,620.00	1,046.00	13.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,650.00	400.00	19.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,716.00</b>	<b>8,270.00</b>	<b>1,446.00</b>	<b>14.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,000.00</b>		
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	9,716.00	5,500.00	4,216.00	43.39
+ GST 7.00/7.00% (S\$)	680.12	385.00	295.12	43.39
<b>Nett Amount (S\$)</b>	<b>10,396.12</b>	<b>5,885.00</b>	<b>4,511.12</b>	<b>43.39</b>

### INSPECTION

Date of Assignment: 31/10/2018 Present Location: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)  
Date Inspected: 01/11/2018 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)  
Blk 3 Pioneer Road North, #01-18  
Singapore 628457  
Estimated Period of Repair: 6.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 19 Mar 2019)
Parts:	N/A	NISSAN URVAN 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA7936A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	15.00 FS	*15.00 FS
2	1		*FRT BUMPER	Deformed	280.00 F	*280.00 F
3	2		*FRT BUMPER SIDE RETAINER	Necessary	130.00 F	*130.00 F
4	1		*FRT BUMPER REINFORCEMENT	Bent	155.00 F	*155.00 F
5	1		*FRT FOGLAMP (RH)	Distorted	245.00 F	*245.00 F
6	1		*FRT FOGLAMP COVER(RH)	Deformed	65.00 F	*65.00 F
7	1		*FRT HEADLAMP (RH)	Cracked	220.00 F	*220.00 F
8	1		*FRT GRILLE EMBLEM	Cracked	50.00 F	*50.00 F
9	1		*FRT GRILLE	Cracked	230.00 F	*230.00 F
10	1		*FRT SIGNAL LAMP (RH)	Cracked	55.00 F	*55.00 F
11	1		*FRT HORN	Bent	75.00 F	*75.00 F
12	1		*FRT PANEL	Bent	550.00 F	*550.00 F
13	1		*FRT CORNER PANEL (RH)	Bent	240.00 F	*240.00 F
14	1		*FRT PANEL INNER PANEL (RH)	Not Necessary	240.00 F	*- F
15	1		*AIR CON CONDENSER ASSY	Not Necessary	780.00 F	*- F
16	1		*INTERCOOLER	Bent	1,400.00 F	*1,400.00 F
17	1		*AIR CON BLOWER ASSY	Cracked	1,300.00 F	*1,300.00 F
18	1		*FRT DOOR ROC STICKER (RH)	Necessary	20.00 FS	*20.00 FS
19	1		*FRT WINDSCREEN MOULDING	Necessary	80.00 F	*80.00 F
20	1		*FRT WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
21	1		*ERP BRACKET	Not Necessary	26.00 FS	*- FS
<b>Supplementary #1</b>						
22	1		*RADIATOR	Bent / Dented	480.00 F	*480.00 F
23	1		*RADIATOR FAN BLADE	Cracked	105.00 F	*105.00 F
24	2		*ENGINE MOUNTING	Deformed / Distorted	150.00 F	*150.00 F
25	1		*RADIATOR FAN CLUTCH	Distorted	300.00 F	*300.00 F
26	1		*FRT HEADLAMP PANEL RH	Bent	210.00 F	*210.00 F
27	1		*RADIATOR FAN COWLING	Cracked	115.00 F	*115.00 F
28	2		*FRT BUMPER BRACKET	Bent	110.00 F	*110.00 F

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>7,666.00</b>	<b>6,620.00</b>
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	30.00	30.00
2	TO REMOVE & REFIX FRT WINDSCREEN	New	120.00	120.00
3	TO TOP UP AIR CON GAS	New	100.00	100.00
4	TO REMOVE & REFIX FRT DASHBOARD	New	200.00	0.00
5	TO KNOCK FRT DOOR (RH),WELD,REMOVE & REPLACE ABOVE PARTS	New	800.00	700.00
6	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS	New	800.00	700.00
Gross Labour Cost (S\$)			<b>2,050.00</b>	<b>1,650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >